

## FORD A4LD NO ENGAGEMENT IN REVERSE

**COMPLAINT:** No engagement in reverse on late model vehicles with reverse engagement control valve.

**CAUSE:** The cause may be, the Number 2 retainer missing or off location.

**CORRECTION:** Position the Number 2 retainer in the valve body in the location shown in Figure 1.




Figure 1