

FORD AXOD

SOFT 1-2 SHIFT

COMPLAINT: Soft or mushy 1-2 upshift only.

CAUSE: Fill time for intermediate clutch too slow.

CORRECTION: Install stronger spring on the 1-2 capacity modulator valve located in pump body (See Figure 1).




Figure 1