



Technical Service Information

VOLKSWAGEN/AUDI "01M" NO FORWARD OR SLIPS FORWARD

COMPLAINT: Before or after overhaul, vehicles equipped with the 01M transaxle may exhibit a "no forward" engagement or a slipping condition on take-off in first gear.

CAUSE: The cause may be, that the K1 (Forward) Piston is cracked, as shown in Figure 1, which can cause a loss of forward clutch pressure.

CORRECTION: Replace the K1 (Forward) Piston as part of every overhaul.

SERVICE INFORMATION:

At the time of this printing, the K1 (Forward) Piston is not sold, from Volkswagen, seperatly from the complete drum assembly. Aftermarket suppliers have available a "piston kit" to service the K1 drum as well as all of the other bonded pistons.




Figure 1