



Technical Service Information

THM 440-T4 / 4T60-E BOTTOM PAN OIL FILTER CHANGES

COMPLAINT: Some 1993 and 1994 L, N, and W Cars (See Models Below), equipped with a THM 4T60-E transaxle with the structural (Cast Aluminum) side cover may exhibit a fluid leak between the structural side cover and transaxle case. The transaxle case **MUST** be identified with die number 723, as shown in Figure 1.

THIS BULLETIN APPLYS ONLY TO VEHICLES THAT USE THE STRUCTURAL SIDE COVER AND CASE I.D. 723, AND FOUND IN THE FOLLOWING;

1994 Chevrolet Beretta(L), Corsica(L), and Lumina(W)

1994 Buick Skylark(N), and Regal(W)

1994 Oldsmobile Achieva(N)

93-94 Oldsmobile Cutlass Supreme(W)

1994 Pontiac Grand-Am(N), and Grand-Prix(W)


CAUSE: Casting change implemented on case die I.D. 723, which reduced the thickness of a section of case wall affecting the gaskets sealing ability, when used with a structural side cover (See Figure 2).

CORRECTION: Replace the original molded steel side cover gasket with a new replacement gasket service package, available under OEM part number 8651940. This new service package should be used **ONLY** on 93-94 THM 4T60-E transaxles that have case I.D. 723, use a structural side cover, and exhibit a side cover leak.

SERVICE INFORMATION:

Side Cover Gasket Service Package 8651940

THM 4T60 (440-T4)
PREVIOUS DESIGN OIL FILTER



THM 4T60 (440-T4)
NEW "SEALED SEAM" DESIGN OIL FILTER






Figure 1

THM 4T60 (440-T4)
CURRENT DESIGN OIL FILTER



THM 4T60-E
CURRENT DESIGN OIL FILTER



THM 4T60 AND 4T60-E TRANSAXLE OIL FILTERS WILL NOT INTERCHANGE!

Figure 2