



Technical Service Information

TOYOTA A40 SERIES HARSH 1-2 SHIFT

COMPLAINT: Harsh 1-2 shift.

CAUSE: Missing or mis-positioned check ball. High line pressure.

CORRECTION: Install check-ball in proper location or replace Primary Valve Spring with a new spring, part # 90501-18028.




Figure 1