



"2000" SEMINAR INFORMATION "FIXES TODAY FOR Y2K"

INDEX GM & FORD

Video (GM)

New Converter Clutch Strategy.....	4
4T60-E.....	9

Slides (GM)

4L60-E.....	16
4L80-E.....	19
ALLISON.....	53
4T60.....	71
4T80-E.....	73
SATURN.....	79

Video (Ford)

4R70W.....	87
4R100.....	96
5R55N.....	109

ADVERTISER'S

Raybestos.....	IFC	Zoom Technologies.....	57
Lube Guard.....	2	Wesco.....	64
Transtar.....	13	Borg Warner.....	70
Superior.....	18	Sonnax.....	76
Sea Tac.....	26	TCRS.....	95
Rostra.....	32	A-Z Tools.....	108
ATC.....	40	Drive Tech.....	120
Torrington.....	46	Transtech.....	IBC
		Life Products.....	BC

AUTOMATIC TRANSMISSION SERVICE GROUP

9200 South Dadeland Boulevard Suite 720

Miami, Florida 33156

WWW.TRANSONLINE.COM

(305) 670-4161

WWW.ATSGMIAMI.COM



"2000" SEMINAR INFORMATION "FIXES TODAY FOR Y2K"

1

INTRODUCTION

ATSG welcomes you to the year 2000 and WOW the changes we have seen in this 20th century! One of the more significant changes seen is how ATSG's Tech team continues to remain on the cutting edge of today's ever-changing automotive technology. This means valuable and useful information to those who attend ATSG's seminars presenting information in both Video and Slides all in Manuals that can be brought back to the shop to be used the very next business day. That is why for the year 2000, ATSG is proud to present another well orchestrated DO NOT MISS seminar appropriately named "FIXES TODAY FOR Y2K!"

The information and part numbers contained in this booklet have been carefully compiled from industry sources known for their reliability, but ATSG does not guarantee its accuracy.

Copyright © 2000 ATSG

ROBERT D. CHERNAY
TECHNICAL DIRECTOR

JIM DIAL
TECHNICAL CONSULTANT

JERRY GOTT
TECHNICAL CONSULTANT

DAVID CHALKER
TECHNICAL CONSULTANT

ED KRUSE
TECHNICAL CONSULTANT

GREGORY LIPNICK
TECHNICAL CONSULTANT

WAYNE COLONNA
TECHNICAL SUPERVISOR

PETER LUBAN
TECHNICAL CONSULTANT

GERALD CAMPBELL
TECHNICAL CONSULTANT

JON GLATSTEIN
ELECTRICAL CONSULTANT

MARIO ARISTIDES
MERCEDES CONSULTANT

DALE ENGLAND
FIELD SERVICE CONSULTANT

AUTOMATIC TRANSMISSION SERVICE GROUP

9200 South Dadeland Boulevard Suite 720
Miami, Florida 33156

WWW.TRANSONLINE.COM

(305) 670-4161

WWW.ATSGMIAMI.COM

The 28% factor is one reason OEM's choose



Face the facts, the reason you should use LUBEGARD® is the same reason OEM's do... solid test results and years of proven performance.



LUBEGARD® 28% LESS

BETTER WORSE

**INCREASING
INSTABILITY & DAMAGE**

LUBEGARD® 28% LESS

The World's Finest Lubricants



Sea Foam SF® TRANS-TUNE (Sea Foam Sales Co.) 122.2

DURA LUBE™ Advanced Trans Treatment (The Dura-Lube Corp.) 88.3

DR. TRANNY™ Instant Shudder Fixx (ILJ) 71

ATP® ATF Protectant (Automatic Transmission Parts, Inc., Morton Grove, IL) 66.2

Smart Blend™ ATF Protectant (Life Automotive Products Inc. - Version B) 66.2

STP® Trans Treatment (First Brand Corp.) 63.5

Petron Plus™ Automatic Trans Supplement (Petron Intl. Inc.) 50.0

Heartland™ Trans Sealer & Conditioner (Heartland Mfg. Co. Inc.) 49.2

K&W® TRANS-X® (K&W Products) 34.9

GUN
Cond

Trans-Life™ (Life Autom
Products Inc. - Version A)

ENERGY RELEASE® Antifricition Metal Conditioner (Entech Co.) 46.8

MEGA POWER® Automatic Trans Conditioner (Mega Power Inc.) 51

SNAP® Automatic Trans Sealer & Conditioner (Snap Automotive Prod.) 56.3

Slick 50® Auto Trans (Quaker State Corp.) 73.8

JB Trans Stop-Leak (Justice Brothers, Inc.) 111.3

100% Dura-Lube Trans-X® products were tested under conditions to determine the amount of sludge and deposits that would build up in the transmission and engine over a 100,000 mile test cycle. The results showed that Dura-Lube Trans-X® products significantly reduced the amount of sludge and deposits that would build up in the transmission and engine over a 100,000 mile test cycle.

Here are some other reasons to choose LUBEGARD®



GENERAL MOTORS

ELECTRONICALLY CONTROLLED CLUTCH CAPACITY (EC³)

In the 1996 model year a new type of TCC control system was introduced into GM vehicles equipped with 3.8 DOHC engines and the 4T60E transmission and is now in most GM car, truck and van applications except those vehicles equipped with the 4L80E and the 4T80E transmissions.

This system is known as, Electronically Controlled Clutch Capacity (ECCC), or **EC CUBED** for short. This system was designed so that the converter clutch pressure plate would not fully lock to the converter cover which means that this converter clutch was *designed to SLIP!* The ECCC system was introduced in order to reduce the possibility of noise, vibration or chuggle caused by TCC apply.

It is however, a controlled slip, meaning that what the technician was used to seeing on the scan tool as far as TCC duty cycle and TCC slip in the previous TCC system is now quite different and may lead the technician into thinking there is a transmission component slipping.

When viewing the scan tool data with the previous type of TCC control system, TCC duty cycle usually began after the shift into 4th gear, after which, the TCC slip would (if everything was working the way it should), drop to zero and at this point in time TCC duty would be at or about 100% and the converter clutch would now be fully locked to the front of the converter housing.

The only time duty cycle would change would be in a "no torque demand" cruise condition, at which time the duty cycle would drop to about 60% while keeping the TCC slip near zero.

If throttle was increased, the TCC duty cycle would immediately rise back up to about 100% to maintain a near zero TCC slip condition.

This is no longer the case with the EC Cubed TCC control system.

The ECCC system is designed to allow 10 to 60 rpm of slippage, depending on vehicle model. TCC duty cycle will begin as soon as the shift to 2nd gear is made and the scan tool will indicate about 20 rpm of slip.

The movie in figure 1 shows a 4T65E transmission with EC Cubed TCC in first gear, TCC slip is high, there is zero TCC duty cycle. In figure 2 a shift to second gear is made, and now there is 20 rpm of slip and TCC duty cycle is 50%.

In figure 3 a shift is made to third gear and TCC slip is now at 42 rpm and TCC duty cycle is 63%.

NOTE: Notice, due to the slip allowed by the computer the input and output rpm are NOT the same in third gear!

Finally, the movie in figure 4 indicates a shift to fourth has been made and TCC slip is now brought to zero and TCC duty cycle is at 100%.

This small amount of slip will be maintained throughout 3rd and 4th gears as well UNTIL 55mph (88kmh) to 65mph (105kmh) when full TCC application will take place and TCC slip will be near zero. A similar type of TCC operation will be seen during coast down shifts as well.

The technician can expect to see a very active duty cycle through the entire range of TCC operation with the exception of steady cruising speed.

This means that duty cycle will be changing continuously as the system controls slip which means two important concerns to the technician. The first concern is the TCC duty cycle timing and TCC slip factors that the technician will view on the scan tool.



"2000" SEMINAR INFORMATION VIDEO

5

GENERAL MOTORS

ELECTRONICALLY CONTROLLED CLUTCH CAPACITY (EC³)

Due to the fact that a certain degree of slip is acceptable, when does slip become unacceptable?

If the computer sees TCC slip reach 130 rpm, code P1870 will be stored.

The second concern with slip is the heat generated as a result of this slip, which means there must be a change in the converter clutch material in order to withstand the heat. The previous design converter clutch material was either a cellulose based material or in some applications it was Kevlar®. The cellulose based cannot tolerate slip without being destroyed. The Kevlar® can withstand more heat, but with constant slip it would eventually succumb to destruction.

The converter clutch material used with the ECCC system is a woven carbon fiber which allows slippage with little effect on the converter clutch since this material is highly conductive and transfers the heat generated by slip to the converter housing.

It now becomes apparent that a converter with a cellulose based clutch material would be instantly destroyed if installed in a vehicle with ECCC and a ECCC converter put into a vehicle with a conventional TCC control system would produce TCC application feel that would be severely harsh with a washboard effect.

The cellulose based, the Kevlar® converter clutch and the carbon fiber converter clutch materials are shown in figure 5.

Many thanks to Dynamic Manufacturing Co. for their assistance in providing this information.

**GENERAL MOTORS
ELECTRONICALLY CONTROLLED CLUTCH CAPACITY (EC³)****FIRST GEAR**

1998 BUICK 3.8L V6 BUICK SFI		A/C	A/T
** CODES AND DATA. (NO CODES AVAILABLE IN THIS MODE)		OK TO DRIVE	**
-46 OUTPUT RPM	1398	ENGINE RPM	2656
INPUT RPM	2301	VEHICLE SPEED (MPH)	17
TFT (V)	2.45	ECT (°F)	196
TORQUE SIGNAL (PSI)	32	TFT (°F)	179
THROTTLE %	38	GEAR RATIO	2.92
TCC DUTY CYCLE %	0	TP (V)	1.61
ACTUAL PCS AMP	0.58	TCC SLIP (RPM)	356
BRAKE REQUEST	NO	DES PCS AMP	0.58
BATTERY (V)	14.3	BRAKE SW	OPEN
PRESS CTRL %	35	TCC REL PRESS	YES
CURRENT GEAR	1ST	SHIFT MODE	NORMAL
1-2 SOLENOID	ON	CURRENT TAP (PSI)	-11
RANGE A	OFF	2-3 SOLENOID	ON
RANGE C	ON	RANGE B	ON
TFP RANGE	04	TRAC. CTRL	INACTIVE
1-2 SHIFT (SEC)	0.28	A/C CLUTCH	OFF
3-4 SHIFT (SEC)	0.03	2-3 SHIFT (SEC)	0.35
IMS A/B/C/P	OFF/ON/ON/OFF	CRUISE	DISABLED
SHIFT ADAPT	NO	ENGINE RUN TIME	00:1:12
		HOT MODE	NO

Figure 1

SECOND GEAR

1998 BUICK 3.8L V6 BUICK SFI		A/C	A/T
** CODES AND DATA. (NO CODES AVAILABLE IN THIS MODE)		OK TO DRIVE	**
-44 OUTPUT RPM	1506	ENGINE RPM	2234
INPUT RPM	2274	VEHICLE SPEED (MPH)	29
TFT (V)	2.45	ECT (°F)	196
TORQUE SIGNAL (PSI)	65	TFT (°F)	179
THROTTLE %	39	GEAR RATIO	1.57
TCC DUTY CYCLE %	50	TP (V)	1.63
ACTUAL PCS AMP	0.53	TCC SLIP (RPM)	20
BRAKE REQUEST	NO	DES PCS AMP	0.52
BATTERY (V)	13.9	BRAKE SW	OPEN
PRESS CTRL %	30	TCC REL PRESS	NO
CURRENT GEAR	2ND	DES PCS AMP	0.49
1-2 SOLENOID	OFF	SHIFT MODE	NORMAL
RANGE A	OFF	2-3 SOLENOID	ON
RANGE C	ON	RANGE B	ON
TFP RANGE	04	TRAC. CTRL	INACTIVE
1-2 SHIFT (SEC)	0.28	A/C CLUTCH	OFF
3-4 SHIFT (SEC)	0.03	2-3 SHIFT (SEC)	0.35
IMS A/B/C/P	OFF/ON/ON/OFF	CRUISE	DISABLED
SHIFT ADAPT	NO	ENGINE RUN TIME	00:1:34
		HOT MODE	NO

Figure 2



GENERAL MOTORS

ELECTRONICALLY CONTROLLED CLUTCH CAPACITY (EC³)

THIRD GEAR

1998 BUICK 3.8L V6 BUICK SFI		A/C		A/T	
** CODES AND DATA.		OK TO DRIVE		**	
(NO CODES AVAILABLE IN THIS MODE)		ENGINE RPM		2390	
-42 OUTPUT RPM	2351	VEHICLE SPEED (MPH)		31	
INPUT RPM	2348	ECT (°F)		196	
TFT (V)	2.45	TFT (°F)		179	
TORQUE SIGNAL (PSI)	49	GEAR RATIO		1.00	
THROTTLE %	31	TP (V)		1.45	
TCC DUTY CYCLE %	65	TCC SLIP (RPM)		42	
ACTUAL PCS AMP	0.63	DES PCS AMP		0.62	
BRAKE REQUEST	NO	BRAKE SW		OPEN	
BATTERY (V)	14.3	TCC REL PRESS		NO	
PRESS CTRL %	37	SHIFT MODE		NORMAL	
CURRENT GEAR	3RD	CURRENT TAP (PSI)		-16	
1-2 SOLENOID	OFF	2-3 SOLENOID		OFF	
RANGE A	OFF	RANGE B		ON	
RANGE C	ON	TRAC. CTRL		INACTIVE	
TFP RANGE	04	A/C CLUTCH		OFF	
1-2 SHIFT (SEC)	0.28	2-3 SHIFT (SEC)		0.35	
3-4 SHIFT (SEC)	0.03	CRUISE		DISABLED	
IMS A/B/C/P	OFF/ON/ON/OFF	ENGINE RUN TIME		00:1:52	
SHIFT ADAPT	NO	HOT MODE		NO	

Figure 3

FOURTH GEAR

1998 BUICK 3.8L V6 BUICK SFI		A/C		A/T	
** CODES AND DATA.		OK TO DRIVE		**	
(NO CODES AVAILABLE IN THIS MODE)		ENGINE RPM		2296	
-40 OUTPUT RPM	2968	VEHICLE SPEED (MPH)		64	
INPUT RPM	2972	ECT (°F)		196	
TFT (V)	2.45	TFT (°F)		179	
TORQUE SIGNAL (PSI)	52	GEAR RATIO		0.71	
THROTTLE %	45	TP (V)		2.15	
TCC DUTY CYCLE %	100	TCC SLIP (RPM)		0	
ACTUAL PCS AMP	0.51	DES PCS AMP		0.52	
BRAKE REQUEST	NO	BRAKE SW		OPEN	
BATTERY (V)	14.3	TCC REL PRESS		NO	
PRESS CTRL %	38	SHIFT MODE		NORMAL	
CURRENT GEAR	4TH	CURRENT TAP (PSI)		-14	
1-2 SOLENOID	ON	2-3 SOLENOID		OFF	
RANGE A	OFF	RANGE B		ON	
RANGE C	ON	TRAC. CTRL		INACTIVE	
TFP RANGE	04	A/C CLUTCH		OFF	
1-2 SHIFT (SEC)	0.28	2-3 SHIFT (SEC)		0.35	
3-4 SHIFT (SEC)	0.03	CRUISE		DISABLED	
IMS A/B/C/P	OFF/ON/ON/OFF	ENGINE RUN TIME		00:8:01	
SHIFT ADAPT	NO	HOT MODE		NO	

Figure 4

GENERAL MOTORS
ELECTRONICALLY CONTROLLED CLUTCH CAPACITY (EC³)




Figure 5



THM 4T60-E TAPERED ROTOR PUMP CASTING IDENTIFICATION AND INTERCHANGE

CHANGE: Beginning at the start of production for 1994 models, all THM 4T60-E transaxles were produced with a new design "Tapered" pump rotor and new design pump casting with location changes for the suction passage. Refer to Figures 1, 2 and 4. Beginning at the start of production for 1996 models, another new "Light Weight" pump casting was introduced that also requires the tapered rotor. Refer to Figures 1, 2 and 5.

REASON: New tapered rotor increases pump capacity and reduces cavitation for improved durability, and the random vane spacing reduces a noise concern.



PARTS AFFECTED:

- (1) **PUMP ROTOR** - New design is now "Tapered" instead of the previous straight rotor, as shown in Figure 1. The "L" Body and "N" Body vehicles were built using the random spacing of the rotor vanes (34°, 40° and 46°) similar to the 4L60-E design. All other models will use a "Tapered" rotor with equal spacing of the rotor vanes (40°) as shown in Figure 1. All slides, rotors and vanes are still selective sizes.
- (2) **PUMP BODY** - The new design pump body for the tapered rotor has the suction slot in the pump pocket re-sized and moved closer to the center hole for the oil pump drive shaft as shown in Figure 2.

INTERCHANGEABILITY:



- (1) **1ST DESIGN PUMP CASTING** - This pump casting can use either the straight rotor or the new design tapered rotor, as the tapered rotor will retro-fit back in all models of the 4T60-E transaxle. This pump casting can be identified with the presence of two threaded holes for the pump cover and by the casting number, as shown in Figure 3.
- (2) **2ND DESIGN PUMP CASTING** - This pump casting **requires** the tapered rotor as the suction slot in the pump pocket was re-sized and moved closer to the center hole for the oil pump drive shaft, as shown in Figure 4. This pump casting can be identified by the presence of only one threaded hole for the pump cover and by the casting number, as shown in Figure 4. This pump casting, with the tapered rotor will back service all models of the 4T60-E transaxle, but will not replace the 3rd design pump body.
- (3) **3RD DESIGN PUMP CASTING** - This pump casting also **requires** the tapered rotor as the suction slot is in the same position as the 2nd design casting and is obviously a much lighter weight pump with the removal of much material, as shown in Figure 5. This pump also has a different casting number, and does not have any threaded holes for the pump cover, as shown in Figure 5. This pump casting **will not** retro-fit back on the first design valve body as it leaves open the second clutch passage.

PREVIOUS DESIGN "STRAIGHT" PUMP ROTOR





NEW DESIGN "TAPERED" PUMP ROTOR

L & N CAR



A, H, C, K, U & W CAR



Copyright © 1999 ATSG

Figure 1







Figure 2

"1ST DESIGN" PUMP BODY CASTING



THIS PUMP CASTING CAN USE EITHER STRAIGHT OR TAPERED ROTOR



Copyright © 1999 ATSG

Figure 3

Transtar. One company. One philosophy.

Serving your parts needs is our only business.

We're the guys you can count on. The ones who always come through with the parts you need, when you need them. We think of our business as helping you stay in business. And we take that role seriously.

Transtar stocks the world's largest and most comprehensive inventory of parts and kits. We have the quality and



selection you demand, available from our network of 22 locations nationwide. And we back it with service and expertise developed over nearly a quarter century in business.

So call us for your parts needs. Timely delivery. And expert customer service. We do it best because it's all we do.


TRANSTAR®
TRANSTAR INDUSTRIES, INC

7350 Young Drive, Cleveland, OH 44146 U.S.A. Main Office & International Division 440-232-5100 www.transtarindustries.com

*Automatic Transmission Kits & Parts • Manual Transmission Kits & Parts • Flywheels • Torque Converters
• Mounts & Service Items • LuK Clutches • Shop Equipment • Specialty Tools • Test Equipment • Electrical Products*


Call toll free 800-359-3339 for a location near you.

"2ND DESIGN" PUMP BODY CASTING



THIS PUMP CASTING "REQUIRES" TAPERED ROTOR

If the previous design straight pump rotor is used in this casting, the rotor will cover a portion of the "suction slot" as shown in Figure 2, and result in transaxle damage.




Copyright © 1999 ATSG

Figure 4

"3RD DESIGN" PUMP BODY CASTING


Casting Number



*There Are "No"
Threaded Holes
For Cover Bolts*

**THIS PUMP CASTING "REQUIRES" TAPERED ROTOR AND
"WILL NOT" BACK SERVICE PREVIOUS MODELS.**

*If the previous design straight pump rotor is
used in this casting, the rotor will cover a
portion of the "suction slot" as shown in
Figure 2, and result in transaxle damage.*



Copyright © 1999 ATSG

Figure 5



**THM 4L60-E
NEW DESIGN 1-2 ACCUMULATOR PISTON**

CHANGE: Beginning on May 11, 1998 (Julian Date 131) all THM 4L60-E transmissions were built with a new design plastic 1-2 Accumulator Piston, and an ovate (oval) wire outer accumulator spring, to replace the previous design aluminum piston and round wire outer accumulator spring, as shown in Figure 1.

REASON: More cost effective than the aluminum piston.

PARTS AFFECTED:

- (1) 1-2 ACCUMULATOR PISTON - Now manufactured out of plastic instead of the previous aluminum, which necessitated a dimensional change, as the plastic piston is thicker as shown in Figure 1.
- (2) 1-2 ACCUMULATOR OUTER SPRING - Now manufactured out of an ovate (oval) wire instead of the previous design round wire, to eliminate coil bind as shown in Figure 1.

INTERCHANGEABILITY:

The different 1-2 Accumulator Pistons and Outer Springs are not interchangeable. When replacing these parts you must remove the 1-2 Accumulator Assembly and inspect for the presence of either the aluminum or plastic 1-2 accumulator piston.

The plastic piston must use the ovate wire outer spring, and the aluminum piston must use the round wire outer spring to ensure against coil bind and spring breakage.

Refer to "Service Information" below for the proper service package part numbers if replacement is necessary.


SERVICE INFORMATION:

1-2 Accum. Piston Service Package, 4L60, (1982-1993 Aluminum)	24204495
1-2 Accum. Piston Service Package, 4L60-E, (1994-1997 Aluminum).....	24204496
1-2 Accum. Piston Service Package, 4L60-E, (1998-1999 Plastic)	24214343

Note: All service packages include the proper outer spring.


SLIDE

*Aluminum 1-2 Accumulator Piston
"Round Wire" Outer Spring
1982-1993 Only
Part Number 24204495*



Copyright © 1998 ATSG

*Aluminum 1-2 Accumulator Piston
"Round Wire" Outer Spring
1994-1997 Only
Part Number 24204496*



*Plastic 1-2 Accumulator Piston
"Ovate Wire" Outer Spring
1998-1999 Only
Part Number 24214343*





Figure 1

Try These Superior Products!



The 4L80E Shift Correction Package!

Improve overall transmission performance with Superior Transmission Parts' new 4L80E Shift Correction Package. For **normal or heavy duty applications**, the 4L80E Kit comes with a complete custom pressure regulator valve train and a custom anti-shudder converter clutch control valve.



Part # K4L80-E

Helps To Eliminate:


- Runaway high pressure
- Erratic pressure rise
- Converter shudder
- Inconsistent shift feel
- Premature unit failure
- Shift solenoid filter blow-out
- Full time lube

Be Sure To Try Our E4OD Kit!

Like all Superior Shift Correction Packages, the popular E4OD Kit offers simple solutions to today's complex transmission problems. Featuring quality parts, consistent performance and easy-to-use instructions, it's easy to see why the Superior line of Shift Correction Packages is fast becoming the first choice of rebuilders everywhere.

The E4OD Shift Correction Package helps to eliminate the following Problems:

- | | |
|---------------------|--------------------------------|
| • Converter shudder | • Reverse problems |
| • Stacked shifts | • Front seal blow outs |
| • Converter burn up | • Weak shifts |
| • Lube problems | • Improves overall performance |



Part # KE4OD

Make The Shift To...



SUPERIOR
TRANSMISSION PARTS, INC.
THE SIMPLE SOLUTION™

Call For The Distributor Nearest You: 800-451-3115
or Visit Us On Our Website @ www.superior-transmission.com

Shift Correction Packages Available For: TF-TC, 440-T4, 700-R4, 200-4R, 400, 350, 200, 125, E4OD, A4LD, AXOD, 722.3-4, AOD, C-6, AOD-E, AXOD-E, 4L60E, 4L80E, ATX, 500/618 High Performance Kits Also Available For: 200-4R HP, AOD HP, 350 HP, & 700-R4 HP.

THM 4L80-E/4L80-EHD
NEW SHIFT SOLENOID ASSEMBLIES

CHANGE: As a running change during production for the 1999 model year, all 4L80E/4L80EHD transmissions were built with revised Shift Solenoids.

REASON: Revised plastic material for seats in the Shift Solenoids, for improved durability.

PARTS AFFECTED:

- (1) SHIFT SOLENOID "A" - Revised plastic material in the seat area, and connector is still Black in color, and the color of plastic for snout where the "O" ring goes is still Brown just like the previous design (See Figure 1).
- (2) SHIFT SOLENOID "B" - Revised plastic material in the seat area, and connector is still Gray in color, and the color of plastic for snout where the "O" ring goes is still Brown just like the previous design (See Figure 1).

INTERCHANGEABILITY:

The new design Shift Solenoids, will retro-fit back on *all* previous models.

SERVICE INFORMATION:

Shift Solenoid "A" (Black connector, Brown snout)	10478147
Shift Solenoid "B" (Gray connector, Brown snout)	10478148




Figure 1



THM 4L80-E/4L80-EHD
CENTER GEAR BOX DIFFERENCES
ON CENTER LUBE TRANSMISSIONS

CHANGE: Beginning at the start of production for all 1997 model 4L80E/4L80EHD transmissions were produced with center lube, in addition to front and rear lube. ATSG Bulletin No. 97-38 covers some of the changes that occurred. This bulletin covers changes that occurred in the center gear box area that was not covered in bulletin 97-38.



REASON: Provides a more desirable distribution of lube flow to the center of transmission.

PARTS AFFECTED:

- (1) **SUN GEAR SHAFT** - Has revised bushing journals to accommodate the new center support, as shown in Figure 1, and *must* be used with the new center support.
- (2) **SUN GEAR** - Has larger lubrication passages on the inside splines of the sun gear, and the new design has a smaller hole between the gears, as shown in Figure 2.
- (3) **REAR RING GEAR SHAFT** - The lube holes that were cross drilled in the previous shaft, as well as the lube passage through the center, have been eliminated in the new design shaft, as shown in Figure 3.
- (4) **REAR INTERNAL RING GEAR** - New design level has lube passages cut through the area where the shaft splines into the ring gear, and lube passages cut into the bearing race that goes on the internal ring gear in this location, as shown in Figure 4.
- (5) **OUTPUT SHAFT** - New design has eliminated the lube hole that was present in the previous models, as shown in Figure 5.

INTERCHANGEABILITY:





None of the parts listed will interchange with any of the previous design level parts, and none of the previous design level parts can be used in the center lube design level units.

**PREVIOUS DESIGN LEVEL
SUN GEAR SHAFT****1997-UP DESIGN LEVEL
SUN GEAR SHAFT**

*Shortened
Bushing
Journal*


Copyright © 1999 ATSG

Figure 1

**PREVIOUS DESIGN LEVEL
SUN GEAR****1997-UP DESIGN LEVEL
SUN GEAR**



Smaller Hole Here

Figure 2

SLIDE



Copyright © 1999 ATSG

Figure 3

SLIDE**PREVIOUS DESIGN LEVEL
REAR RING GEAR AND BEARING RACE****1997-UP DESIGN LEVEL
REAR RING GEAR AND BEARING RACE**

Copyright © 1999 ATSG

Figure 4

SLIDE**PREVIOUS DESIGN LEVEL
OUTPUT SHAFT****1997-UP DESIGN LEVEL
OUTPUT SHAFT****Copyright © 1999 ATSG****Figure 5**



The SEATAC Difference

SEATAC PARTS WAREHOUSE stocks the most intense coverage of AC DELCO transmission parts available. An extensive inventory on the shelf ready to ship to any place in the US or International. From Cases, Hard Parts, O-rings, plus an extensive line of electronics to small screws...

all available at dealer cost.

Two generations of parts experience tells you our sales and technical service representatives have the knowledge to answer questions regarding installation or interchangeability.

For quick service and delivery, call the SEATAC "Hot Line". SEATAC also carries a broad range of Chrysler and Ford parts, and is a full service aftermarket warehouse.



**SEATAC PARTS
WAREHOUSE, INC.**

1 • 8 0 0 • 7 3 5 • 7 1 9 1

2627 S. 248th • Kent, WA. 98032

Fax: 253 • 946 • 0478



"2000" SEMINAR INFORMATION
SLIDE

27

G. M. DIESELS
WHAT IS A CODE "88"

COMPLAINT: After TCM replacement a no 3-4 shift and no TCC occurs with a code 88 stored.

CAUSE: A code 88 indicates that Top Dead Center is offset by plus or minus two degrees. This can be caused by a pump priming problem or that the TCM has lost its memory (i.e. disconnected battery). When a TCM has been replaced or loses its memory, it will need to be flashed with the required TDC OFFSET parameters to eliminate code 88. Once new parameters are set, code 88 will be erased and Overdrive and TCC will be restored.

CORRECTION: Have the TCM flashed with new TDC OFFSET parameters. Note: If codes 91-98 are present, they too will need to be addressed. These are cylinder balance fault codes. An injector balance test can be performed with a factory scanner for each cylinder. The injection pump should also be checked for timing.

G.M. PICK UPS


IGNITION SWITCH REPLACEMENT

COMPLAINT: No solenoid supply voltage at pin E in the case connector.

CAUSE: G.M. Trucks with 4L60-E and 4L80-E transmissions can loose voltage to the solenoids at pin E because of a faulty ignition switch. The most common switch to go bad are on vehicles with air bags. Apparently the switch was made smaller to accommodate room for the air bag making it prone to premature wear. Ignition switches can be as high as \$200.00 plus dollars and requires a couple of hours of work to replace the switch.

CORRECTION: One method is to just simply replace the switch. Dan Tucker from Pine Bluff Arkansas has developed a less expensive method both in parts and time. In his own words, this is what he does:

The relay I use is a Ford Bosh relay part number F0AZ-14NO89-A (it is the least expensive relay I could find, though many vendors make it such as Standard...part # Ry115). I excite the relay with the ignition fuse under the hood in the under hood fuse box. It is located on the drivers side. The ignition fuse that is on a separate circuit from the PRNDL's circuit is the FRONT MOST OUTSIDE small fuse in the underhood box. It is normally a 20 amp fuse. You can get an "add a circuit fuse tap" and get the IGNITION voltage you need to excite the relay. Since the relay draws very low amps, the ignition circuit will never "feel" the draw of the added relay. The next step is to ground the relay. This is easily done by grounding it to the master cylinder mounting stud. You then need a 12 volt power source to send to the "E" terminal through the relay. This can be found behind the underhood fuse box. Now all you got to do is run the relay switched wire to the transmissions "E" terminal. The "E" terminal is most easily accessed at the transmission's case connector. Just splice it into the existing "E" wire. Do NOT cut the "E" wire. We always hole punch and attach a laminated business card with a brief description on the back of the added circuit, to the relay. This way, if someone down the road works on it, they aren't in the dark. The whole job takes about 20 minutes, and the fix is BETTER than new. We make up several relay and harnesses up at a time, which greatly reduces the time. Below is the drawing.



GM 4L80E

STUCK IN FIRST GEAR, NO VEHICLE SPEED SIGNAL

COMPLAINT: The transmission is stuck in first gear, when scanning for codes on 1991-93 trucks and vans, there are no codes stored. On 1994 trucks and vans a code 74 is stored for "no input speed sensor signal".

When data is displayed on the scan tool, in addition to no input rpm, no output rpm is seen and with the vehicle moving forward, the scan tool data display indicates vehicle speed is 0 mph.

CAUSE: 1991-94 trucks and vans equipped with the 4L80E transmission has computer strategy that will *not allow the PCM to look at output rpm if there is no input rpm*.

Without input rpm the PCM ignores output rpm causing the PCM to not see any vehicle speed signal when the vehicle moves in a forward direction, and therefore the PCM has no reason to shift the transmission out of first gear.

It wasn't until the 1994 model year that the PCM acquired the ability to store a code 74 when no input speed sensor signal was seen.

On 1995 and later trucks and vans the computer strategy was changed to eliminate this problem. On those trucks and vans there will be output rpm and vehicle speed even though there is no input speed signal.

CORRECTION: When a no upshift condition exists, do not assume it is a vehicle speed system problem. On 1991-93 trucks and vans scan for data and make certain you have an input rpm signal. On 1994 vehicles, if code 74 is stored with the above symptoms, that is a definite indicator that the input speed sensor is causing the problem.




Figure 1



SLIDE

DIGITAL RATIO ADAPTER CONTROLLER (DRAC)

VEHICLE SPEED BUFFER

The Digital Ratio Adapter Controller ("DRAC") or what is now called the Vehicle Speed Buffer, receives an AC voltage signal from the vehicle speed sensor (VSS), it then converts this AC voltage signal to a digital signal which can be interpreted by the PCM/TCM (Refer to Figure 1) as well as changing the frequency of that signal which can then be used to upshift the transmission, and is also used for Speedometer Operation and Accuracy, the ABS System, Cruise Control and other systems dependant on a vehicle speed signal as well as shift timing calibration and speedometer accuracy on vehicles equipped with four wheel drive when 4W Low is selected.

Vehicle Speed Sensor locations for the 4L80E and 4L60E transmissions in both 2 wheel and 4 wheel drive models can be identified in figures 2 and 3.

The "DRAC" also allows changes in tire size and axle ratio to be easily adapted to the vehicle systems by utilizing "DRAC" modules of different calibrations.

The "DRAC" helps the vehicle computer to calculate vehicle speed by pulsing a voltage signal sent to it by the PCM/TCM at an extremely rapid speed and the PCM/TCM will calculate vehicle speed by monitoring the time between these pulses.

One of the problems the technician has to be aware of is, the owner of the vehicle may change tire and wheel size or change the differential to a different axle ratio which would affect transmission operation as well as the other systems that depend on the "DRAC" for their operation.

Of course, if you are expected to diagnose and repair the "DRAC" the first thing you have to do is **FIND IT!**

The Drac shown in figure 4 would be extremely difficult to find unless you know where to look, as you can see *it is an integral part of the speedometer cluster!* This is found on 1991 "C" and "K" trucks with 4L80E transmission only, however, it was used on earlier trucks that are equipped with the 4L60 (700-R4) transmission that have a PM Generator for a speed sensor.

When a problem occurred with the internal Drac, it was replaced as an assembly, and although the internal parts were never made available at the parts counter, the illustration in figure 5 shows the internal parts and how it is calibrated according to the tire chart also shown.

To diagnose the internal Drac use the schematic and diagnostic tree in figure 6. The location of the external Drac for the 1992 and later "C" and "K" trucks is shown in figure 7, the location of the Drac in 1991 and later "G" Vans is shown in figure 8. In figure 9 the location of the Drac for the 1991 "R" and "V" trucks is shown, make note that even though this is a 1991 pickup truck, the "R/V" series used an externally mounted Drac and is **NOT** to be confused with the 1991 "C/K" pickup truck models. 1991 was the last year for the "R/V" models.

In figures 10, 11 and 12 are the Drac locations for the "P" series vans and "P" series commercial chassis and motor home models. The schematic and diagnostic tree for the 1992 and later "C/K", "G" and "P" series vehicles can be found in figure 13.

The location of the Drac in the 1993-94 "M" and "L" Vans can be found in figure 14 and the 1995 model Drac location can be found in figure 15.

NOTE: Any 1995 and later truck or van equipped with an external Drac that is mentioned in this material, is **NON-OBDII**. Any truck that is OBDII certified will **NOT** have an external Drac because this function is performed internally within the Vehicle Control Module (VCM). Car models never had an external drac.

In figure 16 the location of the Drac for the 1993 and later "S" and "T" Trucks can be found. The schematic and diagnostic tree for the "M/L" Vans and the "S" truck only is shown in figure 17. (The "T" Truck diagnostics can be found in the four wheel drive section).

DIAGNOSTIC TIP: When diagnosing the codes stored by a malfunctioning vehicle speed system, it is important to know that code 24 is a loss of vehicle speed signal from a stop, while code 72 is far more difficult because it means there was a loss of vehicle speed signal "on the fly" or, intermittently. Codes 24 and 72 are usually generated by circuit 437 malfunctions. With the start of the 1994 model year, you will notice an additional circuit in the schematics which indicates miles per hour to the computer. A malfunction in these circuits will usually generate code 16 and is **ALMOST** always a faulty Drac.

The four wheel drive section begins with figure 18 and will require some additional diagnostics.

DIGITAL RATIO ADAPTER CONTROLLER (DRAC)




Figure 1





Figure 2


Rostra Introduces Four New Solenoid Kits for Toyota




52-9001 Three solenoids; 2 shift solenoids, and 1 lock-up solenoid for the Toyota A240E and A241E transmissions



52-9002 Three solenoids; 2 shift solenoids, and 1 lock-up solenoid for the Toyota A340E, 340F, and 340H transmissions



52-9003 Three solenoids; 2 shift solenoids, and 1 lock-up solenoid for the Toyota A540E transmissions



52-9004 Three solenoids; 2 shift solenoids, and 1 lock-up solenoid for the Toyota A245E and A246 transmissions

Our solenoid kits

are more convenient and less expensive than buying individual parts. Order one part number instead of three!




**Rostra
Precision
Controls, Inc.**

2519 Dana Drive, Laurinburg, NC 28352
Phone 910/276-4853 • Fax 910/276-1354

A New Generation of Technology

Now available from your local distributor.

DIGITAL RATIO ADAPTER CONTROLLER (DRAC)



4L60E

Figure 3

1991 "C & K" TRUCK ONLY




Figure 4

DRAC LOCATION AND DIAGNOSIS

1991 "C & K" SERIES 4L80E DRAC CALIBRATION

SPEEDOMETER CALIBRATION CHART

AXLE RATIO	TIRES	RPO	HWY/OOR AT/ALS	PBS TO REMOVE
2.73 (GL2)	P205/75R15	(VCE,YCB)	ALS	1,4,5
	P235/75R15	(YFL,YFN,YFM)	ALS	3,5
	P195/75R15	(VAR,VAS)	ALS	1,2,4,5
	P225/75R15	(YET,YEV,YEU)	ALS	2,3,5
3.08 (GL4)	P205/75R15	(VCE,YCB)	ALS	3,5
	P195/75R15	(VAR,VAS)	ALS	2,3,5
	P225/75R15	(YET,YEV,YEU)	ALS	6
	P235/75R15	(YFL,YFN,YFM)	ALS/OOR	2,3,4,5
3.42 (GL6)	P205/75R15	(VCE,YCB)	ALS	1,3,4,5
	P195/75R15	(VAR,VAS)	ALS	1,2,3,4,5
	P225/75R15	(YET,YEV,YEU)	ALS	1,4,5
	P235/75R15	(YFL,YFN,YFM)	ALS	4,5
	LT225/75R16	(YHE,YHV,YHQ)	ALS	2,3,5
	LT245/75R16	(YHM,YBK,YBL)	ALS	2,5
	LT265/75R16	(YGL,YGM)	OOR	1,2,3,4,5
	LT225/75R16	(YHR,YHU,YHN)	OOR	2,3,5
	LT245/75R16	(YHK,YBN,YBK)	OOR	2,5
	7.50-16LT	(YFF)	HWY	1,2,3,4,5
3.73 (GE4)	P205/75R15	(VCE,YCB)	ALS	1,3,5,6
	P195/75R15	(VAR,VAS)	ALS	1,2,3,5,6
	P225/75R15	(YET,YEV,YEU)	ALS	1,5,6
	P235/75R15	(YFL,YFN,YFM)	ALS	1,2,3,4,5
	LT225/75R16	(YHE,YHV,YHQ,YHP)	ALS	2,3,4,6
	LT245/75R16	(YHM,YBK,YBL)	ALS	2,4,6
	7.50-16LT	(YGF)	HWY	2,3,5
	LT245/75R16	(YHK,YBN,YBK)	OOR	2,4,6
	LT265/75R16	(YGL,YGM)	OOR	2,3,5
	LT225/75R16	(YHR,YHU,YHN)	OOR	1,3,4,6
4.10 (GE5)	LT245/75R16	(YHM,YBK,BVL)	ALS	1,2,5,6
	LT225/75R16	(YHP,YHQ)	ALS	1,2,3,5,6
	7.50-16LT	(YFF)	HWY	1,2,3,4,5
	LT225/75R16	(YHR)	OOR	2,3,5,6
	LT245/75R16	(YHK,YBN,YBK)	OOR	2,5,6
	LT225/75R16	(YGL,YGM)	OOR	1,2,3,4,5
4.56 (MC4)	LT225/75R16	(YHP)	OOR	1,7
	LT225/75R16	(YHP,YHQ)	ALS	2,7
	LT245/75R16	(YHM)	ALS	3,4,5,6
	LT245/75R16	(YHK)	OOR	3,4,5,6
	7.50-16LT	(YFF)	HWY	4,5,6





Figure 5

1991 "C/K" TRUCK *ONLY* WITH INTERNAL DRAC WITH 4L80E








Figure 6

DRAC LOCATION AND DIAGNOSIS**1992 & LATER "C & K" SERIES TRUCKS NON-OBDII**

**BEHIND GLOVE BOX
(REMOVE GLOVE BOX INSERT
AND ACCESS DRAC THROUGH
GLOVE BOX OPENING)**





REAR OF DASH


Figure 7

DRAC LOCATION AND DIAGNOSIS

1991 & LATER NON-OBDI "G" SERIES VAN



**PARKING
BRAKE
BRACKET**



**CRUISE CONTROL
MODULE**

DRAC




Figure 8

DRAC LOCATION AND DIAGNOSIS

1991 R/V SERIES PICKUP TRUCK




Figure 9

1991 "P" SERIES STEP VAN






Figure 10

SLIDE**DRAC LOCATION AND DIAGNOSIS****1992 & LATER NON-OBDII "P" SERIES STEP VAN****Figure 11****1991 & LATER NON-OBDII "P" SERIES MOTORHOME AND COMMERCIAL CHASSIS****Figure 12**



Committed to Quality


You told us what you want. Converters that work when you install them. You want quality.

That's why we're investing in better tooling in our plants, and training our employees to build the best converter in the industry.

To meet our commitment, we:

- Balance every torque converter to eliminate vibration
- Check end-play and run-out to insure the tightest tolerances in the industry
- Manufacture hubs using state-of-the-art CNC machines that allow us tolerances within .000005 of ATC specs
- Burnish all hubs to extend bushing and hub life.

You work hard to satisfy your customers. We're listening and we're working hard to satisfy you. ATC delivers.



Converter Spec Tag



Mamco
Converters

TRANS MART

TRUCK-ONE
EQUIPMENT

TRANZPARTS

ALL
PARTS

SPENCER
INDUSTRIES

METRAM

DIVERCO

TRUCK
EQUIPMENT

TRUCK
EQUIPMENT

Working together to keep you moving.

SLIDE

1991 "R" & 1992 & LATER "C" NON-OBDII 2WD TRUCKS
1991 & LATER "G & P" NON-OBDII VANS WITH EXTERNAL DRAC






Figure 13

DRAC LOCATION AND DIAGNOSIS

1993-94 "M & L" VANS NON-OBDI



VIEW IS FROM REAR OF DASHBOARD

Figure 14

DRAC LOCATION AND DIAGNOSIS







Figure 15

DRAC LOCATION AND DIAGNOSIS

1993 & LATER "S & T" TRUCKS NON-OBDII



VIEW IS FROM REAR OF DASHBOARD

Figure 16

SLIDE

1993 & LATER 2WD "S" TRUCKS NON-OBDII WITH 4L60E

1993 & LATER "M & L" VANS NON OBDII WITH 4L60E




Figure 17



Winners Know How To Make Every Second Count.



Torrington Transmission Bearings Kits get you to the finish line faster.

Whether you're tearing down a drag strip or tearing down a transmission, you know that every second counts.

For you, the winning edge comes from doing a transmission job quickly and efficiently. And making sure it doesn't come back to haunt you.

Ask your parts supplier for Torrington Transmission Bearings Kits. Or ask yourself this question, "Do I have time to waste

looking for old, worn out transmission bearings and reducing my profit margin when I can replace them for a fraction of the total cost of the job?"

Torrington Kits make it easy. You get the entire set of quality replacement bearings in one neat package.

If your goal is smooth running transmission repair work, let Torrington put you in the driver's seat.

**TORRINGTON
INGERSOLL-RAND**

Progress Through Performance

4 WHEEL DRIVE SECTION**1991-93 4WD "K & V" TRUCKS WITH EXTERNAL DRAC WITH 4L80E**

The 1991-93 4x4 vehicles indicated above equipped with the 4L80E transmission, utilize a 4WD system whereby when 4 wheel low is selected, the gear reduction is seen by the computer by comparing output shaft speed to prop shaft speed via the VSS in the transfer case and the output shaft speed sensor. At this time the computer switches strategy to allow for the gear reduction in 4 wheel low so that shift timing and speedometer operation is accurate.

Otherwise it is the Transmission Output shaft Speed Sensor that upshifts the transmission, it is the VSS in the transfer case that calibrates shift timing and speedometer accuracy in 4 wheel low only, as seen in figure 18.

The diagnostics for this type of system require some additional diagnostic steps due to the TOSS being the speed sensor that upshifts the transmission and is "HARD WIRED" to the PCM/TCM and is internally buffered by the PCM/TCM and the VSS in the transfer case which is wired to the Drac and is responsible for the gear reduction calibration to compensate for shift timing and speedometer accuracy that is necessary when 4 wheel low is selected. The schematic and diagnostic tree for this system can be found in figure 19.




Figure 18

1991-93 4WD "K & V" TRUCKS WITH EXTERNAL DRAC WITH 4L80E




Figure 19

4 WHEEL DRIVE SECTION

1994 & LATER 4WD "K" TRUCKS NON-OBDII WITH 4L80E

1993 & LATER 4WD "K" TRUCKS NON-OBDII WITH 4L60E

The 1994 & later 4x4 vehicles indicated above with 4L80E transmission and the 1993 and later 4x4 vehicles indicated above with 4L60E transmission that are non-OBDII, utilize a **4WD Low Switch**, located in the transfer case to signal the computer that 4W LOW has been selected. It does this by supplying 12V to the PCM when in 2WD or 4W HI modes. When 4W LOW is selected the 4W LOW switch grounds its 12V signal changing it to ZERO VOLTS. The computer, recognizing this voltage difference, then changes its strategy which adjusts for correct shift timing and speedometer operation in order to compensate for the gear reduction that occurs when 4W Low is selected.

Vehicles equipped with the 4L80E transmission may have a dummy speed sensor located in the output speed sensor location, there is no wiring for this speed sensor, it is there only to plug the hole!

Later models will have a plug in this location, the TOSS function on 1994 and later vehicles with the 4L80E transmission was eliminated, the VSS in the transfer case along with the 4W Low Switch takes over the functions of calibrating vehicle speed signal input, shift timing and speedometer operation and accuracy in all transfer case modes as shown in figure 20.

1993 and later vehicles equipped with the 4L60E transmission will have the VSS in the transfer case ONLY and the 4W Low Switch located there as well. Circuit diagnosis for this type of system is illustrated in figure 21.

NOTE: *Just because the vehicle you are working on is a 2WD model and it is stuck shifting, it is wired for a 4 Wheel Low Switch which could be grounded somewhere causing this problem.*

Be sure to check the status of the 4W Low Switch parameter on your scan tool, if it says "YES", look for a grounded circuit!

The VSS system diagnostics for 1993 and later 4WD NON-OBDII "T" trucks become more involved and vary depending on whether it is equipped with a mechanically shifted transfer case or an electronically shifted transfer case.

The schematic and diagnostic tree for the mechanically shifted transfer case model can be found in figure 22, and, the schematic and diagnostic tree for the electronically shifted transfer case model can be found in figure 23.




Figure 20

SLIDE

1994 & LATER 4WD "K" TRUCKS NON-OBDII WITH 4L80E
1993 & LATER 4WD "K" TRUCKS NON-OBDII WITH 4L60E





Figure 21



**STUCK IN 1ST GEAR, SPEEDOMETER MAY OR MAY NOT WORK
MPH INDICATES ZERO, CODES 16, 24 OR 72 MAY BE STORED**

**STACKED OR LATE
SHIFTS,
SPEEDOMETER
INACCURATE**





Figure 22

1993 & LATER 4WD "T" TRUCKS NON-OBDII WITH ELECTRIC SHIFT TRANSFER CASE



STUCK IN 1ST GEAR, SPEEDOMETER MAY OR MAY NOT WORK MPH INDICATES ZERO, CODES 16, 24 OR 72 MAY BE STORED




Figure 23



"2000" SEMINAR INFORMATION

SLIDE

53

ALLISON 1000/2000 SERIES PRELIMINARY INFORMATION

Allison Transmission has now developed a family of two new automatic transmissions, referred to as the 1000 Series and the 2000 Series, for light duty (8600-19850 GVW) and medium duty (19850-30000 GVW) commercial trucks. These two new transmissions are scheduled to start appearing in General Motors vehicles for the 2000 model year and come in two wheel drive and four wheel drive configurations, as shown in Figure 1. Both the 1000 and 2000 Series are available with an optional PTO gear. The PTO gear is driven off of the torque converter, and thus is turbine driven. Engine driven performance can be obtained by engaging the torque converter clutch during neutral PTO operation. PTO mounting provisions are in the form of a standard SAE 6 bolt pad on each side of the transmissions main case, as shown in Figure 1.

The 1000 and 2000 Series transmissions both have helical cut planetary gear systems to minimize noise concerns and come in two different gear ratio configurations. The 1000 Series uses closer steps to improve the shift quality that we now expect from an automatic transmission. The 2000 Series uses wider steps to accommodate the greater vehicle weights associated with the 2000 Series. The gear ratios for both of the new units are shown in Figure 2.

The 1000 and 2000 Series transmissions have a Park position, Reverse, Neutral and five forward speeds with 5th gear being overdrive, and are completely electronic shift controlled. Notice in Figure 2 that the standard General Motors case connector has been utilized, and the Park/Neutral switch is exactly the same switch used currently on the THM 4L60-E transmission. Two different bottom pan configurations are also provided to make these units even more versatile, and the dimensions have been provided in Figure 3. The 1000 and 2000 Series transmissions utilize five clutch packs (No Bands-No Freewheels) to obtain the five forward gears and reverse. We have provided you with a cut-away illustration to identify the clutch packs and their location in the unit, and a clutch application and solenoid chart to assist you in diagnosis as shown in Figure 4.



The illustration in Figure 5 identifies the six solenoids on the valve body that are used to control the shifting from gear to gear, shift feel as it is clutch to clutch, and the converter clutch apply and release. A solenoid resistance chart and terminal identification has been provided in Figure 6, and a wiring schematic of the internal wire harness and colors is shown in Figure 7.

Both of the new units also utilize the familiar GM Pressure Switch Assembly with the normally open and normally closed switches, and temperature sensor. We have provided you with terminal identification and function in Figure 8. Figure 9 illustrates the bottom side showing switch location and whether they are "Normally Open" or "Normally Closed". The Pressure Switch Assembly bolts to the main valve body as shown in Figure 10.

Air pressure test passages have been provided for you in Figure 11, and Figures 12 thru 14 will show you retainer locations, and the only screen in the valve body. Notice that there are not any checkballs.

We should have a manual available soon.


ALLISON 1000/2000 SERIES TRANSMISSION



Copyright © 2000 ATSG



Figure 1

GEAR	1000 Series Ratios	2000 Series Ratios
<i>First</i>	<i>3.10</i>	<i>3.51</i>
<i>Second</i>	<i>1.81</i>	<i>1.90</i>
<i>Third</i>	<i>1.41</i>	<i>1.44</i>
<i>Fourth</i>	<i>1.00</i>	<i>1.00</i>
<i>Fifth</i>	<i>0.71</i>	<i>0.74</i>
<i>Reverse</i>	<i>4.49</i>	<i>5.09</i>



Copyright © 2000 ATSG

Figure 2




Copyright © 2000 ATSG

Figure 3



HYDRAULIC CIRCUIT ANALYZER



What could make more sense – test now...save later!

PRESSURIZED ATF

UNIT TEST PLATES

You can now hydraulically check every transmission you work on – before you put it into the vehicle!

HYDRAULIC PROBE

it's that easy!

EASY TO READ GAUGE

transmission.

without dismantling the

SHOP POWER

MOBILE

ZOOM TECHNOLOGY, INC.

1003 Industrial Drive • West Berlin, NJ 08091

1.856.767.8840 • Toll Free: 1.800.322.0806


Fax: 1.856.767.8839 • www.zoom-tech.com

Patents #4809544, #4998437. Other US & Foreign Patents Pending.



SLIDE

ALLISON 1000/2000 SERIES TRANSMISSION



Range	C1 Clut	C2 Clut	C3 Clut	C4 Clut	C5 Clut	Sol "A"	Sol "B"	Sol "C"	Sol "D"	Sol "E"	Sol "F"	Ratios	
												1000	2000
<i>Park</i>					ON	**	**	X	X	X			
<i>Reverse</i>			ON		ON	**	**		X	X		4.49	5.09
<i>Neutral</i>					ON	**	**	X	X	X			
<i>OD-1st</i>	ON				ON	**	**		X			3.10	3.51
<i>OD-2nd</i>	ON			ON		**	**				*	1.81	1.90
<i>OD-3rd</i>	ON		ON			**	**	X			*	1.41	1.44
<i>OD-4th</i>	ON	ON				**	**	X		X	*	1.00	1.00
<i>OD-5th</i>		ON	ON			**	**			X	*	0.71	0.74

X = Electrical Power Applied To Solenoid


** = Apply Solenoid "F" To Apply Converter Clutch*

*** = Solenoids "A" and "B" are "Trim" solenoids used to control oncoming, off-going, and holding pressure to the five clutch packs.*

Copyright © 2000 ATSG

Figure 4

SOLENOID I.D.




Solenoid's "A" and "B" are clutch pressure control solenoids and are "Normally Closed"

Solenoid's "C", "D" and "E" are shift solenoids and are "Normally vented"

Solenoid "F" is the TCC pwm solenoid

Figure 5

SOLENOID AND TEMP. SENSOR RESISTANCE CHART




CONNECTOR FACE VIEW AS IN THE VEHICLE


<i>Solenoid</i>	<i>Terminals</i>	<i>Resistance In Ohms</i>
A	L and M	6 Ω
B	N and P	6 Ω
C	C and W	22 Ω
D	C and B	22 Ω
E	C and A	22 Ω
F	J and S	11 Ω
TEMP SENSOR	H and G	2.8K Ω @ 72° F

All Ohms readings are actual at room temperature.

INTERNAL WIRE SCHEMATIC




CONNECTOR FACE VIEW



Copyright © 2000 ATSG

Figure 7


PRESSURE SWITCH ASSEMBLY TERMINAL IDENTIFICATION



Copyright © 2000 ATSG

Figure 8

PRESSURE SWITCH ASSEMBLY "BOTTOM SIDE"



*Five "Normally Open" (N/O) Switches
One "Normally Closed" (N/C) Switch*

Figure 9



Wesco

**AUTOMATIC
TRANSMISSION PARTS**

AVE. LOMAS VERDES N-24 BAYAMON, PUERTO RICO 00956 USA
(787)785-4329 • 780-6643 • 798-2270 • Fax: 785-7623

Visit our web site at: www.wescotrans.com e-mail: wesco@tld.net

Distributors for:


**Alto Products
Toledo Trans-Kits
Sonnax
Norco
Teckpak
Transtec
Southeast/Craz-Soap
Lubegard
SPX/OTC
Interparts
Zoom Technology**

**High Performance Clutch Plates, Hard Parts, Torque Converter,
Flywheels, Lubricants, Mounts, CV-Joints, Shop Equipment,
Specialty Tools, Automatic Transmission Kits, Soft Parts, Oil Cooler, Electronic Equipments,
Power Steering & Rack Pinion Kits**

USED AND REBUILD TRANSMISSIONS

WE EXPORT
wesco transmissions


ALLISON SERIES 1000/2000 COMPLETE VALVE BODY



Copyright © 2000 ATSG

Figure 10


AIR PRESSURE TEST PORTS



Copyright © 2000 ATSG

Figure 11


ALLISON 1000/2000 SERIES
UPPER VALVE BODY RETAINER LOCATIONS



Copyright © 2000 ATSG

Figure 12


TYPICAL SPACER PLATE



Copyright © 2000 ATSG

Figure 13

ALLISON 1000/2000 SERIES
LOWER VALVE BODY RETAINER AND SCREEN LOCATION



Copyright © 2000 ATSG

Figure 14

EDMOND RICHARDSON

As two-time National Hot Rod Association (NHRA) World Champ,
12 time division champ, and 39 national events winner,
Edmond knows that winning is all about confidence.
Confidence in yourself and the products you rely on.



LET BORG-WARNER RACING PRODUCTS HELP PUT YOU IN THE WINNER'S CIRCLE


Two-time National Hot Rod Association (NHRA) World Champion Edmond Richardson loves driving with Borg-Warner's powerful line-up of high performance racing products.

Borg-Warner is the market leader in automatic transmission system technology. We design and manufacture our parts to meet or exceed rigid OEM specs for over 80 transmissions world-wide, including Edmond's extreme duty applications – like GM's powerglide band for racing-only transmissions, racing grooved high-energy clutch plates, sprags for racing torque converters, pro-stock transmissions and high performance automatics.

So, whether Edmond's lighting up the race track or handling the demands of daily driving, he's confident he's using the best parts available because Borg-Warner parts are the original parts designed for his transmissions.

That's the kind of confidence that breeds
world champions. And winners like you.

Ask for Borg-Warner high performance
automatic transmission parts at
fine distributors nationwide.



 **BorgWarner**

Borg-Warner Automotive Automatic Transmission Systems Corporation 1140 North DuPage Avenue Lombard, IL 60148

www.bwauto.com

The Borg-Warner Indianapolis 500 Trophy is a registered trademark of Borg-Warner Automotive.



CADILLAC

4T60 CODE 39 VCC ENGAGEMENT/ELECTRICAL PROBLEM

COMPLAINT: Reoccurring diagnostic trouble code 39, VCC engagement or electrical problem. The converter has been replaced with another VCC converter or a Buick FY9B converter and the code remains. The solenoid has been changed as well. No visual problems are observed with the valve body, channel plate, accumulator, sealing rings, pump and pump shaft.

CAUSE: One cause may be a defective brake switch (See Figure 1). The brake switch may not be expected as the converter clutch apply is felt before the code is stored. Before the code is stored, the converter clutch apply can be released when the brake is depressed. The problem with the brake switch is that it does not allow the full battery voltage to be sent to the solenoid (See Figure 2). When the computer grounds the solenoid, insufficient current draw is detected and the computer produces code 39.

CORRECTION: The wiring diagram in figure 2 shows how battery voltage is supplied to the Brake Switch on terminal A. The voltage goes through the switch and out terminal B which then supplies voltage to the transaxle at the A terminal in the case connector. Voltage at the A terminal in the case connector can be observed with a volt meter. If less than 10 volts is observed, a check should be made at the Brake Switch to verify that the proper voltage is being supplied to the switch at terminal A. If battery voltage is seen at terminal A of the Brake Switch connector and less than 10 volts on the B terminal, replace to brake switch.




Figure 1




Figure 2



"2000" SEMINAR INFORMATION

SLIDE

73

THM 4T80-E

MIL INDICATOR LAMP ILLUMINATED AND DTC CODE P0503 STORED

COMPLAINT: Some owners of 1998-1999 Cadillac or 1998-1999 Auroras equipped with the 4T80-E transaxle, built prior to January 21, 1999 (Build Year 9, Julian Date 021), (See Figure 1) may comment on one of the following conditions: Speedometer fluctuates or is inoperative; Cruise Control is inoperative; Decreased fuel economy; Malfunction Indicator Lamp (MIL) indicator lamp is illuminated and Diagnostic Trouble Code (DTC) P0503 is stored in PCM memory. This DTC is Vehicle Speed Sensor Intermittent.

CAUSE: The cause may be, an air gap variation between the output speed sensor and the differential carrier created by movement of the final drive internal ring gear relative to the transaxle case. This also causes wear of the bushing in the final drive housing. Some affected transaxles may have a mis machined final drive internal ring gear on the outside diameter and a final drive internal ring gear snap ring, with a corner break at the thickest side as shown in Figure 3. Some vehicles with the 3.11 or the 3.71 final drive ratio carrier may also have one or more planet pinions with mis-machined gear teeth, as shown in Figure 2.

CORRECTION: Inspect and replace as necessary all of the parts and concerns listed above, using the part numbers found in "Service Information" below. We have also provided you with a chart for final drive ratio information for the various models, as the ratios *will not* interchange from model to model.

SERVICE INFORMATION:

Final Drive Internal Ring Gear	8677862
Final Drive Housing (Bushing not serviced)	8683544
Final Drive Housing Seal	8679017
Final Drive Ring Gear Snap Ring	8681080
Final Drive Carrier, 3.11 Ratio (Pinions not serviced)	24205234
Final Drive Carrier, 3.71 Ratio (Pinions not serviced).....	24205233
Bottom Pan Gasket	24209512

TAG IN TRUNK	FINAL DRIVE RATIO	RING GEAR	SUN GEAR	PINION GEAR	VEHICLE
FV4	3.71:1	114 TEETH	42 TEETH	36 TEETH	Cadillac
FV3	3.11:1	114 TEETH	54 TEETH	30 TEETH	Cadillac
FQ2	3.48:1	114 TEETH	46 TEETH	34 TEETH	Aurora

Copyright © 2000 ATSG




Figure 1





Figure 2



Copyright © 2000 ATSG

Figure 3

Is it TASC Force Approved?

FOR PEACE OF MIND...



IT'S IN OUR ORIGINAL PACKAGING —

Be sure you get
Genuine Sonnax Quality.

Sonnax

Automatic Drive • P. O. Box 440 • Bellows Falls, VT 05101-0440 • USA
802/463-9722 • 800/843-2600 • Fax: 802/463-4059 • <http://sonnax.com> • Email: info@sonnax.com






THM 4T80-E
FINAL DRIVE IDENTIFICATION

- COMPLAINT:** There may be several different complaints and/or trouble codes stored, such as but not limited to, gear ratio error, converter clutch slippage, internal component slipping, and usually right after a salvage yard unit has been installed.
- CAUSE:** The cause may be, the wrong unit installed, as there are two different final drive ratios for the 4T80-E in Cadillacs, 3.71 ratio and 3.11 ratio, that *will not* interchange. There is now another gear ratio to contend with in the Oldsmobile Aurora (See Figure 1).
- CORRECTION:** The first thing that must be done is to determine which final drive ratio belongs in the vehicle that you have. This can be done only by referring to the component identification tag located in the trunk. Next to the word "Trans" will be one of 3 codes, either FV4, FV3, or FQ2. After you have this information, refer to the chart in Figure 1 to determine the proper amount of teeth on the final drive components, and install the proper final drive assembly for the vehicle.

Oldsmobile Aurora has been added to the final drive chart in Figure 1.

4T80-E FINAL DRIVE IDENTIFICATION

TAG IN TRUNK	FINAL DRIVE RATIO	RING GEAR	SUN GEAR	PINION GEAR	VEHICLE
FV4	3.71:1	114 TEETH	42 TEETH	36 TEETH	<i>Cadillac</i>
FV3	3.11:1	114 TEETH	54 TEETH	30 TEETH	<i>Cadillac</i>
FQ2	3.48:1	114 TEETH	46 TEETH	34 TEETH	<i>Aurora</i>



Copyright © 2000 ATSG

Figure 1


SATURN
WHINE NOISE IN 2ND GEAR "ONLY"

COMPLAINT: Some 1998 or 1999 Saturn vehicles equipped with the Base Automatic (MP6) transaxle, built after 1998 VIN WZ312775 through 1999 VIN XZ114349 may exhibit excessive "whine" noise in 2nd gear only that is related to vehicle speed. The pitch increases with vehicle speed and becomes audible soon after the 1-2 upshift, and is present until the transaxle shifts to 3rd gear. The noise is most noticeable while driving the vehicle in the Manual D2 range.

CAUSE: The cause may be, an improperly machined gear surface on the 2nd/Reverse Drive Gear.

CORRECTION: Remove the transaxle from the vehicle, using the appropriate service manual, and replace the 2nd/Reverse Drive Gear with OEM part number 21003233. Refer to Figures 1 and 2.

2ND/REVERSE DRIVE GEAR
SATURN PART NUMBER 21003233



Copyright © 2000 ATSG

Figure 1




Figure 2


SATURN TAAT
GRIND OR BIND IN REVERSE

COMPLAINT: After overhaul, vehicles equipped with TAAT transaxles, may exhibit a grinding condition on Reverse application or a binding condition in Reverse.


CAUSE: The cause may be, during overhaul the Dog Clutch Sleeve or the Dog Clutch Hub, as shown in Figure 1, were installed incorrectly.

CORRECTION: Install the Dog Clutch Hub with the "Wide Slots" towards 2nd Driven gear as shown in Figure 2. Install the Dog Clutch Sleeve with the I.D. groove toward Reverse Driven gear as shown in Figure 2.

DOG CLUTCH SLEEVE




DOG CLUTCH HUB



Copyright © 2000 ATSG

Figure 1

COUNTER SHAFT



Copyright © 2000 ATSG

Figure 2

SATURN
ERRATIC SHIFT PATTERN, AFTER REBUILD
OR AFTER REPROGRAMING PCM

COMPLAINT: *After rebuild*, the vehicle exhibits one of the following "Erratic Upshift" patterns:

- A. Shifts 1st to 3rd, with no 2nd or 4th.
- B. Starts in 2nd, with no 1st, and upshifts to 3rd and 4th.
- C. Shifts from 1st to 4th, with no 2nd or 3rd.

This condition usually occurs after one complete upshift pattern from 1st to 2nd to 3rd to 4th, and will normally store one or more of the following Diagnostic Trouble Codes (DTC), depending on the particular "Gear Ratio Error":

1991-1995 Model Years

DTC 16 = No 1st Gear
DTC 18 = No Gears Available
DTC 22 = No 2nd Gear
DTC 23 = No 3rd Gear
DTC 24 = No 4th Gear

1996-2000 Model Years

DTC P0730 = No Gears Available
DTC P0731 = No 1st Gear
DTC P0732 = No 2nd Gear
DTC P0733 = No 3rd Gear
DTC P0734 = No 4th Gear

These Diagnostic Trouble Codes may be set after replacing the complete transaxle assembly, after replacing individual gear components, or after reprograming the PCM.

CAUSE: The cause may be, a mis-match of gear train parts (Drive and Driven Gears), between the 1st design "MP6" Base Transaxle, and the 2nd design "MP6" Base Transaxle, or the "MP7" Performance Transaxle.

Another cause may be, incorrect calibration installed due to a wrong VIN in the PCM. If the wrong calibration has been installed, a gear ratio table may be used by the PCM which will not match the actual gear ratios and result in DTCs setting.

CORRECTION: When rebuilding a Saturn transaxle, and gear train replacement is necessary, *ensure* that the replacement gears have the *exact* same tooth counts as the originals. Refer to the charts in Figures 1 and 2 for the proper gear tooth counts for the model that you are rebuilding.

Important Note: Refer to Figure 3 to identify the transaxle design level and type of transaxle. They are as follows: *"MP6" Base = 1st Design*

"MP6" Base (With "SV") = 2nd Design

"MP7" = Performance Version

If the incorrect calibration or VIN information has been written to the PCM, reprogram the PCM with the proper VIN and calibration information. Compare the VIN plate on the dash to VIN identified in the PCM. Obviously they must match.

SLIDE

GEAR TOOTH COUNTS AND GEAR RATIOS					
<i>All SOHC Engines Use MP6 Transaxle</i>			<i>All SOHC Engines Use MP6 Transaxle</i>		
GEAR	<i>1991-1993 1st Design* MP6 Base</i>	<i>1993-1994 2nd Design** MP6 Base</i>	<i>1991-1994 Performance MP7 Base</i>	<i>1995-1999 2nd Design MP6 Base</i>	<i>1995-1999 Performance MP7 Base</i>
<i>1st Drive</i>	21	19	19	19	19
<i>1st Driven</i>	47	48	48	48	48
<i>2nd Drive</i>	30	30	27	30	27
<i>2nd Driven</i>	38	38	42	38	42
<i>3rd Drive</i>	37	37	33	37	33
<i>3rd Driven</i>	30	30	34	30	34
<i>4th Drive</i>	42	42	40	42	40
<i>4th Driven</i>	25	25	28	25	28
<i>Reverse Drive</i>	21	21	21	21	21
<i>Reverse Driven</i>	40	40	40	40	40
<i>Output Shaft</i>	15	15	15	16	16
<i>Ring Gear</i>	62	62	62	65	65
<i>1st Gear</i>	2.24	2.53	2.53	2.53	2.53
<i>2nd Gear</i>	1.27	1.27	1.56	1.27	1.56
<i>3rd Gear</i>	0.81	0.81	1.03	0.81	1.03
<i>4th Gear</i>	0.60	0.60	0.70	0.60	0.70
<i>Reverse Gear</i>	2.35	2.35	2.35	2.35	2.35
<i>Final Drive</i>	4.13	4.13	4.13	4.06	4.06
* Vehicles built prior to, and including VIN PZ156139 ** Vehicles built after, and including VIN PZ156140					
<div>Copyright © 1999 ATSG</div>					

Figure 1



INDIVIDUAL DRIVE AND DRIVEN GEAR IDENTIFICATION

Figure 2

**STAMPED IDENTIFICATION CODE
CAN BE FOUND IN THIS AREA**



IDENTIFICATION CODE DESCRIPTION

3	MP7	1	043	0	4
1	2	3	4	5	6

1 = Model Year (3 = 93)

2 = Model Code:

MP2 = Base Manual

MP3 = Performance Manual

MP6 = Base Automatic



MP7 = Performance Automatic

3 = Plant Code (1 = Spring Hill, TN)

4 = Julian Date (043 = Feb. 12)

5 = Hour of Day (0 = Midnight)

6 = Update Code (Increments 0 - 9)



Identification "SV" here is 2nd design level

Copyright © 1999 ATSG

Figure 3



FORD 4R70W
INTERNAL HARNESS AND CASE
CONNECTOR CHANGES FOR 1998

CHANGE: Beginning at the start of production for 1998 models, all Ford AODE/4R70W transmissions were built using a molded circuit board to replace the previous internal wire harness assembly, as shown in Figure 1.

REASON: More economical to produce and install and increased durability.

PARTS AFFECTED:



- (1) CASE CONNECTOR - Now produced to accommodate the new molded circuit board assembly and case connector pin functions have changed. Refer to Figures 1, 2, and 3.
- (2) INTERNAL HARNESS - Changed to a molded circuit board, as shown in Figure 1.
- (3) EPC SOLENOID - Connector changes to accommodate the new molded circuit board.
- (4) SHIFT SOLENOID ASSEMBLY - Connector changes to accommodate the new circuit board.
- (5) TCC SOLENOID ASSEMBLY - Connector changes to accommodate the new circuit board.

INTERCHANGEABILITY:


- (1) 1992-1997 internal harness and solenoid assemblies **must** be used on 92-97 models. Refer to "Service Information" below for the current part numbers.
- (2) 1998-Up internal harness and solenoid assemblies **must** be used on 1998-Up models. Refer to "Service Information" below for the current part numbers.

SERVICE INFORMATION:

Internal Wiring Harness and Case Connector Assy, 92-97 Models	F2VY-7G276-A
Case Connector for Molded Internal Wiring, 1998-Up Models	F8AZ-7G276-AA
Molded Internal Wiring Assembly, 1998-Up Models	F8AZ-7G276-BA
Shift Solenoid Assembly, 92-97 Models	F7AZ-7G484-AA
Shift Solenoid Assembly, 1998-Up Models	F8AZ-7G484-AA
EPC Solenoid Assembly, 92-97 Models	F6AZ-7G383-AA
EPC Solenoid Assembly, 1998-Up Models	F8AZ-7G383-AA
TCC Solenoid Assembly, 92-97 Models	F5AZ-7G136-A
TCC Solenoid Assembly, 1998-Up Models	F8AZ-7G136-AA



The colors listed here are found on the replacement harness part number F2VY-7G276-A



1992-1997 MODELS

PIN	FUNCTION
1	Shift Solenoid 1 Ground
2	Shift Solenoid 12V Power
3	TCC Solenoid Ground
4	Not Used
5	TOT Sensor
6	Shift Solenoid 2 Ground
7	EPC Solenoid 12V Power
8	TCC Solenoid 12V Power
9	TOT Sensor Return
10	EPC Solenoid Ground






Figure 1

**VIEW LOOKING INTO THE 92-97
TRANSMISSION CASE CONNECTOR**



**VIEW LOOKING INTO THE 92-97
VEHICLE HARNESS CONNECTOR**



PIN NO.	IDENTIFICATION	INTERNAL COLOR	EXTERNAL COLOR	CIRCUIT NUMBER	EEC IV ECM PIN NUMBER 92-95	EEC V ECM PIN NUMBER 96-97
1	SS-1 Ground Signal	WHITE	ORG - YEL	237	51	27
2	Shift Solenoid Power 12V	WHT - BLK	RED	361	37 & 57	71 & 97
3	MCC Ground Signal	GREEN	**	480	53	54
4	NOT USED					
5	TOT -	WHT - RED	GRY - RED	923	49	91
6	SS-2 Ground Signal	BLACK	PPL - ORG	315	52	1
7	EPC Power In	WHT - BLU	RED	361	37 & 57	71 & 97
8	MCC Power In	WHT - GRN	RED	361	37 & 57	71 & 97
9	TOT +	RED	ORG - BLK	359	46	37
10	EPC Ground Signal	BLUE	WHT - YEL	925	38	81


** TAN - WHT, BRN - ORG, PPL - YEL, DEPENDING ON YEAR AND MODEL.

SOLENOID	PIN NO.	RESISTANCE
SHIFT SOLENOID - 1	1 & 2	20 - 30 OHMS
SHIFT SOLENOID - 2	6 & 2	20 - 30 OHMS
TORQUE CONVERTER CLUTCH (SOME 1995 MODELS)	3 & 8	1.0 - 3.0 OHMS
	3 & 8	10 - 16 OHMS
EPC SOLENOID	7 & 10	2.48 - 5.66 OHMS


Copyright © 1999 ATSG

Figure 2

VIEW LOOKING INTO THE 1998-UP TRANSMISSION CASE CONNECTOR



VIEW LOOKING INTO THE 1998-UP VEHICLE HARNESS CONNECTOR



PIN NO.	IDENTIFICATION	INTERNAL COLOR	EXTERNAL COLOR	CIRCUIT NUMBER	EEC-V ECM PIN NUMBER 1998-UP
1	NOT USED				
2	TOT -	CIRCUIT BOARD	GRY - RED	359	91
3	MCC GROUND SIGNAL	CIRCUIT BOARD	PPL - YEL	126	54
4	SOLENOID POWER IN 12V	CIRCUIT BOARD	RED	361	71 & 97
5	TOT +	CIRCUIT BOARD	ORG - BLK	923	37
6	EPC GROUND SIGNAL	CIRCUIT BOARD	WHT - YEL	925	81
7	SS-1 GROUND SIGNAL	CIRCUIT BOARD	ORG/YEL	237	6
8	SS-2 GROUND SIGNAL	CIRCUIT BOARD	PPL - ORG	315	11
9	NOT USED				
10	NOT USED				

SOLENOID	PIN NO.	RESISTANCE
SHIFT SOLENOID - 1	4 & 7	20 - 30 OHMS
SHIFT SOLENOID - 2	4 & 8	20 - 30 OHMS
TORQUE CONVERTER CLUTCH (SOME MODELS)	4 & 3	1.0 - 3.0 OHMS
	4 & 3	10 - 16 OHMS
EPC SOLENOID	4 & 6	2.48 - 5.66 OHMS

Copyright © 1999 ATSG

Figure 3



FORD 4R70W
INTERMITTENT TCIL ILLUMINATION
DTCS P0741, P0750, P0755 AND P1746
MAY BE STORED IN MEMORY

COMPLAINT: Intermittent Transmission Control Indicator Lamp (TCIL) or Malfunction Indicator Lamp (MIL) illumination may occur on some vehicles equipped with the 4R70W transmission. Diagnostic Trouble Codes (DTCs) P0741, P0750, P0755 and P1746 may be stored in the processors memory.


CAUSE: The cause may be, the solenoid interconnect molded lead frame not being fully seated on the solenoid pack or the bulkhead interconnect clips not being fully seated between the solenoid interconnect molded lead frame and bulkhead interconnect.

CORRECTION: Refer to the following service procedure:

- (1) Perform the normal diagnosis routines for the DTCs retrieved from processor memory.
- (2) Remove the transmission oil pan per the appropriate model Workshop Manual.
- (3) Verify that the solenoid interconnect molded lead frame is fully seated on all the solenoid connectors as shown in Figure 1. If the solenoid interconnect molded lead frame is fully seated, then gently remove the solenoid interconnect molded lead frame, valve body and the bulkhead interconnect.
- (4) With the bulkhead interconnect removed, push down on the terminal cover and check to see if any of the terminals are slightly protruding above the plastic cover as shown in Figure 2. Gently pry off the terminal cover using a small screwdriver (See Figure 3). With the terminal cover off, inspect the bulkhead interconnect for spreading terminals as shown in Figure 4.
- (5) Replace parts as necessary using the part numbers listed below and reassemble unit.

SERVICE INFORMATION:

Bulkhead Interconnect (Case Connector) F8AZ-7G276-AA
Solenoid Interconnect (Internal Molded Harness) F8AZ-7G276-BA



Copyright © 2000 ATSG

Figure 1





Figure 2



Copyright © 2000 ATSG

Figure 3




Figure 4

TCRS

The name in Torque converter rebuilding equipment. Become part of the TCRS family today.

JUST A FEW SATISFIED TCRS CUSTOMERS: CHRYSLER, FORD, GM, AARONS, JASPERS, WILLIAMS TECH, TORCO, GILLECE TRANSMISSION, YOUR TRANSMISSION MAN, CUSTOMERS ALL OVER THE WORLD.

THE TCRS ROBOTIC "AUTO TACK SYSTEM™"



PATENT PENDING

VERTICAL AUTO-WELD ALIGNER

The TCRS Robotic "Auto Tack System™" automatically indexes and fully tacks the converter in seconds. Upon completion of the last tack it makes a complete 360 weld and automatically shuts off.

PB-2002 PISTON BONDER

- Easy as 1-2-3
- Bonds a piston every 5 min.
- Adjustable heat & timer controls
- Aluminum bonder dies provide even heat distribution
- Compact & efficient
- No wait-no freight
- Comes with 20 die sets Am. & Foreign
- Pat. # 5.141.586





PATENT PENDING

ATS-100 SUPERTANKER AIR TEST STAND

- Fastest on the market today
- Operator friendly and safe
- Air operated hand lever
- Reservoir raises water level to any height on the converter
- Air adjusted regulators
- Torque converter locks in place at 90° Angle - In the event of a leak, flip to lock position and tack leak fast and easy


TCRS HB-4000 MICROPROCESSOR, MOTORIZED FLUID OR DRY BALANCER

- Hoffman is known for precision balancing equipment since 1931.
- Easy operator service.
- Only 5 seconds to balance.
- Rugged motor drive system.
- Push button calibrated, automatic true zero.
- State-of-the-Art Technology. Self diagnostics.
- No bolting necessary.
- The most reliable, accurate and easy to operate torque converter balancer on the market today.
- Fluid or dry balance
- Add life to your shelf converters-no rust build-up
- Computer touch key pad for entering torque converter diam.



PS-100 PASS-THROUGH CONVEYOR WASHER

TCRS Multi-Purpose Pass Through Conveyor Washer is designed to clean efficiently any kind of part, whether it's a transmission case, hard part, or torque converter. Available in Electric, Natural gas or Waste oil fuel. Save hundreds of dollars with the waste oil version. Saves electricity and waste oil pick-up.



PATENT PENDING

TCRS PRODUCTS

TCRS SPECIAL APPLICATION LATHE
PRECISION TOOLING
FRONT LOADING JET SPRAY WASHER
ELECTRICAL, NATURAL GAS OR
WASTE OIL FIRED
SUPERTANKER AIR TEST STAND
PISTON BONDER
VERTICAL AUTO WELD ALIGNER
GAS MIXER
TORQUE CONVERTER BALANCER

PRODUCTION REBUILDER
RETROFITTED TURRET LATHE
MULTI-POSITION VERT/HORIZONTAL
AUTO WELD ALIGNER

DUAL TORCH AUTO-WELD ALIGNER
HORIZONTAL WELDER
HUB MASTER
CONVEYOR WASHER - ELECTRICAL, NATURAL
GAS OR WASTE OIL FIRED
OPTIONAL CYCLONIC FILTER OR AIR
DRYER SYSTEM
HUB POLISHER
SPECIAL PRICE ON ROLLS OF
.035 WELDING WIRE (44LB. ROLL)

ADDITIONAL PRODUCTS
TCR-500 HEAVY DUTY HYDRAULIC RIVETER
CONVEYOR HEIGHT GAGE
TCRS BUSHING DRIVER SET

BELT SANDER
FORD STUD REPAIR KIT
GM STUD REPAIR KIT
200/700 PUMP PAL
E40D PUMP PAL
LOCK-UP PISTON LEAK CHECKER
CONVERTER LOCK-UP TESTER
DELUXE METAL BENCHES
SYNCHRO-WAVE TIG WELDER
ECONO-TIG WELDER
END PLAY GAGE
AIR RAM ASSEMBLY
ROLLER BURNISHING MACHINE
SOLVENT TANK
HUB LEAK CHECKER

1-800-598-1933

TCRS

TORQUE CONVERTER REBUILDING SYSTEMS

775-352-6800 FAX 775-352-6813 • 2010 KLEPPE, SPARKS, NV 89431

**KEEPING YOU ON THE LEADING EDGE
OF TECHNOLOGY**

**CHECK US OUT ON THE WEB TCRSINC.COM
E-MAIL JMYERS6048@AOL.COM**

TCRS

The name in Torque converter rebuilding equipment. Become part of the TCRS family today.

JUST A FEW SATISFIED TCRS CUSTOMERS: CHRYSLER, FORD, GM, AARONS, JASPERS, WILLIAMS TECH, TORCO, GILLECE TRANSMISSION, YOUR TRANSMISSION MAN, CUSTOMERS ALL OVER THE WORLD.

THE TCRS ROBOTIC "AUTO TACK SYSTEM™"




PATENT PENDING

VERTICAL AUTO-WELD ALIGNER

The TCRS Robotic "Auto Tack System™" automatically indexes and fully tacks the converter in seconds. Upon completion of the last tack it makes a complete 360 weld and automatically shuts off.

PB-2002 PISTON BONDER


- Easy as 1-2-3
- Bonds a piston every 5 min.
- Adjustable heat & timer controls
- Aluminum bonder dies provide even heat distribution
- Compact & efficient
- No wait-no freight
- Comes with 20 die sets Am. & Foreign
- Pat. # 5.141.586



PATENT PENDING


ATS-100 SUPERTANKER AIR TEST STAND

- Fastest on the market today
- Operator friendly and safe
- Air operated hand lever
- Reservoir raises water level to any height on the converter
- Air adjusted regulators
- Torque converter locks in place at 90° Angle - In the event of a leak, flip to lock position and tack leak fast and easy




TCRS HB-4000 MICROPROCESSOR, MOTORIZED FLUID OR DRY BALANCER

- Hoffman is known for precision balancing equipment since 1931.
- Easy operator service.
- Only 5 seconds to balance.
- Rugged motor drive system.
- Push button calibrated, automatic true zero.
- State-of-the-Art Technology. Self diagnostics.
- No bolting necessary.
- The most reliable, accurate and easy to operate torque converter balancer on the market today.
- Fluid or dry balance
- Add life to your shelf converters-no rust build-up
- Computer touch key pad for entering torque converter diam.



PS-100 PASS-THROUGH CONVEYOR WASHER

TCRS Multi-Purpose Pass Through Conveyor Washer is designed to clean efficiently any kind of part, whether it's a transmission case, hard part, or torque converter. Available in Electric, Natural gas or Waste oil fuel. Save hundreds of dollars with the waste oil version. Saves electricity and waste oil pick-up.



PATENT PENDING

TCRS PRODUCTS

TCRS SPECIAL APPLICATION LATHE
PRECISION TOOLING
FRONT LOADING JET SPRAY WASHER
ELECTRICAL, NATURAL GAS OR
WASTE OIL FIRED
SUPERTANKER AIR TEST STAND
PISTON BONDER
VERTICAL AUTO WELD ALIGNER
GAS MIXER
TORQUE CONVERTER BALANCER

PRODUCTION REBUILDER
RETROFITTED TURRET LATHE
MULTI-POSITION VERT/HORIZONTAL
AUTO WELD ALIGNER

DUAL TORCH AUTO-WELD ALIGNER
HORIZONTAL WELDER
HUB MASTER
CONVEYOR WASHER - ELECTRICAL, NATURAL
GAS OR WASTE OIL FIRED
OPTIONAL CYCLONIC FILTER OR AIR
DRYER SYSTEM
HUB POLISHER
SPECIAL PRICE ON ROLLS OF
.035 WELDING WIRE (44LB. ROLL)

ADDITIONAL PRODUCTS
TCR-500 HEAVY DUTY HYDRAULIC RIVETER
CONVEYOR HEIGHT GAGE
TCRS BUSHING DRIVER SET

BELT SANDER
FORD STUD REPAIR KIT
GM STUD REPAIR KIT
200/700 PUMP PAL
E400 PUMP PAL
LOCK-UP PISTON LEAK CHECKER
CONVEYOR LOCK-UP TESTER
DELUXE METAL BENCHES
SYNCHRO-WAVE TIG WELDER
ECONO-TIG WELDER
END PLAY GAGE
AIR RAM ASSEMBLY
ROLLER BURNISHING MACHINE
SOLVENT TANK
HUB LEAK CHECKER

1-800-598-1933

TCRS


TORQUE CONVERTER REBUILDING SYSTEMS

775-352-6800 FAX 775-352-6813 • 2010 KLEPPE, SPARKS, NV 89431

**KEEPING YOU ON THE LEADING EDGE
OF TECHNOLOGY**

**CHECK US OUT ON THE WEB TCRSINC.COM
E-MAIL JMYERS6048@AOL.COM**

4R100 CASE "NON-PTO" AND "PTO"




Copyright © 2000 ATSG

Figure 1

Automatic Transmission Service Group

4R100 MAIN SPACER PLATE "NON-PTO"




Copyright © 2000 ATSG

Figure 2

Automatic Transmission Service Group

4R100 MAIN SPACER PLATE "PTO"




Copyright © 2000 ATSG

Figure 3

Automatic Transmission Service Group


"UPPER SIDE" 4R100 MAIN VALVE BODY "NON-PTO"



Copyright © 2000 ATSG

Figure 4
Automatic Transmission Service Group


"UPPER SIDE" 4R100 MAIN VALVE BODY "PTO"



Copyright © 2000 ATSG

Figure 5
Automatic Transmission Service Group


"LOWER SIDE" 4R100 MAIN VALVE BODY "NON-PTO"



Copyright © 2000 ATSG

Figure 6
Automatic Transmission Service Group

"LOWER SIDE" 4R100 MAIN VALVE BODY "PTO"




Copyright © 2000 ATSG

Figure 7

Automatic Transmission Service Group

4R100 LOWER VALVE BODY "NON-PTO"




Copyright © 2000 ATSG

Figure 8

Automatic Transmission Service Group

4R100 LOWER VALVE BODY "PTO"



Copyright © 2000 ATSG

Figure 9

Automatic Transmission Service Group






Figure 10
Automatic Transmission Service Group

"NON-PTO" 3-4 SHIFT VALVE HYDRAULIC CIRCUIT



"PTO" 3-4 SHIFT VALVE HYDRAULIC CIRCUIT



Copyright © 2000 ATSG

Figure 11

Automatic Transmission Service Group

TIME SAVING TOOLS DESIGNED FOR YOU, THE TRANSMISSION TECHNICIAN

NEW

UNIVERSAL SPEEDOMETER DRIVEN
GEAR REMOVER



E-Z SQUEEZE® CHRYSLER A-604
SNAP RING REMOVER/INSTALLER



"Longer"

UNIVERSAL
END CLEARANCE
GAUGE



E-Z UNIVERSAL
SPEEDOMETER GEAR
INSTALLER



BIG 3


FRONT PUMP
PULLER




FORD, G.M., CHRYSLER U.S. PAT 5,243,749

NEW

E-Z UNIVERSAL SEAL DRIVER KIT.



E-Z SQUEEZE® SERVO PISTON REMOVER
FOR: FORD AOD-E



NEW


Universal Quick Lock
Clutch Spring Compressor
Model No: 2987A

Ideal for all clutches
even GM 350 and Chrysler
604 - In the case.

Ring Adapters for
Compressing Diaphragm Springs




TOOLS FROM A TO Z



AXEL SEAL INSTALLER
#1250



CLUTCH SPRING
COMPRESSOR KIT
#2987 U.S. PATENT



UNIVERSAL BUSHING
DRIVER SET
#1001



P.R. VALVE SNAP
RING INSTALLER
#2993 U.S. PATENT



#280
SEAL PULLER



PUMP ALIGNMENT
TOOLS




#200


#125

#350

BUSHING DRIVERS BY
TRANSMISSION TYPE




CHRYSLER
BEARING CUP & CONE
SERVICE TOOLS
U.S. PATENT NO. 4339865



AOD-E SOLID RING INSTALLER

New E40D



GEAR & PUMP PULLER

#2996

U.S. PATENT
#2997



RACE DRIVER




U.S. PATENT
TUFFY
#2994



LO/REV. CLUTCH TOOLS
#125-200
U.S. PATENT



EXT. HOUSING BUSHING
TOOL #2200
U.S. PATENT



BUSHING EXTRACTORS



#280C
BUSHING & SEAL CUTTER
U.S. PATENT



VALVE
SPRING
COMPRESSOR

#2995

CALL FOR
CATALOG



CALL US TODAY AND SAVE!

TAKE ADVANTAGE OF
A.T.S.G. PROMOTION PRICES!



COD Welcome

ALL TOOLS AND PARTS MADE IN USA

GUARANTEED A to Z TOOL, INC.
AGAINST DEFECTS IN QUALITY AND WORKMANSHIP.

• 446 W. ST. CHARLES ROAD • VILLA PARK, ILLINOIS 60181
Fax: (630) 279-4134

• (630) 279-4118
CALL US TODAY!

FORD's NEW 5R55N TRANSMISSION
PRELIMINARY INFORMATION

(Adapted from Ford Bulletin 99-8-13)

Ford's new 5R55N is a 5 speed rear wheel drive non-synchronous transmission (See Figure 1). Currently this transmission is installed in the 2000 Lincoln LS and the Jaguar X200. The internal components are similar to the 5R55E transmission. However, the 5R55N shares very few components to the 5R55E as major upgrades took place through its development.

Electro-Hydraulic Shift Control Features

- Torque Converter Clutch Modulation for smooth clutch engagement and shift.
- Full electronic shift control by our new 32-bit Powertrain Electronic Controller (PTEC) for smooth and responsive powertrain performance.
- Closed Loop Shift Control, Electronic Clutch Pressure Control and Engine Torque modulation for smooth shift.
- Adaptive Shift Control for consistent shift quality throughout the life of the vehicle.
- Reactive Shift Scheduling to react to throttle position and the rate of throttle change.
- Overdrive (5th gear) lockout in automatic mode in D4 shifter position (Figure 2).
- Manual Shift Capability (*Optional* Select Shift Transmission (SST) (Figure 3) to allow the driver to control the transmission shift point by tapping the shift lever forward or rearward.
- Three speed sensors for precise shift control (Transmission Speed Sensor (TSS), Idle Speed (ISS), and Output Shaft Speed Sensor (OSS) (See Figure 4).
- Integrated Solenoid Body Assembly (Figure 5), contains: three Pressure Control Solenoids (PCS A, B & C), four Shift Solenoids (SS A, B, C & D), Torque Converter Clutch (TCC) Solenoid, and a Transmission Fluid Temperature (TFT) Sensor.
- Reverse Pressure Switch (Figure 5) to detect pressure in the main control valve body (mounted on the main control).

Hydraulic/Mechanical Features

- Wide ratio span 5speed with close ratio steps for smooth shift quality and improved performance:

Gear	1st	2nd	3rd	4th	5th	Reverse	Ratio Span
Ratio	3.25	2.44	1.55	1.00	0.75	3.07	4.33

- Three One Way Clutches for smooth nonsynchronous shift.
- Engine braking capability during coast operation in all gears.
- One piece die cast aluminum case with the reenforcement ribs to minimize powertrain Noise, Vibration & Harshness (NVH).
- Fixed output flange to minimize driveline disturbances.
- High capacity torque converter clutch to maximize the lockup capability in all throttle conditions.

5R55N Continued

- Brazed torque converter blades for high speed capability and improved efficiency.
- Dedicated air-to-oil transmission cooler for low transmission operating temperature.
- High output trochocentric pump with flow control capability.
- Friction on steel plates (single sided clutch plates).
- New design Reverse Servo Piston Assembly.
- Semi-synthetic fluid for improved durability MERCON® V for service.
- Transmission fluid leveling pipe which eliminates the need of conventional fill tube and dipstick. This new feature requires a special fluid fill procedure as described in the transmission Workshop Manual.
- Adapter plate between the torque converter and flywheel assembly (V8 application only).
- Single bolt transmission rear mount.
- Transmission wire harness with five connectors.

MODEL COMPLEXITY				
Transmission Assembly (-7000-)	Model Code (ID Tag Color)	Vehicle Application	Engine	Axle Ratio
XR8P-AC	RJL-D (Apricot)	Jaguar X200	4.0L, V8	3.31
XR8P-BC	RJL-C (Light Green)	Jaguar X200	3.0L, V6	3.31
XW4P-AC	RJL-B (Yellow)	Lincoln LS	3.9L, V8	3.58
XW4P-BC	RJL-A (White)	Lincoln LS	3.0L, V6	3.58

Valve Body and Case

- Figure 7 is a view of the valve body providing the Technician with all retainer locations.
- Figure 8 is a view of the valve body providing the Technician with all check ball and check valve locations.
- Figure 9 is a view of the case providing the Technician with the location for the spring loaded lube seal.

Non-Syncounous Up-Shift

- Unlike the 5R55E, the 5R55N uses a sprag on the back side of the sun gear which will be used to make the non-synchronous shift. Figure 10 provides a view of the sprag providing the Technician with its proper rotation and hold direction.
- Figure 11 is a view of the single sided clutch plates which will be used to hold the sun gear through the sprag providing the ability of having a non-synchronous upshift

5R55N Continued




Figure 1

5R55N Continued




Figure 2




Figure 3




Figure 4

5R55N Continued






Figure 5

5R55N Continued



RESISTANCE CHECK CHART			
DEVICE	POSITIVE TERMINAL	NEGATIVE TERMINAL	VALUE
PCS PCS PCS	3	1	5 ohms
		4	5 ohms
		11	5 ohms
SS SS SS SS		5	24 ohms
		6	24 ohms
		15	24 ohms
		16	24 ohms
TCCS		14	10 ohms
R.P.S.	13	12	Open/Close
T.F.T	2	12	34.93K ohms @ 75° F

Figure 6

**FORD 5R55N
VALVE BODY RETAINER LOCATION**

Copyright © 2000 ATSG

Figure 7

Automatic Transmission Service Group

FORD 5R55N
VALVE BODY CHECK BALL LOCATION





Figure 8



FORD 5R55N SUPPORT SEAL AND SPRING LOCATION

Copyright © 2000 ATSG

Figure 9

Automatic Transmission Service Group

**WITH THE OUTER RACE HELD
THE SUN SHELL AND GEAR MUST
TURN IN THE DIRECTION OF THE ARROW**




OUTER RACE HELD

Copyright © 2000 ATSG

Figure 10

Automatic Transmission Service Group



Copyright © 2000 ATSG

Figure 11

Automatic Transmission Service Group



***Transmission Training Academy
offering a full range of training at ALL skill levels***

- *Update your building skills***
- *Learn the latest R & R techniques***
- *Get new electronic and hydraulic info***
- *Acquire current diagnostic procedures***
- *Understand the basic principles of operation***

***ONLY SIX (6) STUDENTS PER INSTRUCTOR
HANDS-ON TRAINING WITH LIVE CORES AND DYNO TESTING***

CLASSES BEGINNING EACH MONDAY - YEAR ROUND

FOR MORE INFORMATION

1-812-284-2930

e mail: DRIVETEK 1 @ AOL.COM

Housing available during training

Airport drop off/pickup available 24 hours/day

213 East Market Street
Jeffersonville, IN 47130
Phone: 812-284-2930
Fax: 812-284-1981
E-mail: drivetek1@aol.com