



Technical Service Information

VOLKSWAGEN/AUDI ZF5HP19FL/FLA NO REVERSE

COMPLAINT: Volkswagen and Audi vehicles equipped with the ZV5HP19FL/FLA may exhibit a no Reverse condition before or after overhaul.

CAUSE: The cause may be, a broken D clutch housing, as shown in Figure 2, causing no application of the D clutch which is the Low Reverse Clutch.

CORRECTION: Replace the D clutch housing with the correct part number, based on the tag number located in Figure 1.


SERVICE INFORMATION:

D CLUTCH HOUSING	1060 373 002
Used in models 002, 012, 013, 036	
D CLUTCH HOUSING.....	1060 373 003
Used in models 018, 030, 054, 073, 101	
D CLUTCH HOUSING.....	1060 373 014
Used in models 035, 044, 053, 063, 065, 075, 087, 093, 100, 103	

NOTE: Use Figure 1 for reference as to what model you are working on. The part numbers listed above are for ZF distributors only and will not be recognized by car dealers.

*Special thanks
to Dino at
Lee Miles*

TAG AND MODEL IDENTIFICATION



The last three digits on the tag will identify the part number needed listed in Service Information for the correct D clutch housing


The part number for the D clutch housing according to the tag identification shown above is 1060 373 002

Copyright © 2005 ATSG

D CLUTCH HOUSING

The top of the snap ring area of the housing breaks

The snap ring groove depth has been redesigned to help prevent breaking



Copyright © 2005 ATSG

Figure 2