



# Technical Service Information

## FORD AXOD-E PREMATURE PLANETARY FAILURE

**COMPLAINT:** Front planetary and gear train failure with no visible reason.

**CAUSE:** The cause may be, a limited volume of lube oil to the front planetary due to hydraulic control system demands.

**CORRECTION:** Install a new crossover rear lube tube, OEM number F2DZ-7G084-A, and a new differential/speed0 lube tube, OEM number F2DZ-7G086-A, that will increase the volume of lube to the front planetary. The rear lube tube and the differential/speed0 lube tube, Figure 1, have been reversed in the transaxle case. This requires the rear lube tube to "Cross-Over" the differential/speed0 lube tube. This crossover will allow for a larger volume of uninterrupted lube to the front planetary.  
This change has been incorporated in mid-year 1992 for ALL AXOD-E transaxles.

### SERVICE INFORMATION:

Crossover Rear Lube Tube .....F2DZ-7G084-A  
Differential/Speed0 Lube Tube .....F2DZ-7G086-A





Figure 1



**Figure 1**