



G.M. POPPET VALVE CONVERTERS

A complaint of no converter release on coast down shift or stalls engine after vehicle has been driven, can be caused by mismatch of gasket Figure 2 (1984 installed in 1982) or a mis-position cup plug in the Aux Valve body. A mismatch of a 1982 gasket in a 1984 gives a no converter clutch apply condition





Figure 2

Copyright © 2000 ATSG