



Technical Service Information

RE4RO1A BEARING CHANGE


CHANGE: The three piece needle bearing located at the rear of the low one way clutch inner race in RE4RO1A transmissions has changed (See Figure 1).

REASON: Improved durability.

PARTS AFFECTED:
The previous design 3 piece bearing has been replaced by 2 thrust washers (See Figure 2).

INTERCHANGEABILITY:
The 2 new design thrust washers will retro fit backwards. These thrust washers must be used in a pair. If not, premature bearing failure, lubrication and or end play problems **will** arise.

SERVICE INFORMATION:
THRUST WASHER (NEW DESIGN-2 REQUIRED).....31508-41X01



Copyright © 2001 ATSG

Figure 1




Figure 2