


## THM 440-T4 DELAYED 2-3 SHIFT

A long and/or delayed 2-3 shift on THM 440-T4 transaxle may be caused by a leaking 3rd clutch inner seal (Figure 1, Item 635A). A new, thicker seal is used in production and available for service replacement. The new seal can be recognized by a small group of hash marks on the inside diameter of the seal.



Copyright © 2001 ATSG

Figure 1