



Technical Service Information

THM 325/325-4L NO UPSHIFT, CUP PLUG MISSING

COMPLAINT: No 2-3 shift at any vehicle speed.

CAUSE: The cause may be the 3rd accumulator cup plug missing from the case, creating a loss of all direct clutch oil (See Figure 1).

CORRECTION: Install new 3rd accumulator orificed cup plug, available under OEM part number 8628864. See Figure 1 for location.




Figure 1