



# Technical Service Information

## TOYOTA A40 SERIES HARSH 1-2 SHIFT

**COMPLAINT:** Harsh 1-2 shift at all throttle positions.

**CAUSE:** Viton check ball missing, or off location.

**CORRECTION:** Install check ball in proper location (See Figure 1)




Figure 1  
AUTOMATIC TRANSMISSION SERVICE GROUP