



# Technical Service Information

## CHRYSLER A404 SECOND GEAR STARTS (GRIND FLATS)

**COMPLAINT:** 2nd gear starts after overhaul.

**CAUSE:** If all other possibilities have been eliminated, the cause may be cross leaks causing governor pressure at a stand still.

**CORRECTION:** Carefully grind 3 small flats on the second land of the free floating governor valve (without spring) to provide an exhaust. see figure 1.




Figure 1