

HONDA M24A

NO REVERSE

COMPLAINT: After overhaul, vehicles equipped with M24A transaxles may exhibit a no Reverse condition.

CAUSE: The cause may be, that the bore plug, which retains the servo control valve in its bore, was assembled backwards exhausting line pressure from the Manual Valve in Reverse.

CORRECTION: Locate the Servo Control Valve, which is in the Secondary Valve Body, and assemble the bore plug correctly as shown in Figure 1.




Figure 1