



Technical Service Information

FORD E4OD HARSH 3-4 SHIFT

COMPLAINT: Harsh 3-4 shift, and/or upon transmission dis-assembly the O.D. Clutch retaining ring is dislodged from groove (See Figure 1).

CAUSE: Insufficient snap ring tension.

CORRECTION: Replace snap ring with updated (More Tension) snap ring available under OEM part number F0TZ-7A527-A.




Figure 1