



Technical Service Information

FORD CD4E

NO FORWARD ENGAGEMENT AND/OR NO 3RD GEAR


COMPLAINT: No forward engagement and/or no 3rd gear engagement may be present, before rebuild, on some CD4E transaxles built between Sept. 28, 1994 and Oct. 30, 1994. The transaxle serial numbers that are of concern are 4271-0000 thru 4303-9999.

CAUSE: The cause may be due to a defective weld condition on the Forward/Coast/Direct Clutch Cylinder, which results in fluid leakage from the forward clutch into the direct clutch. The clutch cylinder and hub weld condition may not be identifiable visually.

CORRECTION: When extensive wear is observed on the forward clutch plates and/or the direct clutch plates, and the transaxle serial number is 4271-0000 thru 4303-9999, built between the dates listed above, replace the Forward/Coast/Direct Clutch Cylinder Assembly with the appropriate service part number listed below.

SERVICE INFORMATION:

| | |
|--|--------------|
| Clutch Cylinder and Hub Assembly (4 Cyl) | F5RZ-7G120-A |
| Clutch Cylinder and Hub Assembly (6 Cyl) | F4RZ-7G120-A |



Copyright © 2000 ATSG