



Technical Service Information

FORD AXOD HARSH COAST DOWNSHIFTS

COMPLAINT: Harsh downshift when coasting to a stop at closed throttle.

CAUSE: Insufficient travel of the 1-2 piston against the cushion spring.

CORRECTION: Remove 1/8" from the boss on the inside of the 1-2 servo piston as shown in Figure 1. We have shaded the area to be machined.




FIGURE 1

Copyright © 1999 ATSG