



Technical Service Information

THM 4L80-E/4L80-EHD

TROUBLE CODE 68 IN OVERDRIVE

TROUBLE CODE 39 IN DRIVE 3

ALL ELECTRICAL OKAY

- COMPLAINT:** After rebuild, the vehicle displays a no converter clutch condition, stores trouble code 68 when the vehicle is driven in the Overdrive gear selector position, and stores trouble code 39 when the vehicle is driven in the "D3" gear selector position.
- CAUSE:** There are many electrical and mechanical reasons for these codes to be stored. After all of the electrical has been eliminated, the cause may be the TCC Enable Valve, in the pump cover assembly is in backwards.
- CORRECTION:** Remove the pump assembly and install the TCC Enable Valve in the direction that is shown in Figure 1, and ensure free movement after installation.




Figure 1