



Technical Service Information

FORD C-6



DELAYED ENGAGEMENT FORWARD AND REVERSE

COMPLAINT: Any complaint of delayed engagement drive or reverse, any unexplained burn out or any shift related complaint.

CAUSE: The cause can be a bent or cracked internal detent Lever.

CORRECTION: The way to check the alignment is to use an old style C-6 valve body that has the detent in the valve body. On that assembly, place the manual valve in drive position. With the detent lever in the case set in drive set the old style valve body on the transmission. and check that the manual valve lines up with the pin in the detent valve. If the valve and pin do not align, replace the linkage. Inspect all linkage parts for cracking and bending.

Copyright © 2000 ATSG



Copyright © 2000 ATSG

Figure1