

## **FORD AOD NO KICKDOWN OR PASSING GEAR**

**COMPLAINT:** No kickdown or passing gear at any vehicle speeds or any throttle Position.

**CAUSE:** The cause may be the governor mis-assembled with the sleeve installed backwards. Proper installation is with the "Castles" towards the counterweight, as shown in Figure 1.

**CORRECTION:** Install sleeve with the "Castles" towards the counterweight, as shown in Figure 1.




Figure 1