


FORD 5R110W "Torqshift"

INTERNAL HARNESS OR SOLENOID BODY SERVICE

If it becomes necessary to replace the internal wire harness and/or the entire solenoid body on a 5R110W Torqshift transmission, please be aware of the following:

1. You may have to install a new service harness, without pressure switch connectors, into a unit that has pressure switches in the solenoid body. (See Figure 1 for locations)
2. You may have to install a new service solenoid body, without pressure switches, into a unit that has the original internal harness with pressure switch connectors. (See Figure 1 for locations)

Note: *These are both acceptable repairs and will not affect the function or operation of the transmission. Use of the pressure switch input was dropped from the vehicle calibration before the 2003 model year went into production.*



Copyright © 2005 ATSG

Figure 1