



Technical Service Information

FORD AOD NO 4TH GEAR

COMPLAINT: Very late 4th gear, or NO 4th gear.

CAUSE: Valve Body and/or Case cross leaks.

CORRECTION: Drill a vent hole through valve body casting, in the 3-4 T.V. modulator circuit, using a .020" drill bit. See Figure 1 for the location. The smaller drill bits can usually be obtained at the local hobby shop.




Figure 1