

NISSAN RE4FO2A AND RL4FO2A NO SECOND OR FOURTH AFTER REBUILD

COMPLAINT: After rebuild, the transaxle exhibits a no second and no fourth condition.

CAUSE: The cause may be, a mis-assembled 2-4 servo piston.

CORRECTION: Assemble the servo piston in the proper direction, as shown in Figures 1, 2, and 3.
Refer to Figure 1 for RL4FO2A and RE4FO2A, 1988-Up models.
Refer to Figure 2 for RL4FO2A, 1986 models only.
Refer to Figure 3 for RL4FO2A, 1987 models only.




Figure 1

SERVO AND ACCUMULATOR ASSEMBLY RL4FO2A 1986 MODELS ONLY




Figure 2

SERVO AND ACCUMULATOR ASSEMBLY RL4FO2A 1987 MODELS ONLY




Figure 3