



Technical Service Information

MAZDA RA4A-EL NISSAN RE4R03A

LOCK-UP SHUDDER (2 LOCK-UP SOLENOID UNITS ONLY)

COMPLAINT: Some Mazda or Nissan vehicles equipped with the RA4AEL or RE4R03A may exhibit a lock-up shutter upon application of the lock-up clutch.

CAUSE: One cause may be lock-up release oil not exhausting quickly enough through the lock-up control valve.

CORRECTION: Drill hole and open orifice in the bottom of the valve-body as shown in Figure 1 below.




Figure 1