


THM 440-T4 HARSH DRIVE ENGAGEMENT

COMPLAINT: Harsh garage shift from Park/Neutral to Drive.

CAUSE: The cause may be:

1. Low vacuum supply to vacuum modulator.
2. Stuck modulator valve in case.
3. No. 12 checkball missing or off location.

CORRECTION: AFTER ALL OF THE ABOVE ARE ELIMINATED:
There is now available a new 1-2 Servo Cushion Spring. Replacing this spring should correct the harsh drive condition (See Figure 1).
Spring, 1-2 Servo Cushion (All).....8668123



Copyright © 2001 ATSG

Figure 1