



Technical Service Information

FORD 4EAT PROBE LOW PUMP PRESSURE

COMPLAINT: Low pump pressure.

CAUSE: The spool valve in the pump did not have a seat for the spring. The spring will hang the valve and cause low line pressure (figure 1).

CORRECTION: Order updated valve from Ford. It has a seat formed on the valve for the spring and will work on both units (figure 2) part # FO2Z-7Z306-A.




Figure 1




Figure 2