

FORD AOD **NO FORWARD AFTER COAST-DOWN FROM 4TH GEAR**

COMPLAINT: Some Ford Motor Company vehicles equipped with the AOD transmission may exhibit a no forward drive condition after coast down from fourth gear.

CAUSE: One cause may be a small particle of contamination causes the 3-4 shift valve to stick in an up-shifted position causing the forward clutch to remain exhausted.

CORRECTION: Remove the main control body and repair or replace as necessary.




Figure 1