



Technical Service Information

VOLVO AW55-50SN NEUTRAL BANG ON TAKE-OFF

COMPLAINT: Some Volvo models equipped with the AW 55-50 SN transaxle, as shown in Figure 1, may exhibit a neutral bang on take-off before or after overhaul.

CAUSE: The cause may be, that when the accelerator pedal is depressed rapidly, the customer may feel a re-engagement of the C1 clutch on take-off because of a Transmission Control Module software issue.


CORRECTION: To correct this complaint, the TCM will have to be reflashed by a Volvo dealer, which will deactivate or de-sensitize this feature. TCM 012B Neutral Control Flash.

SERVICE INFORMATION:

TCM UPGRADE NUMBER (Volvo).....30677036

*Special thanks
to Joe at Highland
Transmission*

AW55-50 SN



Copyright © 2005 ATSG

Figure 1

AUTOMATIC TRANSMISSION SERVICE GROUP

07-25
Page 1 of 1