



Technical Service Information

THM 4L80-E HIGH LINE PRESSURE IN REVERSE

COMPLAINT: Before and/or after rebuild, the vehicle has a very high line pressure reading when the selector lever is in the Reverse position, and may repeatedly break direct clutch piston and/or reverse band assembly.

CAUSE: The cause may be, a worn boost valve sleeve and/or boost valve in the pimp assembly.

CORRECTION: Replace the Boost Valve and/or Boost Valve Sleeve, as necessary (See Figure 1). Parts are currently available from G.M. Service Parts, and part numbers are listed below.

SERVICE INFORMATION:

Boost Valve Sleeve	8682856
Boost Valve, Line Pressure	8680549

