



Technical Service Information


THM 325

NO SHIFTS AFTER KICK DOWN

COMPLAINT: Late upshifts or erratic shifting after using kick down.

CAUSE: The T.V. Valve may be binding due to the roll pin in the throttle lever and bracket assembly, which is extending beyond the T.V. Lever paddle See Figure 1.

CORRECTION: Drive the roll pin towards the bracket to have clearance between the valve and the roll pin.



Copyright © 2000 ATSG

Figure1