



Technical Service Information

THM 4L60-E SOFT 1-2 UPSHIFT


COMPLAINT: Some 1994 model vehicles, equipped with the THM 4L60-E transmission may exhibit a soft 1-2 upshift condition.

CAUSE: The cause may be, calibration of the 1-2 accumulator valve in the valve body.

CORRECTION: There is now available a new calibration service package consisting of a 1-2 accumulator valve, valve spring, and 1-2 accumulator valve bushing for the valve body. These are items 370, 371, and 372, as shown in Figure 1 below. This new service package is available under OEM part number 24202698.

SERVICE INFORMATION:

1-2 Accumulator Valve Service Package 24202698



Copyright © 2000 ATSG

Figure 1

AUTOMATIC TRANSMISSION SERVICE GROUP

96-16
Page 1 of 1