



Technical Service Information


FORD C-6

LACK OF LUBE TO REAR

COMPLAINT: Failure of number nine thrust washer on the C-6 transmission, in heavy duty applications such as tow trucks or modified ambulances.

CAUSE: Lack of lube to thrust washer

CORRECTION: On the back side of the overrun roller clutch inner race there is a lube hole that goes half way through the race. To get more lube to the number 9 thrust washer, drill the lube hole all the way through the race so it breaks out on the other side. The drilling will probably blue the drill, since the race is a hardened part.



Copyright © 2000 ATSG

Figure1