




Technical Service Information

THM 4L80-E

2ND GEAR STARTS AND NO LINE RISE

- COMPLAINT:** Some THM 4L80-E/4L80-EHD transmissions may exhibit a twisting or breakage of the turbine shaft and/or breaking of the O.D. carrier assembly, usually in "P" series cube vans.
- CAUSE:** The cause may be more torque load than the parts are capable of carrying, usually vehicle weight in heavy throttle conditions.
- CORRECTION:** There is now available from OEM a new service package that includes a heavy duty turbine shaft and overdrive carrier assembly. Refer to Figure 1. This service package, OEM part number 24200130, should be installed in "P" series cube vans, or any vehicle carrying a lot of extra weight.
- SERVICE INFORMATION:**
- | | |
|--|----------|
| Turbine Shaft and O.D. Carrier Asm. (Heavy Duty) | 24200130 |
|--|----------|

**HEAVY DUTY TURBINE SHAFT
AND O.D. CARRIER**



**OEM PART NUMBER
24200130**