



Technical Service Information

FORD 4R44E/4R55E/5R55E DELAYED REVERSE ENGAGEMENT

COMPLAINT: Some vehicles equipped with the 4R44E/4R55E may exhibit a delayed engagement in reverse .

CAUSE: One cause may be, insufficient feed to the direct clutch in reverse.

CORRECTION: Remove and discard the check ball as shown in Figure 1.




Figure 1