



# Technical Service Information

## SUBARU 3 SPEED SLUGGISH AFTER SITTING OVERNIGHT

- COMPLAINT:** Transmission works fine until it sits, with the engine off, for a period of an hour or more. When started you have a slip and/or extreme sluggishness.
- CAUSE:** Oil pump drive shaft bushing has been installed on the wrong end of the shaft, or is missing, creating converter drain back and requiring fill time for the pump to refill torque converter.
- CORRECTION:** Install the oil pump drive shaft bushing into "Converter End" of turbine shaft, between turbine shaft and oil pump drive shaft (Refer to figure 1).




Figure 1

Copyright © 2000 ATSG