



Technical Service Information

ZF 5HP-24

SLIPPING OR NO FORWARD ENGAGEMENT


COMPLAINT: Vehicles equipped with the ZF 5HP-24 transmission may exhibit a Slipping or no Forward engagement.

CAUSE: The cause may be, a broken snap ring groove in the "A" Clutch Drum allowing the "A" Clutch to slip, as shown in Figure 1.

CORRECTION: Replace the "A" Clutch Drum with the updated drum available from ZF.

SERVICE INFORMATION:

A CLUTCH DRUM (ZF part number).....1058 270 036



Copyright © 2004 ATSG

Figure 1