



1996 SEMINAR INFORMATION

## "THE BEST FIX IN '96"

### INDEX

#### *GENERAL MOTORS*

4L80E.....	4
4L60E.....	30
4T60E.....	58
4T80E.....	82

#### *FORD*

CD4E.....	84
4R44E/4R55E.....	90
AX4N/AXODE.....	98
E4OD.....	109

AUTOMATIC TRANSMISSION SERVICE GROUP  
9200 S. DADELAND BLVD. STE 720  
MIAMI, FLORIDA 33156  
(305) 670-4161

# My customers count on me. I count on Transtar.



The transmission business is simple. Customers want their cars fixed right the first time. They want them back fast. And they count on you to do that. No excuses. Which is why so many transmission shops across the country rely on Transtar. You can trust our OEM-quality parts.

And, with over 96% order fill, we'll come through for you with the right parts delivered fast. So your customers stay happy. And stay away from the competitor on the corner.



## **TRANSTAR®**

**TRANSTAR INDUSTRIES, INC.**

7350 YOUNG DRIVE, CLEVELAND, OHIO 44146 U.S.A.

Main Office & International Division 216/232-5100

**Thirteen "neighborhood" locations to serve you.**

**Main Office & International Division 7350 Young Drive, Cleveland, OH 44146 U.S.A.**

**Toll Free 800-321-8830 • Telephone 216-232-5100 • Fax 216-232-0632**

**Cincinnati, OH**  
800/543-2723

**Chicago, IL**  
800/214-8710

**Denver, CO**  
800/525-9096

**Edison, NJ**  
800/654-3442

**Houston, TX**  
800/882-8844

**Nashua, NH**  
800/446-9888

**New Orleans, LA**  
800/525-2512

**Sacramento, CA**  
800/446-2600

**Sarasota, FL**  
800/899-9623

**St. Louis, MO**  
800/446-7171

**Van Nuys, CA**  
800/231-9000

**Yauco, Puerto Rico**  
800/981-3332



# "THE BEST FIX IN '96"

## INTRODUCTION

In this second manual on "THE BEST FIX IN '96" seminar, we continue with the General Motors portion of the seminar. Concluding with updates and fixes to the 4L80E, 4L60E, 4T60E and the 4T80E transaxle. With the General Motors segment concluded, the manual then details the Updates to the FORD CD4E, 4R44E/4R55E and the AX4N/AXODE transaxle with the Video section on these transmission. The manual concludes with the beginning of the live presentation on the E4OD transmission.

The information and part numbers contained in this booklet have been carefully compiled from industry sources known for their reliability, but ATSG does not guarantee its accuracy.

Copyright © ATSG 1996

ROBERT D. CHERRNAY  
TECHNICAL DIRECTOR

DALE ENGLAND  
FIELD SERVICE CONSULTANT

WAYNE COLONNA  
TECHNICAL SUPERVISOR

ED KRUSE  
TECHNICAL CONSULTANT

PETE LUBAN  
TECHNICAL CONSULTANT

JIM DIAL  
TECHNICAL CONSULTANT

GREGORY LIPNICK  
TECHNICAL CONSULTANT

JERRY GOTT  
TECHNICAL CONSULTANT

DAVID CHALKER  
TECHNICAL CONSULTANT

*AUTOMATIC TRANSMISSION SERVICE GROUP*  
9200 S. DADELAND BLVD.  
SUITE 720  
MIAMI, FL 33156  
(305) 670-4161

## 4 WHEEL DRIVE LOW CIRCUIT 1991-93 4X4 WITH 4L80E




Figure 33

GM 4 wheel drive equipped vehicles with 4L80E transmissions will use the VSS located in the transfer case to calculate vehicle speed when in 2 wheel drive and 4 wheel high modes.

But what happens, when 4 wheel LOW is selected, which results in a gear reduction? How can the VSS be accurate? How will the transmission know when to shift?

In model years 1991-93, when 4 wheel low is selected, the gear reduction is seen by the computer through the VSS in the transfer case. At this time the computer switches strategy and now uses the output shaft speed sensor to calculate vehicle speed which is sent unbuffered to the PCM/TCM. (Refer to Figures 33 and 34)




Figure 34

## 4 WHEEL DRIVE LOW CIRCUIT

### 1994-95 4X4 WITH 4L80E




Figure 35




Figure 36

1994 & up vehicles with 4L80E transmission utilize a 4WD low switch to signal the computer that 4W LOW has been selected. It does this by supplying 12V to the PCM when in 2WD or 4W HI mode. When 4W LOW is selected the 4W LOW switch grounds the 12V signal changing it to 0V. The computer then changes its strategy in order to calculate vehicle speed. (Refer to figures 35, 36 and 37)




Figure 37

## SPEED SENSOR FREQUENCY INTERFERENCE

Frequency interference in today's electronically controlled vehicles has become a relatively common problem. The interference occurs when a magnetic field produced by an electrical device interferes with the magnetic field of another electrical device.

For instance if a cellular telephone is installed in a vehicle with a 4L80E, the magnetic field produced by the telephones transmitter can interfere with the transmissions speed sensor signal causing various types of erratic operation.

Some of the devices which are known to cause this interference are:

- CELLULAR TELEPHONES
- 2 WAY RADIOS
- ELECTRONIC TRAILER BRAKES
- HIGH POWERED STEREO SYSTEMS
- ELECTRONIC ALARM SYSTEMS
- PROPANE CONVERSION SYSTEMS

Frequency interference can also be caused by OEM equipment such as a faulty ALTERNATOR or an ENGINE RPM SENSOR which are both AC generators.

Beginning with the 1994 model year the Engine RPM Sensor is replaced by a Crankshaft sensor which is NOT an AC generator.




Figure 38

*Automatic Transmission Service Group*

## 4L80E PRESSURE SWITCH MANIFOLD (PSM) DIAGNOSIS

The pressure switch manifold is a multi-switch assembly made up of 5 normally open pressure switches which are fed line pressure direct from the manual valve. These fluid pressures, depending on manual valve position, will determine the signal delivered to the PCM/TCM so the PCM/TCM will know which gear shift position has been selected. (Refer to figure 39)

The fluid pressure switches contained in the Pressure Switch Manifold are normally open. When no fluid pressure is present at these switches, a 12 volt signal will result at PSM terminals A, B and C. When fluid pressure closes these switches, a ground path is provided which results in 0 volts at PSM terminals A, B or C, depending on manual valve position. (Refer to figure 40) Therefore, when 12 volts are present the circuit is OPEN. When 0 volts are present the circuit is CLOSED. This can better be seen in the example in figure 41 which is manual third. Notice the PSM switch pattern as shown in the chart in figure 42. The switch pattern is A is CLOSED, B is CLOSED and C is OPEN if the scanner is reading the 12 volt side of the circuit. If the scanner is reading the ground side of the circuit, the scanner would display the range parameters reversed which would be A=OPEN, B=OPEN, C=CLOSED. This is how the computer knows that manual third has been selected and will now prevent an upshift to 4th.

It is this opening and closing of these pressure switches which creates the 7 valid switch combinations as seen in the chart in figure 42. There are however, 2 invalid gear combinations which will result in a code 28 being stored. In most cases a malfunctioning PSM will not log any codes, therefore it must be checked to see if the gear combination that is present agrees with the actual gear shift position.

This can best be accomplished through a scanner where the PSM RANGE can be viewed. The PSM can also be checked, removed from the transmission, with an ohmmeter.




Figure 39

## 4L80E PRESSURE SWITCH MANIFOLD (PSM) DIAGNOSIS




Figure 40





Figure 41

RANGE INDICATOR	OIL PRESSURE				
	REV	D4	PRND4	PRND43	LO
PARK					
REVERSE					
NEUTRAL					
D4					
D3					
D2					
LO					

 OIL PRESSURE PRESENT

VALID PSM COMBINATION CHART			
	A	B	C
PARK	12	0	12
REV	0	0	12
NEUTRAL	12	0	12
4TH	12	0	0
3RD	12	12	0
2ND	12	12	12
1ST	0	12	12
ILLEGAL	0	12	0
ILLEGAL	0	0	0

**EXPECTED VOLTAGE READINGS**

Figure 42



## SLIDE

## GM DIESEL TRUCKS 1994 AND UP

### ACCELERATOR PEDAL POSITION MODULE

The Accelerator Pedal Position Module (APP) is currently used in 1994 and later GM trucks equipped with the 6.5 liter diesel engine which is a "drive by wire" electronic fuel injected system. In other words, a throttle cable is not used with this system.

The APP module contains 3 throttle position sensors (Refer to figure 43) which overlap each other. This is done to prevent over fueling or a WOT condition, which could occur if one TPS were used and it failed.

The APP module will find its way into the next generation of gasoline powered engines produced by GM. Figure 44 shows the location of the APP module which is serviced as a complete unit.

All 3 TP Sensors can be viewed on a scanner. They are displayed as follows:

APP SENSOR 1>>> 0.45 V @ CLOSED THROTTLE to 3.7 V @ WOT

APP SENSOR 2>>>> 4.5 V @ CLOSED THROTTLE to 1.5 V @ WOT

APP SENSOR 3>>>> 4.0 V @ CLOSED THROTTLE to 2.0 V @ WOT

It can be seen that APP 1 starts at low voltage and goes high, while APP 2 starts high and goes low, while APP 3 fills in the middle. In this manner, all accelerator pedal positions are compensated for while proper fuel delivery is maintained. Both idle and wot operation are illustrated in figures 45 and 46.

Should ONE sensor fail, a trouble code would be stored with no further action being taken.

Should TWO sensors fail, the engine will operate at reduced power, and the "SERVICE THROTTLE SOON" lamp will be illuminated.

Should THREE sensors fail, The PCM will reduce engine power to an idle as well as all of the above.

The codes that a malfunction of this module can generate are 21, 22, 25, 26, 27, 63, 64, 65, 84 and 99.




Figure 43




Figure 44



## GM DIESEL TRUCKS 1994 AND UP ACCELERATOR PEDAL POSITION MODULE

### KEY ON...ENGINE RUNNING @ IDLE

1995 GMC	INCOMPLETE	A/C
6.5L V8-T	CHEV DIESEL	A/T
-58 CODES & DATA		OK TO DRIVE
NO CODES PRESENT		THROTTLE(%) _____ 0
RPM _____ 769		COOLANT(F) _____ 161
DESIRED IDLE _____ 769		BARO(V) _____ 4.94
BARO ("Hg) _____ 30.0		PEDAL POS 2(V) _____ 4.26
PEDAL POS 1(V) _____ 0.78		INTAKE AIR _____ -9
PEDAL POS 3(V) _____ 3.98		EGR PRESS(V) _____ 4.04
EGR PRESS("Hg) _____ 29.9		WASTEGATE(%) _____ 67
EGR DUTY CYCLE _____ 0		BOOST PRESS(V) _____ 2.12
BOOST("Hg) _____ 31.4		FUEL RATE(MM) _____ 16.0
FUEL TEMP _____ -2		GLOW PLUG RLY(V) _____ 0.1
GLOW PLUG(V) _____ 0.1		DES INJ TIM _____ 9.1
INJ TIMING _____ 9.3		TDC OFFSET _____ 0.00
INJ PW(MS) _____ 1.68		CRANK REF MISSED _____ 0
CAM REF MISSED _____ 0		IGNITION(V) _____ 13.5
VEH SPEED(MPH) _____ 0		2-3 SOLENOID _____ OFF
1-2 SOLENOID _____ ON		CC BRAKE SW _____ CLSD
CC ON/OFF SW _____ OFF		TCC APPLIED _____ NO
TCC BRAKE SW _____ OPEN		
PROM ID _____ 6875		

Figure 45

### KEY ON...ENGINE OFF @ WOT

1995 GMC	INCOMPLETE	A/C
6.5L V8-T	CHEV DIESEL	A/T
-34 CODES & DATA		OK TO DRIVE
NO CODES PRESENT		THROTTLE(%) _____ 100
RPM _____ 0		COOLANT(F) _____ 86
DESIRED IDLE _____ 750		BARO(V) _____ 4.94
BARO ("Hg) _____ 30.0		PEDAL POS 2(V) _____ 1.20
PEDAL POS 1(V) _____ 3.92		INTAKE AIR _____ -10
PEDAL POS 3(V) _____ 2.14		EGR PRESS(V) _____ 4.04
EGR PRESS("Hg) _____ 29.9		WASTEGATE(%) _____ 0
EGR DUTY CYCLE _____ 0		BOOST PRESS(V) _____ 2.12
BOOST("Hg) _____ 31.4		FUEL RATE(MM) _____ 0.0
FUEL TEMP _____ -5		GLOW PLUG RLY(V) _____ 0.1
GLOW PLUG(V) _____ 0.1		DES INJ TIM _____ 0.0
INJ TIMING _____ 8.3		TDC OFFSET _____ 0.00
INJ PW(MS) _____ 1.95		CRANK REF MISSED _____ 0
CAM REF MISSED _____ 0		IGNITION(V) _____ 11.8
VEH SPEED(MPH) _____ 0		2-3 SOLENOID _____ OFF
1-2 SOLENOID _____ OFF		CC BRAKE SW _____ OPEN
CC ON/OFF SW _____ OFF		TCC APPLIED _____ NO
TCC BRAKE SW _____ CLSD		
PROM ID _____ 6875		

Figure 46



SLIDE

## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER SKEWED OR SHIFTED SENSORS

COMPLAINT: Vehicle exhibits a symptom without storing fault codes

CAUSE #1: This condition is caused by a sensor malfunction that did NOT remain BAD ENOUGH, LONG ENOUGH, or the sensor return voltage remained at a fixed value which did not exceed specification or time limits.  
The Snap-on Scan Gra-Fix® program, which is responsible for the graph shown in figure 47, indicates a normal pattern of throttle position sensor operation.  
The movie frame shown in figure 48 indicates all electrical functions are normal.  
When computer software is designed for a given application, a spec value and a time clock is programmed into the computer. In order to store a code for this sensor, the sensor must fail outside the specification window and the internal time clock.  
If the sensor failure stays within the time limit or the spec value, this will create **a symptom but not a code**.  
In movie frame -26 shown in figure 49, the only parameter that is incorrect is the TCC duty cycle which went to zero. Consequently TCC slip goes up and as a result of the slippage created by the converter being unlocked, the gear ratio is incorrect.  
However, when an engine data movie frame is viewed, such as the one in figure 51, we can see that the TPS voltage has spiked to 4.56 volts for 2/10 of a second as shown in the graph in figure 50. The sensor was not out of range for a long enough period of time. This causes a symptom but not a code, which in this case caused the converter to unlock.  
Eventually a code 68 would be stored due to the converter remaining unlocked, which would be totally misleading.

CAUSE #2: If the sensor skirts the spec or time operating window but does not go outside this window, this is a shifted sensor which is shown in the graph in figure 52 and in the Snap-on Scan-Gra-Fix® printout in figure 53.  
The TPS voltage is frozen at .6 volts for a little over a second. The printout in figure 53 indicates TCC unlocked, input and engine rpm went up drastically in frame -53, force motor amps went up causing a drop in line pressure and at 43 mph the transmission went to neutral because at that speed low gear is unobtainable.  
In frame -53 the transmission went to low gear due the TPS voltage drop.  
If this condition were to happen repeatedly, the complaint could be shift hunting.  
Once again, you have a symptom but no codes.

CORRECTION #1: A skewed sensor is typically caused by an outside influence such as a faulty engine rpm sensor or a faulty alternator.

CORRECTION #2: A shifted sensor is typically caused by the sensor which will require replacement.

WE JUST GOT  
**BIGGER**  
TO SERVE YOU  
**BETTER**

**LARGEST PARTS INVENTORY • IMMEDIATE SHIPMENT**

**#1 Source for  
STANDARD  
TRANSMISSION  
PARTS  
OEM PARTS FOR  
IMPORTS**

**\*Mitsubishi, Monteros, Pick-Ups**

**\*Dodge D50, RAM 50, Raider**

**\*Ford-Mitsubishi, Toyo Kogyo, ZF**

**We carry a complete line of Parts for  
AMERICAN STANDARD TRANSMISSIONS  
and TRANSFER CASES**



**Rockland**

**Standard Gear, Inc.**

**300 Airport Executive Park (Bldg. 306)**

**Nanuet, NY 10954**

**800•227•1523**

**914•425•7557**

**FAX 914•425•3163**



## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER

### SKEWED THROTTLE POSITION SENSOR

NORMAL PATTERN...41% THROTTLE OPENING...ELAPSED TIME=2/10 SECOND




Figure 47

-27 INPUT RPM _____ 2980	OUTPUT RPM _____ 2977
CODES & DATA	OK TO DRIVE
NO CODES PRESENT	
I/O RPM (RATIO) _____ 1.00	VEH SPEED (MPH) _____ 64
TURBINE RPM _____ 2234	COOLANT (F) _____ 188
TCC DUTY CYCLE _____ 87	TRANS FLUID (F) _____ 186
TORQUE SIG (PSI) _____ 52	GEAR RATIO _____ 0.75
BRAKE REQUEST _____ NO	BRAKE SW _____ OPEN
TCC SLIP (RPM) _____ 4	THROTTLE (%) _____ 41
BATTERY (V) _____ 13.8	
PRESS CTRL AMP _____ 0.51	DES PCS AMP _____ 0.49
ENGINE RPM _____ 2285	INPUT RPM _____ 2980
OVERDRIVE RATIO _____ 0.75	VEH SPEED (MPH) _____ 64
CURRENT GEAR _____ 4TH	PRNDL SW _____ 4TH
SOLENOID A _____ ON	SOLENOID B _____ ON
RANGE A _____ CLSD	RANGE B _____ OPEN
RANGE C _____ OPEN	POWER ENRICH _____ NO
1-2 SHIFT (SEC) _____ 0.38	2-3 SHIFT (SEC) _____ 0.50
3-4 SHIFT (SEC) _____ 0.03	A/C REQUEST _____ NO
A/C CLUTCH _____ OFF	

CLUES: This truck had over 100,000 miles on the odometer.  
This truck is gasoline powered.  
In movie frame -27 shown above all parameters are normal.

Figure 48



## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER SKEWED THROTTLE POSITION SENSOR

-26 INPUT RPM_____ 3184	OUTPUT RPM_____ 3183
CODES & DATA	
NO CODES PRESENT	OK TO DRIVE
I/O RPM (RATIO)_____ 1.00	VEH SPEED (MPH)_____ 64
TURBINE RPM_____ 2388	COOLANT (F)_____ 188
TCC DUTY CYCLE_____ 0	TRANS FLUID (F)_____ 186
TORQUE SIG (PSI)_____ 42	GEAR RATIO_____ 0.86
BRAKE REQUEST_____ NO	BRAKE SW_____ OPEN
TCC SLIP (RPM)_____ 44	THROTTLE (%)_____ 41
BATTERY (V)_____ 13.8	
PRESS CTRL AMP_____ 0.57	DES PCS AMP_____ 0.59
ENGINE RPM_____ 2303	INPUT RPM_____ 3184
OVERDRIVE RATIO_____ 0.75	VEH SPEED (MPH)_____ 69
CURRENT GEAR_____ 4TH	PRNDL SW_____ 4TH
SOLENOID A_____ ON	SOLENOID B_____ ON
RANGE A_____ CLSD	RANGE B_____ OPEN
RANGE C_____ OPEN	POWER ENRICH_____ NO
1-2 SHIFT (SEC)_____ 0.28	2-3 SHIFT (SEC)_____ 0.38
3-4 SHIFT (SEC)_____ 0.03	A/C REQUEST_____ NO
A/C CLUTCH_____ OFF	

CLUE: In frame -26 shown above TCC duty cycle went to zero, TCC slip has gone up. Gear ratio is incorrect.  
All other parameters appear normal.

Figure 49



## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER SKEWED THROTTLE POSITION SENSOR

SKEWED PATTERN...41% THROTTLE OPENING...ELAPSED TIME=2/10 SECOND




Figure 50

1991 CHEVROLET TRUCK AC  
7.4L V8 CHEV TBI A/T  
CODES & DATA

**NO CODES PRESENT**

-43 RPM	2450
OPEN/CLSD LOOP	CLSD
TPS (V)	4.56
DESIRED IDLE	750
IDLE AIR CONTROL	74
IAC COIL ENABLE	YES
IAC DIRECTION	REV
MAP (Hg)	24.1
BARO (Hg)	29.2
COOLANT (F)	190
EGR DUTY CYCLE	75
A/F LEARNED	YES
VEH SPEED (MPH)	64
CLEAR FLOOD	NO
BATTERY (V)	14.1
LOW BATTERY	NO
PRNDL SW	4TH
TCC APPLIED	NO
TCC SLIPPING	NO

**OK TO DRIVE**

O2 (MV)	451
EXHAUST OXYGEN	LEAN
TPS (%)	41
BLK LEARN	122
IAC COIL A	ON
IAC COIL B	OFF
PROM ID	8091
MAP (V)	3.86
BARO (V)	4.78
START CLNT (F)	92
AIR CONTRL SOL	NORM
A/F RATIO	14.7
KNOCK	NO
SPARK ADV(DEG)	24
FUEL PUMP (V)	14.1
TRANS TEMP HOT	NO
A/C REQUEST	NO
TIME	7:42
TCC FORCED OFF	NO

CLUE: Why are we concerned with ENGINE data?

Why is the TPS voltage 4.56 with only a 41% throttle opening.

TCC is not applied at 64 MPH.

System indicates that TCC was NOT forced off.

Why are there no codes stored?

Figure 51



## SLIDE

**4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER**  
**SHIFTED THROTTLE POSITION SENSOR**

SHIFTED PATTERN...31% THROTTLE OPENING...ELAPSED TIME=1.2 SECONDS




Figure 52

4l80eshiftpsmovie		1991 CHEVROL 7.4L V8 CHEVY TBI						
Frame:	-57	-56	-55	-54	-53	-52	-51	
INPUT RPM	2101	2117	2125	2141	3241	3282	3351	
OUTPUT RPM	2097	2113	2120	2135	1893	1109	1837	
I/O RATIO	100	100	100	100	270	256	261	
VEH SPEED (MPH)	45	46	46	46	43	41	38	
TURBINE RPM	2101	2117	2125	2141	3241	3282	3351	
COOLANT (degF)	202	202	202	202	202	202	202	
TCC DUTY CYCLE (%)	0	0	0	0	0	0	0	
TRANS FLUID (degF)	174	173	173	174	174	174	174	
TORQUE SIG (PSI)	34	34	34	34	29	26	23	
GEAR RATIO	100	100	100	100	270	256	255	
BRAKE REQUEST	NO	NO	NO	NO	NO	NO	NO	
BRAKE SW	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	
TCC SLIP (RPM)	243	258	277	321	556	576	614	
TPS (V)	00.6	00.6	00.6	00.6	00.6	00.6	00.6	
THROTTLE (%)	31	31	31	31	31	31	31	
BATTERY (V)	13.4	13.4	13.4	13.4	13.4	13.4	13.4	
PROM ID	2061	2061	2061	2061	2061	2061	2061	
PRESS CTRL AMP	0.63	0.63	0.63	0.63	0.75	0.78	0.82	
DES PCS AMP	0.63	0.61	0.62	0.62	0.74	0.76	0.82	
ENGINE RPM	2329	2351	2373	2379	3797	4115	4353	
OVERDRIVE RATIO	111	109	109	109	331	295	284	
CURRENT GEAR	3RD	3RD	3RD	3RD	LOW	LOW	LOW	
PRNDL SW	4TH	4TH	4TH	4TH	4TH	4TH	4TH	
SOLENOID A	OFF	OFF	OFF	OFF	ON	ON	ON	
SOLENOID B	ON	ON	ON	ON	OFF	OFF	OFF	
RANGE A	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	
RANGE B	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	
RANGE C	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	
POWER ENRICH	NO	NO	NO	NO	NO	NO	NO	
1-2 SHIFT (SEC)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
2-3 SHIFT (SEC)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
3-4 SHIFT (SEC)	0.03	0.03	0.03	0.03	0.03	0.03	0.03	
A/C REQUEST	YES	YES	YES	YES	YES	YES	YES	
A/C CLUTCH	ON	ON	ON	ON	ON	ON	ON	

Figure 53



**MECHANICAL PROBLEM OR ELECTRICAL PROBLEM?****4L80E FALLS OUT OF 4TH INTO NEUTRAL OR 3RD GEAR****CODE 68...OVERDRIVE RATIO INCORRECT**

The most common cause of this problem is faulty shift solenoids that are stuck open due to the rubber seat inside them deteriorating. This problem will generate a code 68 (Overdrive Ratio Incorrect) because when the solenoid exhausts the transmission will instantly downshift into 3rd gear when the "A" shift solenoid malfunctions or neutral when the "B" shift solenoid malfunctions, which in reality is a downshift to 1st gear. The transmission goes to neutral because at cruising speed low gear is unobtainable.

The chart in figure 54 illustrates which gear is commanded and which gear will result when either "A" or "B" shift solenoid malfunctions. It is important to realize, when the solenoid is shown OFF it is OPEN, and when it is shown ON it is CLOSED.

**4L80E SHIFT SOLENOID MECHANICAL FAILURE CHART**

<b>COMMANDED GEAR</b>	<b>SOLENOID A MECHANICAL FAULT</b>	<b>SOLENOID B NORMAL</b>	<b>ACTUAL GEAR</b>
1st	OFF	OFF	2nd
2nd	OFF	OFF	2nd
3rd	OFF	ON	3rd
4th	OFF	ON	3rd
1st	ON	OFF	1st
2nd	ON	OFF	1st
3rd	ON	ON	4th
4th	ON	ON	4th

<b>COMMANDED GEAR</b>	<b>SOLENOID A NORMAL</b>	<b>SOLENOID B MECHANICAL FAULT</b>	<b>ACTUAL GEAR</b>
1st	ON	OFF	1st
2nd	OFF	OFF	2nd
3rd	OFF	OFF	2nd
4th	ON	OFF	1st
1st	ON	ON	4th
2nd	OFF	ON	3rd
3rd	OFF	ON	3rd
4th	ON	ON	4th

Figure 54



## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER

### CODE 68...OVERDRIVE RATIO INCORRECT

The "Movie" feature that current scan tools offer can be one of the most valuable diagnostic aid available to the technician. It is most valuable when an intermittent problem occurs because in some instances the malfunction happens so quickly (2/10 of a second) that the only way it would be seen is by recording a movie.

The SNAP-ON scanner, for example, will record approximately 75 frames of data stream information before the movie was triggered and 25 frames after the movie was triggered allowing the technician to return to the shop and review what has malfunctioned during the road test. In this way the technician can determine what has caused the malfunction which, under other circumstances would not have been detected.

The information in figures 55, 56 and 57 are actual recorded movies which will display the information that will lead to the diagnosis of these examples of faults that generate code 68.

-15	INPUT RPM	2841	OUTPUT RPM	2841
	CODES & DATA		OK TO DRIVE	
68	OVERDRIVE RATIO INCORRECT			
	I/O RPM (RATIO)	1.00	VEH SPEED (MPH)	58
	TURBINE RPM	2841	COOLANT (F)	190
	TCC DUTY CYCLE	0	TRANS FLUID (F)	186
	TORQUE SIG (PSI)	59	GEAR RATIO	1.00
	BRAKE REQUEST	NO	BRAKE SW	OPEN
	TCC SLIP (RPM)	255	THROTTLE (%)	55
	BATTERY (V)	13.8		
	PRESS CTRL AMP	0.41	DES PCS AMP	0.43
	ENGINE RPM	2508	INPUT RPM	2841
	OVERDRIVE RATIO	0.75	VEH SPEED (MPH)	58
	CURRENT GEAR	4TH	PRNDL SW	????????
	SOLENOID A	ON	SOLENOID B	ON
	RANGE A	CLSD	RANGE B	OPEN
	RANGE C	OPEN	POWER ENRICH	NO
	1-2 SHIFT (SEC)	0.47	2-3 SHIFT (SEC)	0.41
	3-4 SHIFT (SEC)	0.03	A/C REQUEST	NO
	A/C CLUTCH	OFF		

Figure 55

CLUES: Comanded solenoid state is 4th gear

Overdrive gear ratio is 0.75

There should be at least a 3-5 rpm difference between output rpm and input rpm.

TCC duty cycle has gone to zero which will raise the TCC slip rpm.

Question marks at PRNDL SW indicates an invalid gear ratio.

PSM range indicates the manual valve is in the D4 position.

**SLIDE**

## 4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER

## CODE 68...OVERDRIVE RATIO INCORRECT

-15 INPUT RPM	2577	OUTPUT RPM	2498
CODES & DATA		OK TO DRIVE	
NO CODES PRESENT			
I/O RPM (RATIO)	1.00	VEH SPEED (MPH)	55
TURBINE RPM	1977	COOLANT (F)	190
TCC DUTY CYCLE	98	TRANS FLUID (F)	210
TORQUE SIG (PSI)	59	GEAR RATIO	0.79
BRAKE REQUEST	NO	BRAKE SW	OPEN
TCC SLIP (RPM)	234	THROTTLE (%)	55
BATTERY (V)	13.8		
PRESS CTRL AMP	0.41	DES PCS AMP	0.43
ENGINE RPM	2208	INPUT RPM	2501
OVERDRIVE RATIO	0.75	VEH SPEED (MPH)	55
CURRENT GEAR	4TH	PRNDL SW	7777777
SOLENOID A	ON	SOLENOID B	ON
RANGE A	CLSD	RANGE B	OPEN
RANGE C	OPEN	POWER ENRICH	NO
1-2 SHIFT (SEC)	0.47	2-3 SHIFT (SEC)	0.41
3-4 SHIFT (SEC)	0.03	A/C REQUEST	NO
A/C CLUTCH	OFF		

Figure 56

-14 INPUT RPM	2967	OUTPUT RPM	2842
CODES & DATA		OK TO DRIVE	
68 OVERDRIVE RATIO INCORRECT			
I/O RPM (RATIO)	1.00	VEH SPEED (MPH)	58
TURBINE RPM	2941	COOLANT (F)	190
TCC DUTY CYCLE	0	TRANS FLUID (F)	210
TORQUE SIG (PSI)	255	GEAR RATIO	0.89
BRAKE REQUEST	NO	BRAKE SW	OPEN
TCC SLIP (RPM)	330	THROTTLE (%)	55
BATTERY (V)	13.8		
PRESS CTRL AMP	0.00	DES PCS AMP	0.00
ENGINE RPM	2508	INPUT RPM	2841
OVERDRIVE RATIO	0.75	VEH SPEED (MPH)	58
CURRENT GEAR	4TH	PRNDL SW	??????
SOLENOID A	ON	SOLENOID B	ON
RANGE A	CLSD	RANGE B	OPEN
RANGE C	OPEN	POWER ENRICH	NO
1-2 SHIFT (SEC)	0.47	2-3 SHIFT (SEC)	0.41
3-4 SHIFT (SEC)	0.03	A/C REQUEST	NO
A/C CLUTCH	OFF		

Figure 57

**CLUE:** In frame -15 the duty cycle of the TCC solenoid is 98%, TCC slip is 234 RPM.

Input rpm and output rpm have to much of a difference.

Gear ratio is higher than it should be in 4th gear.

In frame -14, code 68 is stored.

**Gear ratio is higher than in the previous frame.**

Pressure control solenoid amps are zero.

**TCC duty cycle is at zero resulting in a higher TCC slip rpm.**

[illegible]

### Automatic Transmission Service Group



## SLIDE

**4L80E MOVIE DIAGNOSIS WITH SNAP-ON SCANNER  
CODE 39...TCC STUCK OFF**

4l80econslpmovie	1991 CHEVROL 7.4L V8 CHEVY TBI						
Frame:	-24	-23	-22	-21	-20	-19	-18
INPUT RPM	2093	2105	2120	2141	2148	2156	2158
OUTPUT RPM	2091	2100	2120	2135	2142	2152	2154
I/O RATIO	109	109	109	111	111	109	109
VEH SPEED (MPH)	45	45	46	46	46	47	47
TURBINE RPM	2097	2105	2125	2140	2147	2156	2158
COOLANT (degF)	210	210	210	210	210	210	210
TCC DUTY CYCLE (%)	98	98	98	98	98	98	98
TRANS FLUID (degF)	198	198	198	198	198	198	198
TORQUE SIG (PSI)	41	41	41	38	42	38	35
GEAR RATIO	109	109	109	111	111	109	109
BRAKE REQUEST	NO	NO	NO	NO	NO	NO	NO
BRAKE SW	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD
TCC SLIP (RPM)	243	258	277	321	556	576	614
TPS (V)	1.78	1.78	1.78	1.62	1.56	1.45	1.33
THROTTLE (%)	33	32	32	30	27	24	20
BATTERY (V)	13.4	13.4	13.4	13.4	13.4	13.4	13.4
PROM ID	2061	2061	2061	2061	2061	2061	2061
PRESS CTRL AMP	0.64	0.55	0.64	0.57	0.64	0.57	0.66
DES PCS AMP	0.63	0.53	0.62	0.60	0.63	0.59	0.63
ENGINE RPM	2345	2329	2330	2357	2318	2324	2318
OVERDRIVE RATIO	109	109	109	111	111	109	109
CURRENT GEAR	3RD	3RD	3RD	3RD	4TH	4TH	4TH
PRNDL SW	3RD	3RD	3RD	3RD	3RD	3RD	3RD
SOLENOID A	OFF	OFF	OFF	OFF	ON	ON	ON
SOLENOID B	ON	ON	ON	ON	ON	ON	ON
RANGE A	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD
RANGE B	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD	CLSD
RANGE C	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN
POWER ENRICH	NO	NO	NO	NO	NO	NO	NO
1-2 SHIFT (SEC)	0.28	0.28	0.28	0.28	0.28	0.28	0.28
2-3 SHIFT (SEC)	0.28	0.28	0.28	0.28	0.28	0.28	0.28
3-4 SHIFT (SEC)	0.03	0.03	0.03	0.03	0.03	0.03	0.03
A/C REQUEST	YES	YES	YES	YES	YES	YES	YES
A/C CLUTCH	ON	ON	ON	ON	ON	ON	ON

Figure 58

CLUES: The movie in figure 58 indicates the PSM and PRNDL switch ranges are in the manual 3rd position.

TCC duty cycle is high, yet the TCC slip rpm is also high. Code 39 is stored.

Third gear ratio should be 1.00. It is not.

The transmission is in manual third, therefore the 4th clutch cannot be slipping which was suspected in the previous code 68 movie in figure 57.

TIP: Beginning in frame -20 the current gear is 4th and the commanded solenoid state is 4th gear, yet the transmission is in D3.  
This is NORMAL. Sensor input is telling the PCM that the transmission SHOULD be in 4th gear, therefore 4th gear is commanded, but the manual valve hydraulically blocks oil from applying the

**THM 4L80-E/4L80-EHD  
NEW DESIGN TURBINE AND OUTPUT  
SHAFT SPEED SENSORS**


There is now available from G.M. Service Parts, a 4th design Turbine and Output Shaft Speed Sensor for the THM 4L80-E/4L80-EHD transmissions, as shown in Figure 59.

The previous OEM part number does not automatically supersede to the current part number. The new design level Speed Sensor is available under OEM part number 24203876, and two per transmission are required for all models except 1994 and later 4WD models.


*Always replace the Turbine and Output Shaft Speed Sensors with the newest design level part.*

**4L80-E TURBINE AND OUTPUT SPEED SENSORS**

**PREVIOUS DESIGN LEVEL  
NO LONGER AVAILABLE**



**NEW DESIGN LEVEL  
PART NO. 24203876**



**SENSOR RESISTANCE SHOULD BE 1260-1540  
OHMS WHEN MEASURED AT 70°F.**

Figure 59



**THM 4L80-E/4L80-EHD**  
**1994 OUTPUT SPEED SENSOR CHANGES**

**CHANGE:** Beginning at the start of production for the 1994 model year, *all 4WD models only* of the THM 4L80-E/4L80-EHD transmissions have revised vehicle speed sensor wiring circuits, and the Output Shaft Speed Sensor in the case has been eliminated, *on 4WD models only*. The speed sensor in the transfer case is now used for both output shaft speed and vehicle speed.

**REASON:** Cost considerations, and improved reliability when the Transfer Case is placed in 4WD LOW.

**PARTS AFFECTED:**

- (1) TRANSMISSION OUTPUT SHAFT SPEED SENSOR - Eliminated *on 4WD models only*, and a plated steel expansion plug was installed in the case bore to retain a common case, as shown in Figure 60. All 4WD models now use the Output Speed Sensor located on the transfer case as the *only* vehicle speed information sent to the speed buffer (See Figure 61).

**NOTE:** The Output Speed Sensor Bore Plug may *fall out*, or fluid may leak past the bore plug. Beginning on January 21, 1994, 4L80-E, 4WD models will have a speed sensor installed in the output speed sensor bore in the transmission case.


***THE SPEED SENSOR IS USED AS A PLUG ONLY.  
IT WILL NOT BE ELECTRICALLY CONNECTED.***

- (2) TRANSFER CASE SWITCH - Previously used to energize the front drive axle thermal actuator, now has an added set of contacts incorporated inside the switch, and an added wire to signal the PCM/TCM when the *4WD LOW* range has been selected (See Figure 61).
- (3) SPEED SENSOR ROTOR - Located on the Output Carrier, has been eliminated on *1994-1996 4WD models only*, as there is no longer any need for it, and is a cost savings. Extra care should be used to ensure that a late Output Carrier *without* the Speed Sensor Rotor, does not inadvertently get installed into a 2WD transmission (See Figure 62).

**SERVICE INFORMATION:**

Transmission Output Shaft Speed Sensor (*New Design*) ..... 24203876

**4WD VEHICLES WITH 4L80-E TRANSMISSION  
1994-1996 MODELS**



**CAUTION:** The Output Speed Sensor Bore Plug may *fall out*, or fluid may leak past the bore plug. Beginning on January 21, 1994, 4L80-E 4WD models will have a speed sensor installed in the output speed sensor bore in the transmission case.

**THE SPEED SENSOR IS USED AS A PLUG ONLY.  
IT WILL NOT BE ELECTRICALLY CONNECTED.**

Figure 60

4WD VEHICLES WITH 4L80-E TRANSMISSION  
1994-1996 MODELS




Figure 61




# Serious Rebuilders KEEP YOUR PROFITS

Comebacks eat up profits and damage your image. Axi-Line's NEW Dynadrome M310-AL with the variable loading device option adds more testing capabilities by simulating a greater range of road driving conditions, and helps prevent costly comebacks.

Your Axi-Line equipment:

- Lowest Initial equipment cost
- Reduces labor — more profit per job
- Needs less floor space
- Provides greater job confidence



## *Dynadrome* **M310AL**

**Transmission Road Test Simulator**

All gears — planetaries, sun, etc.  
Noise — mechanical, hydrosonic.  
Hot and cold testing.  
All AFT pressure patterns — line, boost.  
Shift points.  
Front pump — capacity, flow, pressure.  
Leaks — internal, external.  
Stall speed — forward, reverse.  
TV pressure.  
Auto and manual upshifts, downshifts.  
Vacuum pressure modulator.

### TESTING CAPABILITIES

Toll Free  
**1-800-245-2203**  
Nationwide

- ☐ Solenoid.
- ☐ Converter — lockup, non-lockup types.
- ☐ Output loading and inertia loading.
- ☐ RPM test — left and right outputs.
- ☐ Converter and cooling line temperature.
- ☐ Throttle valve.
- ☐ Flow metering of cooling line.
- ☐ Hydraulic function of the governor, clutch, valve body and overdrive.
- ☐ Kick down.
- ☐ FWD differential matching.

### EQUIPMENT FEATURES

Inertia discs matched to brake horsepower  
Foot operated hydraulic brake  
Fast alignment with precision dowel pins  
Vibration free running  
Line bored bearing mounts  
Full instrumentation  
Engine remains level in FWD and RWD modes  
Frames stress relieved to remain in constant alignment  
Easy to convert from FWD to RWD


**axi**  
**line®**  
Precision Products  
Dynadrome Division

P.O. Box 70, Suamico, WI 54173

### SAFETY FEATURES

- ☐ Inertia discs ultrasonically inspected.
- ☐ Four new disc brakes and calipers per model.
- ☐ Drive shaft safety guards.
- ☐ Microswitch engine shutoffs in turret and guards, to prevent unsafe operation.
- ☐ Torque converter crash belt, prevents loose tools from contacting moving flexplate, converter.
- ☐ Automatic overspeed protection.

**4WD VEHICLES WITH 4L80-E TRANSMISSION  
1994-1996 MODELS**




**CAUTION: TWO WHEEL DRIVE TRANSMISSIONS *MUST*  
HAVE SPEED SENSOR ROTOR INSTALLED.**

Figure 62

## THM 4L80-E/4L80-EHD

NEW PART NUMBER FOR THE  
FORCE MOTOR/PRESSURE CONTROL SOLENOID


### PREVIOUS DESIGN (BOSCH)



G.M. PART NUMBER  
FOR THE BOSCH 8677314

CAN BE USED ON 4HP22  
(CANNOT BE USED ON 4HP24)

### NEW DESIGN (HOLLEY)



G.M. PART NUMBER  
FOR THE HOLLEY 24203101

USE THIS ONE ON  
ALL 4L80-E TRANSMISSIONS

BRACKET REQUIRED WHEN INSTALLING  
HOLLEY TO REPLACE THE BOSCH  
PART NUMBER 8684217

Figure 63

## THM 4L80-E CONVERTER CLUTCH SHUDDER

**COMPLAINT:** Before and/or after rebuild, the vehicle displays a Converter Clutch Shudder condition as the torque converter clutch is applying.

**CAUSE:** The cause may be, an inadequate amount of "Regulated Apply" oil to the converter.

**CORRECTION:** Machine a 45 degree chamfer that is .030" wide, on the TCC Regulator Apply Valve, on the land that is shown in Figure 64. This will allow more line pressure in to the TCC regulated apply circuit. Do not machine any wider than .030".

Compliments of *Ed Lee*  
DELTRANS  
NEWARK, DELAWARE




Figure 64

## THM 4L80-E/4L80-EHD HIGH LINE PRESSURE IN REVERSE

**COMPLAINT:** Before and/or after rebuild, the vehicle has a very high line pressure reading when the selector lever is in the Reverse position, and may repeatedly break direct clutch piston and/or reverse band assembly.

**CAUSE:** The cause may be, a worn boost valve sleeve and/or boost valve in the pump assembly.

**CORRECTION:** Replace the Boost Valve and/or Boost Valve Sleeve, as necessary (See Figure 65). Parts are currently available from G.M. Service Parts, and part numbers are listed below.

**SERVICE INFORMATION:**

Boost Valve Sleeve .....	8682856
Boost Valve, Line Pressure .....	8680549




Figure 65



**THM 4L60-E**  
**TCC "PWM" SOLENOID ADDED IN 1995**  
**AND NEW OIL PUMP ASSEMBLY FOR 1995**

**CHANGE:** Beginning at the start of production for 1995 models, all THM 4L60-E transmissions were built with an added "PWM" solenoid on the valve body to control TCC apply feel. The new TCC PWM Solenoid ramps the torque converter clutch on and off, as in most other GM units.

**REASON:** Improved pleaseability of torque converter clutch apply and release.

**PARTS AFFECTED:**

- (1) VALVE BODY CASTING - 1995 models are now machined to accept the added TCC PWM Solenoid, as shown in Figure 1. The added TCC PWM Solenoid is exactly the same and will interchange with the 3-2 downshift solenoid (See Figure 1).
- (2) VALVE BODY SPACER PLATE - There were two holes added in the spacer plate to accommodate the added TCC PWM Solenoid as shown in Figure 2. The 1995 spacer plate can be identified with the first letter of the two digit code being either an "M" or "N", as shown in Figure 2. The first letter of the two digit code on the 1994 spacer plate will be "K" or "L". The 1993 spacer plate first letter will be "J". Refer to Figure 2 for location of the I.D. code stamped into the spacer plate
- (3) OIL PUMP BODY - There were changes in the worm track configuration on the new design pump body to accommodate the added TCC PWM solenoid. The pump body can be easily identified with "PWM" cast into the pump body, in the location shown in Figure 4. Refer to Figure 3 for the differences in the worm track area, which we have shaded for easy reference.
- (4) OIL PUMP COVER (STATOR) - There were changes in the worm track configuration on the new design pump cover to accommodate the added TCC PWM solenoid. The pump cover can be easily identified with "PWM" cast into the pump cover, in the location shown in Figure 6. Refer to Figure 5 for the differences in the worm track area, which we have shaded for easy reference.
- (5) TURBINE SHAFT BALL CAPSULE - Change in orifice sizes to accommodate the added TCC PWM solenoid, and calibrate converter release oil to the new TCC PWM solenoid.


**INTERCHANGEABILITY:**

*None of the parts listed above will interchange with one another, nor will any of these parts back service any 1993-1994 model transmissions.*

**SERVICE INFORMATION:**

TCC PWM Solenoid (95-96 Models) .....	8683187
Turbine Shaft Ball Capsule (Bronze - 298mm Converter) .....	24201472
Turbine Shaft Ball Capsule (Silver - 245mm Converter) .....	8654326

**1993-1994 VALVE BODY  
WITH 3-2 DOWNSHIFT SOLENOID  
(REQUIRES "NON PWM" PUMP ASSEMBLY)**



**1995 VALVE BODY  
WITH 3-2 DOWNSHIFT SOLENOID  
AND TCC APPLY FEEL SOLENOID  
(REQUIRES "PWM" PUMP ASSEMBLY)**





Figure 1

1995 SPACER PLATE




THESE TWO HOLES ADDED FOR 1995  
MODELS FOR TCC PWM SOLENOID


IDENTIFICATION CODE

Figure 2



**1993-1994 "NON PWM"  
PUMP BODY ASSEMBLY**

SHADED AREAS ARE DIFFERENT  
BETWEEN THE "PWM" AND THE  
NON PWM PUMP BODY

**1995 "PWM"  
PUMP BODY ASSEMBLY**

SHADED AREAS ARE DIFFERENT  
BETWEEN THE "PWM" AND THE  
NON PWM PUMP BODY

Figure 3

**1995 "PWM" PUMP BODY  
IDENTIFICATION**

"PWM" IS CAST INTO  
THE PUMP BODY AND  
LOCATED HERE






Figure 4

**1993-1994 "NON PWM"  
PUMP COVER ASSEMBLY**

SHADED AREAS ARE DIFFERENT  
BETWEEN THE "PWM" PUMP COVER  
AND THE NON PWM PUMP COVER

**1995-1996 "PWM"  
PUMP COVER ASSEMBLY**

SHADED AREAS ARE DIFFERENT  
BETWEEN THE "PWM" PUMP COVER  
AND THE NON PWM PUMP COVER

Figure 5

**JOIN THE**

**HEAVYWEIGHTS**



**leave the guesswork to the other guys**

Can you chance picking up today's mushrooming tech-information 'job to job' by the seat of your pants ? ATSG is the tech service that spends all day every day making sure it has up to the minute information on *foreign and domestic* computers and hydraulic controlled transmissions.

All of this is available to you in bulletins, manuals, videos, hot line service and tech training courses.

It helps to belong to a tech service... but belong to a tech service that helps. Call 1 (800) 245-7722 today and let us tell you why your choice should be ATSG ... or better still, ask about our seminar special.

**That number again for subscriber information is:**

**1 (800) 245-7722**

**AUTOMATIC TRANSMISSION SERVICE GROUP**

9200 S. Dadeland Blvd. • Suite 720 • Miami, FL 33156 • (305) 670-4161

1995-1996 "PWM" PUMP COVER  
IDENTIFICATION

"PWM" CAST INTO THE PUMP  
COVER AND LOCATED HERE




Figure 6



**THM 4L60-E  
CHANGES IN 3-2 DOWNSHIFT VALVE  
AND THE 3-2 DOWNSHIFT SOLENOID**

**CHANGE:** Beginning at the start of production for all 1996 models, the THM 4L60-E transmissions were built with a new design "On-Off" 3-2 downshift solenoid, and a new design 3-2 downshift valve line-up in the valve body.

**REASON:** Improved 3-2 downshift quality and 2-4 band durability.

**PARTS AFFECTED:**

- (1) 3-2 DOWNSHIFT SOLENOID - Changes from a Pulse Width Modulated (PWM) solenoid to a regular "On-Off" (Normally Open) solenoid, which also requires a different Powertrain Control Module (PCM). The new design "On-Off" 3-2 downshift solenoid can be identified by the case diameter, which is smaller than the previous design, and the new design solenoid also has a **plastic** stem that fits into the valve body bore, where the previous design was **metal**. The solenoid connector was also changed to prevent the solenoids from being accidentally installed in the wrong models. Refer to Figure 7 for 1995 models, and Figure 8 for 1996 models.
- (2) 3-2 DOWNSHIFT VALVE - The entire 3-2 downshift valve line-up changes to accommodate the new design "On-Off" 3-2 downshift solenoid. Refer to Figure 7 for 1995 models, and Figure 8 for 1996 models.
- (3) VALVE BODY SPACER PLATE - There were two holes eliminated in the 1996 spacer plate, over the 3-2 downshift valve line-up, to accommodate the new design 3-2 downshift valve. The 1995 spacer plate can be identified with the first letter of the two digit code being either an "M" or "N", as shown in Figure 9. The 1996 spacer plate can be identified with the first letter of the two digit code being a "P", as shown in Figure 10.

**INTERCHANGEABILITY:**

None of the parts listed above will interchange with one another.

***1995 parts must be used on 1995 models.***

***1996 parts must be used on 1996 models.***

**SERVICE INFORMATION:**

3-2 Downshift Solenoid (PWM for 95 Models) ..... 8683187  
3-2 Downshift Solenoid (On-Off for 96 Models) .....24203267




Figure 7

NOTE CONNECTOR  
CHANGES IN 1996

1996 3-2 DOWNSHIFT SOLENOID  
AND 3-2 DOWNSHIFT VALVE LINE-UP





Figure 8



**1995 SPACER PLATE  
USES "PWM" 3-2 DOWNSHIFT SOLENOID**

THESE TWO HOLES ELIMINATED ON THE 1996 MODELS  
THAT USE THE "ON-OFF" 3-2 DOWNSHIFT SOLENOID





Figure 9

**1996 SPACER PLATE  
USES "ON-OFF" 3-2 DOWNSHIFT SOLENOID**

TWO HOLES ELIMINATED  
OVER 3-2 LINE-UP



IDENTIFICATION CODE

Figure 10

**THM 4L60-E**  
**PREMATURE LOW/REVERSE CLUTCH FAILURE**  
**(1993-1995 MODELS ONLY)**

**COMPLAINT:** Premature and/or repeat failure of the Low/Reverse Clutch pack, on 1993-1995 models only, and may occur in as little as 5000 miles.

**CAUSE:** The cause may be, the Low/Reverse Clutch not totally exhausting the apply oil when the shift lever is moved from Park to the Drive position. On 1993-1995 models, the exhaust path for L/R apply oil is not large enough.

**CORRECTION: STEP 1:** Drill a .030" hole through the Low/Reverse Piston, in the tapered area between the outer seal and the center seal, as shown in Figure 11. This will provide an immediate exhaust path for PR apply oil when the selector lever is placed into the Drive position.

**STEP 2:** Remove the **ball only** from the capsule in the reverse passage at the rear of the case worm track area, as shown in Figure 12. Leave the capsule in the case. This will allow a larger volume of oil to the piston to overcome the leak we have created with the exhaust hole we drilled in the piston. This is now a **feed-bleed** system.

**STEP 3:** *If you have a "T" Truck*, which is the small "S" type truck with 4 wheel drive, **remove and discard the brace from transmission bell to the transfer case**, as shown in Figure 13. This will require a shorter bolt at the bell housing.




Figure 11




Figure 12




Figure 13



**THM 4L60-E  
NEW MANUAL VALVE AND  
VALVE BODY CASTING FOR 1996**

**CHANGE:** Beginning at the start of production for all 1996 models, the THM 4L60-E transmissions were built with a new design Manual Valve, and a new design Valve Body Casting. Refer to Figures 14 and 15.

**REASON:** Improved exhaust path for Lo/Reverse clutch oil, when the selector lever is in the Drive position, which greatly improves Lo/Reverse clutch durability.

**PARTS AFFECTED:**

- (1) VALVE BODY CASTING - Added exhaust hole through the valve body casting in the manual valve bore, to exhaust Lo/Reverse clutch oil at a faster rate when the manual valve is in the Drive position. Refer to Figure 14 for 1995 models, and to Figure 15 for 1996 models.
- (2) MANUAL VALVE - Totally different design to accommodate the added exhaust hole in the valve body casting. Refer to Figure 14 for 1995 models, and to Figure 15 for 1996 models.

**INTERCHANGEABILITY:**

None of the parts listed above are interchangeable with one another. The 1996 valve body and manual valve cannot be used on 1995 models because of other changes that occurred in the 3-2 downshift valve line up, and the 3-2 downshift solenoid.

*1995 parts must be used on 1995 models.*

*1996 parts must be used on 1996 models.*

1995 MANUAL VALVE AND VALVE BODY CASTING





Figure 14

1996 MANUAL VALVE AND VALVE BODY CASTING




Figure 15



## THM 4L60-E BOLT-ON BELLHOUSING

**CHANGE:** Beginning at the start of production for 1996 models, some THM 4L60-E transmissions were built with a bolt-on bellhousing. The 4.3L V6 engine is the only one to receive the bolt-on bellhousing for 1996 models, and will be expanded to most other engine sizes for 1997. Refer to Figure 16 for illustrations.

**REASON:** Makes the THM 4L60-E transmission much more versatile, for a wide variety of engine sizes and a wide variety of vehicles.

### PARTS AFFECTED:


- (1) **BELLHOUSING** - Now bolted to the main case with eight bolts that require what appears to be a normal 50 Torx-bit to remove. *These bolts require a "TORX PLUS 50-IP" bit to remove.* The normal 50 Torx-bit will strip the head on most bellhousing bolts, if used for removal. Refer to Figure 16 for the profile of both bits.
- (2) **MAIN CASE** - Totally different casting to accommodate the bolt-on bellhousing, as shown in Figure 16. There were no changes in worm track configuration, or bolt hole locations for the bottom pan and valve body area.
- (3) **EXTENSION HOUSING** - Totally different casting to accommodate the changes in the case design, and notice the new design has six retaining bolts instead of the previous four, as shown in Figure 16.
- (4) **OIL PUMP BODY** - A machined ring has been added to the front of the pump body to accommodate and center the bolt-on bellhousing, as shown in Figure 17.

### INTERCHANGEABILITY:

All of the parts listed above are unique to the 1996 model 2-piece case. However, the pump body with the added machined ring, will be found in some 1995 models, and will back service to 1995 models *only*. It cannot be used in 93-94 models because of worm track cavity differences that occurred in 1995.





1996 BOLT-ON BELLHOUSING




USED IN 4.3L V6 ENGINE ONLY FOR 1996  
EXPANDED TO MORE ENGINES FOR 1997

USE "TORX-PLUS 50-IP" BIT ONLY  
ON BELLHOUSING BOLTS



"TORX PLUS 50-IP"  
OK TO USE



50 TORX BIT  
DO NOT USE





Figure 16

**1995-1996 "PWM" PUMP BODY  
FOR REGULAR CASE**

"PWM" CAST INTO PUMP BODY  
AND LOCATED HERE



**1996 "PWM" PUMP BODY  
FOR BOLT-ON BELL HOUSING**

"PWM" CAST INTO PUMP BODY  
AND LOCATED HERE

ADDED MATERIAL AND MACHINED  
TO CENTER THE BELLHOUSING




Figure 17

**THM 4L60-E**  
**"SKF" SINGLE CAGE**  
**FORWARD SPRAG CHANGE**

**CHANGE:** Beginning in January 1995, all THM 4L60-E transmissions were built with dimensional changes on the Forward Sprag Inner Race and the Overrun Clutch Hub.

**REASON:** Greatly improved durability of the "SKF" Forward Sprag Assembly.

**PARTS AFFECTED:**

- (1) **FORWARD SPRAG INNER RACE** - Dimensional changes on the new design inner race, and it now fully supports the sprag end bearing on the end bearing inside diameter. Compare the previous cutaway illustration in Figure 19, with the current cutaway illustration in Figure 20.
- (2) **OVERRUN CLUTCH HUB** - Dimensional changes on the new design clutch hub, with the elimination of the raised tabs on the teeth. The back side of the clutch hub is now flat. Compare the previous clutch hub illustration in Figure 19, with the current clutch hub illustration in Figure 20.

**INTERCHANGEABILITY:**

The new design parts listed above will not interchange unless both are used as a package, and they are not serviced separately. Complete Forward Sprag Assembly is available as a service package under OEM part number 8657928.

**NOTE:** Do not use the "SKF" single cage aprag, unless the new design inner race and the new design overrun clutch hub are used with it as a package (See Figure 18).




Figure 18

PREVIOUS "SKF" INPUT SPRAG






Figure 19  
Automatic Transmission Service Group

CURRENT "SKF" INPUT SPRAG



OVERRUN  
CLUTCH HUB

FLAT SURFACE  
ON LATE HUB TEETH




Figure 20

## THM 4L60-E PUSH-IN COOLER LINE FITTINGS FOR TRUCK AND VANS

**CHANGE:** Beginning at the start of production for 1996 models, all "C" and "K" Trucks and "G" Vans were built with a new design "Push-In" cooler line fittings for the transmission, as shown in Figure 21.

**REASON:** Ease of installation at the Truck Assembly Plants.

**PARTS AFFECTED:**

VEHICLE COOLER LINES - Modified oil cooler lines to accommodate the new design "Push-In" transmission cooler line fittings.

**NOTE:** General Motors recommends that the retaining "Clip" in the new design cooler line fittings be replaced every time that the cooler line is removed.

**SERVICE INFORMATION:**

Cooler Line Fitting (5/16" Lines) .....	8637742
Cooler Line Fitting (3/8" Lines) .....	8651654
Cooler Line Fitting (Push-In) .....	24205102
Cooler Line Fitting Retaining Clip (Push-In).....	24205103




Figure 21



**THM 4L60-E  
NEW DESIGN OUTPUT SHAFT  
SPEED SENSOR**

**CHANGE:** Beginning at the start of production for 1996 models, some THM 4L60-E transmissions were built with a new design Output Shaft Speed Sensor, as shown in Figure 22. Corvette models will be the only vehicle that will continue to use the previous design speed sensor, as shown in Figure 22.

**REASON:** Ease of assembly and cost savings.



**PARTS AFFECTED:**

- (1) EXTENSION HOUSING - New casting with smaller speed sensor bore diameter, to accept the new design Output Shaft Speed Sensor, as shown in Figure 22.


**SERVICE INFORMATION:**

Output Shaft Speed Sensor (Previous Design) .....	8673299
Output Shaft Speed Sensor (1996 New Design) .....	10456194

1996 SPEED SENSORS



**1996 SPEED SENSOR  
ALL "EXCEPT" CORVETTE  
PART NUMBER 10456194**



**1996 SPEED SENSOR  
CORVETTE ONLY  
PART NUMBER 8673299**

Figure 22



## THM 4L60-E SOFT 1-2 UPSHIFT

**COMPLAINT:** Some 1994 model vehicles, equipped with the THM 4L60-E transmission may exhibit a soft 1-2 upshift condition.

**CAUSE:** The cause may be, calibration of the 1-2 accumulator valve in the valve body.

**CORRECTION:** There is now available a new calibration service package consisting of a 1-2 accumulator valve, valve spring, and 1-2 accumulator valve bushing for the valve body. These are items 370, 371, and 372, as shown in Figure 23 below. This new service package is available under OEM part number 24202698.

### SERVICE INFORMATION:

1-2 Accumulator Valve Service Package ..... 24202698




Figure 23



**THM 4T60-E**  
**ENGINE STALLS IN DRIVE ONLY**  
**DOES NOT STALL IN REVERSE**

**COMPLAINT:** After rebuild, the vehicle will have a good reverse, but when the manual shift lever is placed into the Drive position, the engine will stall immediately.

**CAUSE:** The cause may be, the wires and connector for Shift Solenoid "B" and the TCC Apply Solenoid reversed. This can happen very easily when the wire conduit is removed from the internal wiring harness (See Figure 1). In this configuration, the transaxle will be in 4th gear, with the converter clutch applied when the selector lever is placed into Drive.

**CORRECTION:** Install the solenoid connectors in their proper locations. *Most all* of the 4T60-E transaxles, have the wire colors on the internal wire harness as shown in Figure 1. However, some models are different colors. To positively identify the wire and connector that belongs on the TCC Apply Solenoid, look for the diode in the harness (under shrink-wrap), as shown in Figure 1. The other long wires and connector will go to Shift Solenoid "B" *regardless* of the color of the ground wire, which could be Blue, Green, or Yellow, depending on the model.





Figure 1

*Automatic Transmission Service Group*



**THM 4T60-E**  
**TIE-UP IN PARK AND REVERSE**  
**MOVES FORWARD IN NEUTRAL**  
**TIE-UP ON 2-3 SHIFT**

**COMPLAINT:** After rebuild, the vehicle displays a tie-up condition (In Gear) while the selector lever is in the Park position, a tie-up condition in Reverse, moves forward in Neutral, and a tie-up condition on the 2-3 shift.

**CAUSE:** The cause may be, the rear lube pipe and the apply pipe for the 2-1 manual servo, reversed in the accumulator housing cover (See Figure 2). This will allow lube oil to apply the 2-1 manual servo and the band as soon as the engine is started.

**CORRECTION:** Install the tubes into the accumulator housing cover with the 2-1 manual servo apply pipe in the "Center" hole, as shown in Figure 3, and the rear lube pipe in the right hand hole, as shown in Figure 3. The forward servo apply pipe cannot be installed in the wrong hole as it is a larger diameter than the other two.


**NOTE:**

*Figure 2 shows the "Incorrect" assembly of the pipes.*

*Figure 3 shows the "Correct" assembly of the pipes.*

# HERE IT IS!!!

THE MOST COMPLETE LINE OF  
DOMESTIC AND IMPORT MANUALS  
ATSG TECHNICAL BULLETINS FROM 1986 - '95  
ALL IN THE PALM OF YOUR HAND



Are you tired of looking through piles of technical information for a bulletin or manual and not remembering where you saw it last? The paper chase is over. ATSG now has technical bulletins 1986 - 1995 Most Domestic & Import manuals on CD-ROM. Search for information first by manufacturer then by transmission type, its never been easier!! At the touch of a button you can:

- SEARCH FOR INFORMATION QUICKLY
- SAVE PERSONAL NOTES DIRECTLY ON THE PAGE FOR FUTURE REFERENCE
- PRINT OR FAX SPECIFIC PAGES OR COMPLETE DOCUMENTS

Don't waste any more valuable time searching through piles and piles of paper. Order the ATSG CD-ROM NOW!!!

FOR MORE INFORMATION CALL  
(800) 245-7722

**"INCORRECT" INSTALLATION**

**REAR LUBE PIPE IS IN CENTER HOLE IN ACCUMULATOR COVER**




Figure 2

**"CORRECT" INSTALLATION**

**REAR LUBE PIPE IS IN RIGHT HOLE IN ACCUMULATOR COVER**




Figure 3



**THM 4T60-E**  
**TRANSAXLE CASE SEAL POCKET CHANGE**  
**AND NEW DESIGN 2-1 SERVO SEAL**

**CHANGE:** Beginning on February 20, 1995, approximately half way through the 1995 model year, all THM 4T60-E transaxles were built using a new design 2-1 servo square cut seal, which also required a deeper seal pocket in the transaxle case (See Figure 4). Since this was implemented as a running change about half of the 95 models will require the previous seal and the other half will require the new design seal.

**REASON:** Developed to improve the assembly process.

**PARTS AFFECTED:**

- (1) 2-1 SERVO "SQUARE CUT" SEAL - New design square cut seal was made twice as tall as the previous design seal. The new design square cut seal measures .132" tall, and the previous design measures .066" tall, as shown in Figure 4. The wall thickness and seal diameter did not change. This seal retains drive oil in the forward servo circuit to apply the forward band.
- (2) TRANSAXLE CASE - The seal pocket in the case was machined deeper to accommodate the new design square cut seal. The new design seal pocket measures .112" deep, and the previous design seal pocket measures .054" deep, as shown in Figure 4.

**NOTE:** *The new design square cut seal is not currently included in all gasket packages, but is available seperately under OEM service package part number 24204817, which will get you both design seals.*

**INTERCHANGEABILITY:**

The 2-1 servo square cut seals are not interchangeable.


*Previous design seal must be used in .054" deep case pocket.*

*New design seal must be used in .112" deep case pocket.*


**SERVICE INFORMATION:**

2-1 Servo Square Cut Seal Package (Includes Both Seals) ..... 24204817


**PREVIOUS DESIGN  
1991-PARTIAL 1995**




CASE SEAL POCKET



**NEW DESIGN  
PARTIAL 1995-1996**



CASE SEAL POCKET



**SEAL AND POCKET  
LOCATION IN CASE**




Figure 4





**THM 4T60-E**  
**1-2 ROLLER CLUTCH FAILURE**

**COMPLAINT:** NO. 1: Some 1991-1995 model vehicles equipped with the THM 4T60-E transaxle may exhibit a no movement condition, with the selector lever in the D4 or D3 ranges, but will move when the selector lever is placed into D2 or Lo range.

NO. 2: When the engine RPM is increased with the selector lever in the Park or Neutral position, you may hear a noise that sounds like "Marbles in a Can", but still moves and shifts properly.

**CAUSE:** The cause for both complaints listed above is a 1-2 roller clutch failure.


**CORRECTION:** Replace the 1-2 Roller Clutch Assembly and any related parts that may be damaged or broken (See Figure 5).

Before installing into the transaxle, always replace the OEM 1-2 roller clutch springs with Sonnax part number **K84956-SP**, which contains 16 **stronger** accordian springs and is available from your aftermarket parts supplier (See Figure 5).

*This is recommended as part of every rebuild to increase transaxle durability.*

**WARNING:** ***DO NOT EXCEED 3000 RPM WITH THE SELECTOR LEVER IN REVERSE AND THE WHEELS OFF THE GROUND.***  
***IF YOU DO THIS WITH OEM 1-2 ROLLER CLUTCH SPRINGS, YOU CAN FAIL THE 1-2 ROLLER CLUTCH BEFORE IT EVER LEAVES THE SHOP!***

**1-2 ROLLER CLUTCH ASSEMBLY**



***ALWAYS REPLACE THE 1-2 ROLLER CLUTCH SPRINGS  
WITH SONNAX PART NUMBER K84956-SP***




Figure 5



**THM 4T60-E**  
**NEW DESIGN 1-2 ROLLER CLUTCH**

**CHANGE:** Beginning at the start of production for 1996 models, all THM 4T60-E transaxles were built with a new design 1-2 Roller Clutch Assembly, as shown in Figure 6.

**REASON:** Eliminates a potential high speed freewheel failure and reduces the number of parts needed for the assembly process.

**PARTS AFFECTED:**

- (1) 1-2 ROLLER CLUTCH SUPPORT - Roller clutch cam is now the inside diameter design instead of the previous outside diameter design, and the bushing that supports it on the final drive ring gear has doubled in width for much improved stability of the 1-2 Roller Clutch Support. Refer to Figure 6 for illustrations.
- (2) THRUST BEARING - Dimensional changes to accommodate the new design 1-2 roller clutch support (See Figure 6).
- (3) 1-2 SUPPORT SPACER - Eliminated, as shown in Figure 6.
- (4) 1-2 ROLLER CLUTCH ASSEMBLY - Dimensional changes to accommodate the new inside diameter cam design 1-2 roller clutch parts, as shown in Figure 6.
- (5) 1-2 ROLLER CLUTCH SNAP RING - Eliminated, as shown in Figure 6.
- (6) 1-2 ROLLER CLUTCH INNER RACE - Eliminated, as shown in Figure 6.
- (7) REACTION SUN GEAR DRUM - Redesigned with the 1-2 roller clutch outer race now made as part of the sun gear drum, to accommodate the new design 1-2 roller clutch parts, as shown in Figure 6.
- (8) FINAL DRIVE RING GEAR - Revised lubrication hole sizes and locations in support to accommodate the new design 1-2 roller clutch assembly, as shown in Figure 7.

**INTERCHANGEABILITY:**

The new design 1-2 Roller Clutch Assembly will back service all THM 4T60-E transaxles to 1991, however, *all* parts listed above *must* be used as a package.





Figure 6

**1991-1995 FINAL DRIVE  
RING GEAR SUPPORT**



**1996 FINAL DRIVE  
RING GEAR SUPPORT**




Figure 7



## THM 4T60-E INPUT CLUTCH CHANGES

**CHANGE:** Beginning on August 22, 1994 (Julian Date 234) all 1995 model 4T60-E transaxles were produced with a revised thickness input clutch plates on both lined and steels. This was implemented as a running change and **will** have an affect on service, as the previous design steel plates are no longer available.

**REASON:** Greatly improved durability of the input clutch plates.

### PARTS AFFECTED:

- (1) INPUT CLUTCH LINED PLATES - Were made thinner by approximately .026" to accommodate the thicker steel plates. The new design input clutch lined plates are approximately .065" thick, and the previous design lined plates are approximately .091" thick, as shown in Figure 8.
- (2) INPUT CLUTCH STEEL PLATES - Were made thicker by approximately .020" to improve heat displacement and thereby improve durability. The new design input clutch steel plates are approximately .070" thick, and the previous design steel plates are approximately .050" thick, as shown in Figure 8. The new design input clutch steel plates are now the same as the 3T40 (125C) steel plates.

### INTERCHANGEABILITY:


- (1) The new design input clutch pack, available under OEM part number 24203185, as a service package, **will** back service all 1991-1995 4T60-E transaxles.
- (2) The new design input clutch pack, available under OEM part number 24203185, as a service package, will also back service 4T60 (440-T4) transaxles from late 1990 (Julian Date 016 and later), through 1993 models. These are the transaxles with the input clutch accumulator eliminated and a wave plate added to a new input housing. They **cannot** be used on any 4T60 (440-T4) models previous to the Julian Date listed above.
- (3) Previous and new design clutch plates **cannot** be mixed. Clutch plates must be measured to verify their thickness. Refer to Figure 9 for the previous design, and new design input clutch stack-ups.

### SERVICE INFORMATION:

Service Package, Input Clutch Plates (Lined and Steel - New Design) .....	24203185
Lined Plate, Input Clutch (Previous Design - .091" Thick) .....	8662850
Steel Plate, Input Clutch (Previous Design - .050" Thick) .....	8651446
Lined Plate, Input Clutch (New Design - .065" Thick) .....	24202333
Steel Plate, Input Clutch (New Design - .070" Thick) .....	8683084

# INPUT CLUTCH PLATES

## PREVIOUS DESIGN



## NEW DESIGN




Figure 8




Figure 9





**THM 4T60-E**  
**"TWO" NEW DESIGN DRIVE CHAINS FOR 1995,**  
**AND DIFFERENT MEASUREMENT PROCEDURE**

**CHANGE:** There have been "Two" new design rocker joint drive chains introduced as a running change for 1995 model 4T60-E transaxles, to replace the previous design rocker joint drive chain. The first models to receive the **"Elastically Tuned"** rocker joint drive chain were 5ATW, 5YDW and 5YNW, and these were implemented on October 3, 1994 (Julian Date 276). The remaining models will phase into production by the end of the model year, except Buick Riveria and the Oldsmobile Aurora (5BFW, 5CAW). These two models (5BFW, 5CAW) use a **"Special"** rocker joint drive chain, as shown in Figure 10.

**REASON:** **"Elastically Tuned"** rocker joint drive chain has strength improvements to improve high mileage durability.

**"Special"** rocker joint drive chain is specifically designed to reduce noise in the 1995 Buick Riveria, and Oldsmobile Aurora.

**PARTS AFFECTED:**

- (1) **"ELASTICALLY TUNED"** DRIVE CHAIN - Can be identified by the "Mouse Ears" shape of the outer guide links, as shown in Figure 10, and has one copper colored master link.
- (2) **"SPECIAL"** DRIVE CHAIN - Can be identified by the two copper colored master links, where the previous design rocker joint chain has only one copper colored master link, as shown in Figure 10. The internal links also have a slightly different profile.

**SPECIAL NOTE:** Only use the drive chain measurement procedure listed in the ATSG Service Manual when checking the "Round Pin Drive Chain" for wear. A **"Good"** Rocker Joint Drive Chain may not check as acceptable, using the procedure in the service manual. Use the following procedure to check all Rocker Joint Drive Chains for wear:

1. Pull the drive chain toward the case at the location of arrows, as shown in Figure 11.
2. Measure the gap between the drive chain and case with a straight edge ruler.
3. If the measurement is 1/8" or greater, the drive chain can be reused. If the measurement is less than 1/8", replace the drive chain (See Figure 11).

**INTERCHANGEABILITY:**

The **"Elastically Tuned"** rocker joint drive chain will back service any 1993-1995 4T60-E transaxle that was originally equipped with the previous design rocker joint drive chain, except Riveria and Aurora. The **"Special"** rocker joint drive chain should be used on Riveria and the Aurora models for noise reduction, as the chain is chordal compensating.

On the 1991-1993 4T60-E transaxles equipped with the "Round Pin" design drive chain (See ATSG Bulletin 93-38), the drive and driven sprockets **must** be updated to the rocker joint design to use the "Elastically Tuned" drive chain. Part numbers for the rocker joint design sprockets are included in "Service Information" on the next page.




*1996 SEMINAR INFORMATION*  
*SLIDE*

**74**

**SERVICE INFORMATION:**

Rocker Joint Drive Chain (Previous Design - One Copper Link) .....	8682603
Rocker Joint Drive Chain ("Elasticall Tuned" - "Mouse Ears) .....	24202447
Rocker Joint Drive Chain ("Special" - Two Copper Links) .....	24200771
Drive Sprocket, 33 Tooth (Rocker Joint Design) .....	8682597
Drive Sprocket, 35 Tooth (Rocker Joint Design) .....	8682598
Drive Sprocket, 37 Tooth (Rocker Joint Design) .....	8682599
Driven Sprocket, 33 Tooth (Rocker Joint Design) .....	8682600
Driven Sprocket, 35 Tooth (Rocker Joint Design) .....	8682601
Driven Sprocket, 37 Tooth (Rocker Joint Design) .....	8682602



**PREVIOUS DESIGN  
ROCKER JOINT  
DRIVE CHAIN**




**ONE COPPER COLORED  
MASTER LINK**

**NEW DESIGN  
"ELASTICALLY TUNED"  
ROCKER JOINT  
DRIVE CHAIN**



**ONE COPPER COLORED  
"MOUSE EARS"  
MASTER LINK**

**95 RIVERIA & AURORA  
"SPECIAL"  
ROCKER JOINT  
DRIVE CHAIN**




**TWO COPPER COLORED  
MASTER LINKS**

***ALL THREE OF THESE DRIVE CHAIN DESIGNS USE THE ROCKER JOINT DESIGN DRIVE AND DRIVEN SPROCKETS. ON UNITS ORIGINALLY EQUIPPED WITH THE ROUND PIN DRIVE CHAIN (SEE ATSG BULLETIN 93-38), THE DRIVE AND DRIVEN SPROCKETS MUST BE UPDATED TO THE ROCKER JOINT DESIGN.***

Figure 10

**DRIVE CHAIN MEASUREMENT FOR ALL  
"ROCKER JOINT" DESIGN CHAINS *ONLY*.**



**IF MEASUREMENT IS LESS THAN 1/8", REPLACE THE DRIVE CHAIN**

***NOTE: FOR THE ROUND PIN DRIVE CHAIN MEASUREMENT REFER  
TO THE 4T60-E SERVICE MANUAL, AS THE PROCEDURE IS  
DIFFERENT THAN THE "ROCKER JOINT" DRIVE CHAINS.***

Figure 11

# ANSWERMATIC®


## ANSWERS YOU CAN TAKE TO THE BANK!

### 1-800-322-0806

Losing valuable time and income due to superficially worn hard parts or non-sealing soft parts? Then bank on the original Answermatic® VBT-2000, or our AMI® Hydraulic Circuit Analyzer.

Let Answermatic® answer all your transmission repair questions. Call toll free **1-800-322-0806** or Fax (910) 754-2954 for our free brochure.

- Eliminate no-goes and come-backs.
- Locate small cracks and imperfections in seconds.
- Custom calibrate your transmissions.
- Adapts to electronic transmissions.
- Very affordable, units start at \$3,995.
- Easy-to-learn and easy-to-use.
- Fits virtually all foreign and domestic front and rear wheel cars and trucks.





*Equipment For Rebuilding Profits!*

**Answermatic, Inc.**

225 SMITH AVE., SHALLOTTE, NC 28470  
(910) 754-2944 • FAX (910) 754-2954

Answermatic's AMI Hydraulic Circuit Analyzer uses ATF under pressure to completely test units before, during or after rebuilding.



The Answermatic VBT-2000 can be adapted to test electronic transmissions using any compatible electronic exciter, such as the TRAN-X shown here.

Answermatic®  
Patent #4809544, 4998437  
Other patents pending.



**THM 4T60-E  
NEW DESIGN HEAVY DUTY FINAL DRIVE  
ASSEMBLY, FOR SUPERCHARGED MODELS**

**CHANGE:** Beginning at the start of production for 1996 models, some models of the 4T60-E transaxles were built with a "Heavy Duty" final drive assembly. The models affected will go behind the new 3800 Supercharged (L67) applications.

**REASON:** Torque load requirements because of 3800 supercharged engine.


**PARTS AFFECTED:**

- (1) **FINAL DRIVE ASSEMBLY** - The final drive housing has added material in the cross shaft area, is longer than the previous model, has larger side gears and pinion gears, has a larger diameter cross shaft, and a hardened sleeve added that rides in a new Torrington bearing in the final drive housing. Refer to Figure 12 for comparisons between the previous and new design.
- (2) **FINAL DRIVE HOUSING** - Now a different dimension to accommodate the new design final drive assembly and has an added needle bearing that replaces the previous design bushing, and is shown in Figure 13.
- (3) **OUTPUT SHAFT** - Approximately 1/4" longer to accommodate the thicker and larger side gears. There is also a new bearing added to support the 4th clutch hub (See Figure 14).
- (4) **4TH CLUTCH HUB AND SHAFT** - The previous needle bearing inside the 4th clutch hub has been eliminated, and a hardened sleeve added to the inside diameter to accommodate the new design bearing on the output shaft (See Figure 14).

**INTERCHANGEABILITY:**

*None* of the parts listed above will back service *any* previous model 4T60-E transaxle. All of these parts are unique to the supercharged models.

**CURRENT FINAL DRIVE HOUSING**



**HEAVY DUTY FINAL DRIVE HOUSING  
FOR SUPERCHARGED APPLICATIONS**




Figure 12





Figure 13




**NEW DESIGN 4TH CLUTCH HUB  
AND OUTPUT SHAFT**

PREVIOUS BEARING ELIMINATED  
AND HARDENED SLEEVE ADDED  
TO INSIDE DIAMETER



NEW BEARING



NEW OUTPUT SHAFT  
TO ACCOMMODATE BEARING




Figure 14



**THM 4T80-E  
NEW DESIGN CENTER SUPPORT  
AND CENTER GASKET**

**CHANGE:** Beginning at the Start Of Production for 1995 models, all THM 4T80-E transaxles were produced with a new design level Driven Sprocket Support and center gasket (See Figure 15). This allowed the use of four 2nd clutch plates, instead of the previous three.

**REASON:** Improved 2nd clutch durability.

**PARTS AFFECTED:**

- (1) **DRIVEN SPROCKET SUPPORT** - New design level to accommodate 4 second clutch plates instead of the previous 3 second clutch plates. This required moving the two "Bathtub" feed holes in the Driven Sprocket Support (See Figure 15).
- (2) **SPROCKET SUPPORT GASKET** - The two "Bathtub" feed holes in the gasket were moved to accommodate the new design sprocket support. The slot in the gasket was also removed on the new design gasket (See Figure 15).

**INTERCHANGEABILITY:**

***The Driven Sprocket Support Gaskets "WILL NOT" interchange.*** The 93-94 gasket must be used with the 93-94 sprocket support, and the 95-96 gasket must be used with the 95-96 sprocket support (See Figure 15).

**SERVICE INFORMATION:**


Driven Sprocket Support Gasket (93-94 Model Only) .....	8683149
Driven Sprocket Support Gasket (95-96 Model Only) .....	24201535

**Compliments of, *Joe Smith*  
TRANCOR TRANSMISSION  
CHICAGO, ILL**


**1993-1994  
DESIGN LEVEL PARTS**

SLOT IN  
GASKET

8683149



NOTE POSITION OF BATHTUB  
HOLES IN SUPPORT AND GASKET




"BATHTUB"  
FEED HOLES


**1995-1996  
DESIGN LEVEL PARTS**

NO SLOT IN  
GASKET

24201535



NOTE "NEW" POSITION OF BATHTUB  
HOLES IN SUPPORT AND GASKET



"BATHTUB"  
FEED HOLES

Figure 15



**FORD CD4E**  
**TCC SOLENOID MEASURES HIGH RESISTANCE**  
**REVISED TCC SOLENOID FOR 1995**

**COMPLAINT:** When checking resistance values on the solenoid pack on 1995 CD4E transaxles during rebuild, the TCC Solenoid shows a resistance value well above the specification shown in the service manuals.

**CAUSE:** Some 1995 CD4E transaxles, built after May 1995, were assembled with solenoid bodies that contain a **high impedance** TCC Solenoid, is identified with a Natural/Beige colored case connector, and has a resistance value of 12.5 - 19.0 ohms.  
The previous design solenoid bodies contain a **low impedance** TCC Solenoid, identified with a Black colored case connector, and has a resistance value of 1.0 - 2.0 ohms, as indicated in the service manuals.

**CORRECTION:** 1993-1995 CD4E transaxles may be serviced with a Solenoid Body Assembly containing **either the high impedance or low impedance** TCC Solenoid, with no adverse effects. The TCC Solenoid resistance can be checked across pins 3 and 4 of the transaxle case connector as shown in Figure 1.  
The Natural/Beige colored connector should measure 12.5 - 19.0 ohms resistance.  
The Black colored connector should measure 1.0 - 2.0 ohms resistance.

**CAUTION: DO NOT USE SOLENOID BODY WITH LOW IMPEDANCE (BLACK CONNECTOR) FOR SERVICE ON CD4E TRANSAXLES BEYOND THE 1995 MODEL YEAR.**

**SERVICE INFORMATION:**

Solenoid Body Assembly (High Impedance-Beige Connector) ..... F6RZ-7G391-A

# CD4E CASE CONNECTOR AND SOLENOID PACK ASSEMBLY




Figure 1

## FORD CD4E LUBE TUBE LOCATIONS

The CD4E transaxle provides lubrication for rotating mechanical components through two lubrication tubes, and the lube tube locations are shown in Figure 3.

Lubrication for final drive parts is fed through one of these tubes, which has a seal located in the case which must be replaced during the rebuild process, and requires Tool T91P-76085-A (or equivalent), as shown in Figure 2 below. The Final Drive Lube Tube is fed with oil from the solenoid feed circuit.

The Differential Lube Tube fits directly into the case (press fit) and must be seated fully, and is retained on the other end with a 8mm bolt through the bracket, as shown in Figure 3. The Differential Lube Tube is fed with "To Cooler" oil from the pressure regulator valve, and also lubricates the drive chain (See Figure 3).

**NOTE: USE CARE NOT TO BEND LUBE TUBES DURING THE DISASSEMBLY PROCESS, AND INSTALL BOTH LUBE TUBES INTO CASE BEFORE ASSEMBLING THE TRANSAXLE.**




Figure 2

### CD4E LUBE PIPE IDENTIFICATION AND LOCATIONS






Figure 3

## FORD CD4E DRIVE CHAIN MEASUREMENT

**SQUEEZE CHAIN TOGETHER AND MEASURE DIMENSION "A".  
IF DISTANCE BETWEEN CHAIN TEETH IS 5-1/2" OR LESS,  
THEN REPLACE THE DRIVE CHAIN**



### SERVICE PARTS INFORMATION

Drive Chain (2.0L 4 Cyl - 3/4") .....	F3RZ-7G249-A
Drive Chain (2.5L 6 Cyl - 1") .....	F5RZ-7G249-B
Driven Sprocket (2.0L 4 Cyl - 3.92 F.D.) .....	F3RZ-7G132-A
Driven Sprocket (2.5L 6 Cyl - 3.77 F.D.) .....	F4RZ-7G132-B
Drive Sprocket (2.0L 4 Cyl - .605" Wide) .....	F3RZ-7A153-A
Drive Sprocket (2.5L 6 Cyl - .855" Wide) .....	F3RZ-7A153-B

Figure 4



**FORD CD4E**  
**NO FORWARD ENGAGEMENT**  
**AND/OR NO 3RD GEAR**

**COMPLAINT:** No forward engagement and/or no 3rd gear engagement may be present, before rebuild, on some CD4E transaxles built between Sept 28, 1994 and Oct 30, 1994. The transaxle serial numbers that are of concern are 4271-0000 thru 4303-9999.

**CAUSE:** The cause may be due to a defective weld condition on the Forward/Coast/Direct Clutch Cylinder, which results in fluid leakage from the forward clutch into the direct clutch. The clutch cylinder and hub weld condition may not be identifiable visually.

**CORRECTION:** When extensive wear is observed on the forward clutch plates and/or the direct clutch plates, and the transaxle serial number is 4271-0000 thru 4303-9999, built between the dates listed above, replace the Forward/Coast/Direct Clutch Cylinder Assembly with the appropriate service part number listed below.

**SERVICE INFORMATION:**

Clutch Cylinder and Hub Assembly (4 Cyl) ..... F5RZ-7G120-A  
Clutch Cylinder and Hub Assembly (6 Cyl) ..... F4RZ-7G120-A




Figure 5

## FORD 4R44E/4R55E

### PRELIMINARY INFORMATION AND ELECTRICAL DIAGNOSIS

The Ford 4R44E and 4R55E were introduced by Ford Motor Company in model year 1995, and are basically total electronic controlled A4LD units. Refer to illustration in Figure 6. They are found in Ranger and Explorer vehicles for 1995 model year as standard equipment. The difference in the number designations is identification for different torque carrying capacity, as shown in the chart in Figure 6. Notice also in Figure 6 that the 4R55E transmission is found behind the 4.0L engines, and the 4R44E transmission is found in 2.3L and 3.0L models. The 4R55E version has more clutch plates.

Continued on next Page




Figure 6



## *1996 SEMINAR INFORMATION*

### *VIDEO*

**91**

We have provided you with the clutch and band application chart and the shift solenoid pattern, as shown in Figure 7. This unit has a total of 6 solenoids mounted on the valve body, 3 Shift Solenoids, EPC Solenoid, Coast Clutch Solenoid, and TCC Solenoid. Solenoid locations are identified in Figure 8. Case connector pin functions, and resistance specifications for all internal components, can be found in the charts in Figure 9, and case connector pin locations are identified in Figure 10.

The Turbine Shaft Speed Sensor, which is mounted inside the unit and bolts into the center support, is also unique to this unit. The Turbine Shaft Speed Sensor is triggered by a new "Wheel" pressed onto the overdrive carrier, and the set-up of all of these parts are shown in Figure 11.

### CLUTCH AND BAND APPLICATION CHART

FUNCTION	POSITION	OVERDRIVE BAND	INTERMEDIATE BAND	LOW/REVERSE BAND	FORWARD CLUTCH	DIRECT CLUTCH	COAST CLUTCH	OVERDRIVE ONE-WAY CLUTCH		REAR ONE-WAY CLUTCH	
								DRIVE	COAST	DRIVE	COAST
PARK	P										
REVERSE	R			A		A	A/W	H	OR*		
NEUTRAL	N										
1ST	⊙				A		A/W	H	OR*	H	OR
2ND	⊙		A		A		A/W	H	OR*	OR	OR
3RD	⊙				A	A	A/W	H	OR*	OR	OR
4TH	⊙	A			A	A		OR	OR	OR	OR
MANUAL 2ND	2		A		A		A	H	H		
MANUAL 1ST	1			A	A		A	H	H	H	H
PLANETARY COMPONENT		OS	FS	RP	FR	FS	OS/OP	ODR/OP	ODR	RP	RP

A = APPLIED

H = HOLDING

OR = OVER RUNNING

ODR = OVERDRIVE RING GEAR

OS = OVERDRIVE SUN GEAR

FS = FORWARD SUN GEAR

AW = APPLIED WITH TCIL ON  
OVERDRIVE CANCELLED

RP = REAR PLANETARY ASSEMBLY

FR = FORWARD RING GEAR

OP = OVERDRIVE PLANETARY  
ASSEMBLY

\* = HOLDING WITH OVERDRIVE CANCELLED - TCIL ON

### SOLENOID APPLICATION CHART

GEAR SELECTOR POSITION	POWERTRAIN CONTROL MODULE (PCM) GEAR COMMANDED	SOLENOIDS				
		ENGINE BRAKE	SS1	SS2	SS3	CCS
P	P	NE	On	Off	Off	Off
R	R	No	On	Off	Off	Off
R	R*	Yes	On	Off	Off	On
N	N	NE	On	Off	Off	Off
⊙	1st	No	On	Off	Off	Off
⊙	1st*	Yes	On	Off	Off	On
⊙	2nd	No	On	On	Off	Off
⊙	2nd*	Yes	On	On	Off	On
⊙	3rd	No	Off	Off	Off	Off
⊙	3rd*	Yes	Off	Off	Off	On
⊙	4th	No	Off	Off	On	Off
MAN 2nd	2nd	Yes	On	On	Off	On
MAN 1st	1st	Yes	On	Off	Off	On

NE = No Effect

\* = Overdrive Cancelled - TCIL ON

Figure 7

## 4R44E/4R55E SOLENOID LOCATIONS




Figure 8



1996 SEMINAR INFORMATION  
VIDEO

94

PIN NUMBER	INTERNAL WIRE COLOR	CIRCUIT FUNCTION
1	BLACK	TCC SOLENOID POWER IN
2	RED	TSS SIGNAL
3	WHITE	TSS SIGNAL RETURN
4	RED	TFT SENSOR SIGNAL
5	PURPLE	TCC SOLENOID GROUND
6		NOT USED
7	YELLOW	SHIFT SOLENOID 3 GROUND
8	RED	TFT SENSOR SIGNAL RETURN
9	ORANGE	COAST CLUTCH SOLENOID GRND
10	WHITE	SHIFT SOLENOID POWER - 12V IN
11	GREEN	EPC SOLENOID POWER IN
12	BLUE	EPC SOLENOID PWM GRND
13		NOT USED
14	BROWN	SHIFT SOLENOID 2 GROUND
15		NOT USED
16	GRAY	SHIFT SOLENOID 1 GROUND



SOLENOID	OHMS	PIN NUMBERS
SHIFT SOLENOID ONE	22 -48	10 AND 16
SHIFT SOLENOID TWO	22 -48	10 AND 14
SHIFT SOLENOID THREE	22 -48	10 AND 7
COAST CLUTCH SOLENOID	22 -48	10 AND 9
EPC SOLENOID	3.1 - 5.7	11 AND 12
CONVERTER CLUTCH SOLENOID	8.9 - 16.0	1 AND 5
TURBINE SHAFT SPEED SENSOR	64 - 120	4 AND 8
TRANS FLUID TEMP SENSOR	SEE CHART	2 AND 3

°C	°F	OHMS RESISTANCE
0-20	32-68	100k-37k
21-40	69-104	37k-16k
41-70	105-158	16k-5k
71-90	159-194	5k-2.7k
91-109	195-230	2.7k-1.5k
110-130	231-166	1.5k-0.8k
131-150	267-302	0.8k-0.5k

Figure 9

Automatic Transmission Service Group

# CASE CONNECTOR PIN IDENTIFICATION



REFER TO CHART IN FIGURE 9  
FOR CONNECTOR PIN FUNCTION  
AND RESISTANCE READINGS




Figure 10

**TURBINE SHAFT SPEED SENSOR**




Figure 11



**FORD 4R44E/4R55E**  
**SLIPPING AND/OR NO 1-2, 2-3, 3-4 SHIFT**  
**AND POSSIBLE FLASHING "OD OFF" LAMP**

**COMPLAINT:** Some 1995 Ranger and Explorer vehicles equipped with the 4R44E/4R55E transmission may exhibit a slipping condition on upshifts and/or possibly a no upshift condition. If the "OD OFF" lamp is flashing, Diagnostic Trouble Codes (DTCs) 645, 646, 647, 648, P0731, P0732, P0733, P0734 may be stored in the PCM memory. These symptoms are more prevalent on transmissions built before June 20, 1995.

**CAUSE:** The cause may be, a damaged intermediate and/or overdrive servo piston seal, and may be damaged on the release (Case Bore) side.

**CORRECTION:** Replace the intermediate and/or overdrive servo pistons as necessary (See Figure 12).




Figure 12



## FORD AX4N

### PRELIMINARY INFORMATION AND DIFFERENCES WITH AX4S (AXODE)

#### EXTERNAL DIFFERENCES:

The AX4N transaxle was introduced by Ford Motor Company in model year 1994, and has been expanded into more models for 1995. The AX4N is found in *some* Taurus and Sable vehicles, and *all* 1995 Lincoln Continentals. The AX4N transaxle is a completely different unit than the AX4S/AXODE, but could be easily mistaken for an AX4S/AXODE at a quick glance. Refer to Figure 13, and you will notice that there is no servo cover on the AX4N, and "AX4N" is stamped into the side cover.

#### SOLENOID LOCATIONS:

The Shift Solenoids, EPC Solenoid, and TCC Solenoid are in different locations between these two units, as shown in Figure 14.

We have provided you with both of the internal wiring schematics to identify case connector pin cavities and internal wiring colors, as shown in Figure 15. Notice also in Figure 15, that the case connectors and wire colors are the same for 93-96 AX4S/AXODE and the AX4N transaxles. This may present problems in the future, *as these transaxles will not interchange.*

Notice in Figure 16 that *the solenoid shift patterns are different between AX4S/AXODE and AX4N*, even though the resistance values and the OEM part numbers are the same.

#### OIL TUBE LOCATIONS:

The difference in oil tube locations, located in the bottom pan, are shown in Figure 17, and we have shown both the early and the late "Cross-Over" tube locations on the AX4S/AXODE version.

#### OIL FILTER DIFFERENCES:

The bottom pan oil filters are also different between these two units, as shown in Figure 18. Complicating things even further, the AX4N transaxle has two different types of oil filters, two different depth bottom pans, and *some models* require a "Baffle", as shown in Figure 18.


#### INTERNAL DIFFERENCES:

Internally there is an added Low Intermediate Roller Clutch, an added Low Intermediate Clutch Pack Assembly, and an added Overrun Band that goes around the rear sun gear drum to provide engine braking in low and second are just a few of the internal changes. There are many others. Refer to Figure 19 for the new roller clutch changes.

#### SERVICE INFORMATION:

EPC Solenoid, 91-UP, All Models, AX4S/AXODE and AX4N .....	F4DZ-7H144-A
Lock-up Solenoid, 1991 Taurus/Sable Only .....	F1DZ-7G136-A
Lock-up Solenoid, 91-93 Continental (Before 5-15-93) .....	F1OY-7G136-A
Lock-up Solenoid, 1993 Continental (After 5-15-93) .....	F3DZ-7G136-A
Lock-up Solenoid, 92-93 All Models (Before 5-15-93) .....	F1OY-7G136-A
Lock-up Solenoid, 93-95 All Models (After 5-15-93), AX4S/AXODE and AX4N .....	F3DZ-7G136-A
Shift Control Solenoid (3 Req'd), All Models, AX4S/AXODE and AX4N .....	F1DZ-7G484-A
Turbine Shaft Speed Sensor, All Models, AX4S/AXODE and AX4N .....	F1DZ-7M101-A

**AXOD-E (AX4S) TRANSAXLE**



**AX4N TRANSAXLE**






Figure 13

# Tired of AXOD Planetary Failure?

Introducing The AXOD Dam, the simple solution to AXOD lube problems.


The AXOD Dam was developed to help eliminate planetary failure in the AXOD and AXOD-E transmissions. This simple, yet effective, product allows AXOD planetaries to run cooler and last much, much longer.

When properly installed, the Lube Dam floods the section between the reverse cylinder and the rear planet support, where the front and rear planetary assemblies are located. By flooding this section lube oil has adequate time for heat exchange from the pinions to the lube oil. The pinions and needle bearings run in an oil bath, ensuring total lubrication. Since the amount of lubrication is increased dramatically, better cooling is assured.



*The AXOD Dam virtually eliminates planetary failure.*

## Try Our SUPERIOR Shift Correction Packages



### Available For:

**700-R4, 440-T4, 200-4R, 400, 350, 200, 125, E40D, A4LD, AXOD, 722.3-4, AOD, & C-6.**

**High Performance Kits Also Available For:  
200-4R HP, AOD HP, 350 HP, & 700-R4 HP.**


**Ask Your Distributor  
Or Call:  
800-451-3115**

*Make the shift to...*



**SUPERIOR**  
TRANSMISSION PARTS, INC.  
THE SIMPLE SOLUTION

### AXOD-E (AX4S) TRANSAXLE



### AX4N TRANSAXLE






Figure 14

### 91-92 AXODE (AX4S) ONLY



#### 91-92 CASE CONNECTOR ON THE "TOP" OF THE TRANSAXLE

1. EPC POWER (WHITE)
2. TOT (YELLOW)
3. TOT (BLUE)
4. LUS/MLUS POWER (RED)
5. LUS/MLUS GROUND (BLACK)
6. EPC GROUND (GREEN)



#### 91-92 CASE CONNECTOR ON THE "SIDE" OF THE TRANSAXLE

1. SS2 POWER (RED)
2. SS2 GROUND (BLUE)
3. SS3 GROUND (BLACK)
4. SS3 POWER (YELLOW)
5. SS1 POWER (WHITE)
6. SS1 GROUND (YELLOW)

### 93-96 AX4S AND ALL AX4N

1. EPC GROUND (BLUE)
2. EPC/MCCC POWER (GREEN)
3. SS3 GROUND (YELLOW)
4. MCCC GROUND (BROWN)
5. SHIFT SOLENOID POWER (RED)
6. SS1 GROUND (ORANGE)
7. TFT (BLACK)
8. SS2 GROUND (PINK)
9. TOT RETURN (WHITE)




Figure 15

**SHIFT SOLENOID PATTERN**

<b>AX4S/AXODE ONLY</b>				
GEAR SELECTOR	PCM GEAR COMMANDED	SHIFT SOLENOIDS		
		SS1	SS2	SS3
P/N	P/N	OFF	ON	OFF
REV	REV	OFF	ON	OFF
OD	1ST	OFF	ON	OFF
OD	2ND	ON	ON	OFF
OD	3RD	OFF	OFF	ON
OD	4TH	ON	OFF	ON

**SHIFT SOLENOID PATTERN**


<b>AX4N ONLY</b>				
GEAR SELECTOR	PCM GEAR COMMANDED	SHIFT SOLENOIDS		
		SS1	SS2	SS3
P/N	P/N	OFF	OFF	OFF
REV	REV	OFF	OFF	OFF
OD	1ST	OFF	ON	OFF
OD	2ND	OFF	OFF	OFF
OD	3RD	ON	OFF	ON
OD	4TH	ON	ON	ON

**SHIFT SOLENOID RESISTANCE CHART  
AND TFT SENSOR RESISTANCE CHART  
FOR BOTH AX4S AND AX4N**

SOLENOID	SOLENOID RESISTANCE (OHMS)	°C	°F	TFT SENSOR (OHMS)
SS1	15 - 25	0-20	32-58	100k - 37k
SS2	15 - 25	21-40	59-104	37k - 16k
SS3	15 - 25	41-70	105-158	16k - 5k
LUS	21 - 36	71-90	159-194	5k - 2.7k
MLUS	.98 - 1.6	91-110	195-230	2.7k - 1.5k
EPC	3.23 - 5.50	111-130	231-266	1.5k - 0.8k
TSS	100 - 200	131-150	267-302	0.8k - 0.5k

Figure 16

### AXOD-E (AX4S) TUBE LOCATIONS



### AX4N TRANSAXLE TUBE LOCATIONS






Figure 17



**AXOD-E (AX4S) FILTER**



**AX4N FILTER**



**FILTER BAFFLE FOUND ON SOME MODELS**





Figure 18

# Another First ...



## Transmission Manuals Now On CD Rom

### DOMESTIC TRANSMISSIONS

General Motors, Ford, Chrysler,  
Pass Books, Updates and Transfer Cases


### IMPORT TRANSMISSIONS

Toyota, Honda, Nissan, Mercedes,  
BMW, Mitsubishi, Mazda and more

### ATSG TECH BULLETINS

1986 - 1995 on CD Rom


Call Our Toll Free Number for Prices and Information



**1-800-245-7722**

**9200 S. DADELAND BLVD.  
SUITE 720 • MIAMI, FL 33156**

# LOW INTERMEDIATE ROLLER CLUTCH AND LOW INTERMEDIATE CLUTCH PACK ASSEMBLY



1. REAR SUN GEAR ASSEMBLY
2. LOW INTERMEDIATE CLUTCH SNAP RING (SELECTIVE)
3. LOW INTERMEDIATE PRESSURE PLATE
4. LOW INTERMEDIATE STEEL CLUTCH PLATES
5. LOW INTERMEDIATE CLUTCH WAVE PLATE
6. LOW INTERMEDIATE ROLLER CLUTCH ASSEMBLY
7. LOW INTERMEDIATE ROLLER CLUTCH OUTER RACE
8. REAR PLANET SUPPORT BEVELED SNAP RING (SELECTIVE)
9. NUMBER 15 SUN GEAR THRUST BEARING
10. RETAINING SNAP RING
11. NUMBER 15 THRUST WASHER
12. LOW INTERMEDIATE CLUTCH RETURN SPRING ASSEMBLY
13. LOW INTERMEDIATE CLUTCH PISTON AND SEAL ASSEMBLY
14. REAR PLANETARY SUPPORT ASSEMBLY
15. NUMBER 16 THRUST WASHER
16. LUBE OIL TRANSFER TUBE SEALS (2 REQUIRED)
17. LOW INTERMEDIATE CLUTCH LINED PLATES

Figure 19

## FORD MASS AIR FLOW SENSOR DIAGNOSIS

The Mass Air Flow (MAF) sensor is located in between the air cleaner and the throttle body. (See **Figure 20**) The MAF sensor uses a heated wire as a sensing element to measure the amount of air that is entering the engine. The air that passes over the heated wire causes the wire to cool. The MAF sensor then outputs a DC analog voltage signal to the PCM, which uses that signal to determine the amount of air that is entering the engine. The PCM will calculate the fuel injector pulse width in order to provide the proper air/fuel ratio. The MAF sensor signals are also used for electronically controlled transmissions and transaxles in determining EPC pressure control, shift and TCC strategies. For the purpose of transmission and transaxle diagnosis, symptoms of MAF sensor malfunction or failure could include high or low EPC pressure, improper shift scheduling, incorrect TCC scheduling. These symptoms will feel similar to a throttle position sensor malfunction. Testing the MAF will require the use of a Digital Volt-Ohm Meter, set to D.C. volts. Connect the leads to the sensor harness wires at terminals **C** and **D** (See **Figure 21**). With the engine running at an idle, the voltage should read in between .60 - 1.2 volts. This idle reading voltage will vary due to engine and ambient outside temperature. Refer to the chart (See **Figure 22**) below for sensor data.




Figure 20




Figure 21

MAF SIGNAL VOLTAGE	
IDLE.....	.6-1.3 VOLTS
20 MPH.....	1.1 VOLTS
40 MPH.....	1.7 VOLTS
60 MPH.....	2.1 VOLTS

MAF signal voltage is typical for engines at normal operating temperature. Voltage signal may vary due to engine load and temperature.

Figure 22

**FORD E40D****DELAYED FORWARD ENGAGEMENT AND/OR BURNT FORWARD CLUTCH  
AFTER INSTALLING FORD CENTER SUPPORT SERVICE KIT F4TZ-7A130-B**

**COMPLAINT:** Delayed forward engagement and/or prematurely burnt forward clutch plates may be evident on vehicles which have had the new Ford Ball Bearing Center Support Kit, OEM part number F4TZ-7A130-B.

**CAUSE:** The cause may be, forward clutch oil leaking between the steel hub and the aluminum support ring because of mis-machining of the aluminum support ring in the area where the steel hub bolts to it.

**CORRECTION:** Install a new Center Support Service Kit, F4TZ-7A130-B, that has yellow paint on the wide leg of the center support as shown in Figure 1, and a yellow dot on the shipping carton as shown in Figure 1. There was no part number change and Ford has since recalled and reboxed the defective part.




Figure 1



**FORD E4OD  
NEW DESIGN CENTER SUPPORT  
SERVICE KIT WITH BALL BEARING**

**CHANGE:** There is now available, from Ford Motor Co, a new design center support service kit with a ball bearing in the support. The new design service package is available under OEM part number F4TZ-7A130-B, and will back service all past model 89-94 E4OD transmissions only. The parts in this service kit are different dimensions than 1995 model year production parts. Refer to Figure 2 for service package kit contents.

**REASON:** Greatly increases transmission durability.

**PARTS AFFECTED:**

- (1) **CENTER SUPPORT** - Different machining dimensions on the inside bore, to accommodate an added ball bearing that will now support the overdrive center shaft. The new design ball bearing can be identified as a "Service Part", by the letter "S" stamped on the hub, in the location shown in Figure 3. The Service Kit Ball Bearing Center Support has different dimensions than the 1995 production ball bearing center support. Refer to Dimension "A" on the cutaway drawing in Figure 3.
- (2) **OVERDRIVE CENTER SHAFT** - Different machining dimensions on the center shaft to accommodate the added ball bearing, and the pilot on the center shaft has been removed. The new design Overdrive Center Shaft can be identified as a "Service Part", by the letter "S" stamped on the shaft in one of two locations, as shown in Figure 4. The Service Kit Overdrive Center Shaft has different dimensions than 1995 model year production center shaft. Refer to Dimensions "A" and "B" on the cutaway drawing in Figure 4.  
The Overdrive Center Shaft in this service kit is bored to accept either the long or short overdrive planetary carrier assembly and input shaft, and is reflected in Dimension "A", as shown in Figure 4.  
**Special Note:** There is also an updated Overdrive Carrier and Input Shaft, available under OEM part number F4TZ-7B446-B, to help improve durability. Both pieces have different dimensions than the previous parts, as shown in Figure 7. The new overdrive carrier hub is 12mm (.472") shorter than the previous models, and the internal splines now run the full length of the hub which makes it stronger. The Input Shaft is also 12mm (.472") shorter than the previous models, to accommodate the new overdrive carrier, and has I.D. groove cut in shaft for identification (See Figure 7).
- (3) **OUTPUT SHAFT** - Small bushing **must** be removed and the orifice cup plug included in the service kit **must** be installed, to accommodate the removal of the pilot from the overdrive center shaft. This will now ensure that lube oil is directed to the proper areas. Refer to Figure 5 for the bushing removal and orifice cup plug installation.  
The orifice cup plug in this service kit is different dimensions than the 1995 production models, and will fit **only** an output shaft that previously had the bushing.

**Continued on next Page.**



**PARTS AFFECTED: (Continued)**

- (4) NO. 5 NEEDLE BEARING - Make certain the No. 5 Needle Bearing included in service kit is installed with the service kit parts **regardless** of whether your unit had one or did not have one. Some 1994 model year transmissions were built with some or all of the parts that "Resemble" the parts in this service kit, and may or may not have a No. 5 needle bearing. Make certain that the No. 5 needle bearing from the service kit is installed. Refer to Figure 6 for proper installation of the needle bearing.

**INTERCHANGEABILITY:**

- (1) This Service Kit will service all past model E4OD transmissions 1989 thru 1994 model years, when used in it's entirety, and is highly recommended on **all** previous model E4OD units.
- (2) The parts in this Service Kit are different dimensions than 1995 model year production parts and **will not** interchange with 1995 model parts (See Figures 3 and 4).
- (3) Some 1994 model year transmissions were built with some or all of the parts that "Resemble" the parts in this service kit. When servicing these units, use all of the parts in the kit **except**, the orifice cup plug. These units already have a cup plug in the output shaft and it is a different diameter. The Service Kit orifice cup plug will fit **only** an output shaft that previously had a bushing (See Figure 5).
- (4) The Overdrive Carrier Assembly and Input Shaft are matching components and **must** be serviced as a package.

**DO NOT MIX LONG AND SHORT COMPONENTS.**

Refer to Figure 8 to ensure that you have built the unit with matching components. The Input Shaft must extend 1-1/2" past the end of the oil pump stator, if you used the correct input shaft and overdrive carrier. Refer to Figure 8 for proper assembly dimensions.

**SERVICE INFORMATION:**

Ball Bearing Center Support Service Kit (Yellow Dot) ..... F4TZ-7A130-B  
Overdrive Carrier/Input Shaft Service Kit ..... F4TZ-7B446-B

### F4TZ-7A130-B SERVICE KIT CONTENTS




Figure 2



### BALL BEARING CENTER SUPPORT




Figure 3

## OVERDRIVE CENTER SHAFT

### DIMENSION "A"

SERVICE KIT PART = 1.938"

1995 PRODUCTION = 1.710"

### DIMENSION "B"

SERVICE KIT PART = 2.368"

1995 PRODUCTION = 2.592"






Figure 4

### OUTPUT SHAFT AND ORIFICE CUP PLUG



REMOVE THE  
ORIGINAL BUSHING



INSTALL THE ORIFICE CUP  
PLUG FROM SERVICE KIT

THE ORIFICE CUP PLUG MUST BE  
INSTALLED BELOW THIS SURFACE

ORIFICE CUP PLUG

OUTPUT SHAFT

**NOTE: THE ORIFICE CUP PLUG IN THIS SERVICE KIT IS DIFFERENT  
DIMENSIONS THAN 1995 PRODUCTION MODELS, AND WILL  
FIT ONLY AN OUTPUT SHAFT WITH A BUSHING.**

Figure 5

**NUMBER 5 NEEDLE BEARING  
PROPER INSTALLATION**





Figure 6

OVERDRIVE CARRIER AND INPUT SHAFT




NEW DESIGN


PREVIOUS DESIGN

CARRIER  
HUB FULLY  
SPLINED

SPLINES



NEW DESIGN



PREVIOUS DESIGN

PREVIOUS DESIGN SHAFT



NEW DESIGN SHAFT

12mm  
SHORTER




I.D. GROOVE FOR 12mm  
SHORTER INPUT SHAFT

Figure 7


## OVERDRIVE CARRIER AND INPUT SHAFT USAGE

**"INCORRECT"**




PREVIOUS (LONG) INPUT SHAFT USED  
WITH NEW DESIGN OVERDRIVE CARRIER

**"INCORRECT"**



NEW DESIGN (SHORT) INPUT SHAFT USED  
WITH PREVIOUS DESIGN OVERDRIVE CARRIER

**"CORRECT USAGE"**



THE INPUT SHAFT MUST EXTEND 1.5" PAST THE END OF THE PUMP STATOR  
IF THE CORRECT INPUT SHAFT AND OVERDRIVE CARRIER WERE USED.

Figure 8



**FORD E4OD  
NEW DESIGN CAST IRON  
OVERDRIVE CARRIER**

**CHANGE:** There is now available from Ford Motor Company, a new design Overdrive Planetary Carrier that is made out of cast iron and available under part number F5TZ-7B446-A.

**REASON:** Greatly increased durability of the Overdrive Carrier.

**PARTS AFFECTED:**


- (1) OVERDRIVE PLANETARY CARRIER - New design is made out of cast iron and is the shorter design that requires the new design input shaft (See Figure 9).
- (2) INPUT SHAFT - Now 12mm shorter than the previous design shaft to accommodate the new design overdrive planetary carrier, and is required with the new carrier.

**INTERCHANGEABILITY:**


The new design cast iron Overdrive Planetary Carrier will back service all models to 1989, but the new design Input Shaft is required to be used with it (See Figure 9).

**SERVICE INFORMATION:**

Overdrive Planetary Carrier (Cast Iron) .....	F5TZ-7B446-A
Input Shaft (Short with I.D. Groove) .....	F4TZ-7017-D

**NEW DESIGN CAST IRON OVERDRIVE CARRIER**

**PREVIOUS DESIGN ALUMINUM  
OVERDRIVE CARRIER**



**NEW DESIGN CAST IRON  
OVERDRIVE CARRIER  
F5TZ-7B446-A**

**THE NEW DESIGN CAST IRON OVERDRIVE CARRIER IS THE SHORTER  
VERSION OF THE PREVIOUS CARRIERS, AND *MUST* BE USED WITH THE  
SHORT INPUT SHAFT WITH I.D. GROOVE, AS SHOWN BELOW.**

**CAST IRON OVERDRIVE CARRIER CAN BE  
USED ONLY WITH THE SHORT INPUT SHAFT**



**I.D. GROOVE TO IDENTIFY THE  
12mm SHORTER INPUT SHAFT  
F4TZ-7017-D**

Figure 9