



# Technical Service Information

## TOYOTA 241-H NO 3-4 UPSHIFT

**COMPLAINT:** 1990-92 Toyota Corolla, equipped with **241-H All Wheel Drive** transmissions, may exhibit a no 3-4 upshift after overhaul.

**CAUSE:** The cause may be, that during overhaul 240-L No.1 and No.2 valve body gaskets were used in place of the 241-H No.1 and No.2 valve body gaskets. The reason is that the two different gaskets sets have small subtle differences, as shown in Figures 1 and 2, and the 241-H gaskets **do not** come in current overhaul kits.


**CORRECTION:** Install the correct No.1 and No.2 valve body gaskets as per the Service Information listed below. Additional part numbers are provided in Service Information for the Transfer case gasket and seal kit and the left axle seal which are not provided in current overhaul kits.

### SERVICE INFORMATION:

Transfer Case gasket and seal kit (Toyota part number).....	35172-12020
Left axle seal (Toyota part number).....	35172-1220
Valve body gasket No.1 (Toyota part number).....	35433-12040
Valve body gasket No.2 (Toyota part number).....	35434-12020


Copyright © 1998 ATSG

**240 L-No. 1 GASKET**



**240 H-No. 1 GASKET**


**TOYOTA PART**  
**No. 35433-12040**




Copyright © 1998 ATSG

Figure 1

**240 L-No. 2 GASKET**



**240 H-No. 2 GASKET**



Copyright © 1998 ATSG