

## NISSAN RL4FO3A

### HARSH 1-2 UPSHIFT

**COMPLAINT:** Vehicles equipped with RL4FO3A transaxles may exhibit a harsh 1-2 upshift at all throttle openings.

**CAUSE:** The cause may be, the 1-2 accumulator spring is broken.

**CORRECTION:** Remove the 1-2 accumulator plunger and spring, shown in Figure 1, and replace the broken spring with NISSAN part no. 31742-31X63.

#### SERVICE INFORMATION:

1-2 ACCUMULATOR SPRING (NISSAN PART NO.).....31742-31X63




Figure 1