

# DMMGeneral PC User Manual

Ver 2.0 / 2020-03-29 by ZDD

Applicable host computer version:2020-01-20and later versions

## 1. Main interface of the host computer:


If the DMM is not connected via MeterCare's GPIB, only use **direct connection**.



If you use the serial port to connect directly, you need to set the serial port parameters in the options interface.



The settings of the option interface will be introduced in detail later.



The calibration function is currently only available for 34401A and 34420A. If the calibration command of the compatible machine is exactly the same as that of 34401A, It should be possible. In this case, please select "34401A" to connect and calibrate. If you select another model, all calibration-related operations on this interface will be automatically ignored. Calibration information and the number of calibrations should be visible for the 344xx series.




## 2. Connection:

### Temperature sensor settings:

Depending on whether there is a temperature sensor or not, the "Options" Select OK. New version MeterCare If so, you can choose 0, 1, or 2. Other temperature sensor equipment should be selected according to actual conditions. One host computer instance only supports one temperature sensor device (one communication port) and two temperature channels.

Fill in the correct Temperature read command and prefix length. Data returned such as temperature The format is: TMP:+23.0, then the prefix is TMP: Please fill in the length 4. is valid data (here is +23.0) the words before number of symbols, please note +-number is valid, no Negative numbers will also be displayed as positive numbers.



温度传感器设置

☐ 无或不需要温度 ☐ DMM自带温度 ☐ 其它测温设备

☐ 1个温度传感器 温度1命令: CARE\_TEMP? 前缀长度: 0

☒ 2个温度传感器 温度2命令: CARE\_TEMP1? 前缀长度: 0

If DMM Comes with temperature sensor, you can choose "DMM Comes with temperature". pass MeterCare If connected, you can freely combine the temperature by reading the temperature command1 and temperature2. Such as temperature 1 set to DMM Comes with temperature (34461A if SYST:TEMP?), temperature 2 set to MeterCare a certain temperature (CARE\_TEMP1?).

If it is not connected through Taoka DMM, DMM The built-in temperature can only be the temperature1.

"MeterCare or temperature sensor port" Please select the actual temperature sensor device used. serial number and baud rate, in terms of network IP address and port.



选择仪器连接方式

DMM 选择: 34401A 刷新型号

☐ 通过 MeterCare ☒ 直接连接

MeterCare 或温度传感器端口 ☒

☒ 串口 COM6 115200

☐ 网络 192.168.1.2 5025

DMM 端口 COM16 接口类型

Here's a reminder: MeterCare Anything that can be connected can be connected here DMM or other sensor devices. It can be temperature or something else. For example, a voltage or a current, then the temperature The degree characteristic curve is V curve.

### DMM connection method:

#### 1. Direct connection

No MeterCare, you can only choose "direct connection". As shown on the right, select DMM in the drop-down box of the instrument port. associated port. Some DMMs may have several ports. Try to connect and select the one that can be used normally.

If it is not a serial port, such as USB, LAN, and other GPIB adapter cards, you may need to install the IVI driver to see the corresponding VISA standard port in the port drop-down box.



选择仪器连接方式

☐ 通过 MeterCare ☒ 直接连接

MeterCare 端口 ☒

☐ 串口 COM20 115200

☒ 网络 192.168.1.23 5025

34401A 端口 TCPIP0::K-

COM1 串口资源名称.

LPT1

TCPIP0::K-34470A-25218.local::5025::SOCKET

TCPIP0::K-34470A-25218.local::hislip0::INST.

TCPIP0::K-34470A-25218.local::inst0::INSTR


启动波形 刷新

If you connect through the serial port, you also need to set it in the options. **Serial port parameters**, as shown on the right.


表串口参数设置

波特率	9600
数据位	8
停止位	1
校验位	None
流控	None

If it is passed 82357,E5810For direct connection, please install Keysight's IO Libraris Suite. Then check the options shown in the picture below in the settings. Connect the DMM through the GPIB card and turn it on. Then select the GPIB port number corresponding to the DMM in the DMM port drop-down box.




E5810If so, if you can find the device on the web page, you need to set it up as shown below to find the port address in the port drop-down box of the host computer.



NI GPIBCard needs to be installedNI-488.2Driver (domestic cards only support17.0or previous version),CONTEC GPIBCard needs to be installedGPLV (GPIB Labviewversion) runtime library and driver (andNIIncompatible, will be replacedsystem32\GPIB-32.dll, the original file was renamedGPIB-32.1, if usingNIand compatibleGPIBCard, needGPIB-32.1Change backGPIB-32.dll).

## 2. Connect via MeterCare

"MeterCare Port" Don't make the wrong choice. Serial port or network, be sure to choose according to your own MeterCare.



"GPIB address" Select the actual GPIB address of your DMM.



3. Model selection:

If the DMM's remote command supports gear setting command, you can select "Support gear setting". Otherwise select "Can only collect".

choose"Other models", if you need to enter first For remote mode, please add it in the initialization command. Such as skewers port connection, if SYST: REM is required, enter CARE\_NULL:SYST:REM. If the screen off command of some DMM is DISP OFF, enter CARE\_NULL: DISP OFF. Note that it is not connected through Taoka, so there is no need for the CARE\_NULL: prefix. There is no need to enter remote mode in advance when connecting via GPIB. Please refer to the DMM manual for details.

choose"Can only collect"hour,Function gear,NPLC,Measuring rangePlease make the correct selection according to the current actual settings of the DMM, otherwise the host computer will display abnormally.

read commandandData prefix lengthPlease refer to the DMM manual. For example, DMM returns data: "DCV9.99999", then the prefix length is3.

**Notice:**If no data is received after connecting, please check whether the end character of the returned data in the table is "line feed (LF,0x0A)" or "Enter and line feed (CR LF:0x0D 0x0A)". You can use the serial port assistant to view it (hexadecimal display). If not, please refer to the manual of the table and change it to "Newline (LF,0x0A)" or "Enter and line feed (CR LF:0x0D 0x0A)".  
**KEITHLEY**The table seems to be0x0DEnd, it is recommended to set it to0x0AFinish.

4. MeterCare timeout, collection time, and host computer timeout settings:

"MeterCare timeout" is the maximum time to wait for DMM to return data after sending the DMM query command. If the DMM return data is not received after this time, MeterCare will generate a timeout error. Therefore, this timeout value must be greater than the maximum conversion time of DMM. For example, DMM is in AZ When ON + 100PLC, the conversion time is about 4s, so it is appropriate to set the timeout to 5s.

"Collection time" is the time interval for collecting data. This value is valid only if it is greater than the actual conversion time of DMM. Otherwise, the actual conversion time of DMM shall prevail.

"Host computer timeout"Similar to above"MeterCare timeout", just the host computer, etc. Maximum time to wait for MeterCare or DMM to return data. If the return data is not received after this time, a timeout error will occur. So this timeout value must be greater than or equal to "MeterCare timeout" value.

It is recommended that the timeout value be larger, because when the timeout value is close to the response time of the DMM, a timeout may occur more easily due to certain uncertain factors.

支持档位设定

只能采集

功能档位 :

量程 :

NPLC :

DCV

10

10

如果DMM不支持档位和量程等参数查询的,请在配置文件里设置好读取命令。上面选择 [只能采集]。

MeterCare 超时设定

Care超时10000ms

采集时间设定

采集时间1000ms


上位机超时设定

上位机超时10000ms

上位机超时值 > Care超时值 > 表的 最大响应时间。

## 5. Waveform export and import


In the waveform window, right-click to export the waveform data to an Excel file. If you want to import waveforms in the future to be closer to the original waveform resolution, you can increase the number of data digits by one before exporting (right of the main panel) Lower corner "digits" ).



Note: When using the export and import function, the time format below the waveform must have seconds, and the date format must have /. You can refer to the figure on the right to set the data format of the system date and time.

When importing, click the "Import" button in the lower corner of the waveform and select just the Excel file you want to import.

If you want to continue collecting data after previously collected data, you can When opening the host computer, first import the previous data in the waveform interface, then establish the connection and continue collecting.





6. Measurement mode and temperature compensation:

1. Normal mode (no compensation)

It is a direct measurement, and all data does not undergo any temperature compensation processing.

表温度补偿参数

一次温漂 -0.0150 PPM/°C

二次温漂 0.0025 PPM/°C<sup>2</sup>

参考温度 40.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

源温度补偿参数

一次温漂 -0.1080 PPM/°C

二次温漂 0.0272 PPM/°C<sup>2</sup>

标定温度 23.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

选择测量模式

☒ 普通模式（无补偿）

☐ 普通模式（带补偿）

☐ 自身温漂测试模式

☐ 温漂补偿效果检验

2. Normal mode (with compensation)

It means to perform temperature compensation on the measured data according to the temperature drift coefficient of the meter and the actual temperature data of the meter. Note that if the temperature coefficient of the table is quadratic, then the temperature drift coefficient of the first term must correspond to the reference temperature. That is to say, the first-term temperature drift coefficient of the quadratic temperature drift curve is different at different temperatures.

The temperature drift of the watch must be measured in advance. You can follow the following "Self temperature drift test mode" To measure.

表温度补偿参数

一次温漂 -0.0150 PPM/°C

二次温漂 0.0025 PPM/°C<sup>2</sup>

参考温度 40.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

源温度补偿参数

一次温漂 -0.1080 PPM/°C

二次温漂 0.0272 PPM/°C<sup>2</sup>

标定温度 23.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

选择测量模式

☐ 普通模式（无补偿）

☒ 普通模式（带补偿）

☐ 自身温漂测试模式

☐ 温漂补偿效果检验

3. Self-temperature drift test mode

It's the temperature drift of the meter. Be sure to choose 2 temperature sensors. It is necessary to use the temperature transmission corresponding to temperature 2

It is best to fix the temperature of the sensor meter somewhere inside the meter. Otherwise, if the position changes, the temperature coefficient will be different and compensation will not be possible.

The temperature compensation of the source is turned on, and the temperature sensor corresponding to temperature 1 measures the temperature of the source. If the temperature drift of the source can be ignored during the measurement process (for example, the temperature change is very small or the temperature drift itself is very small), the primary and secondary temperature drift coefficients of the source with 0. at this time and

Normal mode (no compensation) it's the same.

If there is only one temperature sensor, use the same read command for both temperature 1 and temperature 2, and only measure the temperature of the meter. Fill in the primary and secondary temperature drift coefficients of the source with 0, or use Normal mode (no compensation) Come test.

Under normal circumstances, the temperature drift of the meter can be measured by cold starting the machine, and the temperature drift of the meter can be measured from cold starting to stable.10For temperature rises above °C, some previous data can be removed during fitting.

表温度补偿参数

一次温漂 -0.0150 PPM/°C

二次温漂 0.0025 PPM/°C<sup>2</sup>

参考温度 40.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

源温度补偿参数

一次温漂 -0.1080 PPM/°C

二次温漂 0.0272 PPM/°C<sup>2</sup>

标定温度 23.00 °C

线性补偿时，将二次温漂设为0即可。注意温漂单位是PPM。

NaN

选择测量模式

☐ 普通模式（无补偿）

☐ 普通模式（带补偿）

☒ 自身温漂测试模式

☐ 温漂补偿效果检验



#### 4. Temperature drift compensation effect inspection


Be sure to choose 2 temperature sensors. Temperature 1 is the measurement source, Temperature 2 is the temperature of the meter. If table and source

If the temperature drift coefficients are correct, the compensated curve should be a horizontal straight line with a temperature drift coefficient close to 0.00. If you do not know the temperature drift of the source, you can fill it all with 0. At this time, the temperature drift of the compensated curve with respect to temperature 1 is the temperature drift of the source.

If there is only one temperature sensor, use the same read command for both temperature 1 and temperature 2, and only measure the temperature of the meter. Fill in the primary and secondary temperature drift coefficients of the source with 0, or use **Normal mode (with compensation)** Come test. If the temperature drift coefficient in the table is correct, you can judge whether the source has temperature drift based on the compensated curve.

表温度补偿参数	源温度补偿参数	选择测量模式
一次温漂: -0.0150 PPM/°C	一次温漂: -0.1080 PPM/°C	<input type="radio"/> 普通模式 (无补偿)
二次温漂: 0.0025 PPM/°C <sup>2</sup>	二次温漂: 0.0272 PPM/°C <sup>2</sup>	<input type="radio"/> 普通模式 (带补偿)
参考温度: 40.00 °C	标定温度: 23.00 °C	<input type="radio"/> 自身温漂测试模式
线性补偿时, 将二次温漂设为0即可。注意温漂单位是PPM。	线性补偿时, 将二次温漂设为0即可。注意温漂单位是PPM。	<input checked="" type="radio"/> 温漂补偿效果检验
NaN	NaN	



The following is the temperature compensation effect of 34401A + LM399. **green** is the internal temperature of the watch, **blue** is the actual measured data before compensation, **pink** This is the curve after temperature compensation has been performed on the meter, and the source has not been compensated. It can be seen that the temperature in the meter changes by 4.6°C before compensation. The measurement results The change is 14uV, and after compensation it only changes about 4uV (from the waveform point of view, it can basically be regarded as noise, and the temperature drift compensation effect is very good).



The picture below is 34461A cold start and temperature compensation curves. **green** is the internal (near reference) temperature of the watch,

**yellow** is the actual value before compensation

measurement data, **pink** is the curve after temperature compensation is performed on the table, **red** is the temperature of the source, and the source is not compensated.



7. Real-time waveform:

Supports arbitrary interval waveform display, customizable upper and lower limits of the vertical axis, elimination of abnormal data, deletion of data within the selected range, smoothing filtering, DMM temperature compensation, fitting temperature selection, relative position adjustment of main measurement data and temperature data, etc. Find out for yourself.

