

# MPLAB® XC8 C Compiler

## Version 1.31 Release Notes

Produced on Monday, 17 March 2014

**THIS FILE CONTAINS IMPORTANT INFORMATION RELATING TO THIS COMPILER.  
PLEASE READ IT BEFORE RUNNING THIS SOFTWARE.**

Overview	2
Introduction	2
Previous Versions	2
System Requirements	2
Devices Supported	2
Editions and License Upgrades	2
Installation and Activation	3
Compiler Documentation	3
Customer Support	3
Documentation Updates	4
User's Guide Clarifications and Corrections	4
What's New	6
Version 1.31	6
Version 1.30	6
Version 1.21	7
Migration Issues	12
Version 1.31	12
Version 1.30	12
Version 1.21	12
Fixed Issues	16
Version 1.31	16
Version 1.30	20
Version 1.21	24
Known Issues	38
Microchip Errata	43

# 1. Overview

## 1.1. Introduction

This is a minor bug-fix update to the Microchip MPLAB® XC8 C compiler. This version fixes a number of reported bug fixes.

## 1.2. Previous Versions

The previous MPLAB XC8 C compiler version was 1.30, released January 2014.

## 1.3. System Requirements

The MPLAB XC C compilers and the licensing software they utilize are available for a variety of operating systems, including Microsoft Windows XP Professional SP3/Vista SP1/Windows 7 Professional; Ubuntu 9.10; or Mac OS X 10.5. The compiler may also run on the various other Linux distributions, such as Oracle Enterprise Linux 5, Ubuntu 8.x and 10.04, Red Hat Enterprise Linux.

If you are running a license server, only computers with operating systems supported by the compilers may be used to host the license server. The license server does not need to run on a server version of the operating system. And specifically, Microsoft Windows Server platforms are *not* supported by the compiler.

## 1.4. Devices Supported

This compiler supports all known 8-bit PIC devices at the time of release. See [pic\\_chipinfo.html](#) (in the compiler's `doc` directory) for a list of all supported baseline and mid-range devices and [pic18\\_chipinfo.html](#) for a list of all supported PIC18 devices. These files also list configuration bit settings for each device.

## 1.5. Editions and License Upgrades

The MPLAB XC8 compiler can be activated in several different operating modes: Free, Standard and PRO. The Standard and PRO modes are licensed modes and require purchase of a key for activation. These two modes offer two levels of improved optimization features compared to the Free mode. A compiler operating in Free mode can be operated indefinitely without a license. You can change to any operating mode (license permitting) from the MPLAB X IDE project properties (or MPLAB IDE v8 Build Options) on a build-by-build basis.

The compiler can be evaluated in any licensed mode for 60 days free of charge. After the evaluation period has expired, the compiler reverts to the Free mode and the trial optimization features are disabled.

You can choose the default operating mode or choose to evaluate the compiler during the installation and activation process.

## 1.6. Installation and Activation

*See also the Migration Issues and Limitations sections for important information about the latest license manager included with this compiler.*

If using MPLAB IDE, be sure to install MPLAB IDE v8.10 (or later) or MPLAB X 1.2 (or later) before installing these tools. Quit the IDE before installing the compiler. Run the `.exe` (Windows), `.run` (Linux) or `.app` (OS X) compiler installer application, e.g.

`XC8-1.00.11403-windows.exe` and follow the directions on the screen. The default installation directory is recommended. If you are using Linux, you must install the compiler using a terminal and from a root account. Install using a Mac OS X account with administrator privileges.

The option "Update MPLAB IDE to use XC8 for existing C18 projects", if set, will change your MPLAB IDE settings so that all existing legacy projects designated to use either MPLAB C18 or MPLAB C Compiler for PIC18 MCUs, will, by default, use this MPLAB XC8 compiler in C18 compatibility mode. To revert this change if you select it here, you will need to manually adjust the toolsuite settings for legacy projects that should continue to use the MPLAB C18 or MPLAB C Compiler for PIC18 MCUs compilers. This option has no effect if you do not have legacy projects.

Activation is now carried out separately to installation. See the document License Manager for MPLAB® XC C Compilers (DS52059) for more information.

The XC License Manager now supports roaming of floating network licenses. Aimed at mobile users, this feature allows a floating license to go off network for a short period of time. Using this feature, you can disconnect from the network and still use your MPLAB XC compiler. See the doc folder of the XCLM install for more on this feature.

MPLAB X IDE v1.40 includes a Licenses window (Tools > Licenses) to visually manage roaming.

## 1.7. Compiler Documentation

The compiler's user's guide covers all aspects of the compiler's operation, as well as other useful information. Check the well-populated index for your search term. A How-to chapter gives answers to common questions relating to the compiler and writing programs.

## 1.8. Customer Support

Common problems are explained in the [FAQ list](#). You can also ask questions of other users of this product in the [XC8 Forum](#).

Microchip welcomes bug reports, suggestions or comments regarding this compiler version. Please direct any bug reports or feature requests via the [Support System](#).

At times, advisory message 1395 may be issued by the compiler. This message is part of a new testing process. The compiler will display this message if it encounters a specific code sequence that results in internal compiler templates being used in a unique way. This message does not imply a bug in the generated code; however, the code sequence encountered could be used to fur-

ther improve the compiler's performance. If you wish to participate by contributing the code that generated this message, you are welcome to send the project to [Support](#); otherwise, you may ignore this message.

## 2. Documentation Updates

A new document is now bundled with the compiler distribution. It is called *MPLAB® XC8 Getting Started Guide* and it is specifically designed for customers just starting out with MPLAB XC8 and Microchip PIC devices. It can be found with all other documentation in the compiler's `docs` directory.

The names of some of the documentation files included with the compiler have changed from those used with previous versions of the compiler. The titles and locations of these documents remain the same.

### 2.1. User's Guide Clarifications and Corrections

The following sections provide additional information to that found in the user's guide shipped with the compiler.

#### 2.1.1. Configuration Bits

The information contained in the user's guide relating to the specification of configuration bits using the `config` pragma (Section: *5.3.5 Configuration Bit Access*) does not indicate that the value specified with the pragma when programming an entire configuration register must not be a binary constant. So, for example, the following code is invalid and might result in the wrong value being programmed:

```
#pragma config CONFIG1L = 0b10001111    // incorrect
```

#### 2.1.2. Predefined Macros

In *Section 5.14.3 Predefined Macros*, the macro `__EXTMEM` is missing. This is defined to be the size of external memory for those PIC18 devices that implement an external memory interface.

#### 2.1.3. Stack Size

In *Section 5.5.2.2.2 Software Stack Operation*, the maximum size of the stack for PIC18 devices is incorrect. It should be 127, not 256.

#### 2.1.4. Error and Warning Messages

The following message is not present in the compiler's user's guide.

##### 1470 trigraph sequence "??\*" replaced ignored (Preprocessor)

The preprocessor has replaced a trigraph sequences in the source code. Was this your intension?

```
char label[] = "What??!"; // you do know that's a trigraph
                        // sequence, right?
```



## 3. What's New

The following are new features the compiler now supports. The version number in the subheadings indicates the first compiler version to support the features that follow.

### 3.1. Version 1.31

**New device support** The following parts are now fully supported by this release: 16LF1554, 16LF1559, 16F1615, 16F1619, 16LF1615 and 16LF1619.

**New speed-enhanced C libraries** The standard C libraries now come in space and speed variants, and the corresponding library filenames include 'sp' or 'sz' strings, respectively, in their name to differentiate them. Space-optimized libraries are used by default, unless the `--OPT=+speed` option (or MPLAB X IDE project properties equivalent) is used. Multiplication and some string routines have been optimized for speed.

**Optimization macros** Dependent on the state of the selected optimization (`--OPT` option), the macros `__OPTIMIZE_SPEED__` and `__OPTIMIZE_SIZE__` are now defined by the compiler driver to indicate optimization for speed or space (size), respectively.

### 3.2. Version 1.30

**Software stack** The compiler can now allocate stack-based (auto and parameter) variables to a software stack (dynamic allocation to a memory area accessed via a stack pointer register) in addition to the compiled stack (static memory allocation). The compiled stack was used exclusively in prior compiler versions and is still the stack used by the default function model. Allocation to the software stack allows for function reentrancy but is less efficient. Function specifiers (`reentrant/software`) or the `--STACK` option can be used to control the stack used for the whole program or for individual functions, if required.

**Function profiling support** The compiler can now generate function registration code that can be used by a MPLAB REALICE debugger to provide function profiling. *To see function profiling results, you must use a version of the MPLAB X IDE that supports MPLAB XC8 code profiling.* When function profiling is enabled, the compiler inserts assembly code into the prolog and epilog of each C function that is defined. This code communicates runtime information to the REAL ICE debugger to signal when a function is being entered and when it exits. This information, along with further measurements made by the Power Monitor Board, can provide a record of the energy being used by each function.

**Better Dwarves** The compiler now uses the DWARF 3.0 Debugging Format Standard in ELF files. Provided you are using a compatible version of MPLAB X IDE and generating an ELF output, this will provide more accurate debugging information in some situations.

**New device support** The following parts (and their corresponding LF variants) are now fully supported by this release: 16F1613 12F1612, 16F1717, 16F1718, 16F1719, 16LF1718, 16F18323, 16F18313, 16F18345, and 16F18325.

**Software Breakpoints** Two new builtins have been added to allow the insertion of opcodes that can trigger software breakpoints. These are `__BUILTIN_SOFTWARE_BREAKPOINT()` (un-

conditional for all builds) and `__debug_break()` (debug builds only). These macros are only available for PIC18 and mid-range devices and are ignored for baseline devices.

**Better detection of function parameter mismatch (XC8-776)** A warning is now issued for calls to a function which is passed arguments, but whose corresponding function definition (as opposed to declaration) has an empty parameter list. The warning is issued for direct and indirect calls.

**Memory range addresses (XC8-339)** A leading `0x` may now be used with any value in a memory range associated with the `--ROM` or `--RAM` option (or IDE equivalent). Note that values that do not use this prefix are still assumed to be in hex format.

**External memory preprocessor symbol (XC8-836)** The preprocessor symbol `__EXTMEM` will be set to the size of the external memory implemented by the target device for those PIC18 devices that provide an external memory interface.

**New assembly operator form (XC8-42)** The use of the `BANKMASK` preprocessor macro in assembly macros (`MACRO..ENDM`) was not permitted as the assembler would see the `&` operator in its expansion as the assembly macro concatenation operator, not bitwise AND. The assembler now allows the use of `and` as well as `&` for bitwise AND operations. The `BANKMASK` preprocessor macro in assembly header files has been updated to use this new operator and so may now also be used in assembly macros.

**Warning on possible write to read-only object (XC8-67)** The compiler may now warn if using a pointer to write values and that pointer has targets that are qualified `const`. This warning may still be accompanied by other error messages. Writing values to `const`-qualified objects has undefined behavior.

**Optimizations (XC886, XC8-79)** The compiler now optimizes some code better, in particular interrupt code. Code which uses 24-bit floating point addition (`ftadd` routine) is now much smaller and faster.

### 3.3. Version 1.21

**New device support** The following parts (and their corresponding LF variants) are now fully supported by this release: PIC16F1713, PIC16F1716, PIC16F1703, PIC16F1707, PIC12F1572, PIC12F1571, PIC16F1705, and PIC16F1709.

**New Installer Features** The Installer application has new options for setting up a network client and displaying the Licensing Information page.

### 3.4. Version 1.20

**New device support** The following parts are now fully supported by this release: PIC16F1704, PIC16LF1704, PIC16F1708, and PIC16LF1708.

**ELF/DWARF debugging** Previously, COFF debug files were produced to allow source-level debugging in MPLAB IDE. The compiler can now produce ELF/DWARF files, although the default output format is still COFF. ELF/DWARF files are not compatible with MPLAB IDE v8 but will be the preferred format if you are using MPLAB X IDE as they

have fewer limitations. You must be using a version of MPLAB X IDE that supports this file format for the MPLAB XC8 compiler. Not all aspects of DWARF are implemented in this compiler release. See the [Known Issues section](#) for more details.

**New Free mode optimizations** The assembler's jump-to-jump optimizations, which previously was only available with a licensed compiler operating mode, is now available in Free mode. By default, this optimization is disabled, but it can be enabled from the `--OPT` option or the Optimization category in MPLAB X IDE in the usual way. If enabled, this optimization reduced the size of code output by the compiler.

**New language extension option** A new driver option `--EXT` can be set to `cci`, `iar` or `xc8` to indicate that the C language extensions accepted by the compiler are those belonging to the Common C Interface, IAR compatibility mode, or the native XC8 syntax, respectively. All of these extensions are discussed in the user's guide.

**Expanded hardware multiply usage** The PIC18 hardware multiply instructions are now used for 16x16 bit integer multiplication. The library routine that implements this feature breaks the multiplication into several operations that can use the 8-bit hardware multiply instruction. The 32-bit integer multiplication routines continue to use an iterative solution and do not use these instructions.

**New listing option** Previously a C list file was produced for each C source file being compiled. If an assembly list file was request (which is the default in MPLAB IDE) then these listing files were overwritten with the assembly listing content. The C listing files are no longer produced by default. If you would like C listing files to be generated, a new option `--CLIST` has been added to request this action.

### 3.5. Version 1.12

**New device support** The following parts are now fully supported by this release: MCP19114, MCP19115, PIC16LF1824T39A, PIC16F570, PIC16F753 and PIC16HV753.

### 3.6. Version 1.11

**New device support** The following parts are now fully supported by this release: PIC16F1788, PIC16F1789, PIC16LF1788 and PIC16LF1789.

**New peripheral libraries** The following devices (and their LF counterparts) now have peripheral library support: PIC18F45K50, PIC18F24K50 and PIC18F25K50. The peripheral libraries for all supported devices have been updated to the latest code base.

**New parsing option** A new driver option has been added that alters the generation of intermediate files produced by the parser. The option is `--PARSER` and can be set to `lean` or `rich`. The `lean` suboption (the default) will not include unused symbols in intermediate files. These are included when selecting the `rich` suboption, but not that this setting will generate larger intermediate (p-code) files and will slow down the compilation considerably. The operation of prior versions of the compiler was equivalent to the `rich` setting. Use the `rich` setting if you need unused symbols to be included in the link stage.



**New enhanced mid-range errata workaround** The compiler now has the ability to employ an errata workaround for some enhanced mid-range devices. This is controlled by the `--ERRATA` option (`CLOCKSW`), which is used to control other PIC18 errata workarounds. The workaround will affect the device startup code, but is not enabled by default. Check your device literature to see if this workaround should be enabled.

### 3.7. Version 1.10

**New device support** The following parts are now fully supported by this release: MCP19110, MCP19111, RF675F, RF675H, RF675K, PIC12F529T39A, PIC12F529T48A, PIC12LF1840T39A, PIC12LF1552, PIC16F527, PIC16F1454, PIC16LF1454, PIC16F1455, PIC16LF1455, PIC16F1459, PIC16LF1459, PIC16F1784, PIC16LF1784, PIC16F1786, PIC16LF1786, PIC16F1787, PIC16LF1787, PIC18F45K50, PIC18F24K50, PIC18F25K50, PIC18LF45K50, PIC18LF24K50, PIC18LF25K50, PIC18F97J94, PIC18F87J94, PIC18F67J94, PIC18F96J94, PIC18F86J94, PIC18F66J94, PIC18F95J94, PIC18F65J94, PIC18F85J94, PIC18F96J99, PIC18F86J99, PIC18F66J99.

**The Common C Interface (CCI)** The Common C Interface is a documented set of ANSI standard refinements, non-standard extensions and guidelines to help you write code which is more portable across all MPLAB XC C compilers. A new chapter has been added to the XC8 User's Guide describing these features.

**User's guide** A new compiler user's guide has been included with this release. See the Documentation Updates section, above, for more information.

**Roam-out Licensing** A new “roam out” feature allows a network license to be checked out for an extended period for use on a particular computer. While the license is checked out, the computer has licensed use to an XC compiler, and need not be in contact with the network license server. When the license is returned to the network license server, it is once more available to be used as a floating license, or to be roamed out to other computers.

**Psect allocation** The CCI `__section()` specifier can also be used in non-CCI mode. Refer to the CCI chapter in the user's guide. It can be used in place of the `#pragma psect` directive.

**Function and module information** Information about each function, which appears in the assembly list file, is now also displayed in the map file. In addition, a summary of program memory usage on a module-by-module basis is shown in the map file. This allows an estimate of the size of the code (excluding data) being generated by each module.

**Bank specification with PIC18 devices** The qualifiers `bank0` through `bank3` may now be used with PIC18 devices to allocate variables to a specific memory bank. These qualifiers must be used with the `--ADDRQUAL` option.

**Implementation of `strftime` function** The `strftime()` function has been implemented and is available in the standard libraries.

**Qualifier synonyms** A side effect of the CCI features is that when *not* in CCI or strict ANSI mode, most of the non-standard specifiers, e.g. `bit`, `near` and `far`, can also be represented with two leading underscores, as in `__bit`, `__near` and `__far` etc.

**SFR structure types** The structures that are defined to represent SFRs are now a typedef type that is available for general use.

**Function in-lining** A new qualifier, `inline`, can be applied to some C functions. A call to any function, thus qualified, will not generate a call-return sequence, but will be replaced by the assembly code associated with the function body. This expansion will save stack usage and may reduce code size if the function body is small. The assembler has always had the ability to inline small assembly sequences, so code size reductions may not be large. The operation of this qualifier is similar to use of the *new* `#pragma inline` directive. The previous (version 1.00 and earlier) `inline` pragma implementation has been renamed to `intrinsic`. (See Migration Issues below.)

**Assembly psect flags** To support function inlining, two new psect flags have been added: `inline` and `keep`. These indicate to the assembler, respectively, that the contents of a psect may be inlined (and then removed), and that the contents of a psect may be inlined but must never be removed.

### 3.8. Version 1.01

**Enhanced PIC optimizations** New optimizations, specifically aimed at the enhanced mid-range PIC devices, have been added. These optimizations reduce code size and target any code that indirectly accesses locations via the FSR registers.

### 3.9. Version 1.00

**Psect merging and splitting** Two new PSECT directive flags have been added to allow splitting or merging of psects by the assembler optimizer. Now, by default, no splitting or merging takes place, but the use of the `split=allow` and `merge=allow` flags can indicate that these optimizations can take place. See the assembly language chapter in the user's guide.

**Unified 8-bit device support** This compiler unifies the two former HI-TECH C compilers which previously supported Microchip 8-bit PIC devices: HI-TECH C Compiler for PIC10/12/16 MCUs and HI-TECH C Compiler for PIC18 MCUs. This MPLAB XC8 compiler supports compilation for any supported 8-bit PIC device from the one application. A single device driver, `xc8`, is used to invoke the compiler regardless of the target device. This driver will invoke the appropriate internal applications based on your device selection. The `picc` and `picc18` drivers which controlled the former compilers are currently still employed, and the baseline/mid-range and PIC18 code generator and assembler applications are still separate. Only one copy of the generic applications, such as the preprocessor (`cpp`), the parser (`p1`), the linker (`hlink`), and utilities like `hexmate`, `objtohex` and `cromwell` are included with the compiler, and these are shared by all device targets.

**Operating modes** The former HI-TECH C Compiler for PIC18 MCUs only operated in a Lite or PRO mode. With XC8, a Free (previously called Lite), Standard and PRO mode are available for all target devices.

## 4. Migration Issues

The following are features that are now handled differently by the compiler. These changes may require modification to your source code if porting code to this compiler version. The version number in the subheadings indicates the first compiler version to support the changes that follow.

### 4.1. Version 1.31

None

### 4.2. Version 1.30

**Psect names (XC8-865)** The names of psects used to hold absolute `const` objects have changed from `xxxx_text` to `xxxx_const`, where `xxxx` is the name of the object being defined.

**Parameter passing (XC8-914)** For PIC18 devices the first byte-sized argument to a function was not passed in WREG in Free or Standard modes. (It was passed in WREG in PRO modes.) This has been changed so that WREG is used regardless of the operating mode. Note that in the new software stack, argument passing is performed in a different way.

**New warning level (XC8-151)** The warning level of message 368, `array dimension on "*" ignored` has been reduced from 0 to -1.

**New library source file locations (XC8-939)** Note that the location of some of the library source files have changed since the previous release. Library source files that are specified to a target device family are located in either the `pic` or `pic18` subdirectory in the `sources` directory of the compiler. Source files that are identical across all device families are located in the `common` subdirectory.

### 4.3. Version 1.21

None

## 5. Version 1.20

**-G option disable** The option that controlled generation of symbol files has been disabled. This option was always selected in MPLAB IDE and there was never a need to disable this feature. Symbol files are now always produced. You can continue to specify this option in builds, but it will be silently ignored.

**C listings disabled by default** C listing files are no longer produced by default. See the [New listing option](#) (in New Features) entry for more information.

**Space number for EEPROM changed** The space number used by psects that hold EEPROM data has changed from 2 to 3. This only affects PIC10/12/16 devices. This will not affect most projects, but if you see an error indicating `memory space redefined: 03/02`, then look for hand-written assembly that defines a psect used to hold EEPROM data and change the space value.

**Warnings for absolute local objects (XC8-652)** Previously the compiler would silently ignore any local (defined inside a function) object which the user had attempted to make absolute. The compiler will now issue a warning to say that the address specification will be ignored.

**Warnings for qualified local objects (XC8-670)** Objects which are local to a function (including autos and static local objects) cannot be qualified as `far` or `near`. The compiler was not indicating that the specifier was being ignored. A warning is now issued for such definitions.

## 5.1. Version 1.12

**Access of multi-byte SFRs** When writing literal values to multibyte `volatile` SFRs, the compiler will write high order byte first, then the low order byte. This conforms to the requirements of some PIC SFRs, such as the NCO register, which must be written in a particular order. This write order is not guaranteed for other expressions.

**Watchdog configuration bit** Some devices have had their configuration bit setting change from `WDTEN` to `WDT`. For these devices you will need to update any `#pragma config` directives that specify this setting.

**Implicit function in-lining** The implicit in-lining of function performed as an assembler optimization is now disabled by default. The assembler optimizer has, in the past, in-lined small assembly routines as part of its optimizations. You can re-enable it using the driver option `-A-auto_inline`. This change does not affect in-lining of C functions, controlled using the `inline` specifier.

## 5.2. Version 1.11

**Inline SFR names** When referencing SFR names specified in `<xc.h>` from in-line assembly code, do not use a leading underscore character with the symbol. So, for example, use the symbols `PORTA` or `RA0_bit` in in-line assembly code. (The same is true for SFR symbols in assembly modules that include `<xc.inc>`; however, the bit symbols have different names, for example, `PORTA` and `RA0`.) See the user's guide for more information on assembly code and accessing SFRs.

**Compiler banner information** The information shown in the compiler banner printed with each compilation has changed. The compiler operating mode is no longer printed, but you can still find this information in the list file. The license manage will now return and print the license type.

**Unused symbol inclusion** Unused symbols are no longer included in intermediate p-code files. This should not affect most customers. See the What's New section for information on the new `--PARSER` option which allows unused symbols to be included in the final link step.

**Pointer comparison warning** Warning number 1413 `"*" is positioned at address 0x0 and has had its address taken; pointer comparisons may be invalid` should now only be issued for symbols that are user-defined and not for temporary variables, such as `"ROM"` or `"RAM"`.

**Specification of config pragma** The arguments to the `#pragma config` can now be quoted. You may prefer to quote the setting-value pairs to ensure that the preprocessor does not perform substitution of these tokens, e.g., `#pragma config "BOREN=OFF"`

### 5.3. Version 1.10

**Re-activation of the compiler** As of version 1.10, the license files used by the XC compiler license manager are installed in a different location. This is automatically handled by the installer; however, if you plan to use an older license file with v1.10, you will need to re-activate the v1.10 XC8 compiler with your activation key before you can use it. Previously, the installers could find older license files and did not require re-activation. Re-activation will not be necessary in future when updating compiler versions.

**PIC10/12/16 Assembly Header Files** The names of some of the assembly header files have changed. Provided code included the generic and recommended `<xc.inc>` assembly header file, then this will be transparent. Specifically, changes relate to using the extension `.inc` instead of `.h` for assembly-domain header files; the names of device-specific assembly header files now match their C-domain counterparts.

**Deprecation of in-line assembly header files** The PIC10/12/16 header files that were usable from assembly that was in-line with C code have been removed. These header files were previously included via the generic file `<caspic.h>`. The content of these files will be included once you include `<xc.h>` in your C source code.

**Removal of single-letter bit definitions** The definitions for SFR bits that used a single letter identifier have been removed, for example the SSP1CON register bit `S`. These register bits are still available in the corresponding SFR structures, for example `SSP1CONbits.S`. The absence of these very poorly chosen identifiers should not be missed.

### 5.4. Version 1.01

**Missing SFR definitions** There have been changes to the header files to ensure correlation with the data sheet. This may result in some SFR definitions being no longer available. If you see undefined symbol errors or other build errors relating to SFR names, please refer to the appropriate device-specific header file and update your code.

**The inline pragma** The much misused `inline` pragma has been changed. What was the `inline` pragma is now known as the `intrinsic` pragma. Since the `inline` pragma was not intended to be used with user-defined routines, this should have no impact on existing projects. Use of the `inline` pragma in this compiler version will be ignored; however, future versions may implement a user-operable inlining feature.

**Filling unused values** The `--FILL` option, which is used to fill unused memory locations, now assumes the value specified is a 2 byte word. Previously the size of this value was the same as the target device program memory addressability i.e. 1 for PIC10/12/16 devices and 2 for PIC18 devices. The width of the value can always be specified with the option. See the user's guide section relating to hexmate.

## 5.5. Version 1.00

**Library functions removed** The following library functions and macros are now longer supported and have been removed from the libraries and header files.

- `device_id_read`
- `idloc_read`
- `idloc_write`
- `config_read`
- `config_write`
- `checksum8` and the macro `CHECKSUM8`
- `checksum16` and the macro `CHECKSUM16`
- `checksum32` and the macro `CHECKSUM32`

Any attempt to use these will result in a compiler error.

**Memory functions replaced by peripheral library equivalents** Flash and EEPROM functions and macros have been removed from the compiler libraries and header files. They have been replaced with those in the peripheral library.

**Compiler drivers** While you may continue to call the `picc` or `picc18` command-line drivers, it is recommended that projects be swapped to use the unified `xc8` driver. Future compiler releases may discontinue the device-specific drivers or additional functionality may be added to `xc8` that will not be usable if you continue to use the device-specific drivers.

**FN-type directives** All FN-type directives are no longer supported and should not be used. Such directive include: `FNBREAK`, `FNSIZE`, `FNROOT` etc. The `FNCALL` and `FNROOT` directives are still issued by the compiler, but it is recommended that these not be used in handwritten assembly code.

## 6. Fixed Issues

The following are corrections that have been made to the compiler. These might fix bugs in the generated code or alter the operation of the compiler to that which was intended or specified by the user's guide. The version number in the subheadings indicates the first compiler version to contain fixes for the issues that follow. The bracketed label(s) in the title are that issue's identification in the tracking database. These may be of benefit if you need to contact support.

### 6.1. Version 1.31

**Note about Debugging (MPLABX-2129)** Note that an issue in MPLAB X IDE has resulted in poor debugging experiences when using MPLAB XC8 and source code that uses inlined functions. At times, more than one step action is required to advance one C source line, and sometimes stepping might have resulted in jumps to unexpected parts of the program. This has been corrected in version 2.05 of the IDE.

**Bad address formation (XC8-1017)** For enhanced mid-range devices, the formation of the upper byte of an address might have been incorrect when the target was in banks higher than bank 1. This might have affected increment/decrement of a pointer; loading a temporary variable from a software-stack-based pointer; or indirect assignment of a pointer.

**Bad pointer assignment (XC8-1015)** For enhanced mid-range devices, where a pointer is assigned to another pointer, the source pointer is byte-wide and on the software stack (reentrant mode), and the destination pointer is 2-bytes wide and is *not* on the software stack, then the upper byte of the destination pointer may be loaded with an incorrect value.

**Inline delays causing crash (XC8-1009)** In situations where the inline delay routine was used and no code followed in the same function that performed a call or jump to another page, the delay may have jumped to the wrong location and the program crash.

**No warnings for stack overflow (XC8-1012)** A warning indicating an overflow of the data stack was not produced for some reentrant functions which defined too much stack-based variables. A warning is now issued. Note that the MPLAB XC8 User's Guide incorrectly lists the PIC18 stack limit as 255 bytes. This limit is 127 bytes.

**Undefined/redefined symbols for reentrant functions (XC8-1011)** For functions compiled using the reentrant model, some assignments may have defined the wrong local symbol for a branch. Errors indicating undefined or multiply defined symbols, or relative branch/call offsets out of range may have been issued by the compiler.

**Indirect access of structure members (XC8-1010)** In some instances, pointer arithmetic on the address of structure members could be calculated incorrectly.

**Incorrect pointer size with return statements (XC8-999)** In rare instances, pointers returned by functions might have been made the wrong size.

**Can't generate code errors with pointer structure members (XC8-451)** Where a pointer is a member of a structure, it may have been made larger than necessary, or code that dereferenced it might have been less than optimal. In some situations, the compiler might have issued can't generate code messages when dereferencing the pointer.



- Program resets (XC8-970)** Under some circumstances inlining nested functions calls might have resulted in a call to reset and program failure.
- Debug information missing from .asm modules (XC8-1003)** Line number information was missing in generated COF files for assembly files that used a .asm file extension. Files with a .as extension were not affected.
- Bad labels for switch code (XC8-996)** For PIC18 devices, if a `switch` statement was used in a reentrant function that was called by an interrupt function, the code generator created invalid label names for the cases.
- Syntax error with stack-object assignments (XC8-997)** Expressions involving multiple assignments of stack objects in reentrant functions on PIC18 devices, might have resulted in a syntax error from the assembler.
- Incorrectly merged code (XC8-994)** When a statement in the true part of an `if` statement and a statement in the false (else) part was the same except for a conversion (cast) of a symbol from signed to unsigned (or vice versa), the compiler might incorrectly consider these statements identical and merge the generated code.
- Overlap of interrupt code (XC8-983, XC8-945)** On an enhanced baseline devices with oscillator calibration enabled in the runtime startup code and an interrupt service routine defined, a linker warning (596) about segment overlap might have been issued. The warning would have indicated generated code that was corrupted and could result in code failure.
- Overlap of interrupt code (XC8-979)** Programs compiled for PIC18 targets that include a low- and high-priority interrupt function might have had the psects `intcode` and `intcode_lo` overlap. This was especially the case when compiling in Free or Standard modes.
- Byte comparison failure (XC8-978, XC8-990)** Comparison of a byte expression with a constant might have failed when compiling for PIC18 devices. This would have only affected expressions whose results were stored in temporary variables. The temporary variable might have been incorrectly accessed in common memory when it was located in banked memory.
- Bad pointer assignment (XC8-977)** For PIC18 targets, when assigning from one pointer to another and the destination pointer was 2-bytes wide, the upper byte of the pointer might have been cleared rather than assigned the correct value.
- Syntax error with left shifts (XC8-973, XC8-974)** Some PIC18 expressions involving a left shift of a single bit quantity by a constant value might have produced a syntax error due to a malformed assembler instruction.
- Bad parameter load (XC8-959)** In rare instances, where a function call is required to obtain the argument to another function, there may be a corruption of the called-second function's parameters.
- Cromwell crash (XC8-966)** Programs that contain an inline-qualified function that was successfully inlined by the compiler and with no 'outlined' version generated, might have caused cromwell to crash during ELF/DWARF generation.

**Bad call to typeSub error with pointers (XC8-960)** For code that defined function pointers and these pointers were not assigned a valid address of an object, the error 'Bad call to typeSub()' might have been produced.

**Assembler crash with large routines (XC8-955)** For midrange PIC devices compiling extremely large routines that would never actually fit on the target device, the assembler might have crashed. A memory error is now reported in such circumstances.

**Ignored \_\_section specifier (XC8-562, XC8-951, XC8-950, XC8-852, XC8-851)** In some instances, the use of the `__section` specifier was ignored, or might have resulted in the wrong section being used. This would have occurred when objects using custom sections were used across multiple source modules. Bogus warnings issued when using this specifier have also been suppressed. The previous limitations associated with use of the `__section` specifier have been lifted as a result of this fix. You no longer need use the specifier with declarations.

**Driver crash when adjusting memory ranges (XC8-936)** When complex memory reservation ranges were specified (particularly those that contained duplicate or overlapping ranges) or when hand-written assembly code defined absolute psects, the compiler driver may have crashed.

**Code generator crash when using regused pragma (XC8-928)** If the `regused` pragma was used with with no registers specified, the compiler might have crashed. This only affected compilation for baseline and all midrange devices.

**Driver crash when reserving common memory (XC8-1014)** When reserving addresses for an enhanced midrange device and the addresses were within the common memory range, the compiler driver might have failed an assertion.

**Looping around allocGlobals error (XC8-832, XC8-991, XC8-946)** In some instances where a structure contained a pointer member, the error 'looping around allocGlobals' may have been issued.

**Non-detection of multiple use of codeoffset (XC8-509)** When compiling for PIC18 devices, using more than one `--CODEOFFSET` option triggered an error; when compiling for all other devices, it was silently ignored. Now, for all devices, the duplicate option is ignored provided it does try to move the origin of ROM lower than it is currently set; otherwise, a warning is produced.

**Seemingly insane can't find space messages (XC8-502)** Bogus can't find space errors might have been produced for structure or array objects that contained pointers, even though there was ample memory remaining. The message would have been triggered by objects whose size (assuming the pointers were 3-bytes wide) was larger than 256 bytes, but whose final size was less than 256 (after the pointers sizes were determined).

**Missing warning (XC8-491)** The compiler was not producing a warning when code applied the `sizeof` operator to objects of incomplete type e.g. an array with no declared size.

**Error messages referencing inappropriate source code (XC8-490, XC8-207)** Some error and warning messages are not related to specific lines of code; however, even in these circum-

stances the compiler would print a file name and line number (which would typically be the last file and line of source processed). Some messages now include the string "Non line specific message:" instead of a filename to ensure it is clear that there is no single statement that is at fault.

**Bogus warning when comparing function types (XC8-464)** The compiler might have issued warnings indicating a mismatch in type when comparing a function that has an empty parameter list and a function that has a `void` parameter (all else being equal). These are now considered equivalent types.

**Parser crash (XC8-460)** When erroneous code such as the following (attempted use of an incomplete structure definition) was encountered:

```
struct a {  
    int f;  
    /* missing close-curly } */;  
struct a b;
```

the parser component crashed instead of terminating gracefully.

**Memory errors when using sort function (XC8-449)** The buffer size used by the `sort` function has been reduced for non-PIC18 devices to prevent can't find space messages on some devices. Consider adding the source for this function to your project if you want to customize the buffer size for your application and device.

**Detection of square bracket misuse (XC8-443)** The compiler will now flag an error if square, array-subscript brackets (as opposed to round brackets) have been mistaken used to call a function.

**In-line assembly degrading debugging (XC8-329)** Setting breakpoints on lines of code appearing after `#asm ... #endasm` blocks was often not possible, or breakpoints did not match the correct assembly instructions. Use of `asm()` statements did not cause this issue.

**Can't generate code when calling functions via initialized pointers (XC8-238)** The compiler better handles situations where pointers containing `NULL` were been used to call functions, or absolute (literal constant value) functions were called. A warning might be triggered if such a call is made.

**Spurious warnings concerning invalid variable locations (XC8-221)** If the warning level threshold was lowered, spurious warnings about library functions were being printed. Messages appeared similar to "invalid variable location detected: `__asmul` - `__asmul` (warning)"

**Assembly crash with in-line assembler (XC8-182)** In some instances when in-line assembly contained a `GOTO` instruction, the assembler may have crashed. This affected only PIC18 targets.

**Can't generate code messages with comparisons (XC8-164)** A Can't Generate Code error might have been issued for complex relational (greater than) comparisons of `int` types.

**Failure with indirect comparison (XC8-13)** Code that indirectly accessed any 4-byte object and performed a `==` or `!=` comparison might have failed. This might be expected when integer or floating point quantities were converted to boolean values.

**Missing symbol when calling functions indirectly (XC8-968)** When compiling for any baseline or midrange device, functions that are only called indirectly and only from an interrupt might not have been added to the indirect function calling table. This would have resulted in an undefined symbol error.

## 6.2. Version 1.30

**Incorrectly merged code (XC8-924)** When a statement in the true part of an `if` statement and a statement in the false (else) part was the same except for a conversion (cast) of a symbol, the compiler might incorrectly consider these statements identical and merge the generated code.

**MPLAB X Watch objects in wrong memory space (XC8-935)** In some instances, uninitialized (BSS) variables would be reported as being in program memory in the MPLAB X watch window, and the wrong value displayed.

**Build delay** The compiler's license manager (XCLM) was updated to revision 1.23. This disables the RLM option to automatically query the network for a network server when a node locked file was not found. This will prevent a several-second delay with each invocation of the compiler.

**Recursive call to function error (XC8-913)** In some instances the compiler falsely reported that a compiler library function was called recursively.

**Reset to main in debugger (XC8-926, XC8-1008)** The compiler produced a debugging image lacked sufficient information to support the MPLAB X feature that breaks the debugger at `main()` on restart. Note that changes to resolve these issues were also made in MPLAB X IDE and will be available in the v2.06 release.

**Bad right shift (XC8-938)** For all devices, some expressions involving a right shift of an unsigned object that was cast to be a signed object, might have produced an incorrect result.

**Bad pointer access (XC8-908)** Dereferencing a pointer with program and data space targets may have resulted in the wrong value. This issue is known to have caused bad output when using `printf()`.

**Copying const structures (XC8-806)** Code that indirectly copied (via a pointer) a structure larger than 4 bytes in size to another structure may have failed if the source structure was in program memory and the source pointer had both RAM and program memory targets. This affected PIC18 devices only.

**Duplicate advisory messages printed (XC8-840)** Advisory messages might have been issued twice when compiling code in some situations.

**Bad code after indirect data memory access (XC8-839)** Code which indirectly accessed RAM using an FSR may have overwritten the content of WREG, resulting in subsequent code failure. This would have only affected enhanced mid-range devices.

**Truncation of Operand Value messages when accessing linear objects (XC8-837, XC8-889)**

For enhanced mid-range devices that accessed objects placed in linear memory, the wrong address may have been accessed. The warning "truncation of operand value" might have been issued for such code.

**Compiler crash when copying structure pointers (XC8-779)** When casting a pointer to a structure to another structure pointer, the compiler may have become stuck in a recursive loop (and ultimately crash) if the source and destination structure types both had a self-referential pointer member at the same member position in the structure.

**String labels (STR\_x) defined more than once (XC8-527)** Some string labels may have been reused resulting in a multiply defined label error from the compiler. String labels look similar to STR\_2, STR\_10 etc.

**Can't Generate Code errors when casting structure pointers (XC8-722)** This error may have been issued when casting pointers to packed structures to other pointer types.

**Inappropriate pointer warning issued (XC8-599)** The message "a pointer to eeprom cannot also point to other data types" may have been issued in some situations that were not appropriate.

**Linker errors when adjusting program memory ranges (XC8-522)** If compiling for an enhanced mid-range device and overriding the default program memory with an option similar to: `--ROM=0-7ff` (options in which the default memory is removed and new ranges are specified), the `STRING` linker class was not being allocated the specified memory. Linker errors such as 'psect "strings" not specified in -P option' might have resulted and string objects might have been linked at invalid addresses.

**Undefined symbols using `interrupt_level` pragma (XC8-535, XC8-133, XC8-3)** If a function was only called in interrupt code and the `interrupt_level` pragma was applied to it, it was not output at all, resulting in "undefined symbol" errors.

**Bad Pointer conversion (XC8-761)** Implicit conversion of a 2-byte pointer to a 3-byte pointer might have failed in some situations. The upper byte of the destination pointer was always being cleared.

**Bad pointer comparisons (XC8-604)** In some situations, comparisons of 3-byte pointers with `NULL` may have been incorrectly performed.

**Errors using `##` preprocessor operator (XC8-526)** When expanding preprocessor macros whose expansion involved the concatenation operator, `##`, and the argument to such a macro was a floating-point number which had a sign character and one and only one exponent digit (e.g. `1.23e+1`), the expansion may have failed and generated compile-time errors.

**Bad Pointer conversion (XC8-761)** Implicit conversion of a 1-byte pointer to a 3-byte pointer might have failed in some situations.

**Driver crash when reserving memory (XC8-688)** The compiler may have crashed if reserving program memory that included all the configuration memory. It is now no longer possible to reserve any of the configuration, idloc, or useridloc memory using the `--ROM` option.

These address ranges are masked from any range specified using this option.

**Can't Generate Code errors and `__section` specifier (XC8-506)** Indirectly accessing objects defined using the `__section()` specifier may have produced this error for any mid-range or baseline device.

**Bogus Can't Find Space messages (XC8-85)** In situations (typically when writing bootloaders) where the entire memory which is normally allocated to a linker class is reserved, the linker might have displayed error messages indicating that psects could not be allocated memory, even if those psects had a size of zero. These errors are now suppressed in this situation.

**Assembler crash with missing labels (XC8-123)** The assembler may have crashed if optimising code that had jumps or calls to labels that were not defined in the assembly code.

**Can't Generate Code errors (General) (XC8-505)** The compiler now performs an extra code generation step before issuing these errors. This might suppress such errors for expression that involve (implicit or explicit) function calls and register allocation.

**Looping Around allocGlobals error (XC8-844)** Some expressions created temporary variables which were not correctly allocated memory. This caused an endless loop which resulted in a "looping around allocGlobals" error to be produced.

**Corruption of const data (XC8-865)** The psects that contained absolute `const` objects were being scanned by the assembler and errata NOPs added after any label in those psects. This corrupted the data these psects held. The names of the psects used to hold these data have changed from ending in `_text` to ending in `_const` and they are no longer scanned by the assembler. This issue only affected devices that required the FETCH or 4000 errata work-arounds (see table at the end of this document).

**General code failure (XC8-866)** Some code sequences involving `char` and `int` types may fail, particularly when casting from one type to another. This only affected mid-range and baseline devices. While a general fault, it was unlikely to affect programs.

**Can't Generate Code when indirectly calling functions (XC8-867)** This error messages might have been issued when calling functions via a pointer which is initialized only with a literal constant or NULL. This issue only affected PIC18 devices.

**Compilation of source files with the same name (XC8-768)** An error was generated when compiling an MPLAB X IDE project that contained two or more C source files with the same filename (but stored in different directories). Such projects are now allowed to compile. Operation on the command-line is similarly less restricted, provided there will be no clash between the intermediate P1 files generated from these source files.

**Complement operator used with boolean results (XC8-167)** The complement of a boolean value, for example `~( ! foobar )`, was returning a boolean type rather than the integral promoted type. This may have produced incorrect values in expressions.

**Error reading CMF (XC8-872)** A user defined psect (either in assembly or created with the `__section()` directive) that was not associated with a linker class (either in a command-line option or in the psect directive) produced a CMF file that could not be read by the Cromwell application. It caused Cromwell to emit the message "error reading CMF: no token at index 6".

**Arguments to indirect calls not correctly passed (XC8-242)** If more than one function was called indirectly via the same pointer and these functions had pointer parameters, in some instances the parameters might not have been passed correctly.

**Incomplete memory summary (XC8-503)** Psects that are created using the `__section()` specifier did not appear in the memory summaries issued by the compiler. These are now included in an "unclassified" part of the psect listing.

**Can't Generate Code errors with structure pointer members (XC8-417)** In some situations, code involving pointers defined in structures produced Can't Generate Code messages. This was most prevalent when the pointer was passed to a function as an argument.

**Bank selection issue with bitfield member (XC8-877)** When accessing a bit-field located at position 6 in the structure, and the expression contains another memory object in another bank, a bank selection instruction may have been omitted resulting in the wrong bit-field location being accessed.

**Incorrect XOR of single bit-field object (XC8-842)** XORing single-bit-wide bit-field objects with the value 1 was always producing the value 1.

**Incorrect memory reservation with user-defined RAM psects (XC8-466)** The compiler was reserving memory during the C code generation step for psects in hand-written assembly code that were not absolute and overlaid. Only absolute and overlaid psects should have memory reserved at the code generation stage, as described in the XC8 User's Guide. This may have resulted in bogus out-of-memory errors.

**Code failure with shift and type conversion in the same expression (XC8-887)** Expressions that involve a variable being shifted by multiples of 8 and a conversion to smaller integer type (whether implicit or a cast) may have accessed the variable in the wrong bank and led to code failure.

**Truncation of Operand Value messages with compound assignments (XC8-873)** Compound assignments of a constant to objects that are in linear memory, e.g. `a=b=100;` might have produced a warning "truncation of operand value" message with subsequent code failure. This only affected enhanced mid-range devices.

**Incorrect delays and Truncation of Operand Value messages (XC8-843)** When using the in-built delay routine `_delay()` and delay values above 1792, the delay time may have been in error and warning messages indicating truncation of operand value may have been issued.

**Bad Fill assignment (XC8-890)** In some instances when the `--CHECKSUM` option was being used, a `--FILL` option was implicitly created by the driver to ensure consistent checksum

results. The fill command passed to HEXMATE was not correctly formed and resulted in a HEXMATE error: (941) bad "-FILL" assignment.

**Parser crash on division/modulus by zero (XC8-886, XC8-888)** Some preprocessor expressions involving a division or modulus by a literal value of zero were not being detected and crashed the parser. The parser now issues an error message for such situations.

**Illegal sized arrays accepted (XC8-898)** Array declarations that specified an array size and the size expression involved the `sizeof()` operator were not flagged as an error if the size expression evaluated to be a negative value. An error is now issued for such code.

**Missing warning or error messages (XC8-899)** Some warnings issued by the compiler may have been lost and not appear during a build. It is possible that builds with this compiler release will produce more warnings than with previous builds.

**Address of objects returning NULL (XC8-76)** For programs with less than 256 bytes of `const` data (`const` objects being placed in the `smallconst` psect), taking the address of a `const` object may have compared equal to `NULL`. The first byte of the space allocated to the `smallconst` psect is now reserved so that this situation can no longer occur.

**Error when using booleans in integer expressions (XC8-131)** The unary `+` and `-` operators may now be used with either `bit` variables or operators that produce a boolean value (such as `==`, `!` and `>`). The boolean values are promoted to an `int` then used in the usual way.

**Negative signs with negative floating-point values (XC8-135)** In some instances, the negative sign was not being printed for negative floating-point values. Note that the `printf` code is customized with each build based on the placeholder your program uses, so not all programs would have been affected by this issue.

### 6.3. Version 1.21

**Incorrect indirect access of absolute objects (XC8-847)** Pointers assigned the address of absolute objects might have been too small to correctly access the target object. This only affected PIC18 devices.

**Wrong pointer sizes (XC8-824, 791, 830)** In some situations pointers may have assumed incorrect sizes which lead to code failure.

**Bad code after addition (XC8-823)** Code which required the addition of an stack-object address with a small literal constant may have clobbered the value in held in `WREG`. Any subsequent code relying on `WREG` may have failed. This only affected enhanced mid-range PIC devices.

**Over-enthusiastic optimization of goto to branch instructions (XC8-808)** Regardless of the state of the optimization option, the PIC18 assembler would always consider changing `GOTO` instructions to branch instructions for hand-written assembly modules (this did not affect in-line assembly code).

**Assembler crash with GOTO instruction (XC8-805)** In some instances, the use of a constant literal address as the operand of a `GOTO` instruction caused the PIC18 assembly optimizer to crash. This is only likely to have affected hand-written assembly code.



**Syntax errors with bit expressions (XC8-810)** Assigning the result of an AND between two bit types to a bit type destination, may have resulted in syntax errors. This only affected PIC18 targets.

**Compiler crash with assembly-only projects (XC8-822)** For projects that contain only hand-written assembly code, the compiler driver may have crashed. This only affected compilers running under the Window OS.

**Spurious message when building (XC8-783)** Programs containing functions with identifiers ending in `alt` or `nosup` could have caused the compiler driver to emit messages making reference to `process_nosup_syms`. The messages relate to a "mistaken identity" of symbols used by the linker to convey specific linking information; they do not indicate wrongly generated code.

**Assembly optimizer alters code sequences affecting volatile SFRs (XC8-798)** The assembly optimizer can partially abstract code sequences. Typically, this is of no concern, but for time-sensitive instruction sequences (e.g. special instruction sequences to initiate a flash write), this may cause unexpected behavior. The compiler has been updated to ensure that access of all volatile special function registers are not abstracted. This only affects mid-range PIC devices.

**Assembler optimization produces bad code for if() statements (XC8-825)** When an `if()` expressions involved two tests for equality and the body of the `if()` was an assembly sequence that was only 1 instruction long, an assembly optimization may have corrupted this code sequence causing code failure. This only affected PIC18 devices where assembler optimizations were enabled.

**Wrong bank access with shift code (XC8-828)** Code involving right shifts of long objects, where the object being shifted and the variable containing the shift amount are in different banks, was not correctly registering the bank selected. Subsequent code may have accessed the wrong memory location. This only affected PIC18 target devices.

**Crash when using large command lines (XC8-845)** Executing the compiler with command line arguments totaling more than 8192 characters in length may have caused the compiler driver to crash.

**Wrong bank access in code loops (XC8-567)** For some code sequences that contained loops, tracking the currently selected bank when it was changed inside the loop may have failed. This would have caused wrong variable locations to be accessed on subsequent iterations of the loop.

**Wrong pad values used with download option (XC8-760, 762)** The `download` suboption to the `--RUNTIME` option pads certain records in the HEX file. The pad values used for mid-range and baseline devices were specified using the wrong byte order. This may have led to programming errors. This issue did not affect the operation of the code in any way.

**Crash when using #fi directive (XC8-771)** The `#fi` preprocessor directive is valid when using C18 compatibility mode. Outside of this mode, use of this directive should flag an error. Instead, the preprocessor was crashing when this directive was encountered.

**Incomplete initialization of absolute const arrays (XC8-770)** When compiling for PIC18 devices, the uninitialized elements or members of partially initialized absolute `const` array or aggregate objects, may not have been zeroed. This issue did not affect objects that were not absolute.

**Incorrect byte return value from functions (XC8-769)** For functions that returned a byte and which did not use the regular call stack (this implies that the `stackcall` suboption to `--RUNTIME` was enabled), expressions that used this return value may have read it from the wrong location. This would have resulted in incorrect results from expression that used the return value.

**Recursive function call error (XC8-437)** Code using the `modf()` library function may have triggered the error message *recursive function call to "\_\_\_ftpack"*. The source code for this function has been modified so that this message is no longer generated.

**Function return value corrupts other data or is corrupted by other code (XC8-344)** Insufficient memory was allocated for a function's return value if that value was greater than the size of the auto-parameter block for that function. Specifically this issue only affected PIC18 functions which returned a pointer type and when the size of this pointer was larger than 1 byte in size. This return value may have corrupted other memory locations or have been corrupted itself by other functions or interrupt routines.

**Incorrect pointer size calculated for duplicated function's return value (XC8-461)** If a function returning a pointer was duplicated because it was called from more than one call graph, there were instances where the size of the pointer returned by the function were incorrect.

**Inlined code crashes (XC8-804)** If code that was inlined (specified `inline`) contained more than one jump or more than one call to the same destination label, then only the first jump or call instruction was fixedup to use the new inlined label. If the execution path in the inlined code took any of the latter jump or call paths, this would have caused execution to crash. This issue has been corrected and inlined functions may contain multiple jumps or calls to the same destination label.

**Failure to load ELF file in MPLAB X IDE (XC8-784)** If `inline` functions were used in a program, the ELF files produced may not have loaded into the Windows version of MPLAB X IDE.

**Can't find space for zero bytes message (XC8-800)** The use of some `bit` SFRs on 16F1xxx enhanced PIC devices (for example `SEG43COM3` on the 16F1947) may have resulted in a compiler error indicating that it couldn't find space for zero bytes.

**Missing errata workaround NOP instructions (XC8-803)** The assembler failed to insert a NOP instruction at the entry point of an assembly function defined for PIC18 devices that suffers from the FETCH or 4000 errata issues.

## 6.4. Version 1.20

**Bad conditional code (XC8-640)** An error in an assembler optimization that dealt with a bit-test-and-skip instructions and FSR manipulations caused the sense of some conditional control statements to be inverted.

**Phase errors (XC8-590, XC8-691, XC8-49)** The assembler optimizer was removing redundant page selection instructions, but other parts of the assembler were not taking this into account. This created a mismatch in expected and actual sizes of some jump instructions which led to phase errors being produced. This issue affected hand-written and compiler-generated assembly code.

**Absolute function placement (XC8-203)** The address specified for functions made absolute was rounded down to the nearest 0x10 value. So, for example, if you attempted to place a function at address 0x56, it was actually located at address 0x50. This only affected programs compiled for PIC18 devices.

**Missing errata NOP instructions (XC8-692)** The assembler was not correctly adding in NOP instructions that form part of the `fetch` errata workarounds for some PIC18 devices. (See the user's guide `--ERRATA` option section for more information.) Delay routines that required these instructions were known to run too fast. A consequence of this fix is that code size will increase for devices that require the `fetch` errata workarounds.

**Wrong UINT24\_MAX value (XC8-565)** The value for this `<stdint.h>` macro was higher by 1 than it should have been.

**Bad variable access after calls (XC8-694)** The compiler was, on occasion, placing a bank selection instruction before the call to a routine. This bank selection was not properly being tracked and may have resulted in incorrect access of objects once in the called function.

**Assertion failure using --ROM or --RAM options (XC8-517)** When attempting to reserving memory that was outside your target device's on-chip memory, these options may have caused an assertion failure.

**Invalid access via pointer (XC8-643)** In some situations, the compiler was not detecting that the upper TBLPTR register was being changed from its assumed state. As a result, code that dereferenced a pointer with both RAM and ROM targets may have corrupted this register and triggered a subsequent failure in the code.

**Assembler crash with bad options (XC8-510)** If options were passed directly to the assembler application but no file names were present, the assembler issued an error and continued processing. The error produced in this situation is now a fatal error to prevent the crash. This issue would have only affected users driving the assembler directly.

**Assembler crash when specifying functions as inline (XC8-589)** In some instances, when a function was declared `inline` the assembler crashed.

**Can't Generate Code message associated with unused objects (XC8-636)** In cases where a pointer was not used but was assigned the address of an object, this message may have been emitted. Optimizations associated with such code are now restricted and the message will not be issued.

**Parser crash with enumerated types (XC8-637)** The parser may have crashed when scanning code associated with enumerated types. This may have been associated with taking the address of enumerated objects.

**Qualifiers silently ignored for local objects (XC8-670)** Objects which are local to a function (including `auto` and static local objects) cannot be qualified as `far` or `near`. The compiler was not indicating that the specifier was being ignored. A warning is now issued for such definitions.

**Absolute addresses silently ignored for local objects (XC8-652)** Objects which are local to a function (including `auto` and static local objects) cannot be made absolute. The compiler was not indicating that the `@` or `__at()` construct was being ignored. A warning is now issued for such definitions.

**Linear memory allocation of objects (XC8-501)** Absolute objects that specified a linear memory address may not have been allocated correctly if the object's equivalent banked addresses mapped into the common memory. This only affected enhanced mid-range devices and objects that were not large enough to be automatically allocated to linear memory. The compiler now correctly allocates these objects.

**Identical case label values in a switch statement (XC8-493)** The compiler was not detecting the use of more than one identical `case` label value inside a `switch()` statement. This is now correctly identified and will trigger an error.

**`__DEVICENAME__` not defined (XC8-659)** This predefined macro was not being defined by the compiler. This is now defined unconditionally.

**Procedural abstraction of in-line assembly code (XC8-660)** The assembler optimizer was performing procedural abstraction on assembly code that was placed in-line with C code. The optimizer should not perform *any* optimization of in-line assembly code. The optimizer has been prevented from performing these optimizations.

**BSR register not recognized by `regsused` pragma (XC8-663)** Any attempt to list the BSR register in the `regsused` pragma would have resulted in an error. This has been corrected and this register may now be used with this pragma for those devices that implement this register.

**Allocation of PIC18 far variables (XC8-582)** In some instances, `far`-qualified variables may have been linked at address 0, not in the memory defined as the far RAM.

**Indexing array with constant expression failure (XC8-648)** With enhanced mid-range devices only, any operation that involved adding a integer constant to an address (typically this will be an array access with a constant integer index) may have caused subsequent code to fail. Such code was not correctly reporting its use of WREG.

**Initialization of large objects on enhanced mid-range device (XC8-672)** Initialization of large objects (such as arrays or structures) that contained a pointer may not have been assigned the appropriate values by the runtime startup code. This only affected PIC16F1xxx devices.

**Uninitialized `const` objects not assigned zero (XC8-553)** If `const` objects were not initialized, they were not being automatically assigned the value 0 by the compiler. These objects had

no memory reserved for them at all and this may have resulted in them appearing to overlap with other `const` objects. This is now corrected; any `const` object that does not have an initial value is implicitly assigned 0 by the compiler.

**Assertion failure reserving RAM (XC8-662)** In some instances, reserving RAM when using any non-enhanced mid-range part using the `--RAM` option would result in an assertion failure `hi >= lo`.

**Integers allowed with specifiers (XC8-549)** The integer constants usable with specifiers such as `__at()` were limited to 16-bit values. These values can now be specified as 32-bit values.

**Multiply defined symbols (XC8-516)** If code used the `__section()` specifier with variables, there may have been symbols contained in the runtime startup code that were defined more than once, producing an error. (Such symbols might be `clear_ram` or `clrloop`, for example.) This duplication has been corrected.

**`__mediumconst` symbol undefined (XC8-621)** In some circumstances, particularly when using the peripheral library, the compiler may have produced an undefined symbol error for `__mediumconst`.

**Functions not inlined (XC8-521)** When a function qualified as `inline` was called from `main()`, it was never inlined and a regular call was made. Inlining should now take place for any suitably qualified function called from `main()`.

**Incorrect return instruction (XC8-525)** For some baseline devices (most notably the 12F529T39A and 12F529T48A), the compiler may have attempted to use the non-existent `RETURN` instruction instead of a `RETLW` instruction.

**Partial access to ID locations (UDBC-678)** The compiler did not allow access to the entire ID location for devices that implement this memory as being 14-bits wide (e.g., the PIC16F1503). This has been corrected and you may now program all the bits of these ID locations.

**Code failure accessing absolute objects straddling a bank (XC8-601)** The wrong bank may have been selected when accessing absolute objects that straddle a bank boundary. Code may have failed when accessing the addresses in banks following that of the bank of the object's base address.

## 6.5. Version 1.12

**Compile times and crash (XC8-127)** A sorting issue related to pointer variables may have significantly increased the compilation time of projects. Not all projects were affected by this issue. This issue may also have caused the code generator to run out of memory, or even crash in some situations.

**Compile times (XC8-498)** A further issue affecting compilation times was corrected. This issue affected the assembler when `--ASMLIST` was used. (This option is on by default when using the IDE.)

**Installer operation** The installer program was not correctly setting the write permissions for some files. This was reported on Windows XP, but may have affected other platforms.

**Bank selection issue (XC8-494)** In an expression such as:

```
A = B + C;
```

where A and C are unsigned 16-bit objects in different banks and B is an unsigned char, a bank select instruction may have been omitted resulting in the wrong value being assigned to the destination variable.

## 6.6. Version 1.11

**Compilation times (XC8-441)** Large projects, particularly those targeting PIC18 devices, may have experienced increased compilation times. This was due to the compiler processing more symbols. A new option has been added, and enabled by default, to limit the symbol list. The new option is `--PARSER`. See the New Features section for more information.

**Looping around pointGraphComplete() Error (XC8-442)** A non-deterministic pointer-related issue was causing this error to be printed, and terminating compilation.

**Debugging absolute objects (XC8-447)** Some SFRs and absolute addressed objects residing in RAM would appear as being located in program memory during a MPLAB X or v8 debugging session. The content of these values would, thus, be incorrect. Absolute symbols should now appear to be located in their correct memory space and their contents shown correctly.

**Parsing of config pragma arguments (XC8-452)** The parsing of arguments to the `#pragma config` directive was erratic when it came to quoted arguments. The quote character `' '` is now a token delimiter and you may quote the arguments to this pragma, e.g. `"WDTEN=ON"`. Doing so will avoid any macro substitutions by the preprocessor. If you have defined macros for `ON`, `OFF` or any other token used by the `config` pragma, consider quoting the pragma arguments or moving the pragmas to a module that is not exposed to your macros.

**Incorrect access of array of strings (XC8-454)** Code which used a variable to access an element of a string array may have failed when the index was non-zero.

**Unsupported short long message using CCI (XC8-429)** When using the CCI, a warning may have been issued indicating that the short long type was not supported. The header files that referenced this type have been updated and use a plain long type when compiling for the CCI.

**Undefined symbols with bitwise operations (XC8-424)** Some bitwise operations, for example `|` or `&`, when used in functions that were in the interrupt call graph, may have produced code that contained references to undefined temporary symbols. Such symbols would look similar to `i2u49_41`.

**Can't generate code with printing floats (XC8-108)** For some placeholders associated with `float` types, a can't generate code error may have been triggered with `(s)printf`. This has been corrected.

**Detection of incomplete types (XC8-109)** The parser was not detecting definitions using incomplete types, for example:

```
typedef struct foo foo_t; // where foo has not been defined
foo_t x;
```

Code which is defined in such a way will now trigger an error from the parser.

**Can't generate code for library string routines (XC8-413)** Some string library functions may have caused "can't generate code errors". These have been adjusted to ensure correct compilation.

**Assignment to volatile bytes (XC8-427)** In some operating mode, when assigning 'l' to a `volatile` byte variable, it may not have been updated atomically (with one write rather than clear and increment instruction). This problem did not affect absolute objects and may have only caused runtime problems if the byte was accessed from main code and interrupt.

**--ROM option** The `--ROM` option was not processing its arguments correctly which may have resulted in it not reserving the memory specified.

## 6.7. Version 1.10

**Using far with Functions (XC8-337)** If the `far` qualifier was used with functions, it confused the compiler into thinking the function identifier was that of a variable destined for RAM. This may have triggered an error, if no far memory was defined, or caused a runtime code failure.

**Non-functional --ADDRQUAL option (XC8-293)** The `reject` suboption of this option was not working correctly for PIC10/12/16 device. The `require` and `request` suboptions were not working correctly for PIC18 devices. This option should now work as expected for all devices.

**Conversion of integer to bit-field (XC8-353)** The compiler was treating single-bit bit-fields as a boolean rather than an integer quantity when it came to assignment. Code that assigned a byte or larger integer to a single-bit bit-field may have failed.

**Can't Generate Code for Duplicated Functions (XC8-358)** The compiler may have issued Can't Generate Code error messages in situations where a function was duplicated in interrupt and main-line code and this function used pointers.

**Handling of incomplete types (XC8-374)** The parser was producing incorrect type information where a type used in a declaration was, at that point, incomplete, e.g. if you used a structure tag in a declaration, but that tag had not been defined. The code generator would subsequently crash if such incomplete type information was encountered. types should always be defined before they are used, but the compiler will no longer crash on such situations.

**Testing of volatile bytes (XC8-388)** The code that tested `volatile` bytes variables for (in)equality was using a `MOVF x, f` instruction. This was not in keeping with the spirit of the `volatile` keyword and could also play havoc with certain registers, such as the TMR0 register, on some baseline devices, such as the 10F222, which require a read delay after

being written. This code sequence is no longer used and access of SFRs will be well behaved.

**Pointer assignment failure (XC8-342, XC8-343)** In some circumstances, assignment of a structure member address to a pointer may have resulted in an incorrect destination pointer size being determined by the compiler. This would have resulted in subsequent pointer dereferences being invalid. This problem was detected only with assignments to pointer parameters as part of a function call, but could have potentially occurred elsewhere.

**Pointer access failure with duplicated functions (XC8-377)** If a function that has a pointer parameter is called from main-line and interrupt code (i.e. it is duplicated by the code generator), the compiler may have issued a "looping around allocGlobals", or "can't generate code" error message. In other situations, the code may have compiled, but accesses to the pointer may have been incorrect. The issue could have affected any device with interrupts.

**Undefined btemp symbol (XC8-371)** In some circumstances, exacerbated by the use of a debugger and devices with small amounts of RAM, the internal compiler symbol `btemp` may not have been defined and an error results. This symbol is now correctly defined.

**Incorrect access of high program memory (XC8-363)** The compiler was not correctly setting the TBLPTRU register for accesses of absolute-addressed `const` data located above 0xFFFF in PIC18 program memory.

**Incorrect configuration bit/user ID settings (XC8-385)** Attempts to program the configuration bit or user ID settings may have failed due to a sorting bug that may have resulted in the bits being programmed in the wrong order. The issue was inconsistent, but could affect all devices.

**Improved error relating to IDLOC (XC8-384)** If non-hex digits were used in for any nibble in the `IDLOC()` macro a confusing error was issued. A new message (#1436) has been created for this situation.

## 6.8. Version 1.01

**Looping around allocGlobals error (XC8-318)** This error may have been triggered, but is not specific to any particular code sequence. The compiler has been updated to ensure this trigger will not result in this error.

**Access of char arrays (XC8-304)** If the index expression used with an array of `char` consists of a non-constant expression (e.g. a plain variable) from which is subtracted a constant (e.g. `myArray[idx-1]`), then the index calculation may have been incorrect and the wrong element accessed. This issue mostly affected PIC18 devices and arrays no larger than a bank. It may have affected enhanced mid-range parts with array sizes larger than 256 bytes. The issue has been resolved for all devices.

**Code jumps to wrong location (XC8-295)** If the assembler optimizer is enabled, assembly code that directly wrote to the program counter may have been abstracted which may have caused a jump to the wrong location and code failure. C code affected would produce a lookup table of some description, but it unlikely that C code would trigger this issue. Hand-



written assembly would only be affected if the option to optimize assembly source files was enabled.

**Duplicated SFRs (XC8-319)** Some SFR bit-field structures had duplicate entries in the device-specific header files and have been removed.

**Bit objects on baseline devices** Uninitialized global bit objects may not have been zeroed for baseline devices, and in some instances, the generated startup code may have corrupted other memory locations or caused the device to restart.

**Call graph inconsistencies** The call depth of some functions was not correctly indicated in the call graph shown in the assembly list file. The total amount of auto, parameter and temporary variable usage was also incorrectly displayed for some functions in the call graph.

**Wide bit-fields in header files (XC8-289)** Some header files were being generated with SFR bit-fields that were wider than a byte. This is not allowed by the compiler. Such definitions are no longer contained in the header files.

**Wrong external memory access (XC8-286)** The `--EMI` options was not correctly being processed and this may have meant that access to external memory may have been incorrect. Only several PIC18 devices have such memory.

**Error on assembly directives after including header file (XC8-285)** After including the `xc8.inc` header file into assembly code, some assembly directives, e.g. the `DS` directive, may have generated an error. This was due to SFR names conflicting with the directive's name. The header files will on longer use any SFR name that conflicts with a directive. This will mean that SFR names may not always match those listed in the device data sheet.

**Bad access at start of function (XC8-94)** The code at the beginning of function could have accessed the wrong address (bank) for a variable if the compiled stack was built up over multiple banks and `WREG` was used to pass a function argument.

**Incorrect RAM ranges with 12F1501 (XC8-274)** The RAM ranges associated with this device did not reserve the memory from 50-6F. Allocation of user-defined objects to this memory may have caused code failure.

**Bad results with 24-bit expressions (XC8-227)** The code generated for some arithmetic and bitwise operations involving 24-bit integers were missing some necessary bank selections which may have generated wrong results.

**Compiler crash with conditional operator (XC8-117)** Assigning a pointer the result of an expression using nested conditional statements could have caused the compiler to crash for PIC18 devices.

**Bad results with long arithmetic (XC8-241)** The results of some long arithmetic expressions may not be correctly assigned due to a bank selection bug.

**Build errors in MPLAB X IDE (XC8-101, XC8-104)** Source file paths that contained spaces were being written to the dependency files without the spaces escaped. This resulted in these files containing erroneous targets and dependancies which may have resulted in incorrect builds. In addition, the preprocessor would generating a dependency file for assem-

bly modules incorrectly assuming that the intermediate file to have a ".p1" extension and not ".obj" resulting in the same behavior.

**Crash with compiler-domain symbols (XC8-18)** User-define variables and functions should never start with an underscore character as such symbols are in the compiler's domain. Inappropriate use of these symbols in a program, however, was leading to a compiler crash. The crash no longer will occur; however, you should continue to avoid using symbols beginning with an underscore.

**MPLAB X IDE plugin** Previously the XC8 MPLAB IDE plugin overwrote the HI-TECH Universal Plugin such that the universal plugin no longer appeared in the toolsuite list. This is no longer the case. The XC8 v1.01 installer will install and reinstate both the XC8 and universal plugins so that they will both be selectable from the IDE.

**Bad if() code (XC8-58)** In some instances the assembler optimizer would incorrectly move `MOVLW` instructions which could cause some logical expressions (such as those used by if statements) to be incorrectly evaluated.

**Not honoring message disable (XC8-62)** When compiling for PIC10/12/16 targets the assembler was not honoring the `--MSGDISABLE` option. Thus, it was impossible to disable warning messages produced by this application. This issue did not affect other applications or any application when compiling for PIC18 targets.

**Bad call to subtype() Error (XC8-73)** In some instances where a function has a pointer type as its first parameter but the function is never called, a "bad call to typeSub()" error may occur.

**Incorrect optimizations involving carry bit (XC8-77)** The assembly optimizer may have incorrectly moved instructions that set the carry bit above other code that would subsequently clear carry before it was being used.

**Bad optimization of indirect access (XC8-95)** In some situations, expressions with the form `*ptr = *ptr op A;` may fail. In particular it is the optimization of assignment-operations when the destination is an indirect access which can lead to incorrect results.

**Bad right shift code (XC8-105)** In some instances for PIC18 targets, the code generated for right-shift a `signed long` operand would access the wrong file registers, giving an incorrect result.

**Memory reservation using --CODEOFFSET (XC8-230)** This option should have reserved memory in all linker classes associated with program memory. It was only reserving this memory from the `CODE` class but not for other classes that hold `const` objects. This was unlikely to cause issues since `const` objects are typically not allocated to low address; however, all classes are now adjusted.

**Badly optimized if() code (XC8-75)** The assembler optimizer may have procedurally abstracted code that erroneously contained return-style instructions. This may have caused code such as `if()` statements to be ignored and fail. This has now been corrected.

**Redundant MOVLP instructions (XC8-49)** Redundant `MOVLP` instructions were being produced for some call sequences for Enhanced mid-range devices.

## 6.9. Version 1.00

**Bogus warning on -B option (XC8-11)** If compiling under MPLAB v8, in some instances a warning indicating that the -B option was defunct was issued. This option is indeed defunct, but the compiler has been adjusted so that this is not produced when compiling under the IDE.

**Parser crash (PICC18-618)** If an unexpected attribute was used with function definitions, e.g. `__attribute__ ((const))`, the parser crashed instead of giving an error. This has now been corrected.

**Parser crash (PICC-684, PICC-688, PICC18-596, PICC18-607, PICC18-616, PICC18-619, PICC18-620, PICC18-621)** In some circumstances, the parser would crash when encountering illegal or unusual source code. This has been seen with code that accesses some structure members, passing malformed arguments to functions, or with non-prototyped (K&R) function definitions. Changes to the parser should prevent the application crashing.

**Bad code associated with negation (PICC-652)** In certain cases, negating a 16-bit integer may have overwritten WREG. This has been corrected.

**Crash on structure with no members (PICC-597)** If a structure was defined that had no members, the parser application crashed. This has been rectified.

**Arrays of structures in MPLAB not watchable (PICC-544, PICC18-593)** In some circumstances, the watch window in MPLAB IDE v8 would show elements of a structure array correctly. Changes have been made to the compiler output to correct this.

**Redirecting function using psect pragma (PICC-514)** There were instances where use of the `#pragma psect` would not appear to work as the name of the psect being redirected was changing as a result of psect merging by the assembler optimizer. A new system of identifying mergable and splittable psects was introduced, which will assist in reducing this problem.

**MPLAB IDE popup about source code using #include (PICC18-565, PICC18-566)** If you are using any of the printf family of functions, an MPLAB IDE popup may have appeared warning that "The project contains source files that use the #include directive from within a function to include source code". Although this would not have affected normal debugging operations in this particular instance, the trigger for message has been adjusted so that this message will no longer be produced.

**Zeroing of config bits (PICC18-600)** If you used the PIC18 pragma to program only the lower byte of a configuration location, the compiler may have zeroed the upper byte rather than use the default configuration value. Ideally, all configuration words should be specified in your programs or the `--RUNTIME` option to program the device with the default config words should be enabled. However, this zeroing of the upper byte will no longer occur.

**Undefined symbol with empty loops (PICC18-524)** The compiler can remove some condition code if the state of variables used in the controlling expressions are known. In some instances, where the true or false statements were an empty loop (e.g. `while`), the compiler

may have deleted a label that was still being referenced by other code. This would have produced an undefined symbol, which might look something like 19.

**Crash with undefined functions (PICC18-532)** If function that were not defined were assigned as the target of a function pointer, the compiler may have crashed. This crash has been fixed and now the linker will report the symbols as being undefined, as expected.

**Errors indicated in unused files (PICC-428)** When an error indicating a variable is too large is emitted, the name of the file that contained the variable definition may have indicated a source file that was not in the project, such as a library file.

**Assignment to structure ignored (PICC-433)** In situations where an assignment is made to a structure is followed by an assignment to a bitfield within that structure, the initial assignment may be removed. This would only occur in PRO mode. This has now been fixed and the compiler notes the distinction between the objects accessed.

**Compiler crash and old library modules (PICC-573)** The compiler may have crashed if some library modules were used from the SOURCES directory of the compiler. This directory no longer include files from non-OCG compilers, as they are not compatible to OCG compilers and will not compile.

**Undefined ?Fake symbol (PICC-589, PICC-581)** This error may have occurred for code that indirectly called a external function defined in assembly code or was part of another build. Only functions that returned a value in memory would be affected by this issue. The error is no longer produce, but you are required to define a symbol that represents the memory location where the return value will be stored. See the User's Guide on External Functions for more information.

**Linker crash with assembler optimizers (PICC-648)** If the assembler optimizers (psect merging) were enabled, in some situations the linker would crash if a psect was removed but was still referenced by a directive. This has been corrected and all assembly optimizations may be employed.

**Compiler crash with bad memory ranges (PICC-608)** If a memory range was specified using the --RAM option, or its equivalent in MPLAB IDE, and that range was excessively large, the compiler may have produced an assertion failure. In such situations, the compiler now prints a more informative error.

**Cromwell error with MCPxxxx targets (PICC-642)** If compiling for an MCP device, an error relating to the "prefix list" would have been triggered. This has been corrected and compilation can be performed for these devices.

**Cromwell crash (PICC-493)** Cromwell may have crashed if encountering information generated from static bit objects that are absolute.

**Crash with malformed warning pragma (PICC-610)** If the message number(s) were omitted from the #pragma warning disable directive, the compiler crashed. An error is now emitted if this situation is encountered.

- Read of write-only registers (PICC-658)** If an attempt was made to read a Baseline device write-only register, e.g. `TRIS`, the compiler would produce a can't generate code error message. A more specific message is now produced alerting you to the offending operation.
- Can't generate code (PICC-683, PICC-499)** The compiler was not able to generate code for some expressions involving logical or bitwise operation on `bit` objects. This has been corrected.
- Prototype for `eeeprom_write` (PICC-675)** The prototype for `eeeprom_write` incorrectly stated that this function returned a value. This was not correct and the prototype now indicates a return type of `void`.
- CLRWDWT appearing in `_delay` output (PICC-460)** For some delay values, the `_delay` in-line function for PIC18 targets only produced `CLRWDWT` instructions as part of the delay. This has been corrected and a `NOP` is used instead. For PIC18 targets, you have a choice of `_delay` or `_delaywdt` to implement in-line delays, which do not use and use, respectively, the `CLRWDWT` instruction as part of the delay.
- Optimization of volatile bits (PICC-606)** The compiler was not generating the appropriate information to prevent the assembler optimizer from optimizing access to volatile bit objects. Although the code would have been functionally correct, subsequent optimizations may have caused runtime failures. This correct information is now generated and volatile bit access will not be optimized unexpectedly.
- `vprintf` and `vsprintf` linker errors (PICC-524, PICC-619)** Trying to use either of these functions may have resulted in the undefined symbols `__doprint`, `_vprintf` or `_vsprintf`. These routines are now fully supported in the libraries and can be called.
- Upper bound of `mktime` (PICC18-126)** The `mktime` function had a upper limit of the year 2020; higher values would return incorrect results. This limit has now been extended to the year 2038.
- Bad call to subtype with `regsused` pragma (PICC18-392)** If using the `regsused` pragma for a function before the definition of that function, this error occurred. This has been corrected and the pragma can be used at any point in the source code.
- Looping around `allocGlobals` error (PICC-570)** This error may have occurred in some situations, particularly when `NULL` pointers were being assigned in the source code. This has been corrected.
- Read of wrong array element (PICC-542)** When reading a `const` array using a constant index, in some situations, the wrong element may be read. This bug did not affect array access using a variable or other expression as the index.
- Memory allocation** An improved memory allocation scheme is used when variables are qualified as being in a particular bank or near and the `--ADDRQUAL` option is set to require. This will reduce the likelihood of Can't find space errors from the linker.
- Code generator crash with undefined functions (PICC18-532)** If a function pointer was assigned the address of a function that is defined in external code, the code generator may

have crashed. External functions might include those defined in assembly source code. This only affect PIC18 targets.

**Can't generate code errors with nested structures (PICC-628)** This error may have occurred for code that accessed bit-fields within structures that themselves were members of other structures.

**No stack allocated to function error (PICC-611, PICC-485, PICC-416, PICC-637)** This error is now unlikely to be triggered by code. It was most likely to occur with complex expressions, particularly involving floating-point arithmetic.

**Can't generate code errors with short long types (PICC-632)** Some assignment operations on short long types, e.g. `|=`, `&=` and `*=` etc may have triggered a "can't generate code" error when compiling for baseline or mid-range parts. The ability to generate code for such expressions has been enhanced.

**Parser crash with bad identifiers (PICC-622)** The parser (`p1`) may have crashed if certain keywords were used as a variable identifier, e.g. if you were to try to define a variable with the name `eeeprom`. A crash may also have occurred if reserved keywords were used in place of variables in expressions. The crash has been corrected, but variable identifiers cannot be reserved keywords.

**Symbol defined more than once for in-line assembly (PICC-563)** If the `REPT` macro was specified in in-line assembly, the code generator was generating additional labels multiple times. This triggered an error indicating the symbol was defined more than once. This has been corrected and `REPT` can safely be used in in-line assembly code.

**RAM ranges for 16(L)F1507** The RAM ranges available when selecting this device extended further than the physical device implementation. This has been corrected.

## 7. Known Issues

The following are limitations in the compiler's operation. These may be general coding restrictions, or deviations from information contained in the user's manual. The bracketed label(s) in the title are that issue's identification in the tracking database. This may be of benefit if you need to contact support.

**ELF debugging issues** Not all aspects of the ELF/DWARF debugging file have been implemented. MPLAB XC8 version 1.30 implements DWARF version 3 which allows for improved debugging. Only MPLAB X IDE supports ELF, but you must ensure that you are using a version of this IDE that can process ELF files produced by the compiler. The following are some of the issues that may not work as expected with this release of the compiler.

- Unused variables will not be identified in the ELF file.

- Constant propagation optimizations may affect which variables are watchable in the IDE or the values that are indicated in the Watch window.
- In-line C functions will not be debuggable.
- Procedural abstraction will affect the operation of breakpoints.
- Nested pointers may not be dereferenced correctly in the watch window, hence the values in reported in the Watch window will therefore be erroneous.
- Variables located in external memory will not be displayed correctly in the Watch window.
- In the Watch window the *type* name (as opposed to the object's name) that appears for a anonymous structure or union typedef or an enumerated typedef will be ".".
- In the Watch window the *type* name displayed for an identifier that was declared using a typedef type will be the identifier's semantic type rather than its typedef type.

**Indirect function calls (XC8-1002)** For midrange and baseline devices, there is a limit on the number of functions that can be called indirectly via a pointer. Typically this will be about 120 functions, but this limit is dependent on where the functions are linked.

**Corruption of parameters (XC8-959)** For expressions involving more than one function call, an instance has been seen where the parameter to one function has been clobbered by parameters to the other call. This has only been observed in Standard or Free mode and for expressions similar to `char = long <= double;`. If you are unable to use PRO mode, assign the long expression to a temporary double temporary variable, then compare this with the other double expression.

**Reentrant encoding of main (XC8-937)** If `main()` indirectly calls a reentrant function, `main()` itself is encoded using a reentrant function model. This will not lead to code failure, but `main()` never needs to use the less efficient reentrant model. Future versions will address this issue.

**Redirecting bss variables** If the `#pragma psect` directive is used to redirect objects that normally reside in any of the `bss` psects, the runtime startup code will not be aware of this and will clear the memory that the variables would have ordinarily be allocated. At such an early stage, this should not affect program execution, but if all `bss` objects are redirected, an undefined symbol error will occur with PIC18 devices. Consider using the `__section()` specifier.

**No support for printf/scanf functions (XC8-425)** The `vsprintf` and `vprintf` functions, as well as all the `scanf` family of functions (`scanf`, `sscanf`, `vscanf`, etc.) are not supported in the compiler libraries. Previous attempts to use it would have resulted in undefined symbol errors. This function is now flagged as unsupported and its use will trigger an error to that effect. Example source code for some of these functions can be found in the compiler's `sources` directory. These examples have not been verified to work on all devices and should be used with caution. Consider modifying this code to suite your application.

**No support for strdup (XC8-939)** As dynamic memory allocation is not supported by the compiler, the `strdup()` function is also not supported.

**Installer execution** On both Mac OS X and Linux, it is necessary to run the installer as root or with superuser privileges (using `sudo`, for example). If the installer is started without superuser privileges on Mac OS X, it will exit and display an informative message. In the same situation on Linux, the installer will fail when it attempts to write to directories for which it does not have adequate rights. The messages displayed will relate to these access failures. For correct operation, run the installer via `sudo`, or as the root user, on these systems.

**PATH environment variable** On Linux systems, the installer, by default, updates the `PATH` environment variable to include paths to the new executables being installed. If the installer is run via `sudo`, the default action will update the `PATH` variable of the user executing the `sudo` command. If the installer is run by root, the installer will only update root's `PATH` variable, and not the `PATH` variables of ordinary users. If installing the compiler while logged in as root, a better choice is to update *all* user `PATH` variables. Alternatively, skip the step to update the `PATH` variable in the installer, and to update the `PATH` variables of users who will use the software, manually.

**C18 code compatibility** The C18 code compatibility feature is only a beta implementation. Legacy C18 projects may not compile, or compile with runtime errors when using XC8.

**PIC12F529T39A/T48A memory restrictions** The previous limitation which restricted memory to the first 4 RAM banks for user-defined variables has been lifted. Note, however, that the compiler will not allow you to define objects that span multiple banks on these devices.

**In-line delay values** The delay value specified with the in-line delay function (`_delay`) is limited to 179,200 on PIC18 devices. With PIC10/12/16 devices, this value may be up to 50,659,000.

**In-line delays** On PIC10/12/16 targets, the only in-line delay function implemented is `_delay`. This uses `NOP` instructions, when required, as part of the delay sequence. There is currently no equivalent version of this function that uses the `CLRWDT` instruction. The function, `_delaywdt` which is available for PIC18 targets, does use the `CLRWDT` instruction.

**Use of hardware multiply** The PIC18 hardware multiply instruction is not used for any 32-bit multiply operations. A library multiply routine is used for such operations. The hardware multiply instruction is used for 8- and 16-bit multiplication.

**Psect pragma and data psects** As described in the manual, the `#pragma psect` directive should not be used to move initialized variables that would normally be located in one of the 'data' psects. The initial values in program memory and space for the variables themselves in RAM must be built up in a strict order. Using this pragma will violate this assumption. Consider using the `__section()` specifier.

**In-line assembly and labels** Functions which are called from both main-line and interrupt code should not contain in-line assembly that defines assembly labels. Such labels will not be assigned the usual duplication prefix (`i1`, `i2` etc) and will result in multiply-defined symbol errors.



**Bank qualifiers** Only `bankx` qualifiers for data banks 0 through 3 are supported by the compiler. (These are enabled using the `--ADDRQUAL` option). Use absolute variables to place objects in other banks, if required.

**Memory Report for Absolute Variables** If the user defines absolute variables (variables placed at an absolute address via the `@` construct), and any of these variables overlap other variables in memory, the compiler will also count overlapping variables when it comes to reporting on memory usage. That is, if two, byte-sized variables are located at the same address, the report will indicate 2 bytes being used, rather than 1.

**Switch strategies** There is only one possible switch strategy currently available for PIC18 devices. It uses the `space` switch type. New strategies will be introduced in future compiler versions so that PIC18 devices have similar options to the baseline/mid-range devices.

**Copying compiler header files** The header files shipped with the compiler are specific to that compiler version. Future compiler versions may ship with modified header files. If you copy compiler header files into your project, particularly if you modify these files, be aware that they may not be compatible with future versions of the compiler.

**SFRs for 12LF1840T48A** The following are inconsistent in this device's header file.

- DACNSS bit not defined in DACCON0 register (118h)
- SSP1M0, SSP1M1, SSP1M2, SSP1M3, SSPEN, SSP1OV defined as SSPM0, SSPM1, SSPM2, SSPM3, SSPEN, SSPOV in SSP1CON1 register (215h)

**SFRs for 16(L)F1507** The following are inconsistent in this device's header file.

- In NCO1ACCU (49Ah) NCO1ACC<23:20> not defined
- CWG1ASD register (695h) defined as CWG1CON2

**Initialization of eeprom arrays** Initialization of large arrays that are qualified `eeprom` may fail on enhanced mid-range devices. When the size of these arrays exceeds the size of the free space in each GP RAM bank, the compiler tries to allocate the array to the linear RAM space, not EEPROM. Small arrays are not affected by this issue.

**Initialization of auto structures** Structures which are `auto` cannot be initialized. Simply define the structure and assign values separately.

**EEPROM variable limitations** There are some limitations to using variables qualified as `eeprom`, aside from them being not supported at all on PIC18 devices. Avoid using these variables in complicated expressions and remember that code which accesses such objects is complex and very slow.

**Size of EEPROM arrays** Arrays that qualified as `eeprom` and which are initialized may not have all initial values written to the EEPROM.

**Absolute initialized variables** Variables which are absolute and which are not `const` cannot be initialized. The following example will not generate an error, but will not work as expected. Define the variable as absolute and initialize it in main-line code.

```
unsigned int varname @ 0x0200=0x40; // will not work as expected
```

**Stack overflow** When the managed stack is used (the `stackcall` suboption to the `--RUNTIME` option is enabled) in some situations the stack may overflow leading to code failure. With this option enabled, if a function call would normally overflow the stack, the compiler will automatically swap to using a lookup table method of calling the function to avoid the overflow. However, if these functions are indirect function calls (made via a pointer) the compiler will actually encode them using a regular call instruction and when these calls return, the stack will overflow. The managed stack works as expected for all direct function calls, and for all indirect calls that do not exceed the stack depth.

**Main function size** If the function `main` produces assembly code that is 0x1FF words long, this cannot be placed in the program memory and a "can't find space" error message is produced. Increasing or decreasing the size of the function will allow it to be positioned correctly and the error will not be displayed. This only affects Baseline PIC devices.

**Functions called from in-line assembly** The code generator will not be able to identify a C function called only from in-line assembly code if the definition for that C function is placed before the assembly call instruction in the source file. Placing the function definition after the call is acceptable. If the function cannot be identified, no code will be generated for the function and the linker will issue undefined symbol errors.

**Can't Generate Code messages** When compiling for baseline devices, some complex expressions may cause compile-time errors (712) Can't generate code for this expression. The expressions should be simplified to work around this. This may require the use of additional variables to store intermediate results. This is most likely with long integer or floating-point arithmetic and particularly those devices with less than 4 bytes of common memory available.

**option and tris** For baseline devices, the `OPTION` and `TRIS` registers must be written as a byte. Writing individual bits is not supported.

**PIC17 support** PIC 17 devices (for example, 17C756) is not supported by this compiler.

**fast32 floats** The option to select the fast 32-bit float or double library for PIC17 devices that was included in the PICC STD compiler is no longer available.

**Configuration words (PIC18 parts only)** The new device support introduced in PICC18 v9.80 will not automatically program the default values into the configuration words when no value is specified. If your project does not program all configuration words explicitly, select the option "Program the device with default config words" in the Linker tab.

**Specifying configuration words on PIC10/12/16 devices** The `__PROG_CONFIG()` and `__CONFIG()` macros can be used to specify the configuration words on PIC10/12/16 devices as well as PIC18 devices. The `__PROG_CONFIG()` macro must use a literal constant argument; you cannot use the configuration setting symbols with this macro. The `__CONFIG()` macro must only use the predefined configuration setting symbols and you may not use a literal value with this macro.

**rfPIC12 parts** To use the rfPIC12 parts, for example the rfPIC12C509AF, you will need to specify to the compiler a part name in a format similar to RF509AF, for example. You can also

use an alias like 12C509AF, for example. The full part name is also not appropriate when compiling from MPLAB IDE.

**MPLAB IDE integration** If Compiler is to be used from MPLAB IDE, then you must install MPLAB IDE prior to installing Compiler.

## 8. Microchip Errata

For 8-bit PIC devices, this release of the XC8 compiler recognizes the published silicon errata issues listed in the table below. Some of these issues have been corrected and no longer apply in recent silicon revisions. Refer to Microchip's device errata documents for details on which issues are still pertinent for your silicon revision. The compiler's chip configuration file records which issues are applicable to each device. Specific errata workarounds can be selectively enabled or disabled via the driver's `--ERRATA` command line option. All these errata are PIC18 specific, except for the CLOCKS<sub>W</sub> errata, which applies to enhanced mid-range devices.

Name	Description	Workaround details
4000	Execution of some flow control operations may yield unexpected results when instructions vector code execution across the 4000h address boundary.	Each block of program code is not allowed to grow over the 4000h address boundary. Additional NOP instructions are inserted at prescribed locations.
FASTINTS	If a high-priority interrupt occurs during a two-cycle instruction which modifies WREG, BSR or STATUS, the fast- interrupt return mechanism (via shadow registers) will restore the value held by the register before the instruction.	Additional code reloads the shadow registers with the correct values of WREG, STATUS and BSR.
LFSR	Using the LFSR instruction to load a value into a specified FSR register may also corrupt a RAM location.	The compiler will load FSR registers without using the LFSR instruction.

Name	Description	Workaround details
MINUS40	Table read operations above the user program space (>1FFFFFFh) may yield erroneous results at the extreme low end of the device's rated temperature range (-40o C).	Affected library sources employ additional NOP instructions at pre- scribed locations.
RESET	A GOTO instruction placed at the reset vector may not execute.	Additional NOP instruction inserted at reset vector if following instruction is GOTO
BSR15	Peripheral flags may be erroneously affected if the BSR register holds the value 15, and an instruction is executed that holds the value C9h in its 8 least significant bits.	Compiler avoids generating MOVLB 15 instructions. A warning is issued if this instruction is detected.
DAW	The DAW instruction may improperly clear the CARRY bit (STATUS<0>) when executed.	The compiler is not affected by this issue.
EEDATARD	When reading EEPROM, the contents of the EEDATA register may become corrupted in the second instruction cycle after setting the RD bit (EECON1<0>).	The EEPROM_READ macro read EEDATA immediately.

Name	Description	Workaround details
EEADR	The result returned from an EEPROM read operation can be corrupted if the RD bit is set immediately following the loading of the EEADR register.	The compiler is not affected by this issue.
EE_LVD	Writes to EEPROM memory may not succeed if the internal voltage reference is not set.	No workaround applied
FL_LVD	Writes to program memory may not succeed if the internal voltage reference is not set.	No workaround applied
TBLWTINT	If a peripheral interrupt occurs during a TBLWT operation, data can be corrupted.	Library routine flash_write() will temporarily disable all applicable interrupt-enable bits before execution of a TBLWT instruction.
FW4000	Self write operations initiated from and acting upon a range within the same side of the 4000h boundary may fail based on sequences of instructions executed following the write.	No workaround applied
RESETRAM	Data in a RAM location can become corrupted if an asynchronous reset (e.g. WDT, MCLR event) occurs during a write operation to that location.	A warning will be issued if the length nvram psect is greater than zero bytes (persistent variables populate this psect).

Name	Description	Workaround details
FETCH	Instruction fetches can become corrupted after certain code sequences.	A NOP instruction is added after TBLRD instructions, returns, destinations of calls and gotos, and ISR vector addresses.
CLOCKSW	An instruction may be corrupted when switching from INTOSC to an external clock source. (Enhanced mid-range devices)	Switch to high-power mode immediately after reset.