

POLITECNICO
MILANO 1863

Production 4.0

Advanced Manufacturing Processes





Table of contents

Table of contents	- 1 -
A. Before you start	- 2 -
1. Gcode preparation:	- 2 -
2. Materials	- 6 -
a. PCB board:	- 6 -
b. Painting:	- 6 -
c. Wooden Socket:	- 7 -
3. Focus setup	- 8 -
B. Single Circuit Marking	- 12 -
1. Material mounting	- 12 -
2. Code input and control:	- 17 -
a. Gcode: speeds	- 17 -
b. Gcode: hatching distance	- 19 -
c. Luban: laser power, fan, run boundary and door detection	- 20 -
d. Material thickness and Start	- 21 -
3. Marking	- 23 -
4. Job End	- 24 -
C. Multiple Circuit Marking	- 25 -
1. Gcode nesting	- 25 -
2. Material mounting	- 26 -
3. Code input and control	- 26 -
4. Marking	- 26 -
5. Job End	- 26 -
Troubleshooting	- 27 -


Luban Version 4.1.3

A. Before you start


1. Gcode preparation:




1 If you open Luban for the first time, make sure you have selected the right machine (Snapmaker 2.0 A250)




2 Go to “Get Started” section of Luban, and select “Laser”




3 Select “3-axis” in the laser menu




- 4 Make sure that the settings of the design space are the same as those shown in the figure




- 5 Click this button



- 6 Now select the DFX file you want to import in Luban.




7 Click this button




8 Now add the text.
Select font, dimension
and position



**Don't change size of
the circuit!**




9 Select the text box and
the circuit. Select
"Process" and then
"Create Toolpath"




- 10 **Jog Speed** should be as high as possible while numerical values of **Work Speed, Number of Passes, Z Step** and **Laser Power** come from Matlab simulations



Method must be “On the Path”!



- 11 Select “*Generate G-Code and Preview*”



- 12 In the Preview window you can see the final result. If it is correct select “*export*” and then “*Export G-Code to file*” to save the the final G-Code.

2. Materials

a. PCB board:

The boards have the following characteristics:


- Core material: FR4
- Single or dual sided copper clad
- 100 x 70 x 1.5 mm



b. Painting:

The following colors are allowed:

- a) Black
- b) White
- c) Red
- d) Blue



Tip: Avoid using an oil-based paint as it will make the laser stripping process worse.

During the painting job, we suggest to:

- Clean the copper surface before painting
- Make sure to distribute paint equally
- Avoid touching board surface with hands if the paint is not dry
- Let the board dry for at least 2 hours before machining




NO




YES

c. Wooden Socket:


The use of the socket is not strictly necessary but facilitates the carrying out of multiple operations. Its use will be described in detail in the paragraph “Material mounting”.




3. Focus setup




Focal point is the point where laser concentration reaches its maximum. It is calculated from the testing material surface (see the picture). We should set it properly to take the most out of laser power. We'll explain how to set the laser height H in the following paragraphs




- 1 Follow the Snapmaker Quick Start Guide in order to mount the laser head, **with the wooden working area**




- 2 Turn on the machine, and enter the “Settings” menu




- 3 Select “Laser” menu



- 4 Make sure the auto focus is off



- 5 Follow the Snapmaker Quick Start Guide in order to set the laser focus manually



- 6 In the same menu of point 3, select “Adjust Laser Height”




- 7 In this window you can see the value of the effective laser height. If you already know it you can set it without doing the procedure explained before


B. Single Circuit Marking

The following section describes the procedure to laser engrave a single circuit in the center of a board.

1. Material mounting




- 1 Follow the Snapmaker Quick Start Guide in order to mount the laser head, with the wooden working area




- 2 Fix the Wooden Socket to the working surface, using two M4x30 screws. Make sure the UP arrow pointing outwards from you




If you use screws longer than 30 mm, make sure that the working area and the laser head move without hitting the screws



3 Open Luban, and select “Workspace”




4 Select “Wi-Fi” as connection method



- 5 Click the refresh button and than “connect” to Idra.4.0



The printer and the PC with Luban must be connected to the same network



- 6 Set the power laser to 5%, and click its refresh button. Than set the “Laser Power” on.

Make sure the door detection is on.



Control			
Axis	Machine Coordinates	Work Coordinates	Action
X	118.601 mm	-7.399 mm	X-
Y	126.000 mm	88.000 mm	Y-
Z	58.500 mm	31.000 mm	Z-

Home
Jog Speed 30...

Y+

X-

Y-

X/Y

X+

Z-

Z+

Z

Run Boundary

Go To Work Origin

Set Work Origin

XYZ Axis Offset

10

1

0.1

0.05

10

+

-

7

Using the navigation controls match the laser point with the diagonals' intersections

After that set the "Laser Power" flag off

Connection

Idra4.0 (A250)

1.6W Laser

Disconnect

Console

```

Welcome to the makers' world!
Supported commands:
help | h | H : Help Information
clear: Clear Console
v | V : Version Information
g | G : G-Command List
m | M : M-Command List

snapmaker-luban 4.1.2
Connected via Wi-Fi
G54
ok
M500
echo:Settings Stored (1064 bytes; crc
Send Command

```

Laser

Laser Power

0 100 0/100 %

Edit Macro

Macro Name

Origin Dima1 Laser

Macro Commands

G53
G0 X119 Y126

Repeat

1

Delete Cancel Save

Enclosure

LED Strips

Exhaust Fan

Door Detection

Control

Axis	Machine Coordinates	Work Coordinates	Action
X	119.000 mm	0.000 mm	X-
Y	126.000 mm	0.000 mm	Y-
Z	124.899 mm	0.000 mm	Z-

Home
Jog Speed 30...

Y+

X-

Y-

X/Y

X+

Z-

Z+

Z

Run Boundary

Go To Work Origin

Set Work Origin

XYZ Axis Offset

10

1

0.1

0.05

11

+

-

Macro

+


- ▶ M1006 Toolhead Status
- ▶ M1007 Origin Info
- ▶ Origin Dima1 CNC
- ▶ Origin Dima1 Laser
- ▶ Origin Dima5 Laser

8

Create the macro to save the coordinates just found.

Click the "+" button, and copy the G53 and G0 commands with the X and Y coordinates.

Run this macro, click "set work origin", and then click "go to work origin". Do this every time you run boundary or launch the marking process.




9

Insert the board inside the socket. Make sure that the top side edge of the board touches the top side edge of the socket


2. Code input and control:

After we have exported our gcode it is time to make final check before launching the process.

a. Gcode: speeds



Click on the exported gcode with the right button of the mouse and chose "Open with".



Select Notepad or any other text editor that you usually use

```
File Edit Format View Help
;Header Start
;header_type: laser
;renderMethod: line
;file_total_lines: 7688
;estimated_time(s): 1647.364
;is_rotate: false
;diameter: 40
;max_x(mm): 9.5
;max_y(mm): 21.754
;max_z(mm): 0
;max_b(mm): 0
;min_x(mm): -9.5
;min_y(mm): -18
;min_b(mm): 0
;min_z(mm): 0
;work_speed(mm/minute): 800
;jog_speed(mm/minute): 3000
;power(%): 0
;thumbnail: data:image/png;base64,iVBORw0KGgoAAAANSUhl
```

Now you should see the set of instructions that machine is going to execute.

You can see how much time (in seconds) marking take in "estimated_time(s)" row.

You can see the **work_speed** (speed of the laser head while it strips) and **jog_speed** (speed while it is not stripping).

Don't pay attention on the power row since it will be overwritten inside luban

Scroll down until appears the first row without semicolon.


a. Jog Speed & Work Speed

```
; Laser multi-pass, pass 1 with Z = 0
; G-code for laser engraving
; Generated by Snapmaker Luban
; G-code START <<<
G90
G21
M106 P0 S255
G0 F3000 ← Jog Speed
G1 F800 ← Work Speed
G0 X9.50 Y-18.00
M3
```

Make sure Jog Speed & Work Speed are correct and if not, you have two options

- **Safe Option:** Create new gcode from the start (from .dwg file)
- **Risky Option:** Manually rewriting those commands for each pass of your circuit

Click Ctrl + F and type in “Header Start”, choose Direction: Down and click “Find Next”



This way you will iterate through each pass of your circuit and you should pay attention to correct G0 F (Jog Speed) and G1 F (Work Speed) in each pass.

Just manually change the number inside the row

```
;Header Start
;renderMethod: line
;Header End

; Laser multi-pass, pass 1 with Z = 0
; G-code for laser engraving
; Generated by Snapmaker Luban
; G-code START <<<
G90
G21
M106 P0 S255
G0 F3000 ←
G1 F800 ←
G0 X9.50 Y-18.00
M3
```

b. Gcode: hatching distance

Find the first row without semicolon; and look at the code after it

```
; Laser multi-pass, pass 1 with Z = 0
; G-code for laser engraving
; Generated by Snapmaker Luban
; G-code START <<<
G90
G21
M106 P0 S255
G0 F3000
G1 F800
G0 X9.50 Y-18.00
M3
G1 X9.50 Y18.00
G1 X-9.50 Y18.00
G1 X-9.50 Y-18.00
G1 X9.50 Y-18.00
M5
G0 X-4.37 Y0.50
M3
G1 X-6.25 Y0.50
M5
G0 X-9.50 Y17.89
M3
G1 X9.50 Y17.89 ←
M5
G0 X-9.50 Y17.74 ←
M3
G1 X9.50 Y17.74
M5
G0 X-9.50 Y17.59
M3
G1 X9.50 Y17.59
M5
```


Find some two consecutive rows (starting either with G0 or G1) and decreasing Y coordinates.
The difference between Y coordinates is hatching distance

In our example $H = 17.89\text{mm} - 17.74\text{mm} = 0.15\text{mm}$


Make sure Hatching distance is correct and if not, you have only 1 option:

Control hatching of your .dxf file in Autocad and create new gcode from the start


c. Luban: laser power, fan, run boundary and door detection




Click + G-code files and open the gcode that you have prepared (make sure it has .nc extension)



Open prepared gcode.




Control that LED Strips, Exhaust Fan and Door Detection are always on




Execute macro that you created in step B.3 then click Set Work Origin and then click “Run boundary” to verify where your circuit will be printed


d. Material thickness and Start




Material Thickness should be equal to the height of material that you put on the work surface (in our case it is the height of the wooden socket)



To set material thickness, click “Start on luban”




The window will pop up where you will be able to set up material thickness. Don't forget to choose Auto Mode




Right after that turn on Laser Power to 100 % and click arrow button

3. Marking



You can track the engraving progress in the following window




Make sure to follow the safety rules in place.

4. Job End



We recommend cleaning the circuit boards with a cloth, do not apply too much force, do not use liquids such as alcohol or water. Enjoy your circuits




Please leave the working space clean.



C. Multiple Circuit Marking

The purpose of this section is to illustrate how to laser stripping a board with multiple circuits, joining n single files, in a single .nc file containing n circuits. To illustrate the procedure, we will refer to the example of joining 4 circuits, but the method can be easily extended to cases where $n > 4$.

1. Gcode nesting



- 1 You can estimate the position of the circuits (purple) relative to board (orange).

You can find the midpoint of each circuit in the following way.

- $C_1(A, B)$
- $C_2(-A, B)$
- $C_3(-A, -B)$
- $C_4(A, -B)$

A & B should be obtained by trial and error.

```

*Test.nc - Notepad
File Edit Format View Help

;#####

;Circuit 1
G92 X-(A) Y-(B)

;Paste here all Circuit 1 Gcode

;#####

;Circuit 2
G92 X(2A) Y0

;Paste here all Circuit 2 Gcode

;#####

;Circuit 3
G92 X0 Y(2B)

;Paste here all Circuit 3 Gcode

;#####

;Circuit 4
G92 X-(2A) Y0

;Paste here all Circuit 4 Gcode


```

- 2 Now you can create a new .nc file, with the following structure.

We use the command **G92** to shift the work origin in the center of each circuit before engraving.

After the **G92** command you need to paste all the contents of the file related to the first circuit. Before starting the next circuit, you need to shift the previous origin to the new position.

This procedure must be repeated for all the 4 circuits. At the end, save and close the final .nc file.



- 3 Now you can import the final .nc file in the workspace preview, and check if all the circuits are in the correct position and fits inside the board perimeter.
If not, return to the point 2, change the A and B values, and check again in the workspace preview if the circuits position are correct.

Repeat this trial and error procedure until the result is correct.



Luban up to version 4.1.3 it is affected by an alleged bug: until the insertion of three circuits the procedure described above works fine. However, starting from the fourth circuit, the position of the centers no longer follows this logic, therefore starting from the fourth circuit it must be determined by trial and error.

2. Material mounting

Same procedure described in paragraph B.1.

3. Code input and control

Same procedure described in paragraph B.2.

4. Marking

Same procedure described in paragraph B.3.

5. Job End

Same procedure described in paragraph B.4.

D. Troubleshooting

Problem	Solutinons
Stripping is ineffective	<ul style="list-style-type: none">- Reduce hatching distance- Raise Laser Power- Slow your work speed down- Raise number of passes- Check laser focus
Process is too slow	<ul style="list-style-type: none">- Check that the work speed is set to the correct value- Raise jog speed- Raise hatching distance- time of process is quality tradeoff
Macro does not work	Make sure there's no break line between G0 and X Y coordinates

If you find any