

Pump Vibration Service Report

****Service Date:**** November 15, 2023

****Service Technician:**** John Smith

****Customer Name:**** XYZ Manufacturing Inc.

****Customer Address:**** 123 Main Street, Anytown, USA

****Contact Information:**** (555) 555-5555, john.smith@email.com

****Pump Information:****

- ****Pump Type:**** Centrifugal Pump v 10

- ****Pump Serial Number:**** PMP-123456

- ****Pump Location:**** Pump Room, Building A, XYZ Manufacturing Inc.

Service Details:

1. Initial Assessment:

Upon arrival at the customer's facility, a comprehensive assessment of the pump with vibration problems was conducted to determine the root cause of the issue. The following observations were made:

- The pump, identified as a Centrifugal Pump, was located in the Pump Room in Building A and was accessible for inspection.
- The pump's serial number PMP-123456 was verified.
- Visual inspection revealed excessive vibration, which was suspected to be caused by issues in the suction piping.
- The suction piping insulation was found to be improperly installed and was contributing to the vibration problem.

2. Vibration Analysis:

A vibration analysis was performed to quantify and diagnose the pump's vibration issue. The analysis confirmed that the vibration was primarily caused by resonance due to the suction piping insulation. The following measurements were taken:

- ****Vibration Measurements:**** Vibration sensors were used to measure the pump's vibration levels, which were found to be outside of acceptable ranges.
- ****Frequency Analysis:**** Frequency analysis indicated that the vibration was consistent with the system's natural frequency due to the insulation issue.

3. Corrective Actions:

To address the root cause of the vibration problem caused by the suction piping insulation, the following corrective actions were taken:

- ****Suction Piping Insulation Adjustment:**** The improperly installed insulation was corrected to eliminate the resonance issue. Proper insulation installation was carried out to minimize vibrations.

4. Equipment Calibration and Testing:

After correcting the insulation issue, the pump was recalibrated to ensure it was properly aligned and functioning as intended. The following tests were conducted:

- ****Vibration Reassessment:**** Vibration measurements were taken again to confirm that the vibration levels had been reduced to acceptable levels.
- ****Functional Test:**** The pump was operated to verify that the vibration issue had been resolved, and the pump was functioning correctly.

5. Documentation:

All service and repair activities were documented, including photographs, vibration analysis data, calibration records, and maintenance records. This documentation will be provided to the customer for their records.

6. Customer Feedback and Approval:

The customer was informed of the service results and provided with the opportunity to inspect the pump and verify its operation. The customer expressed satisfaction with the service provided, and approval was obtained.

7. Recommendations:

The following recommendations were made to the customer based on the assessment and service:

- Regular monitoring of vibration levels to detect any future issues at an early stage.
- Periodic inspection of the insulation system to ensure it remains properly installed and doesn't contribute to vibration problems.

8. Conclusion:

The pump's vibration problem, caused by suction piping insulation issues, was successfully resolved. The customer was satisfied with the service, and all documentation was updated to reflect the service and the customer's approval.

10. Service Technician Signature:

Technician Signature: John Smith
Date: November 15, 2023