


HOSTED BY



ELSEVIER

Contents lists available at ScienceDirect

ScienceDirect

journal homepage: www.jcvaonline.com

Inappropriate Implantable Cardioverter-Defibrillator Therapy During Surgery: An Important and Preventable Complication



Marc A. Rozner, PhD, MD^{*,†}, Edward A. Kahl, MD[‡],
Peter M. Schulman, MD[‡]

^{*}Department of Anesthesiology and Perioperative Medicine, University of Texas MD Anderson Cancer Center, Houston, TX

[†]Department of Cardiology, University of Texas MD Anderson Cancer Center, Houston, TX

[‡]Department of Anesthesiology and Perioperative Medicine, Oregon Health and Science University, Portland, OR

Key Words: implantable cardioverter-defibrillator; cardiovascular implantable electronic device; electromagnetic interference; patient injury

MOUNTING EVIDENCE suggests that inappropriate high-energy therapy from an implantable cardioverter-defibrillator (ICD), whether antitachycardia pacing (ATP)¹ or shock,^{2–4} causes myocardial injury (eg, troponin release or ST-segment changes consistent with injury currents) and increases mortality. In the hospital environment, electromagnetic interference (EMI), which most commonly results from intraoperative monopolar electrosurgery, can precipitate inappropriate ICD therapy, suggesting that failure to prevent or mitigate EMI could increase the risk of patient injury.

This report presents 3 cases from different institutions in which failure to adhere to all recommended precautions from the American Society of Anesthesiologists (ASA)⁵ or Heart Rhythm Society (HRS)⁶ regarding the perioperative management of ICDs resulted in inappropriate ICD therapy during surgery.

To the authors' knowledge, the frequency of inappropriate high-energy therapy from an ICD during surgery remains unknown, and this problem rarely has been reported in the literature. Because the use of cardiovascular implantable electronic devices (CIEDs) continues to increase and these patients are presenting for surgery and other interventional procedures with increasing frequency, routine postoperative ICD checks are not always performed, and no rule from the

Joint Commission or other regulatory agency mandates reporting such events. It is conceivable that inappropriate ICD therapy during surgery constitutes an important and largely preventable patient safety issue that is underrecognized and underreported.⁷

Because these cases were single events, retrospectively reviewed, and without aggregated data, the authors' institutional review board determined that specific written approval for publication was not required.

Case Presentations

Case 1

An 84-year-old man with nasopharyngeal carcinoma, ischemic cardiomyopathy (ejection fraction < 20%), and a Boston Scientific (Natick, MA) E110 dual-chamber ICD, presented for preradiation assessment. His ICD examination revealed the following programmed parameters; mode: VVE-DDDR; lower pacing rate limit: 60 beats/min; upper pacing tracking rate: 130 beats/min; upper pacing sensor rate: 130 beats/min; and ATP or shock rate: > 160 beats/min.

The event log and stored electrogram (Fig 1) demonstrated delivery of inappropriate ATP resulting from EMI during endoscopic sinus surgery at a community hospital. Although preoperative notes from both the surgeon and anesthesiologist acknowledged the ICD, the hospital record contained no discussion of device parameters, plans to mitigate EMI, or recognition that EMI occurred. There was no mention of device reprogramming or magnet application. Operating room

Address reprint requests to Peter M. Schulman, MD, Department of Anesthesiology and Perioperative Medicine, Oregon Health and Science University, 3181 SW Sam Jackson Park Road, Mail Code KPV – 5A, Portland, OR 97239.

E-mail addresses: schulman@ohsu.edu,
peterschulman@gmail.com (P.M. Schulman).

<http://dx.doi.org/10.1053/j.jcva.2016.11.036>

1053-0770/© 2017 Elsevier Inc. All rights reserved.




Fig 2. Electromagnetic interference (EMI), sensed by the implantable cardioverter-defibrillator (ICD) as ventricular fibrillation, instigating a 34-joule shock. The ICD treatment record shows an aborted charge followed by another round of EMI leading to a shock. Recordings (top to bottom) are atrial electrogram, ventricular electrogram, markers (reflecting the ICD decision tree), ventricular timing data (milliseconds), and elapsed time (in seconds). Above the marker line are vertical hash marks identifying the atrial signal (atrial fibrillation), and the small numbers represent the percent match to normal QRS morphology. The symbols immediately below the marker line show the ventricular classification (see the following). The paper speed was 25 mm/sec. *** from time 0 to 4.6 seconds reflects ICD charging due to a ventricular fibrillation (VF) detection with ICD activation that did not deliver a shock because the EMI transiently stopped. Resumption of the EMI at 9.6 seconds led to a second charge at 12.5 seconds (red arrow 1). The charge cycle finished at 16.5 seconds (red arrow 2). The EMI again ended, but a short burst at 17.6 seconds during the rhythm reconfirm period caused the ICD to deliver a shock (red arrow 3). -, ventricular event that could not be characterized because of discrepancy between the average calculated rate over the last 4 events and the short interval from the previous V sense (however, the measured V-V interval is used in the calculation of average V rate); F, a ventricular event falling into the VF zone by timing; (HV), delivery of a shock; "Return To Sinus," the end of the episode; VS, ventricular sense; VP, ventricular pace.

Case 3

A 62-year-old man with a Medtronic (Minneapolis, MN) D224TRK biventricular ICD and suspected ICD pocket infection presented for pocket exploration, debridement, and repositioning of the ICD to a subpectoral location. The ICD was not examined or reprogrammed preoperatively. No magnet was placed. Instead, short bursts of monopolar electrosurgery were planned to mitigate the risk of EMI and prevent unwanted pacing inhibition and ICD firing. In the operating room, a "whole-body electrode" (Megadyne Mega Soft dual-cord patient return electrode system [Draper, UT]) was placed. Soon after the surgical incision, an ICD shock caused apparent patient movement. The patient remained hemodynamically stable in an A-V sequentially paced rhythm. The surgical care team then reprogrammed the ICD to disable its high-energy therapy. At the conclusion of the procedure, ICD high-energy therapy was restored, the patient's airway was extubated, and the patient was taken to the recovery room in stable condition. Postoperative examination revealed the following programmed parameters (mode: VVE-DDDRV): Lower pacing rate limit: 60 beats/min; upper pacing tracking rate: 120 beats/min; upper pacing sensor rate: 120 beats/min; and ATP or shock rate > 182 beats/min.

The stored shock electrogram (Fig 3) shows a "ventricular fibrillation (VF)" event at the 6th short burst of EMI. The additional short bursts of EMI during capacitor charging and the VF reconfirm period led to the inappropriate shock.

Discussion

This article presents three cases, from different institutions, that involved ICDs from each of the 3 major US manufacturers in which failure to adhere to all precautions resulted in inappropriate intraoperative ICD therapy.

The failure to take all steps necessary to prevent inappropriate intraoperative ICD therapy likely was the result of several "systems" issues. These issues included the following: (1) the relative rarity of these cases, (2) the incorrect assumption that inappropriate ICD therapy is not of significant concern,⁹ (3) failure to understand that location of the electrosurgical dispersive electrode is an important consideration when caring for a surgical patient with an ICD,^{5,6,10} and (4) confusion that still exists surrounding the perioperative care of these patients.¹¹⁻¹³

Some of the confusion surrounding the care of patients with these devices likely stems from published recommendations that might be construed as incongruent. For example, the HRS



Fig 3. Short bursts of monopolar electrosurgery do not protect against implantable cardioverter-defibrillator (ICD) shocks. Short bursts of electromagnetic interference (EMI) during surgery resulting from monopolar electrosurgery were sensed by the ICD as atrial fibrillation, ventricular tachycardia, and ventricular fibrillation. At the sixth “burst” of EMI (red arrow 1), the ICD declared a “VF” event and began charging, likely due to the relative periods of EMI on and EMI off, which did not allow the VT/VF counters to completely clear. About 3.9 seconds later, the ICD completed the charge (“CE,” red arrow 2) and began the “reconfirm period.” The EMI during the charge cycle and again 2.3 seconds after CE led to the delivery of a 34.8-joule shock (“CD,” red arrow 3). Recordings (top to bottom) are atrial electrogram, right ventricular electrogram, and markers (atrial markers above the line, ventricular markers below the line) reflecting the ICD decision tree. The numbers reflect the time between 2 adjacent events in milliseconds. The paper speed was 25 mm/sec. Ab, atrial event in the “blanking period” and thus completely ignored by the ICD; AP, atrial pace; AR, atrial event sensed during the postventricular refractory period and therefore not tracked into the ventricle or any atrial event occurring after an appropriately sensed atrial event but before any ventricular event (these events are counted for mode switch determination); AS, atrial sense; BV, biventricular (ie, both right and left ventricular) pace; CD, delivery of high-energy (shock) therapy; CE, end of the ICD charge cycle and beginning of the reconfirm period; FD, tachydysrhythmia episode declaration in the VF zone—initiation of an ICD charge cycle; FS, ventricular sensed event occurring in the VF timeframe; MS, entry into or out of the “mode switch” mode—during MS, the ICD acts as if the pacing mode is DDI rather than DDD; TS, ventricular sensed event occurring in the VT timeframe; VP, ventricular pace; VR, any ventricular event occurring in a nonphysiologic window and that does not inhibit the next expected ventricular pace; VR-VP, a ventricular-sensed event occurring in the safety or crosstalk window that results in a VP approximately 60 milliseconds later; VS, ventricular sense.

Consensus Statement⁶ states that ICD reprogramming may be unnecessary when monopolar electrosurgery only will be used inferior to the umbilicus; however, the ASA Practice Advisory⁵ recommends suspending antitachycardia therapy whenever EMI is “likely” but does not specify when EMI might be “likely” or “unlikely” to occur. Furthermore, even though the ASA Practice Advisory states that all patients ideally should undergo a comprehensive device evaluation before elective surgery, the HRS Consensus Statement states that a preoperative ICD check within 6 months before scheduled surgery generally is sufficient. No statement addresses the use of the “whole-body” dispersive electrode (which was used in case 3), and no testing of this device in a patient with a CIED has been published.

Because ICD therapy rarely causes immediate recognizable harm, practitioners may not appreciate fully the adverse consequences. ICD shocks can injure the myocardium,¹ cause troponin release,² induce ventricular tachycardia,¹⁴ and shorten lives.^{7,15,16} Moreover, even inappropriate ATP can injure myocardium¹ and increase mortality. Inappropriate ATP delivered during atrial fibrillation with rapid ventricular response has induced ventricular tachycardia (VT),¹⁷ and delivery of ATP might alter ICD treatment algorithms, increasing the likelihood of an inappropriate shock with

induction of VF.¹⁸ Whether inappropriate ATP from EMI actually can induce VT remains unclear.

In-hospital EMI (principally from monopolar electrosurgery) appears to confer significant risks to patients with ICDs,⁷ and the authors believe that the majority of events such as those described herein remain undetected and/or unreported. As demonstrated in patients 1 and 2, both shock and ATP might be missed in the operating room because of the following: (1) these therapies can occur very quickly; (2) the 8 beats of ATP at 180 beats/min (approximately 2.6 seconds’ duration) in patient 1 occurred during the use of monopolar electrosurgery, which likely introduced significant electrocardiogram monitor artifact; and (3) many patients who undergo general anesthesia have been treated with muscle relaxants, preventing movement during shock.

These cases reinforce the need for adherence to all published perioperative management recommendations from the ASA and HRS for patients with these devices. In particular, attention should be paid to EMI mitigation. Despite the confusion that continues to exist surrounding the perioperative care of these patients, and the inconsistency of some of the published recommendations on this topic, there appears to be a wide consensus about the importance of protecting patients from inappropriate high-energy therapy during surgery.

Before any elective procedure, the perioperative care team should verify proper ICD function and obtain a prescription from a CIED expert for the perioperative management of the device because not all CIEDs operate correctly.¹⁹ A plan should be developed and carried out for mitigating intraoperative EMI, which might include either ICD reprogramming or the application of a magnet (if appropriate). For some patients, selection of surgical instruments (eg, bipolar electrosurgery or ultrasonic devices) that will not create EMI might be appropriate. Furthermore, the electrosurgery dispersive electrode should be positioned appropriately to prevent the presumed electrosurgery unit current path from crossing the chest and ICD circuitry. Testing of newer equipment, such as the whole-body dispersive electrode, to determine whether it should be used during surgery in the patient with a CIED should take place. In addition, practitioners should not rely solely on the use of short bursts of monopolar electrosurgery; this strategy failed to protect the patient in case 3 from shock because the VT/VF counters were incremented quickly based on the high-frequency EMI but only slowly decremented based on the paced rate of 75 beats/min (800-millisecond cycles).

Finally, because many patients with an ICD transmit their ICD data to the manufacturers, perhaps the manufacturers should report noise-induced therapies to regulatory agencies such as the Food and Drug Administration, and any inappropriate therapy delivered in a medical care setting should be reported to the Joint Commission. Review of noise-induced therapies has resulted in lead recalls.²⁰ This strategy also might be used to enhance perioperative patient safety for patients with CIEDs.

References

- 1 Stempniewicz P, Cheng A, Connolly A, et al. Appropriate and inappropriate electrical therapies delivered by an implantable cardioverter-defibrillator: Effect on intracardiac electrogram. *J Cardiovasc Electrophysiol* 2011;22:554–60.
- 2 Hasdemir C, Shah N, Rao AP, et al. Analysis of troponin I levels after spontaneous implantable cardioverter defibrillator shocks. *J Cardiovasc Electrophysiol* 2002;13:144–50.
- 3 Semmler V, Biermann J, Haller B, et al. ICD shock, not ventricular fibrillation, causes elevation of high sensitive troponin T after defibrillation threshold testing—the prospective, randomized, multicentre TropShock-Trial. *PLoS One* 2015;10:e0131570.
- 4 Yousuf O, Spragg DD. ICD therapy—can we make a life-saving device less lethal? *J Cardiovasc Electrophysiol* 2016;27:200–2.
- 5 Practice advisory for the perioperative management of patients with cardiac implantable electronic devices. Pacemakers and implantable cardioverter-defibrillators: An updated report by the American Society of Anesthesiologists task force on perioperative management of patients with cardiac implantable electronic devices. *Anesthesiology* 2011;114:247–061.
- 6 Crossley GH, Poole JE, Rozner MA, et al. The Heart Rhythm Society (HRS)/American Society of Anesthesiologists (ASA) expert consensus statement on the perioperative management of patients with implantable defibrillators, pacemakers and arrhythmia monitors: Facilities and patient management: This document was developed as a joint project with the American Society of Anesthesiologists (ASA), and in collaboration with the American Heart Association (AHA), and the Society of Thoracic Surgeons (STS). *Heart Rhythm* 2011;8:1114–54.
- 7 Powell BD, Asirvatham SJ, Perschbacher DL, et al. Noise, artifact, and oversensing related inappropriate ICD shock evaluation: ALTTITUDE noise study. *Pacing Clin Electrophysiol* 2012;35:863–9.
- 8 Robinson TN, Varosy PD, Guillaume G, et al. Effect of radiofrequency energy emitted from monopolar bovie instruments on cardiac implantable electronic devices. *J Am Coll Surg* 2014;219:399–406.
- 9 Powell BD, Saxon LA, Boehmer JP, et al. Survival after shock therapy in implantable cardioverter-defibrillator and cardiac resynchronization therapy-defibrillator recipients according to rhythm shocked. The ALTTITUDE survival by rhythm study. *J Am Coll Cardiol* 2013;62:1674–9.
- 10 Medicines and Health Care Products Regulatory Agency: Guidelines for the perioperative management of patients with implantable pacemakers or implantable cardioverter defibrillators, where the use of surgical diathermy/electrocautery is anticipated. Available at: https://www.erbe-med.com/images/uk/Diathermy_Pacemakers-ICDs1.pdf. Accessed on December 9, 2006.
- 11 Schulman PM, Rozner MA. Use caution when applying magnets to pacemakers or defibrillators for surgery. *Anesth Analg*, 117; 422–7.
- 12 Lau W, Corcoran SJ, Mond HG. Pacemaker tachycardia in a minute ventilation rate-adaptive pacemaker induced by electrocardiographic monitoring. *Pacing Clin Electrophysiol* 2006;29:438–40.
- 13 Izrailtayan I, Schiller RJ, Katz RI, et al. Perioperative pacemaker-mediated tachycardia in the patient with a dual chamber implantable cardioverter-defibrillator. *Anesth Analg* 2013;116:307–10.
- 14 Veltmann C, Borggrefe M, Schimpf R, et al. Fatal inappropriate ICD shock. *J Cardiovasc Electrophysiol* 2007;18:326–8.
- 15 Moss AJ, Schuger C, Beck CA, et al. Reduction in inappropriate therapy and mortality through ICD programming. *N Engl J Med* 2012;367:2275–83.
- 16 Raitt MH. Inappropriate implantable defibrillator shocks: An adverse outcome that can be prevented. *J Am Coll Cardiol* 2013;62:1351–2.
- 17 Grimm W, Flores BF, Marchlinski FE. Electrocardiographically documented unnecessary, spontaneous shocks in 241 patients with implantable cardioverter defibrillators. *Pacing Clin Electrophysiol* 1992;15:1667–73.
- 18 Ho RT. Implantable cardioverter-defibrillator discharges despite successful termination of ventricular tachycardia by antitachycardia pacing. *Pacing Clin Electrophysiol* 2009;32:791–3.
- 19 Tseng ZH, Hayward RM, Clark NM, et al. Sudden death in patients with cardiac implantable electronic devices. *JAMA Intern Med* 2015;175:1342–50.
- 20 Ellenbogen KA, Wood MA, Shepard RK, et al. Detection and management of an implantable cardioverter defibrillator lead failure: Incidence and clinical implications. *J Am Coll Cardiol* 2003;41:73–80.