


SYNCHRONOUS-API VERSION 3.0.1.11

RELEASE NOTES

PLT-03649, Rev. A.0

January 2018



Copyright

© 2018 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, and OMNIKEY are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Revision History

Date	Description	Revision
January 2018	Initial release.	A.0

Contacts

For additional offices around the world, see www.hidglobal.com/contact/corporate-offices

Americas and Corporate

611 Center Ridge Drive
Austin, TX 78753
USA
Phone: 866 607 7339
Fax: 949 732 2120

Asia Pacific

19/F 625 King's Road
North Point, Island East
Hong Kong
Phone: 852 3160 9833
Fax: 852 3160 4809

Europe, Middle East and Africa (EMEA)

Haverhill Business Park Phoenix Road
Haverhill, Suffolk CB9 7AE
England
Phone: 44 (0) 1440 711 822
Fax: 44 (0) 1440 714 840

Brazil

Condomínio Business Center
Av. Ermano Marchetti, 1435
Galpão A2 - CEP 05038-001
Lapa - São Paulo / SP
Brazil
Phone: +55 11 5514-7100

HID Global Customer Support: www.hidglobal.com/customer-service

1 Scope

This document provides information for the Synchronous-API (Sync-API) firmware release 3.0.1.11. Included are product enhancements, fixes, known issues, system requirements, and limitations since the prior release. **Note:** The reference numbers associated with these features, issues and fixes are from a HID Global internal tracking system.

2 Enhancements and Fixes

- Added I2C, 2WBP, and 3WBP card support for AVR controller based contact readers.
- Updated the *Synchronous-API Software Developer Guide* (PLT-03635) to document new functionality.
- Replaced the previous **.hlp** file with a **.chm** file.
- Updated the Sync-API Developer Guide to include new functionality.
- Updated the Sync-API SDK package for Visual Studio 2017 edition.
- Created new 32- and 64 bit installer packages.

3 Known Behaviors and Issues

3.1 Appropriate runtime dependencies are required

Sync-API was developed in Visual Studio 2017 so it requires appropriate runtime dependencies to be available on the deployment PC in order to operate. The C++ redistribution package for Visual Studio 2017 (called runtime dependencies) are included within the Sync-API installer but sometimes additional Microsoft patches need to be installed in advance on the PC. Please refer to the following Microsoft page, where minimal service pack information is listed: <https://support.microsoft.com/en-us/help/2661358/minimum-service-pack-levels-for-microsoft-vc-redistributable-packages>

- Windows 10 (x64 and x86)
- Windows 8.1 (x64 and x86)
- Windows Server 2012 R2 (x64)
- Windows 8 (x64 and x86)
- Windows Server 2012 (x64)
- Windows 7 SP1 or later versions (x64 and x86)
- Windows Server 2008 R2 SP1 or later versions (x64)
- Windows Server 2008 SP2 or later versions (x64)
- Windows Vista SP2 or later versions (x64 and x86)
- Windows Server 2003 R2 RTM or later versions (all editions)
- Windows Server 2003 SP2 or later versions (all editions)
- Windows XP SP3 (all editions except Starter Edition) Please be aware, that Windows XP support might be limited due to Microsoft regulations and support policies.

3.2 The AVR controller based version of the OMNIKEY 3121 can not read some older card formats (TTP9938).

The root cause is in the reader as it initializes card communication at an improper voltage level (3V), which can result in communication with the card ending with unpredicted results (error response, positive response but write operation is not performed, etc.). A workaround is described in the *Synchronous-API Software Developer Guide* (PLT-03635).

This page is intentionally left blank.

