

AUTOMATED ASSEMBLY SYSTEM → Assembly involves joining together of two or more separate parts to form a new entity


Automated assembly refers to the use of mechanized and automated devices to perform the various functions in an assembly line or cell

Automated assembly performs a sequence of automated operations to combine multiple components in a single entity.

DESIGN FOR AUTOMATED ASSEMBLY

- Reduce the amt. of assembly required
- Use modular design
- Reduce the no. of fasteners required
- Reduce the need for multiple components to be handled at once
- Limit the dirn of access
- High quality components
- Implement hopperability

TYPES OF ASSEMBLY SYSTEM



PART DELIVERY AT WORKSTATION

- **HOPPER** → container into which the components are loaded at workstation
A separate hopper for each component type
components are usually loaded into hopper in bulk
parts are randomly oriented in hopper
- **PART FEEDER** → It is a mechanism that removes the components from hopper one at a time for delivery to assembly work head. The hopper and the part feeder combine together into 1 operating mechanism.
The vibratory bowl feeder is a common example for hopper-feeder combination
- **SELECTOR AND ORIENTER** → A selector is a device that acts as a filter permitting the parts only in correct orientation to pass through. The reflected parts are sent back to hopper
orienter is a device that allows properly oriented parts to pass thro' and reorients the parts that are not oriented initially.
- **FEED TRACK** → A feed track moves the components from hopper and feeder to the location of assembly work head
↳ Gravity and powered

ESCAPEMENT AND PLACEMENT DEVICES track at time intervals that are consistent with the cycle time of assembly work head

various types

- horizontal and vertical devices for placement of parts onto dial indexing table
- escapement of rivet shaped parts
- pick and place mechanisms

MULTISTATION ASSEMBLY SYSTEM

Assumptions

- Assembly operations have const. time element, although time for different station may vary
- synchronous part transfer
- No internal storage

$m_i q_i$
↓ probability that the defect causes jam
↓ defect rate $0 \leq q \leq 1$
probability that the current part is defective

The component is defective + causes jam

$$P_i = m_i q_i \quad \text{--- (1)}$$

component is defective + does not cause jam

$$P_i = (1 - m_i) q_i \quad \text{--- (2)}$$

component is not defective

$$P_i = 1 - q_i \quad \text{--- (3)}$$

All these 3 must sum to $(1) + (2) + (3) = 1$

$$m_i q_i + (1 - m_i) q_i + 1 - q_i = 1$$

Probability of a good yield

$$P_{ap} = \underbrace{1 - q_i}_{\text{only good components}} + \underbrace{m_i q_i}_{\text{causes jam so no defective component is added}}$$

$$f \text{ (frequency of downtime occurrences)} = \sum m_i q_i$$

$$\text{Avg production time} = \frac{\text{Ideal cycle}}{\text{time}} + (\text{Average downtime})(m_i q_i)$$

$$\begin{aligned} T_p &= T_c + \sum m_i q_i T_d \\ \text{Production Rate} \quad R_p &= 1/T_p \end{aligned}$$

Production Rate of acceptable product

$$R_{ap} = R_p P_{ap} = \frac{P_{ap}}{T}$$

$$\text{line efficiency} \rightarrow E = \frac{R_p}{R_c} = \frac{T_c}{T_p}$$

proportion downtime $D = 1 - E$

$$\text{cost per good assembly} = \frac{\text{cost of material} + (\text{operating cost}) \left(\frac{\text{production}}{\text{time}} \right) + \dots}{\text{yield}}$$

SINGLE STATION ASSEMBLY

$$\begin{array}{lcl} \text{Ideal assembly time} & \text{Handling time} & \text{Element time} \\ T_c & = T_h & + \sum T_{ej} \end{array}$$

$$\begin{array}{lcl} \text{Average production time} & & \\ T_p & = T_c + \sum m_i q_i T_d & \\ & & \downarrow \\ & & \text{when machine stops} \end{array}$$

AUTOMATED FLOW LINES

- PROCESS TECHNOLOGY - Refers to the body of knowledge about the theory and principles of manufacturing processes
- SYSTEM TECHNOLOGY - It includes the metallurgy and machinability of the work material

TERMINOLOGY AND ANALYSIS OF TRANSFER LINES WITH NO INTERNAL STORAGE

Assumptions

- workstations perform operations and not assembly
- processing time at each station are constant though may not be equal
- synchronous transfer of parts
- No internal storage of buffers

$$T_c = T_{si} + T_r \rightarrow \text{Transfer time / Repositioning time}$$

\downarrow Ideal cycle on the line \downarrow slowest process's processing time

REASONS FOR DOWNTIME

- Tool failure
- Tool adjustments
- Scheduled tool changes
- Mechanical failure of work station
- Mechanical failure of transfer line
- stock out of i/p's
- Insufficient space for completed parts

$$\text{Average production time } T_p = \frac{\text{Ideal cycle time } T_c}{\text{Downtime frequency } F \cdot T_d} + F \cdot T_d$$

Downtime per line stops

$$\text{Average production rate } R_p = 1/T_p \quad \text{Ideal production rate } R_c = 1/T_c$$

Line efficiency

$$E = \frac{T_c}{T_p} = \frac{R_p}{R_c} = \frac{T_c}{T_c + F T_d}$$

proportion of down-time

$$D = \frac{F T_d}{T_p}$$

$$E + D = 1.0$$

$$\text{cost per piece} = \text{cost per minute} + \left[\frac{\text{Capital cost / equipment cost}}{\text{minute}} \right] T_p + \text{cost of Tooling price}$$

UPPER BOUND APPROACH

P_i = probability or frequency of a failure at a station
 $n \rightarrow$ no. of workstations

$$F = \sum_{i=1}^n P_i$$

↓
expected
frequency of
line stops per cycle

LOWER BOUND APPROACH

probability that the part will not jam station
($1 - P_i$)

ANALYSIS OF TRANSFER LINE WITH STORAGE

$$E_0 = \frac{T_c}{T_c + FT_d}$$

0 capacity storage
buffer

$$E_\infty = \frac{T_c}{T_c + FT_d}$$

∞ capacity storage
buffer