

ACCELEMOTER PROJECT. AUTO-GUIDE.

February, Summer of 2019.

By me.For me();


(Worked on Ubuntu 18.04Lts)

1. AttollicWorkspace + StmCubeMX for LIS3DSH sensor.

Let's suppose you remember how to use the software of this section. If you don't know this, visit the course in [udemy.com](https://www.udemy.com) and [youtube](https://www.youtube.com)(and more youtube).

a) List of pins. StmCubeMX (* = obligatory requirement for working)

- Four PinLeds(*)
- One SPI Module(*)
- ResetButton



Next, you can press “Generate Code”

b) Modification of *main.c* file

- First, you need to agree a extra library: `#include "MY_LIS3DSH.h"` and **add a path for this file** (File → Proprieties → search “path” → select a directory for add).
- In the begging of *main* section add `LIS3DSH_InitTypeDef MyAccConfDeff;` for establish a configurations of the accelerometer.

- Just up of while(1) loop you need add a configuration parameters for accelerometer

```
/* CONFF PARAMETERS */
MyAccConfDeff.dataRate = LIS3DSH_DATARATE_12_5;
MyAccConfDeff.fullScale = LIS3DSH_FULLSCALE_4;
MyAccConfDeff.antiAliasingBW = LIS3DSH_FILTER_BW_50;
MyAccConfDeff.enableAxes = LIS3DSH_XYZ_ENABLE;
MyAccConfDeff.interruptEnable = false;

LIS3DSH_Init(&hspi1, &MyAccConfDeff);
```

- In the while(1) loop, for initialize a sensor mesure add the next condition:

```
if(LIS3DSH_PollDRDY(1000) == true ){
myData = LIS3DSH_GetDataScaled(); //take a measures of all axis

"rest of the code..."}
```


- For access a data measure of diferent axis write a **myData.x** | **myData.y** | **myData.z**
- When you have the rest of your code compile(and pray), next press the debugger icon and press run.

2. AttolicWorkspace + StmCubeMX for UART communication

a) List of pins. StmCubeMX (* = obligatory requirement for working)

- Two UART modules (*)
- Two leds for see the working

pd: in the configuration of UART you need the see nvic and check the boxes (global interrupt)



b) Modification of *main.c* file

- Add a extra libraries (extra PATH is not necessary in this case)

```
#include "stm32f4xx_hal.h"  
#include <string.h>
```
- Define your data after in the *main* section. For example

```
char TxData1[30] = "15x\n";
```
- In the while(1) loop you can send the data. For example

```
HAL_UART_Transmit(&huart2, (uint8_t *)TxData1, strlen(TxData1), 5);
```


In this case we send TxData1 from huart2.

3. UART Hardware connections

You need to have a ttl-usb conversor

In the case of the photography of below I use a UART2 module and connect PA2(Tx) and PA3(Rx).

Connections from Stm32f4 to TTL-Usb conversor: PA2(Tx) → Rx pin
PA3(Tx) → Tx pin

You can use 5v or 3v pins of TTL-Usb conversor it as a source power of the StmBoard(in this case same connect GND pin) or you can use usb conector and not use the pins of the TTL-Usb conversor (in this case GND is not necessary)

NOW YOU CAN RUN DE UART CODE AND READ SERIAL PORT WITH SOME SOFTWARE.