

RN0074
Release Notes
CoreFIFO v3.0



a  **MICROCHIP** company



a  MICROCHIP company

Microsemi Headquarters

One Enterprise, Aliso Viejo,
CA 92656 USA

Within the USA: +1 (800) 713-4113

Outside the USA: +1 (949) 380-6100

Sales: +1 (949) 380-6136

Fax: +1 (949) 215-4996

Email: sales.support@microsemi.com

www.microsemi.com

©2021 Microsemi, a wholly owned subsidiary of Microchip Technology Inc. All rights reserved. Microsemi and the Microsemi logo are registered trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

About Microsemi

Microsemi, a wholly owned subsidiary of Microchip Technology Inc. (Nasdaq: MCHP), offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions, security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Learn more at www.microsemi.com.

1 Revision History

The revision history describes the changes that were implemented in the document. The changes are listed by revision, starting with the most current publication.

1.1 Revision 10.0

The following are the changes made in this revision.

- Updated changes related to CoreFIFO v3.0.
- Added [CoreFIFO v3.0 Migration](#), page 11.

1.2 Revision 9.0

The following are the changes made in this revision.

- Added PolarFire SoC support.

1.3 Revision 8.0

Updated changes related to CoreFIFO v2.7.

1.4 Revision 7.0

Updated changes related to CoreFIFO v2.6.

1.5 Revision 6.0

Updated changes related to CoreFIFO v2.5.

1.6 Revision 5.0

Updated changes related to CoreFIFO v2.4.

1.7 Revision 4.0

Updated changes related to CoreFIFO v2.3.

1.8 Revision 3.0

Updated changes related to CoreFIFO v2.2.

1.9 Revision 2.0

Updated changes related to CoreFIFO v2.1.

1.10 Revision 1.0

Revision 1.0 was the first publication of this document. Created for CoreFIFO v2.0.

Contents

1	Revision History	3
1.1	Revision 10.0	3
1.2	Revision 9.0	3
1.3	Revision 8.0	3
1.4	Revision 7.0	3
1.5	Revision 6.0	3
1.6	Revision 5.0	3
1.7	Revision 4.0	3
1.8	Revision 3.0	3
1.9	Revision 2.0	3
1.10	Revision 1.0	3
2	CoreFIFO v3.0	7
2.1	Overview	7
2.2	Features	7
2.3	Delivery Types	7
2.4	Supported Families	7
2.5	Supported Tool Flows	7
2.6	Installation Instructions	7
2.7	Documentation	8
2.8	Supported Test Environments	8
2.9	Resolved Issues in the v3.0 Release	8
2.10	Resolved Issues in the v2.8 Release	8
2.11	Resolved Issues in the v2.7 Release	9
2.12	Resolved Issues in the v2.6 Release	9
2.13	Resolved Issues in the v2.5 Release	9
2.14	Resolved Issues in the v2.4 Release	9
2.15	Resolved Issues in the v2.3 Release	10
2.16	Resolved Issues in the v2.2 Release	10
2.17	Resolved Issues in the v2.1 Release	10
2.18	Resolved Issues in the v2.0 Release	10
2.19	Discontinued Features and Devices	11
2.20	Known Limitations and Workarounds	11
2.21	CoreFIFO v3.0 Migration	11
2.21.1	Migration to CoreFIFO v3.0	11
2.21.2	Independent reset ports for write and read clock domain for dual clock FIFO	13
2.21.3	Reset Port Name Change for Single Clock Mode FIFO	14
2.21.4	Discontinue Reset Polarity Feature (RESET_POLARITY)	14
2.21.5	Discontinue Clock Polarity feature (WCLK_EDGE and RCLK_EDGE)	15

Figures

Figure 1	Expected SmartDesign view when migrating to CoreFIFO v3.0	11
Figure 2	Updating SmartDesign to CoreFIFO v3.0 using Update Component option	12
Figure 3	Log messages window when migrating to CoreFIFO v3.0	12
Figure 4	SmartDesign configured for SYNC = 0	13
Figure 5	Asynchronous Reset Synchronizer (When Reset type - SYNC_RESET is set to 0) – external to the IP Core	13
Figure 6	Synchronous Reset Synchroniser (When SYNC_RESET is set to 1) – external to the IP Core . .	14
Figure 7	SmartDesign configured for SYNC=1	14

Tables

Table 1	Resolved issues in the v3.0 Release	8
Table 2	Resolved Issues in the v2.8 Release	8
Table 3	Resolved Issues in the v2.7 Release	9
Table 4	Resolved Issues in the v2.6 Release	9
Table 5	Resolved Issues in the v2.5 Release	9
Table 6	Resolved Issues in the v2.4 Release	9
Table 7	Resolved Issues in the v2.3 Release	10
Table 8	Resolved Issues in the v2.2 Release	10
Table 9	Resolved Issues in the v2.1 Release	10
Table 10	Resolved Issues in the v2.0 Release	10

2 CoreFIFO v3.0

2.1 Overview

These release notes accompany the production release of CoreFIFO v3.0. This document provides details about the features, enhancements, system requirements, supported families, implementations, and known issues and workarounds.

2.2 Features

- Dual and single clock operation
- Clock edge - positive/negative
- Full/empty flag generation
- Almost full and almost empty flag generation
- Empty/full stop generation
- Write and read count
- Variable aspect ratio (depth/width)
- Error status generation with overflow and underflow
- Write acknowledge and read data valid generation
- Supports large RAM and micro RAM or controller only option
- Almost full and almost empty single threshold value for assertion
- Pipelining in the memory read data paths (controller with memory option)
- Pre-fetch mode option to provide read data in the same clock cycle
- FWFT (First-Word Fall-Through)
- ECC capability for RTG4, PolarFire, and PolarFire SoC device families

2.3 Delivery Types

CoreFIFO does not require a license. Complete RTL source code is provided for the core and testbenches.

2.4 Supported Families

- PolarFire® SoC
- PolarFire®
- RTG4™
- IGLOO®2
- SmartFusion®2

2.5 Supported Tool Flows

CoreFIFO v3.0 requires Libero® System-on-Chip (SoC) software v11.0 or later.

2.6 Installation Instructions

The CoreFIFO CPZ file must be installed into Libero software. This is done automatically through the Catalog update function in Libero, or the CPZ file can be manually added using the **Add Core** catalog feature. Once the CPZ file is installed in Libero, the core can be configured, generated, and instantiated within SmartDesign for inclusion in the Libero project. For more information, see the [Knowledge Based article](#).

To know how to create SmartDesign project using the IP cores, refer to [Libero SoC documents page](#) and use the latest SmartDesign user guide.

2.7 Documentation

This release contains a copy of the *CoreFIFO Handbook*. The handbook, describes the core functionality and gives step-by-step instructions on how to simulate, synthesize, and place-and-route this core, and also implementation suggestions. Refer to *Libero SoC documents page* for instructions on obtaining IP documentation.

For updates and additional information, visit the Intellectual Property pages on the Microsemi SoC Products Group website: visit:

<http://www.microsemi.com/products/fpga-soc/design-resources/ip-cores>.

2.8 Supported Test Environments

The following test environments are supported:

- VHDL user testbench
- Verilog user testbench

2.9 Resolved Issues in the v3.0 Release

Table 1 • Resolved issues in the v3.0 Release

SAR Number	Changes
107634	CoreFIFO GUI option to generate RAM's based on HighSpeed or LowPower.
112344	Difference in behavior of CoreFIFO between v2.6 and v2.7.
100673	CoreFIFO synchronizer enhancement needs better description in handbook.
113122	Timing constraints for CoreFIFO.
94791	CoreFIFO: EMPTY flag behavior to be documented for different configuration. Handbook is updated accordingly.
109048	Synthesis Error: Net driven by multiple drivers issues.
107693	CoreFIFO customer enhancement requests.
101842	CoreFIFO for RTG4 is not SET mitigated.
109556	CoreFIFO requirement from NGC.
113985	Undefined variable: almost fully de-assert in CoreFIFO.
118664	CoreFIFO: Handbook enhancement.
118927	Incomplete Die information in TGI code for CoreFIFO.
119129	SET mitigation issue for Active High Reset Polarity.
119068	Improper values of WRCNT and RDCNT values for FULL and EMPTY flags assertion respectively.
120146	Discontinue Clock Polarity feature (WCLK_EDGE and RCLK_EDGE) for CoreFIFO

2.10 Resolved Issues in the v2.8 Release

Table 2 • Resolved Issues in the v2.8 Release

SAR Number	Changes
115858	ECC logic is optimized in CoreFIFO with PolarFire device.

2.11 Resolved Issues in the v2.7 Release

Table 3 • Resolved Issues in the v2.7 Release

SAR Number	Changes
91876	CoreFIFO should double sync the reset with write and read clock.
87120	Support for async reset option for RTG4.
93202	Overflow flag not getting asserted.
95499	CoreFIFO post configuration indicates "controller only".
94791	EMPTY flag behavior to be documented.
93440	EMPTY flag is mentioned as synchronous in HB where as in case of FWFT, it is combinational.
87688	Remove or modify incorrect entry "run run -all" in packager attributes.
98462	glitches on EMPTY and DVLD not getting asserted with PREFETCH or FWFT with single word in FIFO.
97984	PF CoreFIFO does not enable SB_CORRECT/ DB_DETET for valid configuration.

2.12 Resolved Issues in the v2.6 Release

Table 4 • Resolved Issues in the v2.6 Release

SAR Number	Changes
43498	Missing Modules in Libero Design Hierarchy.
80253	RTG4 uses sync reset, but the Handbook mentions async.
80609	Support for PolarFire.
80679	MEMWD and MEMRD are bypassed for controller mode.

2.13 Resolved Issues in the v2.5 Release

Table 5 • Resolved Issues in the v2.5 Release

SAR Number	Changes
68070	CoreFIFO address counter issue (not getting rolled off).
68113	ECC capability missing for RTG4.

2.14 Resolved Issues in the v2.4 Release

Table 6 • Resolved Issues in the v2.4 Release

SAR Number	Changes
66456	RTG4 DRC check failure.
65631	CoreFIFO HB: reset is shown as active-low, however it can be configured to active low/high in the GUI.

2.15 Resolved Issues in the v2.3 Release

Table 7 • Resolved Issues in the v2.3 Release

SAR Number	Changes
57411	Add support for RTG4.
60654	CoreFIFO with prefetch, single clk is not working.
60021	CoreFIFO behavior with gated clock.
60185	Timing diagrams and FWFT issue (simulation).

2.16 Resolved Issues in the v2.2 Release

Table 8 • Resolved Issues in the v2.2 Release

SAR Number	Changes
56536	FWFT (First Word Fall Through) FIFO implementation.
57411	Add support for RTG4.
54647	CoreFIFO does not retain data when RE is de-asserted.
55148	Data lost when data is read back after empty de-assertion.
56537	CoreFIFO issue when the pre-fetch option is checked.

2.17 Resolved Issues in the v2.1 Release

Table 9 • Resolved Issues in the v2.1 Release

SAR Number	Changes
51140	CoreFIFO FIFOs do not operate correctly when the prefetch option is checked.
50808	CoreFIFO simulation errors when "vhdl2008" is checked in the Libero GUI.
49361	Data output is zero from RAM when read/write enable are configured as active low.
49133	Issue with CoreFIFO during compile stage when multiple corefifos are used along with MSS in VHDL.
48624	CoreFIFO prompts error for duplicate instances in VHDL.
48300	SmartFusion2 CoreFIFO simulation is not correct.
48299	CoreFIFO 2.0.101 issue in SF2.
43498	Missing modules in Libero Design Hierarchy > Components view.

2.18 Resolved Issues in the v2.0 Release

Table 10 • Resolved Issues in the v2.0 Release

SAR Number	Changes
46695	One word is missing (read extra after read en de-assertion) in prefetch mode on de-asserting the rd_en and asserting it back.

2.19 Discontinued Features and Devices

The parameter RESET_POLARITY, WCLK_EDGE(Write Clock), and RCLK_EDGE(Read Clock) is discontinued in the release of CoreFIFO v3.0.

2.20 Known Limitations and Workarounds

The user testbench in CoreFIFO v3.0 release provides support for single fixed parameter configuration only.

2.21 CoreFIFO v3.0 Migration

2.21.1 Migration to CoreFIFO v3.0

- When migrating to CoreFIFO v3.0 from earlier versions the user can expect following SmartDesign and logs windows.

Figure 1 • Expected SmartDesign view when migrating to CoreFIFO v3.0




Figure 2 • Updating SmartDesign to CoreFIFO v3.0 using Update Component option





Figure 3 • Log messages window when migrating to CoreFIFO v3.0




Note: User can safely ignore errors reported in the log window.

2.21.2 Independent reset ports for write and read clock domain for dual clock FIFO

Changes

- When Clocks (SYNC) parameter is configured in dual clock mode (SYNC=0), two reset ports, WRESET_N and RRESET_N are exposed to the top-level ports.

Figure 4 • SmartDesign configured for SYNC = 0



Impact

- In the earlier version of the CoreFIFO, only one reset port (RESET) is used (for dual clock FIFO mode). This reset (RESET) input is synchronized internally with respect to the WCLK and RCLK domains.
- For CoreFIFO v3.0, two separate resets (WRESET_N and RRESET_N) ports (for dual clock FIFO mode) are exposed to the user. The user shall synchronize these two resets into the respective clock domain (WRESET_N in WCLK and RRESET_N in RCLK domain) **external** to the IP core.
- CoreFIFO v3.0 is not backward compatible for RESET port connection.
- User can refer to Figure 5 and Figure 6 for asynchronous and synchronous reset synchronizer respectively

Figure 5 • Asynchronous Reset Synchronizer (When Reset type - SYNC_RESET is set to 0) – external to the IP Core





Figure 6 • Synchronous Reset Synchroniser (When SYNC_RESET is set to 1) – external to the IP Core




Note: In the above example figures only two flop synchronisers are shown.

2.21.3 Reset Port Name Change for Single Clock Mode FIFO

Changes

When Clocks (SYNC) parameter is configured in single clock mode (SYNC = 1), single reset port RESET_N is exposed to the top-level ports.

Figure 7 • SmartDesign configured for SYNC=1



Impact

When updating designs to CoreFIFO v3.0 for single clock mode (SYNC = 1) configuration. Then the user must update the component as the port name is changed from RESET to RESET_N.

2.21.4 Discontinue Reset Polarity Feature (RESET_POLARITY)

Changes

Removed RESET_POLARITY parameter.

Impact

- CoreFIFO v3.0 is not backward compatible for designs using active high polarity.
- For the designs requiring Active High reset polarity, the corresponding reset port should be inverted (NOT gate) external to the IP core.

2.21.5 Discontinue Clock Polarity feature (WCLK_EDGE and RCLK_EDGE)

Changes

Removed WCLK_EDGE and RCLK_EDGE parameters.

Impact

- CoreFIFO v3.0 is not backward compatible for designs using negative edge clock polarity.
- For the designs using negative edge clock polarity, the clock port should be inverted **external** to the IP core.