

## EEE6022 (2013-2014) Model solutions

### 1.a

When friction and the inertia of the pulley and belt are negligible, the force required to move the load of mass  $m$  is purely due to acceleration, and given by: (8)

$$F = m \frac{dv}{dt}$$

where the linear acceleration  $dv/dt$  is related to the angular acceleration,  $d\omega/dt$ , of the motor by:

$$dv/dt = r d\omega/dt$$

and the force reflected to the motor axis as a load torque  $T_L$  is given by:

$$T_L = F r$$

Thus the total motor torque required for accelerating/decelerating the drive system, expressed in terms of  $dv/dt$  is given by:

$$T_{em} = (J_m / r + r m) \frac{dv}{dt}$$

As can be seen, the equivalent inertia  $J_{eq} = (J_m/r + rm)$  is a function of radius  $r$ , and reaches its minimum when

$$dJ_{eq} / dr = -J_m / r^2 + m = 0$$

Thus:

$$r = \sqrt{\frac{J_m}{m}}$$

### 1.b

The optimal pulley radius is given by: (9)

$$r = \sqrt{\frac{J_m}{m}} = \sqrt{\frac{0.002}{0.2}} = 0.1(m)$$


and the combined inertia on the motor axis is:

$$J_{eq} = (J_m + r^2 m) = 2J_m = 0.004(kgm^2)$$

The total angular distance to be rotated by the motor is

$$\Theta = 0.4 / 0.1 = 4 \text{ (rad)}$$

The corresponding trapezoidal velocity profile, and torque demand is shown in the figure below:



From the velocity profile, it can be derived that the maximum speed is related to the angular distance  $\Theta$  and the time period  $T$  by:

$$\omega_{\max} = 3\Theta / 2T = 3 * 4 / 2 / 0.1 = 60 \text{ (rad/s)}$$

and the maximum angular acceleration is

$$\alpha_{\max} = \omega_{\max} / (T/3) = 3 * 60 / 0.1 = 1800 \text{ (rad/s}^2\text{)}$$

The peak torque requirement is

$$J_{eq} a_{\max} = 2.4 * 3 = 7.2 \text{ (Nm)}$$

and the rms torque is

$$\sqrt{2 * 7.2^2 / 3} = 5.88 \text{ (Nm)}$$

which is less than the rated rms torque of 6.0 (Nm). Thus the motor would not overheat.

- 1.c** For the triangular velocity profile shown in below, the the maximum speed is related to the angular distance  $\Theta$  and the time period  $T$  by: (3)

$$\omega_{\max} = 2\Theta / T = 2 * 4 / 0.1 = 80 \text{ (rad/s)}$$


and the acceleration is

$$\alpha_{\max} = \omega_{\max} / (T/2) = 2 * 80 / 0.1 = 1600 \text{ (rad/s}^2\text{)}$$


The peak torque and maximum power are given by:

$$J_{eq} a_{\max} = 1600 * 0.004 = 6.4 \text{ (Nm)}$$

$$P = J_{eq} a_{\max} \omega_{\max} = 1600 * 0.004 = 6.4 * 80 = 512 \text{ (W)}$$



- 2.a** The waveforms for the pulse width modulation in bipolar mode are shown below. (6)
- The control input  $v_{con}$  is compared with the triangle carrier,  $v_{tri}$ , if  $v_{con} > v_{tri}$ , S1 and S4 will be switched on while S2 and S3 are off. The output voltage is  $V_d$ , and the motor current increases under the influence of  $V_d$ . If, however,  $v_{con} < v_{tri}$ , S2 and S3 are on, S1 and S4 are off, and the output voltage is  $-V_d$ . The motor current will decrease due to the negative voltage being applied.



- 2.b** With reference to the bi-polar operation waveforms shown above, the average (3)
- voltage output of the converter is given by:

$$V_t = [t_1 V_d - (T_c - t_1) V_d] / T_c = V_d(2D - 1) \quad (1)$$

The duty ratio  $D$  is defined as  $D = t_1 / T_c$

Assume that the command signal is constant within a carrier cycle, from the triangle waveform, one can obtain:


$$\frac{T_c}{2V_{tp}} = \frac{t_1}{(V_{tp} + v_{com})} \quad \therefore \quad 2D = 1 + \frac{v_{com}}{V_{tp}} \quad (2)$$

Substituting (2) into (1) results in:

$$V_t = (V_d / V_{tp}) v_{com} = k v_{com}$$

i.e., the gain of the converter is  $V_d / V_{tp}$

- 2.c** The transfer function block diagram between the control input,  $v_c(s)$ , and the motor speed,  $\omega(s)$  is shown below: (5)



From the motor parameters, the parameters of various blocks are determined as follows:

$$k_T = 10 \text{ Nm} / 20 \text{ A} = 0.5 = k_E; \quad B = 0.0; \quad \text{armature resistance } R_a = 0.37 \Omega$$

armature inductance  $L_a = 1.5 \text{ mH}$ .

The moment of inertia is  $J = 4.0 \times 10^{-3} \text{ (kgm}^2\text{)}$

H-bridge converter gain  $k = V_d / V_{tp} = 20$

From the above block diagram, the transfer function between the control input and motor speed can be derived:

$$G(s) = \frac{\omega(s)}{V_c(s)} \Bigg| = \frac{k k_T}{(R_a + sL_a) s J_{eq} + k_T k_E} = \frac{k}{k_E} \frac{1}{\left( \frac{L_a J_{eq}}{k_T k_E} s^2 + \frac{R_a J_{eq}}{k_T k_E} s + 1 \right)}$$


The electrical and mechanical time constants of the system are given respectively by:

$$\text{Mechanical time constant } \tau_m = \frac{R_a J_{eq}}{k_T k_E} = \frac{0.37 \times 4.0 \times 10^{-2}}{0.5 \times 0.5} = 0.0592(s)$$


Electrical time constant  $\tau_e = \frac{L_a}{R_a} = \frac{1.5 \times 10^{-3}}{0.37} = 4.05 \text{ (ms)}$

**2.d** The block diagram of the PI current control loop, neglecting the effect of back-emf, is shown below:

(6)




where  $k_{ii}$  and  $k_{pi}$  the integral and proportional gains of the current PI control loop, and  $k$  the gain of the H-bridge converter. The above diagram may be redrawn in the following form:



Use pole-zero cancelling,

$$k_{pi}/k_{ii} = \tau_e$$

the resulting transfer function block diagram is:



The closed loop current transfer function is:

$$\frac{I_a^*(s)}{I_a(s)} = \frac{\frac{k_{ii}k}{R_a s}}{1 + \frac{k_{ii}k}{R_a s}} = \frac{k_{ii}k}{R_a s + k_{ii}k} = \frac{1}{\frac{R_a}{k_{ii}k} s + 1}$$

To achieve the desired time constant of 1.0ms

$$R_a/(k_{ii}k) = 0.001 \quad \text{or} \quad k_{ii} = R_a/(0.001*20) = 18.5$$

$$k_{pi} = k_{ii}\tau_e = 18.5*0.00405 = 0.075$$

- 3.a** Let the currents and induced emfs in phases, a, b, and c of the sinusoidal waveform motor be denoted by  $[i_a \ i_b \ i_c]$  and  $[e_a \ e_b \ e_c]$  respectively, the electromagnetic power is given by: (6)

$$P_{em} = i_a e_a + i_b e_b + i_c e_c$$

and the electromagnetic torque is therefore given by:

$$T_{em} = P_{em} / \omega_m = \frac{1}{\omega_m} (i_a e_a + i_b e_b + i_c e_c) = \frac{1}{\omega_m} [e_a \ e_b \ e_c] \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix}$$

where  $\omega_m$  is the angular speed of the motor.

Since

$$\begin{bmatrix} e_a \\ e_b \\ e_c \end{bmatrix} = \frac{d}{dt} \begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix} = \frac{d}{d\theta} \begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix} \frac{d\theta}{dt} = \frac{d}{d\theta} \begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix} p \omega_m$$

$$\therefore T_{em} = \frac{p \omega_m}{\omega_m} \frac{d}{d\theta} [\Psi_a \ \Psi_b \ \Psi_c] \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} = p \frac{d}{d\theta} [\Psi_a \ \Psi_b \ \Psi_c] \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix}$$

Represent the abc quantities of the flux-linkages and currents in their  $\alpha\beta$  counterparts

$$\begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix} = C_{abc \leftarrow \alpha\beta} \begin{bmatrix} \Psi_\alpha \\ \Psi_\beta \end{bmatrix} ; \quad \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} = C_{abc \leftarrow \alpha\beta} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix}$$

$$\therefore T_{em} = p \frac{d}{d\theta} [\Psi_a \ \Psi_b \ \Psi_c] \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} = p \frac{d}{d\theta} ([\Psi_\alpha \ \Psi_\beta] C_{abc \leftarrow \alpha\beta}^T) C_{abc \leftarrow \alpha\beta} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix}$$

Since the transformation matrix is constant

$$\frac{d}{d\theta} ([\Psi_\alpha \ \Psi_\beta] C_{abc \leftarrow \alpha\beta}^T) = \frac{d}{d\theta} [\Psi_\alpha \ \Psi_\beta] (C_{abc \leftarrow \alpha\beta}^T)$$

For a sine wave motor,

$$\begin{bmatrix} \Psi_\alpha \\ \Psi_\beta \end{bmatrix} = \Psi_m \begin{bmatrix} \cos \theta \\ \sin \theta \end{bmatrix} \quad \therefore \quad \frac{d}{d\theta} \begin{bmatrix} \Psi_\alpha \\ \Psi_\beta \end{bmatrix} = \Psi_m \begin{bmatrix} -\sin \theta \\ \cos \theta \end{bmatrix} = \begin{bmatrix} -\Psi_\beta \\ \Psi_\alpha \end{bmatrix}$$

$$\therefore T_{em} = p \begin{bmatrix} -\Psi_\beta & \Psi_\alpha \end{bmatrix} \left( [C_{abc \leftarrow \alpha\beta}]^T \right) C_{abc \leftarrow \alpha\beta} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix}$$

It can be shown that

$$\begin{aligned} & \left( [C_{abc \leftarrow \alpha\beta}]^T \right) C_{abc \leftarrow \alpha\beta} \\ &= \begin{bmatrix} 1 & -1/2 & -1/2 \\ 0 & \sqrt{3}/2 & -\sqrt{3}/2 \end{bmatrix} \begin{bmatrix} 1 & 0 \\ -1/2 & \sqrt{3}/2 \\ -1/2 & -\sqrt{3}/2 \end{bmatrix} = \frac{3}{2} \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} \end{aligned}$$

Finally

$$\therefore T_{em} = p \begin{bmatrix} \Psi_\alpha & \Psi_\beta \end{bmatrix} \frac{3}{2} \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix} = \frac{3p}{2} \begin{bmatrix} -\Psi_\beta & \Psi_\alpha \end{bmatrix} \begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix} = \frac{3p}{2} (\Psi_\alpha i_\beta - \Psi_\beta i_\alpha)$$


- 3.b** From the motor data, the no-load peak flux linkage is produced by the permanent magnets and is given by: (2)

$$\Psi_m = \sqrt{2} \Psi_{rms} = \sqrt{2} E_{rms} / \omega = \sqrt{2} * 25 / (2\pi * 2 * 1000 / 60) = 0.169 \text{ (Wb)}$$

The motor torque constant is:

$$K_T = 3p \Psi_m / \sqrt{2} = 0.716 \text{ (Nm/Arms)}$$

- 3.c** The transfer function block diagram of the motor in dq reference frame is (4)



$$L_d = L_q = L_s = 3/2 * 4.8 = 7.2 \text{ (mH)}, \quad R = R_a = 4.2 \Omega, \\ K_t = 3p \Psi_m / 2 = 0.506, \quad K_e = p \Psi_m = 0.338, \quad J = 0.005 \text{ kgm}^2$$

- 3.d** To compensate for the coupling terms in the dq axis currents, two new control inputs,  $v'_d$  and  $v'_q$  are used and given by: (8)


$$\begin{aligned} v'_d &= v_d + \omega L_q i_q \\ v'_q &= v_q - \omega L_d i_d \end{aligned}$$

The resultant d, q axis current dynamics are now governed by:

$$L_d \frac{di_d}{dt} + Ri_d = v'_d$$

$$L_q \frac{di_q}{dt} + Ri_q = v'_q - K_e \omega_m$$

Each current component may be controlled by a PI controller as shown below:



Since the current response is much faster than the speed response, the effect of the back emf on the q axis current may be neglected in the controller design.

If the PI current controller takes the form of

$$\frac{k_{ii} + k_{pi}s}{s}$$

and using pole-zero cancelling:

$$k_{pi}/k_{ii} = L_d/R$$

The closed loop transfer function for both d, and q axis currents is:

$$\frac{i_{d,q}(s)}{i_{d,q}^*(s)} = \frac{\frac{k_{ii}}{R s}}{1 + \frac{k_{ii}}{R s}} = \frac{k_{ii}}{R s + k_{ii}} = \frac{1}{\frac{R}{k_{ii}} s + 1}$$

To achieve the desired time constant of 1.0ms

$$R/(k_{ii}) = 0.001 \text{ or } k_{ii} = R/(0.001) = 4.2/0.001 = 4200$$

$$k_{pi} = k_{ii} \tau_e = 4200 * 0.0072 / 4.2 = 7.2$$

Note the gains  $k_{pi}$  and  $k_{ii}$  include the dc gain of the power electronic converter. Finally, the actual control outputs for  $v_d$  and  $v_q$  are :



$$v_d = v'_d - \omega L_q i_q$$

$$v_q = v'_q + \omega L_d i_d$$

**4.a** From the definition for the voltage space vector, and note that (8)

$$e^{j2\pi/3} = \cos \frac{2\pi}{3} + j \sin \frac{2\pi}{3} \quad ; \quad e^{j4\pi/3} = \cos \frac{4\pi}{3} + j \sin \frac{4\pi}{3}$$

$$\begin{aligned} \vec{V}_s &= (2/3)(v_a + v_b e^{j2\pi/3} + v_c e^{j4\pi/3}) \\ &= \frac{2}{3} \left[ V_m \sin \omega t + V_m \sin \left( \omega t - \frac{2\pi}{3} \right) * \left( \cos \frac{2\pi}{3} + j \sin \frac{2\pi}{3} \right) + V_m \sin \left( \omega t + \frac{2\pi}{3} \right) * \left( \cos \frac{4\pi}{3} + j \sin \frac{4\pi}{3} \right) \right] \\ &= \frac{2}{3} V_m \left\{ \left[ \sin \omega t - \frac{1}{2} \sin \left( \omega t - \frac{2\pi}{3} \right) - \frac{1}{2} \sin \left( \omega t + \frac{2\pi}{3} \right) \right] + j \frac{\sqrt{3}}{2} \left[ \sin \left( \omega t - \frac{2\pi}{3} \right) - \sin \left( \omega t + \frac{2\pi}{3} \right) \right] \right\} \\ &= \frac{2}{3} V_m \left\{ \left[ \sin \omega t - \sin \left( \frac{\omega t - \frac{2\pi}{3} + \omega t + \frac{2\pi}{3}}{2} \right) \cos \left( \frac{\omega t - \frac{2\pi}{3} - (\omega t + \frac{2\pi}{3})}{2} \right) \right] \right. \\ &\quad \left. + j \frac{\sqrt{3}}{2} \cos \left( \frac{\omega t - \frac{2\pi}{3} + \omega t + \frac{2\pi}{3}}{2} \right) \sin \left( \frac{\omega t - \frac{2\pi}{3} - (\omega t + \frac{2\pi}{3})}{2} \right) \right\} \\ &= \frac{2}{3} V_m \left\{ \frac{3}{2} \sin \omega t - j \frac{3}{2} \cos \omega t \right\} = V_m \{ \cos(\omega t - \pi/2) + j \sin(\omega t - \pi/2) \} = V_m \angle(\omega t - \pi/2) \end{aligned}$$

The result shows that the magnitude of the voltage space vector is constant and equal to  $V_m$ , whilst its angle varies with time, i.e.,

$$\theta = \omega t - \pi/2$$

This is referred to as rotating vector, and its speed of rotation can be found by

$$\frac{d\theta}{dt} = \omega$$

i.e., equal to the frequency of the applied phase voltage.

**4.b.(i)** (8)


At rated speed of 1450 rpm, the slip  $s$  is given by:

$$s = (1500-1450)/1500 = 0.033$$

For small values of  $s$ ,  $sR_s \ll R_r$  and  $s\omega L_l \ll R_r$ , and the motor electromagnetic torque is proportional to slip  $s$ . Thus, at 50% load torque, the slip  $s$  is 0.0167

The rotor speed is  $1500*(1-s) = 1475$  (rpm)

The equivalent circuit diagram is shown below:



$$R_r/s + j\omega L_{lr} = 0.55/0.0167 + j0.95 = 32.93 + j0.95$$

The equivalent impedance of the parallel of the magnetising branch and the rotor branch is

$$\frac{(32.9 + j0.95)j48.6}{32.9 + j(0.95 + 48.6)} = \frac{1601.3 \angle 91.65^\circ}{59.48 \angle 56.42^\circ} = 26.92 \angle 35.23^\circ = 21.99 + j15.53$$

Total impedance seen from the stator terminal:

$$0.35 + j1.20 + 21.99 + j15.53 = 22.34 + j16.73 = 27.91 \angle 36.82^\circ$$

Stator current

$$I_s = 240 / 27.91 \angle 36.82^\circ = 8.60 \angle -36.82^\circ$$

Power factor

$$\cos \varphi = \cos 36.82^\circ = 0.80$$

Induced air-gap voltage

$$\begin{aligned} E_{ag} &= 240 - (R_s + j\omega L_{ls})I_s = 240 - (1.25 \angle 73.74^\circ)8.60 \angle -36.82^\circ = 231.4 - j6.46 \\ &= 231.49 \angle -1.6^\circ \end{aligned}$$

Rotor current

$$I_r = E_{ag} / (R_r / s + j\omega L_{lr}) = 231.49 \angle -1.6^\circ / (32.94 \angle 1.65^\circ) = 7.03 \angle -3.25^\circ$$

Air-gap flux linkage

$$\Psi_{ag} = E_{ag} / 4.44f = 231.43 / 4.44 / 50 = 1.04 \text{ (Wb)}$$

The electromagnetic torque

$$T_{em} = \frac{3R_r I_r^2}{s\omega_s} = \frac{3 * 0.55 * 7.03^2}{0.0167 * 157.08} = 31.1 \text{ (Nm)}$$

Efficiency

$$\eta = P_{out} / 3I_s V_s \cos \varphi = 31.1 * 154.46 / (3 * 240 * 8.6 * 0.8) = 0.97$$

Note the iron loss is not represented in the equivalent circuit, and therefore the efficiency is slightly overestimated.

**4.b.(ii)**

(4)

At the given operation point of the rated torque at 1000 rpm, the assumption of  $sR_s \ll R_r$  and  $s\omega L_l \ll R_r$  is still valid. Thus the electromagnetic torque is approximately given by:

$$T_{em} = \frac{3pV_s^2}{\omega R_r} s$$

For the same output torque, the following must be true:

$$\frac{V_s^2}{\omega} s = \text{constant} = k_1 \quad (1)$$

On the other hand, in order to maintain approximately constant torque capability for all frequencies of motor operation, the ratio of supply voltage to angular frequency,  $(V_s/\omega)$ , should be kept constant, i.e.,

$$\frac{V_s}{\omega} = \text{constant} = k_2 \quad (2)$$

Substituting  $V_s = \omega k_2$  into (1) yields:

$$\begin{aligned} \omega s &= k_1 / k_2^2 \quad \text{or} \quad \omega \frac{\omega - p\omega_r}{\omega} = \omega - p\omega_r = k_1 / k_2^2 \\ \omega &= k_1 / k_2^2 + p\omega_r \end{aligned}$$

The values for  $k_1$  and  $k_2$  can be found at the rated operating point

$$k_1 = \frac{V_s^2}{\omega} s = \frac{240^2}{314} 0.033 = 6.05$$

$$k_2 = \frac{V_s}{\omega} = \frac{240}{314} = 0.764$$

The supply angular frequency at 1000 rpm is

$$\omega_1 = k_1 / k_2^2 + p\omega_r = 6.05 / 0.764^2 + 2 * 1000 * 2 * \pi / 60 = 219.8 \text{ (rad/s)}$$

The frequency and voltage are

$$\begin{aligned} f_l &= 219.8 / (2\pi) = 34.98 \text{ (Hz)} \\ V_s &= 0.764 * 219.8 = 167.93 \text{ (V)} \end{aligned}$$